



FLIGHT READINESS STATEMENT

STS-107/ET-93

EXTERNAL TANK PROJECT

DELTA PRE-FLIGHT REVIEW



EXTERNAL TANK ET-93/STS-107, AS IDENTIFIED IN THE EXTERNAL TANK PROJECT PRE-FLIGHT DELTA REVIEW DATED DECEMBER 16, 2002, IS CONSIDERED READY TO SUPPORT FLIGHT UPON ACCEPTABLE DISPOSITION OF OPEN/PLANNED WORK AND/OR OPEN ACTIONS.


T. F. GREENWOOD/MP31


for J. BULLMAN/ED10


for P. M. MUNAFO/ED30



for A. C. ADAMS/QS20


A. A. MCCOOL/MP01


P. K. McCONNAUGHEY/ED20


S. D. ROSE/ED40


J. S. CHAPMAN/TD01


J. W. SMELSER/MP31, CHAIRMAN

December 16, 2002

**Space Shuttle
External Tank**

Delta Pre-Flight Review

STS-107/ET-93

Agenda

Overview

Program Events Summary

Prior Mission Performance Summary

Current Mission/External Tank Highlights

Special Topic - Vent Valve Relief Pressure

SRM&QA Assessment

KSC Processing

Verification/Certification

Mission Unique Assessment

Readiness Statement

Appendices

- A: Minor Changes
- B: SRM&QA Assessment
- C: KSC Processing
- D: Level II Waivers/Level III Deviations

Lynn Servay

Brian Piekarski
Terry McKeough
Scott Otto
Lynn Servay

Overview

This review includes an updated status of items relative to STS-107 and ET-93

- Summary of changes in the Shuttle mission manifest
- Updated assessment of the STS-107 mission
- Changes to the ET-93 baseline review
 - Requirement changes and items not previously reviewed / flown

FRR Series

• ET/SRB Mate Milestone Review	05/06/2002 (A)
• Michoud Operations President's Review	05/14/2002 (A)
• Pre-Flight Review	06/21/2002 (A)
• Delta ET/SRB Mate Milestone Review	11/01/2002 (A)
• Delta Pre-Flight Review	12/16/2002
• Space Shuttle Vehicle FRR	01/09/2003
• Mission Management Team (L-2 Day)	01/16/2003

Program Events Summary

ET-93 was initially scheduled to fly on STS-107 in July 2002

- ET-93 Project Pre-Flight Review was held in June 2002

Mission was delayed until January 2003 due to programmatic issues

- In June 2002 cracks in flow liners on the OV-104 during inspections of the feedlines
 - Subsequent inspections revealed flow liner cracks all Orbiters
- Delay in the STS-107 was required to develop rationale or repair methods for flow liner cracks, but effects on subsequent missions had to be considered
- Program evaluated options and determined best approach to meet program needs while assuring the safety of the vehicle
 - Mission objectives and available launch dates/windows considered
 - OV-102 had different flow liner configuration than other Orbiters
 - Reallocation of hardware was necessary to meet objectives
- Final manifest moved STS-112 and STS-113 ahead of STS-107
 - Demate of STS-107 was required due to booster stack availability

Prior Mission Performance Summary

STS-113/ET-116, Launch Scrubs

System

11/10/2002

*(High O2 concentration in Orbiter
Midbody Compartment)*

- **OMRSD**

- No ET violations

- **LCC**

- No ET violations

- **Instrumentation**

- Nominal performance

- **MPS**

- No ET issues

- **ET Hazardous Gas**

- No ET violations

- **TPS**

- All observations acceptable per NSTS 08303
 - Typical crack observed in -Y vertical strut closeout
 - One crack observed on Intertank stringer panels

11/22/2002

(Weather violations at TAL site)

- No ET violations

- No ET violations

- Nominal performance

- No ET issues

- No ET violations

- All observations acceptable per NSTS 08303
 - Typical crack observed in -Y vertical strut closeout
 - Ten cracks observed on Intertank stringer panels

Prior Mission Performance Summary

STS-113/ET-116, 11/23/2002 Launch

<u>System</u>	<u>Performance</u>
• OMRSD	• No ET violations
• LCC	• No ET violations
• Instrumentation	• Nominal performance
• MPS	• Nominal performance
• ET Hazardous Gas	• No ET violations
• TPS	• Conditions noted during previous tanking unchanged • Frost/crack observed on side of bipod ramp • Acceptable per NSTS 08303 • Cracks observed in -Y Longeron closeout • MR rationale provided; no impact to countdown
• ET Disposal	• Nominal
• Film Review – Post-Launch Post-Flight	• No ET Issues • Film not available
• Orbiter Tile Damage	• Lower surface hits forward of main landing gear • STS-113: 43 with 6 > 1" • Average: 30 with 6 > 1"

Mission/External Tank Highlights

STS-107/ET-93, 01/16/2003

Mission

Launch

- Window
- Pad
- Orbiter
- Orbital Inclination
- ET Photo Coverage

Primary Payload

Landing

STS-107

* 01/16/2003

2h 30m

* A

Columbia (OV-102)

39° - Insertion at 150 NM

- Crew photos from cockpit window
- Umbilical well cameras

FREESTAR - Fast Reaction Experiments
Enabling Science, Technology, Applications &
Research

* 02/01/2003 at KSC

External Tank

DD250 Acceptance

Shipped to Launch Site

Mass Properties Update

ET-93

11/02/2000

12/14/2000

* Coordination with Level II on December 4,
2002 indicates approximately 857 lbs.
performance margin for STS-107

* Updates since ET-93 Baseline PFR

Agenda

Overview

Program Events Summary

Prior Mission Performance Summary

Current Mission/External Tank Highlights

Special Topic - Vent Valve Relief Pressure

SRM&QA Assessment

KSC Processing

Verification/Certification

Mission Unique Assessment

Readiness Statement

Appendices

- A: Minor Changes
- B: SRM&QA Assessment
- C: KSC Processing
- D: Level II Waivers/Level III Deviations

Lynn Servay

Brian Piekarski

Terry McKeough

Scott Otto

Lynn Servay

Special Topic – Vent Valve Relief Pressure

Issue

- During review of requalification data from the new Vent / Relief Valve supplier, reduced relief pressures were observed for qualification testing
 - All data points were within the requirements in the Procurement Document
- When considering scatter in the valve cracking pressure, there is reduced margin to relief during LH2 tank pre-pressurization

Background

- At ET-101, the margin between the minimum ATP relief pressure and the maximum pressure allowed during pre-press was reduced to accommodate the use of three Block II SSMEs
 - Reduced margin applies only for missions using three Block II SSMEs
 - Four missions have flown with three Block II SSMEs
- Valve designer and engineers early in the program were aware that the valve can relieve at pressures lower than the ATP test pressures
 - Due to effects of environmental conditions (temperature, pressure, vibration) and wear

Special Topic – Vent Valve Relief Pressure


Discussion

- After noting the scatter in the valve relief pressures during qualification, MAF conducted a review of data to determine significance
 - Minimum ATP relief pressures have historically been used for on-pad and in-flight venting analyses
 - Greatest deviation on a qualification unit was 1.52 psi below the average cryogenic ATP relief pressure
- Initial assessment of STS-107/ET-93 was performed using a worst case relief pressure of 1.52 psi less than the minimum relief pressure recorded for ET-93 ATP
 - GO2 valve performance during pre-press and flight
 - GH2 valve performance during pre-press and flight including 1 GH2 flow control valve failed open at engine start and multiple failure cases
 - 5 minute holds at T-31 seconds
 - RTLS
 - ET Separation
- LH2 tank during pre-pressurization was the only case showing insufficient margin when considering the potentially lower relief pressure

Special Topic – Vent Valve Relief Pressure

Summary of Requirements

LH2 Ullage Pressure During Pre-Pressurization



Special Topic – Vent Valve Relief Pressure

Analysis Details

- Additional assessment using ET-93 ullage pressure transducer biases was performed to develop flight rationale
 - Analysis shows positive margin between minimum relief pressure and the maximum pressure allowed during pre-press
- When considering past performance of the H2 pressurization system, greater margin is expected

	<u>Worst Case</u>	<u>ET-93 Assessment</u>
Minimum ATP Relief Pressure	35.00 psig	35.80 psig
Ambient Pressure	<u>14.53 psia</u>	<u>14.53 psia</u>
Elevation correction	49.53 psia	50.53 psia
Potentially Lower Relief	<u>-0.10 psi</u>	<u>-0.10 psi</u>
	49.43 psia	50.23 psia
	<u>-1.52 psi</u>	<u>-1.52 psi</u>
	47.91 psia	48.71 psia
Max Pre-Press pressure	<u>48.90 psia</u>	Worst Case <u>48.66 psia</u>
Margin to Relief	-0.99 psi	Expected <u>47.83 psia</u> 0.88 psi

Special Topic – Vent Valve Relief Pressure

Analysis Details (continued)

- Assessment of past system performance on missions with the higher pre-pressurization band required for Block II SSMEs

	<u>STS-110</u>	<u>STS-111</u>	<u>STS-112</u>	<u>STS-113</u>
ATP Relief Pressure	35.80 psig	36.00 psig	35.80 psig	36.00 psig
Ambient Pressure	<u>14.77 psia</u>	<u>14.64 psia</u>	<u>14.62 psia</u>	<u>14.77 psia</u>
Elevation correction	50.57 psia	50.64 psia	50.42 psia	50.77 psia
	<u>-0.10 psi</u>	<u>-0.10 psi</u>	<u>-0.10 psi</u>	<u>-0.10 psi</u>
Potentially Lower Relief	50.47 psia	50.54 psia	50.32 psia	50.67 psia
	<u>-1.52 psi</u>	<u>-1.52 psi</u>	<u>-1.52 psi</u>	<u>-1.52 psi</u>
	48.95 psia	49.02 psia	48.80 psia	49.15 psia
Max Pre-Press pressure	<u>47.91 psia*</u>	<u>47.73 psia*</u>	<u>47.86 psia*</u>	<u>47.81 psia*</u>
Margin to Relief	1.04 psi	1.29 psi	0.94 psi	1.34 psi
* Corrected for transducer biases				

Special Topic – Vent Valve Relief Pressure

Rationale for Flight

- Analysis of STS-107/ET-93 shows margin between the minimum predicted valve relief pressure and the maximum ullage pressure during prepress allowed in the LCC
 - Based on a review of the vent valve ATP relief pressures and the transducer biases for ET-93
- Review of historical LH2 pressurization performance shows the system does not typically operate near the upper LCC limit

Agenda

Overview
Program Events Summary
Prior Mission Performance Summary
Current Mission/External Tank Highlights
Special Topic - Vent Valve Relief Pressure
SRM&QA Assessment
KSC Processing
Verification/Certification
Mission Unique Assessment
Readiness Statement
Appendices

- A: Minor Changes
- B: SRM&QA Assessment
- C: KSC Processing
- D: Level II Waivers/Level III Deviations

Lynn Servay

Brian Piekarski
Terry McKeough
Scott Otto
Lynn Servay

SRM&QA Assessment

as of 12/12/2002

Item

ALERTS

Status

None

MRB Assessment

Complete - No issues/no impact to hazard controls

Hazard Assessment

Complete - All hazard reports were re-assessed and hazard controls verified

CIL Retention Rationale

Complete - No issues/no impact to CIL retention rationale

Corrective Action Problem Summary (CAPS)

- S-089, Undersized Intertank Stringers
ET-93 cleared – Part thickness inspected upon completion of fabrication
- E-170, Level Sensor ATP Failure
ET-93 cleared –Sensors passed ATP

Agenda

Overview
Program Events Summary
Prior Mission Performance Summary
Current Mission/External Tank Highlights
Special Topic - Vent Valve Relief Pressure
SRM&QA Assessment
KSC Processing
Verification/Certification
Mission Unique Assessment
Readiness Statement
Appendices

- A: Minor Changes
- B: SRM&QA Assessment
- C: KSC Processing
- D: Level II Waivers/Level III Deviations

Lynn Servay

Brian Piekarski
Terry McKeough
Scott Otto
Lynn Servay

KSC Processing - Status

as of 12/12/2002

STS-107 Demate

- TPS on aft ET/SRB fairings was damaged as a result of STS-107 demate activities
 - Fairings successfully refurbished at MAF and returned to KSC

Discrepancy Reports (DRs)/Problem Reports (PRs) Review

- PR/MRB discrepancies/dispositions similar to previously flown vehicles
 - All KSC/MRBs have been reviewed by MAF Reliability for potential SMR
 - No items were elevated to the SMR

Limited Life Component/ET Status

- Updated assessment of limited life components complete
 - All within required life through scheduled launch date plus 90 days

OMRSD Exceptions/Waivers: None

KSC Processing –Status

as of 12/12/2002 – Updates to ET-93 Baseline PFR

Changes

STS-107/ET-93

- ET modifications

- Mod Kits 0
- DC&R 0
- Bldg 45 0
- FEC 0
- OMRSD 2

- Description on subsequent chart

- RCN SS15815 – ET Sensor Requirements
- RCN SS15970 – ET/Orb Visual Leak Monitoring

- LCC

1

- Description on subsequent chart

- LCN 01109 – ET/ORB Visual Leak Monitoring

- Software

0

- GSE Modifications

0

SIM Launch (S0044)

12/06/02

SIM Load (S0056)

12/17/02

KSC Processing

Program Requirement Changes

Two proposed requirement updates for the upcoming mission affect ET systems

- Changes pending approval

ET Sensor Requirements for LO2 Loading (OMRS – RCN SS15815)

- Added/revised tables to clarify the functional requirements of the point level sensors
- Updates will allow certain level sensor failures during LO2 loading without a waiver
- Updates do not compromise the intent of the requirement
- Sensor failures will still be documented in PRACA for recurrence control

ET/Orbiter Propellant Leak Visual Monitoring during cryogenic load

- Relocate requirements for from OMRSD to LCC
- No change in the requirement to visually monitor
 - OMRSD – RCN SS15970 deleted requirement to monitor leakage during cryo load and created a requirement to monitor propellant leakage during a scrub turnaround (OMRSD RCN SS15970)
 - LCC – LCN 1109R1 deleted visual leak monitoring from HAZ-12 and created SSID ICE-04 for the visual leak monitoring

Agenda

Overview

Program Events Summary

Prior Mission Performance Summary

Current Mission/External Tank Highlights

Special Topic - Vent Valve Relief Pressure

SRM&QA Assessment

KSC Processing

Verification/Certification

Mission Unique Assessment

Readiness Statement

Appendices

- A: Minor Changes
- B: SRM&QA Assessment
- C: KSC Processing
- D: Level II Waivers/Level III Deviations

Lynn Servay

Brian Piekarski

Terry McKeough

Scott Otto

Lynn Servay

Verification/Certification

as of 12/12/2002 – Updates to ET-93 Baseline PFR

Item

Status

NSTS 07700, Volume X, Book 1, Baseline

- Revision M, Change 287

Complete - No Issues

Certification documentation

- Hardware Certification Sheets (HCS)
- Certificates of Qualification (COQ)

No new items since baseline review

Waivers/Deviations

No new items

STS-107 Mission Unique Assessment - Update as of 12/12/2002

Category/Item

STS-107 Liftoff Loads Environments

- One ET indicator exceeded the defined limit
 - Assessment shows exceedance is acceptable
 - ET EIS design FS requirements not violated

Status

- Assessment complete and response documented
 - No Issues

Review of MRB actions using updated loads

- Assessment complete
 - No issues

MPS Preflight Prediction

- Mission specific trajectories provided for STS-107
- Boeing assessment indicates potential ICD pressure violations
 - Discussed in subsequent chart

Debris from BSM during SRB Separation

- Boeing identified that contaminant (RTV) in BSM would potentially impact ET
 - Assessment complete
 - No ET issues identified

**All items were identified at the ET-93 Baseline PFR with open status*

STS-107/ET-93 Status

Mission Unique Assessment

LO2 Tank Predicted ICD Pressure Violation

- Boeing performed preflight mission specific MPS predictions and identified potential ICD pressure violations for the LO2 tank for nominal and RTLS missions
 - Predictions used 100.15% liquid load and updated trajectory and hardware performance data
 - Normal Mission Max Limit: 0.15 psi violation between 82 and 102 seconds
 - Normal Mission Min Limit: 0.85 psi violation between 0 and 1 seconds
0.25 psi violation between 2 and 8 seconds
 - RTLS Minimum Limit: 0.3 psi violation between 0 and 0.5 seconds
0.15 psi violation between 3 and 7 seconds
- Analysis has been performed for the predicted LO2 tank ICD ullage pressure violations for the STS-107 mission (ET-93) with no issues identified
 - Critical structural margins of safety are unaffected for the new predicted maximum and minimum ICD limits
- Waiver to LO2 Ullage Pressure ICD requirement was processed
 - IRN written by Boeing Propulsion Integration (KSC/JSC)
 - Approved by PSIG and Loads Panel on 12/2/2002
 - CR S061917 was approved at the 12/10/2002 ICB

Readiness Statement

**The External Tank, ET-93, is certified
and ready for STS-107 flight pending
completion/closure of open and planned work**

Appendices

A: Minor Changes

- No updates to ET-93 Baseline PFR

B: SRM&QA Assessment

- No updates to ET-93 Baseline PFR

C: KSC Processing – Updates to ET-93 Baseline PFR

- PR/MRB Summaries

D: Level II Waivers/Level III Deviations

- No updates to ET-93 Baseline PFR

ET-93 DR/PR/OMRSD Waiver/Exceptions

as of 12/12/2002 – Update to ET-93 Baseline PFR

System	Discrepancy	Problem	MRB Items	Exceptions/ Waivers
• Electrical	0	2	0	0
• Propulsion/ Pneumatics	0	4	0	0
• Structures	4	14	0	0
• Thermal (TPS)	0	16	4	0
Total	4	36	4	0

ET-93 PR/MRBs

as of 12/12/2002 – Items Assessed Since ET-93 Baseline PFR

<u>PR No.</u>	<u>Title/Description</u>	<u>Disposition</u>
ET-93-TS-0008	Foam Damage Aft of ET/SRB Fitting (+Y/-Y)	MRB approved for use-as-is Subsequent closeout will accommodate localized defects
ET-93-TS-0009	Foam Damage Fwd of ET/SRB Fitting (+Y/-Y)	MRB approved for use-as-is Subsequent closeout will accommodate localized defects
ET-93-TS-0014	Voids in Fwd periphery Closeout of –Y ET/SRB Fairing	MRB approved to rework and repair periphery closeout