


FLIGHT READINESS STATEMENT
STS-88/ET-97
EXTERNAL TANK PROJECT
PRE-FLIGHT REVIEW

EXTERNAL TANK ET-97/STS-88, AS IDENTIFIED IN THE EXTERNAL TANK PROJECT
PRE-FLIGHT REVIEW DATED OCTOBER 22, 1998, IS CONSIDERED READY TO SUPPORT FLIGHT
UPON ACCEPTABLE DISPOSITION OF OPEN/PLANNED WORK AND/OR OPEN ACTIONS.


E. C. SMITH/EB01


J. L. LUSK/EE31



A. F. WHITAKER/EH01


A. O. GOODSON/CR01


J. W. KILPATRICK/EL01


B. E. GOLDBERG/ED01


M. D. SMILES/CR70


P. V. COUNTS/SA31, CHAIRMAN

ANSY S.M.B.'s on

Space Shuttle
External Tank

October 22, 1998

STS-88/ET-97
Pre-Flight Review

*1 ACTION: PWC SET UP SEPARATE REVIEW WITH RECORDS TO OUTF. SPEC
#2 ACTION: LAM JIM, FEZBY BLACK/WHITE CHARTS CURRENTLY STANDING THAT OUTF. SPEC CONDITION IS NO IMPACT FOR FLIGHT (RATIONALE FOR FLIGHT)

ATTACH TO MINUTES OF THIS FRZ

REMOVE RELOCATION CHARTS FROM MAINLINE PATCH. ~~KEEP~~ AS A BACKUP CHART FOR LEVEL III ROOM MAP

PWC CONSIDER NO LOWER I CAN ON SMALL INDICATIONS SINCE THEY WERE FIRST BRICKEN TO WHAT FOR ROW 1ST INDICATION TO BEFLOWN (ET 98/ STS 95)

FEZBY ADD TWO ITAMS TO INDICATIONS & BACKGROUND DOCUMENT REVIEW w/ HANNOY - GLOW GREEN ETAL STATE PROBABILITY OF DETECTION RATES

TIPS

- 1) ADD PDL RECORDS
 - 2) ADD RATIONALE FOR FLIGHT WKE ET 98
- OPEN LEVEL III WANNER

Michoud Space Systems

Agenda

- **Overview**
 - ***Current Mission/External Tank Highlights***
 - ET-97 Mass Properties Status
 - Changes
 - Senior Management Review NCD
 - Special Topics
 - SRM&QA Assessment
 - KSC Processing
 - Verification/Certification
 - Mission Unique Assessment
 - Readiness Statement
 - Appendices
 - A: Minor Changes
 - B: SRM&QA Assessment
 - C: KSC Processing
 - D: Previously reviewed material
- Jim Feeley*
- Rick Spring
- Presented as Special Topic
- Terry McKeough
Bill Brandow
Jim Feeley

Overview

- This review for STS-88/ET-97 includes:
 - Items specific to mission STS-88
 - First time changes, differences and “out of family” non-conformances not previously flown and/or reviewed
- **FRR Series**
 - ET/SRB Mate Review 09/16/98
 - Pre-flight Review 10/22/98
 - Space Shuttle Vehicle FRR 11/23/98
 - Mission Management Team (L-1 Day) 12/02/98

Mission/External Tank Highlights

STS-88/ET-97, 12/03/98

Mission

• Launch	<u>STS-88</u>
- Window	12/03/98
- Pad	0445-0455 EST
- Orbiter	A
- Orbital inclination	Endeavour (OV-105)
- ET photo coverage	51.6° - Insertion at 173 NM
• Primary payload	• Crew photos from cockpit window
• Landing	• Umbilical well cameras
- Time	ISS-2A
- Location	12/14/98
	2314 EST
	KSC

External Tank

• DD250 acceptance	<u>ET-97</u>
• Shipped to launch site	3/30/98
	4/02/98

Agenda

- Overview
- Current Mission/External Tank Highlights
- ***ET-97 Mass Properties Status***
- Changes
- Senior Management Review NCD
- Special Topics
- SRM&QA Assessment
- KSC Processing
- Verification/Certification
- Mission Unique Assessment
- Readiness Statement
- Appendices
 - A: Minor Changes
 - B: SRM&QA Assessment
 - C: KSC Processing
 - D: Level II Waivers/Level III Deviations

Jim Feeley

Rick Spring

Presented as Special Topic

Terry McKeough
Bill Brandow
Jim Feeley

ET-97 Mass Properties Status

Issue:

- ET-97 Weight Status (predicted vs. as-weighed)

Background:

- The specification weight for ET-97 is 57,911 lbs
- The nominal control weight for SLWT is 58,005±511 lbs
 - ET-97 was weighed 4/14/98
 - Predicted 57,819 lbs
 - As-weighed 58,244 lbs
 - Delta + 425 lbs
- ET-97 predicted weight meets specification weight requirement
- ET-97 as-weighed weight meets control weight requirement
- ET-97 as-weighed weight exceeded specification weight by 333 lbs
- Revisions to the weight prediction methodology in work to account for delta between predicted and as-weighed weight
 - C/S J31199 Major Assembly Weighing Activity
- CR S060513L is being processed which will revise current control weight to 58,505 ±511 lbs

Propellant Tank Reallocations

J31195/J31195A

Change:

- Reallocated ET-98 LO2 Tank to ET-97

Background/ Reason:

- Management decision to reallocate tanks
 - Standard Procedure 49:12
- Earliest available hardware allocated to first delivered effectivities
 - ET-98 LO2 tank passed proof test before ET-97 LO2 tank

Propellant Tank Reallocations

J31195/J31195A

Summary of SLWT Tank Allocations

			ET As Built		
Mission	Date	ET DD250	LO2	LH2	I/T
STS-91	06/02/98	96	96	96	96
STS-95	10/29/98	98	97	99	98
STS-88	12/03/98	97	98	97	97
STS-93	01/21/99	99	99	98	99
STS-96	05/13/99	100	101	100	100
STS-92	06/17/99	101	102	101	101
STS-97	08/05/99	102	100	102	102
		103	103	103	103

Bold = Missions/Tanks flown
Shaded = Planned Missions

Propellant Tank Reallocations

J31195/J31195A

Basis for
Certification:

Test	Analysis	Similarity	Inspection
X		X	X

- Test/Inspection
 - Methodology: Fracture based proof test and inspection ensures all undetected flaws will not cause failure in 4 mission lives (as demonstrated by coupon testing)
 - Results:
 - Successful proof test demonstrated performance consistent with fracture test program
- Similarity
 - Design requirements identical
 - All parts are either identical or incorporate minor changes that have no effect on form, fit or function
 - No COQ or HCS impacts

Implementation of Dual Cover Pass

J31188

Change:

- Implemented dual cover pass weld process on the LO2 tank O3 and O4 welds



Background/ Reason:

- High incidence of pre- and post-proof cracks on circumferential welds at longitudinal weld intersections
- Dual cover pass reduces sensitivity to intersection cracking and subsequent repairs
 - Eliminates the residual stress element associated with cross-over cover passes
- Implemented on STS-95/ET-98 at several locations
 - LO2 tank: O5 weld
 - LH2 tank: H1 thru H8 welds

Implementation of Dual Cover Pass

J31188

Implement Dual Cover Pass on STS-88/ET-97 O3 and O4 Welds



* Previously implemented on STS-95/ET-98

Implementation of Dual Cover Pass

J31188

Basis for
Certification:

Test	Analysis	Similarity	Inspection
X	X		X

- Test/Inspection
 - Methodology: Fracture based proof test and inspection ensures all undetected flaws will not cause failure in 4 mission lives (as demonstrated by coupon testing)
 - Results:
 - Successful proof test demonstrated performance consistent with fracture test program
 - Demonstrated load capability in proof greater than 100% of flight limit load (O3,O4: 118%-220%)
 - Dual cover pass weld allowables and weld certification developed
 - Allowables met or exceeded those for single cover pass
 - Design allowables remain unchanged
 - Factor of safety analysis unchanged for certification of dual cover pass weld programs

Implementation of Dual Cover Pass

J31188

**Basis for
Certification
(continued):**

- Analysis
 - Methodology: NASTRAN, BOSOR, Weld Margin Programs
 - Requirements/Results:
 - Weld Factors of Safety unchanged
 - No change in weld design allowables

Agenda

- Overview
 - Current Mission/External Tank Highlights
 - ET-97 Mass Properties Status
 - Changes
 - **Senior Management Review NCD**
 - **Special Topics**
 - SRM&QA Assessment
 - KSC Processing
 - Verification/Certification
 - Mission Unique Assessment
 - Readiness Statement
 - Appendices
 - A: Minor Changes
 - B: SRM&QA Assessment
 - C: KSC Processing
 - D: Previously reviewed material
- Jim Feeley
- Rick Spring
- Presented as Special Topic***
- Terry McKeough
Bill Bradow
Jim Feeley

Special Topics

Presenter

- ODG Post Proof NDE Indications
 - LH2 Tank Post Proof X-Ray Indications *
 - Intertank Thrust Panel Foam Loss
(IFA STS-87-T-01)
- Don Bolstad
- Jim Feeley

* *Senior Management Review NCD*

ODG Post Proof NDE Indications

Issue:

- Acceptance of lack of fusion indications on LO2 tank ODG (LO2 tank dome gore) welds

Background:

- Faint linear indication was noted on both sides of ODG-7 weld during post proof X-ray on ET-98 LO2 tank
- Examination of weld with ultrasonic testing (UT) revealed a flat bottom defect (interpass lack of fusion)
 - Approximately 0.20" wide and 15" long
 - NCD disposition was to repair, planish and reproof
- Following ET-98 detection and repair, similar indications were found by UT on ET-97
 - No x-ray indication
- Discovery led to extensive investigation on cause of defect, potential structural impacts, and corrective actions

ODG Post Proof NDE Indications

Discussion:

- Post proof inspection (UT) of the ET-97 LO2 tank detected defects on ODG-6 and ODG-7 welds
- Cause determined to be interpass (I/P) lack of fusion
 - Cover pass did not completely fill the gap between the penetration pass and adjacent weld land
- Structural assessment shows the defect orientation is such that they have no impact to tensile or fracture strength as long as not detectable by x-ray
 - ET-97 ODG-6 and ODG-7 defects were not a threat and were candidates for use-as-is
- Weld defect cause is well understood
- Corrective action initiated
 - Penetration pass modified to eliminate deep gap
 - Depth of cover pass increased
- MAF and MSFC Fracture Control Boards concurred on use-as-is dispositions

ET97ptr.4250.js.10/98



ODG Post Proof NDE Indications

Basis for Certification:

Test	Analysis	Similarity	Inspection
X	X		X

- Test/Inspection
 - Methodology:
 - Reviewed existing test data
 - Performed 86 room temperature and 37 cryogenic tensile tests
 - Performed 74 simulated service tests
 - Results
 - Assessment shows no impact on tensile and fracture strength
 - Successful proof and post proof NDE
- Analysis
 - Correlated test specimen results with NDE indications (x-ray and UT)
 - Established conservative criteria for acceptance of UT indications
 - X-ray indication: repair weld
 - No x-ray indication: use-as-is

LH2 Tank Post Proof X-Ray Indications


Issue:

- Acceptance of small x-ray indications on LH2 tank H4 and H6 welds

Background:

- Two linear indications detected by x-ray after ET-97 LH2 tank proof test
 - H4 weld @ 779" 0.045" indication
 - H6 weld @ 390" 0.030" indication
- Because of the small size of the indications, an analysis performed to determine suitability of use as is disposition
- ✓ • MAF and MSFC Fracture Control Boards approved indications "use-as-is"

LH2 Tank Post Proof X-Ray Indications



LH2 Tank Post Proof X-Ray Indications

Basis for Certification:

Test	Analysis	Similarity	Inspection
X	X	X	X

- Analysis
 - Methodology: JSC FLAGRO fracture analysis program
 - Assumes worst case orientation for flaw
 - Assumes worst-case stresses (outer fiber stress used as thru-the-thickness stress)
 - Assumes reported flaw size is 2x in mission life prediction
 - Results:
 - Critical flaw size $\geq 0.500''$
 - > 1000 mission lives

LH2 Tank Post Proof X-Ray Indications

Basis for Certification (continued):

- Test/Inspection
 - Methodology: Fracture based proof test and inspection ensures all accepted flaws will not cause failure in 4 mission lives (as demonstrated by coupon testing)
- Results
 - Successful proof test demonstrated performance consistent with fracture test program
 - H6: Minimum 108% limit load demonstrated in proof
 - H4: Minimum 97% limit load demonstrated in proof
 - Successful proof and post proof NDE
 - Over 600 fracture tests with AI 2195
- Similarity
 - LWT program has accepted post proof indications for flight
 - Same discipline used to develop AI 2195 data base as used on AI 2219

Intertank Foam Loss

STS-88/ET-97 Thrust Panel Foam Summary

- NASA and Lockheed Martin Investigation Team continue to work foam loss root cause scenario
 - Definitive cause of foam loss undetermined
 - Aggressive test program underway
- STS-88/ET-97 Intertank foam configuration (machined NCFI 24-124 with SS-1171 circumferential rib closeouts) same as flown on STS-91/ ET-96
 - STS-91 post separation photo resolution not sufficient to assess circumferential rib closeout material (SS-1171) performance
 - Orbiter tile hits > 1”
 - STS-91: 45
 - Average: 13
 - Tile replacement not required
- STS-88/ET-97 material properties comparable to STS-91/ET-96
- Waiver to NSTS 07700, Vol. X approved and waiver to EIS processed to document possible ET debris generation
- No constraint to flight
 - Loss of thrust panel foam loss is not a safety of flight concern
 - Orbiter turnaround maintenance issue only

Intertank Foam Loss

Material Properties Comparison

Foam Property	Requirement	STS-91/ET-96	STS-88/ET-97
• NCFI 24-124 – Tensile – Density	30 psi 2.0 - 2.8 psi	40.9 avg (38.2/43.6) 2.40/2.40	46.9 avg (44.3/49.5) 2.38/2.42
• SS-1171 – Tensile +Y -Y – Density +Y -Y	35 psi 1.8 - 2.6 psi	43.5 avg (44.7/42.3) (44.7/42.3) 2.37 avg 2.41/2.34 avg 2.41/2.34 avg	42.1 (39.7/40.6) (47.1/41.2) 2.75 avg 2.93/3.06 avg * 2.55/2.48 avg

* Non-conformance for density out of specification condition accepted per NCD/MRB

Agenda

- Overview
 - Current Mission/External Tank Highlights
 - ET-97 Mass Properties Status
 - Changes
 - Senior Management Review NCD
 - Special Topics
 - ***SRM&QA Assessment***
 - KSC Processing
 - Verification/Certification
 - Mission Unique Assessment
 - Readiness Statement
 - Appendices
 - A: Minor Changes
 - B: SRM&QA Assessment
 - C: KSC Processing
 - D: Previously reviewed material
- Jim Feeley
 Rick Spring
 Presented as Special Topic

Terry McKeough
 Bill Brandow
 Jim Feeley

SRM&QA Assessment

as of 10/20/98

Item

- Alerts

Status

None Open

- MRB Assessment

Complete - No issues/no impact to hazard controls

- Hazard Assessment

Complete - All hazard reports were re-assessed and hazard controls verified

- Corrective Action Problem Summaries (CAPS)

- T-067PF, Loss of Intertank SOFI during Ascent of STS-87/ET-89

Closed pending action

- Previously discussed as Special Topic

KSC Processing - Status

as of 10/20/98

- Discrepancy Reports (DRs)/Problem Reports (PRs) Review
 - All PR/MRB discrepancies/dispositions similar to previously flown vehicles
 - All MRBs have been reviewed by MAF Reliability for potential SMR
- Limited Life Component/ET Status
 - All within required life through scheduled launch date plus 90 days
- OMRSD Exceptions/Waivers: None

KSC Processing - Status

as of 10/20/98

• Changes		
- ET modifications		
• Mod Kits	0	
• DC&R	0	
• Bldg 45 support	1	- Temp/Press recordings to ET-97 weighing *
• FEC	1	- LO2 Ogive TPS Trim *
- OMRSD/LCC	0	
- Software	0	
• SIM Load (S0044)	10/14/98	
• SIM Launch (S0056)	11/11/98	

* Previously implemented/flowed

Agenda

- Overview
- Current Mission/External Tank Highlights
- ET-98 Mass Properties Status
- Changes
- Senior Management Review NCD
- Special Topics
- SRM&QA Assessment
- KSC Processing
- ***Verification/Certification***
- ***Mission Unique Assessment***
- Readiness Statement
- Appendices
- A: Minor Changes
- B: SRM&QA Assessment
- C: KSC Processing
- D: Previously reviewed material

Jim Feeley

Rick Spring

Presented as Special Topic

Terry McKeough

Bill Brandow

Jim Feeley

Verification/Certification

as of 10/20/98

Item

Status

- | | |
|---|--|
| <ul style="list-style-type: none">• NSTS 07700, Volume X Baseline<ul style="list-style-type: none">- Revision L, Change 246 | No Issues |
| <ul style="list-style-type: none">• Certification documentation<ul style="list-style-type: none">- Hardware Certification Sheets (HCS)- Certificates of Qualification (COQ) | Complete - No Issues |
| <ul style="list-style-type: none">• Waivers/Deviations<ul style="list-style-type: none">- Evidence from prior flights showed Intertank foam loss- Potentially violates "debris prevention" paragraph in Level II and Level III specification | <ul style="list-style-type: none">• Level II waiver approved by PRCBD S082962A (10/2/98)• Level III DAR pending MSFC approval |

Mission Unique Assessment

as of 10/20/98

Category/Item

STS-88

- Review of MRB actions using updated loads ECD 11/20/98
- MPS Preflight Prediction Package ECD 11/20/98

Readiness Statement

The External Tank, ET-97, is hereby certified
and ready for STS-88 flight pending
completion/closure of open and planned work

Terry L. Hibbard
Vice President, External Tank Project
Lockheed Martin Michoud Space Systems

Appendices

- A: Minor Changes
- B: SRM&QA Assessment
 - NCD Assessment Criteria
- C: KSC Processing
 - Limited Life Components
 - Modification Summaries/Status
 - Alternate Blowing Agent Usage at KSC
 - Software Changes: None
 - OMRSD Exceptions/Waivers: None
 - OMRSD Changes (RCNs): None
- D: Waivers/Deviations

Minor Changes

B01982AA

Description:

Implemented intermediate step in the revision of longeron machining at Sta 1973 interface

Reason:

Machining changes implemented to enhance producibility by eliminating cracks in the forging during straightening

Basis for

Certification:

Similarity

- Longeron basic configuration and critical failure mode unchanged
- Design change provides additional material for producibility which locally increases longeron robustness

Class II or JS/DCN Changes

- All Class I/II JS/DCN changes have been reviewed by MSFC Resident Office
- All Class II STP/STM/Standards changes have been reviewed by MSFC M&P Lab
- These changes are acceptable for flight and summarized in this appendix (presentation not required)
 - Presentation criteria - Selection for presentation based on changes affecting:
 - Processes
 - Configuration
 - Material
 - Alternate Hardware
 - Presentation rejection criteria - All changes that do not affect configuration, material or processes
 - Revise Point of Incorporation
 - Drawing Clarification
 - Non-Flight Hardware Installation/Removal
 - Datum Changes
 - Update Usage/List of Materials (L/M)
 - Drawing Incorporation Errors
 - Manufacturing Aid
 - Drawing Errors
 - Fastener Type/Grip
 - Tolerance Change
 - Productivity
 - Minor changes taken care of by initial release of Class I Change
(Same categories as above)

Minor Class II Changes

Propulsion/Mechanical

H35809-964 Allowed one seal part number to be substituted for another in the GO2 Vent Duct Assembly. Seals identical and interchangeable

Structures

H35809-802 Seal pass (first pass) added to O2 weld at 629.2+/-7.00 (292.5 ref)

TPS

J31193-001 Revision to Intertank foam application drawing to pick up part no. roll for stringer cap installation change

NCD Assessment Criteria

- Assessment of all MRB Items
 - Adequacy of technical dispositions
 - Completeness of required repair/retest
 - First time occurrences/SMR
 - Verification of margin of safety assessment/documented
 - Review of impact to hazards
 - Engineering review for impact to loads
 - Engineering review for reduced extrusion to plate weld allowables

ET-97 DR/PR/OMRSD Waiver/Exceptions

as of 10/20/98

<u>System</u>	<u>Discrepancy</u>	<u>Problem</u>	<u>MRB Items</u>	<u>Exceptions/ Waivers</u>
• Electrical	0	0	0	0
• Propulsion/ Pneumatics	1	1	0	0
• Structures	1	1	1	0
• Thermal (TPS)	1	7	4	0
Total	3	9	5	0

ET-97 PR/MRBs, Thermal

<u>PR No./Status</u>	<u>Title/Description</u>	<u>Disposition</u>
PET-97-TS-0002	Aft hard point close-out has areas of low foam during close-out	• Use as repaired • Disposition to trim and re-foam aft hard point and MRB repair • Additional bondlines have no affect on material performance
PET-97-TS-0005	Damaged foam on +Y PAL ramp trailing edge above cable tray	• Use as repaired with SS-1171 • Provides adequate thermal protection
PET-97-TS-0006	+Y aft fairing close-out 8 areas not per drawing	• Use as repaired with PDL • Structural temperatures unchanged • Margin of Safety unaffected
PET-97-TS-0007	-Y aft fairing close-out 4 areas not per drawing	• Use as repaired with PDL • Structural temperatures unchanged • Margin of Safety unaffected

ET-97 PR/MRBs, Structures

<u>PR No./Status</u>	<u>Title/Description</u>	<u>Disposition</u>
PET-97-ST-0004	• Scratch on +Y spindle with raised metal and measureable depth (0.015") • Defect is on spindle edge with a minimum part thickness of 0.490"	Remove raised metal • Localized defect • No crack or crack like indications under magnification • Critical M.S. unaffected

ET-97 Field Engineering Changes

- FEC KET-0039
 - SPAR #ET-0041-R04 (TPS ET-97-TS-001)
 - SPAR was approved to reduce foam thickness at the LO2 +Z quadrant to reduce potential of TPS cracking at Sta 536 adjacent to the O2/OAO12 intersection

ET-97 Limited Life Components

Cycle Sensitive

<u>Description</u>	<u>Part No.</u>	<u>Serial No.</u>	<u>Limit</u>	<u>Required</u>	<u>Remaining</u>
LH2 Manhole Cover Assy -Fwd	80914081488 -509	00538060	8	1	8
LO2 Tank Mechanical Assy	80912002000 -500	00611440	8	1	8
LH2 Tank Mechanical Assy	80914002000 -500	00576800	8	1	8
LO2 Manhole Cover Assy	80911001205 -509	00624760	8	1	8

ET-97 Limited Life Components

Cycle Sensitive

<u>Description</u>	<u>Part No.</u>	<u>Serial No.</u>	<u>Limit</u>	<u>Required</u>	<u>Remaining</u>
LO2 Fwd Ogive Cover Plate	80911001207 -509	00543630	8	1	8
LH2 Manhole Cover Assy -Aft	80911001444 -509	00613220	8	1	8
LH2 Tank Siphon Closure	80911001445 -502	00630700	8	1	8

ET-97 Limited Life Components

Age Sensitive

<u>Description</u>	<u>Part No.</u>	<u>Serial No.</u>	<u>Limit</u>	<u>Initiation</u>	<u>Expiration</u>
External Tank	80901000000 -500	000000090	6 Yrs	3/98	3/2004

ET-97 Limited Life Components

Age Sensitive Pyrotechnics - 10 Years Life/Requires Lot Verification Tests After 4 and 7 Years

<u>Description</u>	<u>Part No.</u>	<u>Lot No.</u>	<u>Serial No.</u>	Latest <u>Retest</u>	<u>Expiration</u>
Separator Assy GUCP	PD500020-059	AAH	0001135	04/13/1998	10/2003
Cartridge Assy	PD500020-030	AAH	0001205	04/13/1998	10/2003
Cartridge Assy	PD500020-030	AAH	0001247	04/13/1998	10/2003

ET-97 Alternate Blowing Agent Usage at KSC

<u>Foam</u>	<u>Document</u>	<u>Description</u>	<u>Location</u>	<u>Size</u>
SS-1171	T5141	Aft Hardpoint Closeout	xt 1973-2076, 180 degrees	4410 sq. in.
SS-1171	TS-0005	Foam repair on +Y ET/SRB PAL ramp	Xt 2050, ET/SRB PAL ramp aft edge	22.5 sq. in.

Level II Waivers - Baseline

<u>Document / Requirement</u>	<u>Authority</u>	<u>Paragraph</u>	<u>Waiver No.</u>	<u>Effectivity</u>
NSTS 07700 Vol V – Information Management Requirements				
Generic part name, type, common designation, and part manufacturer H4 code are not required for EEE parts status print out	S00127B 6/28/88	Table C.5 Item 2SR-10	6	ETs 49 & up
Data required in limited life status report is supplied in acceptance data package	S00127B 6/28/88	Table C.6 Item 2SR-7	8	ETs 49 & up
Requirement to deliver element pressure vessel historical data to EPO will remain at contractor facility	S00127B 6/28/88	Table C.6 Item 2SR-7	10	ETs 49 & up

Level II Waivers - Baseline

<u>Document / Requirement</u>	<u>Authority</u>	<u>Paragraph</u>	<u>Waiver No.</u>	<u>Effectivity</u>
-------------------------------	------------------	------------------	-------------------	--------------------

NSTS 07700 Vol X –
Space Shuttle Flight and Ground System Specification, Book 1 Requirements

Electrical wiring of redundant systems NSTS 08080-1, 20A/4B	S040732G 6/18/88	Table 2.0	362	ETs 23, 27- 29, 31 & up
---	---------------------	-----------	-----	----------------------------

Electrical bonding per MIL- B-5087B (2)	S040732M 9/9/88	3.6.14	378	ETs 23, 27- 29, 31 & up
--	--------------------	--------	-----	----------------------------

Soldering, circuit boards, and connectors	S040732M 9/9/88	3.6.15.1.1	379	ETs 23, 27- 29, 31 & up
--	--------------------	------------	-----	----------------------------

PD7400106 circuit boards	S040732M 9/9/88	3.6.15.2.1	382	ETs 23, 27- 29, 31 & up
--------------------------	--------------------	------------	-----	----------------------------

PCM MUX and pressure transducer circuit boards	S040732M 9/9/88	3.6.15.2.1	383	ETs 23, 27- 29, 31 & up
---	--------------------	------------	-----	----------------------------

Soldering of electrical connectors	S094779C 2/21/91	3.6.15.1.1	573	ETs 37, 41 & up
---------------------------------------	---------------------	------------	-----	--------------------

Level II Waivers - Baseline

<u>Document / Requirement</u>	<u>Authority</u>	<u>Paragraph</u>	<u>Waiver No.</u>	<u>Effectivity</u>
NSTS 07700 Vol X – Space Shuttle Flight and Ground System Specification, Book 1 Requirements				
Debris prevention	S082962A 10/2/98	3.2.1.2.14		ETs 92, 97- 105
NSTS 07700-10-MVP-01 – Shuttle Master Verification Plan				
Environmental acceptance of ET components	S002130H 3/7/89	3.7.1	13	ETs 23, 27- 29, 31 & up
NSTS 07700-10-MVP-01 – Shuttle Master Verification Plan				
LH2 feedline bellows	S005203G-R1 8/2/91	1.2	3	ETs 42-45, 47 & up

Level II Waivers - Baseline

<u>Document / Requirement</u>	<u>Authority</u>	<u>Paragraph</u>	<u>Waiver No.</u>	<u>Effectivity</u>
SL-E-0001 – Specification Electromagnetic Compatibility Requirement				
Wire marking is not applicable to the ET	S40732K 9/27/89	3.2.5	3	ETs 23, 27-29, 31 & up
SW-E-0002 -- Ground Support Equipment General Design Requirements				
Factor of safety applied to yield for GUCP leg	S87020L 8/17/88	3.4.2.1	21	ETs 23, 27-29, 31 & up

Level III Deviations

<u>Document / Requirement</u>	<u>Paragraph</u>	<u>Waiver No.</u>	<u>Effectivity</u>
CPT01M09A, External Tank Contract End Item Specification			
- Photographic evidence shows a loss of foam from both +Y and –Y Intertank Thrust Panels - Analysis concluded a low probability of debris impact on Orbiter critical area	3.2.5	233	ETs 92, 97-99, 101-105

