

Operations & Maintenance Cost Study for NASA Facilities

Final Report for Administration Buildings

February 10, 2014

Submitted to:

Peter Aitcheson National Aeronautics and Space Administration

Submitted by:

CBRE | Whitestone 2050 Alameda Padre Serra, STE 200 Santa Barbara, CA 93103-1704

Contract NNC09BA14B



Operations & Maintenance Cost Study for NASA Facilities: Final Report for Administration Buildings

Overview

National Aeronautics and Space Administration (NASA) requires a credible method for estimating the operations and maintenance (O&M) requirements of its facilities.¹ The failure to anticipate future costs can lead to under-funding and diminished service life.

NASA has over 450 buildings totaling 12.6 million GSFT distributed at 24 sites in the selected inventory for this project. It is not cost effective to inspect all facilities, yet NASA needs detailed sustainment and operations estimates to support its budget planning. This project developed cost models for a sample of NASA assets with inventory details collected through site surveys. Estimates were extrapolated by facility type and size and adjusted for location to generate requirements for the selected NASA inventory.

The project employed the MARS Facility Cost Forecast System to provide cost information. Now in its eighth version, MARS is a facility cost modeling tool developed by CBRE | Whitestone and used by many federal and commercial agencies.

Phases 1 and 2 of this project called for inspections of four facility types: Administration Buildings, Propulsion Buildings, Communications Buildings, and Space Science (R&D and Test) Buildings. Eight sample buildings were chosen at two sites: the Goddard Space Flight Center (GSFC) and the Marshall Space Flight Center (MSFC).

Site inspections were conducted by Jacobs Facilities, a long-time CBRE | Whitestone partner experienced in inspecting federal facilities and creating MARS component inventories. A team of three, consisting of an architect, and electrical and mechanical engineers, carried out the facility inspections.

The project scope called for individual reports on two facility types, Administration and Propulsion Buildings. This report describes the project methodology and presents final estimates for the Administration Buildings in the NASA inventory.

Project Methodology

Parametric Estimates for Buildings

The project methodology entailed estimating O&M requirements for the selected NASA inventory based on the inspection and modeling of a sample of facilities. The project included four key steps:

- 1. Validate the existing NASA inventory and develop a sample
- 2. Perform on-site inspections of the sample buildings
- 3. Develop and calibrate MARS models

¹ Operations include custodial (cleaning, pest control, and trash collection), utilities (energy, water, and sewer), grounds (landscape care, mowing, and snow removal), security, telecommunications, and management. Maintenance (also known as sustainment) includes preventative maintenance, minor repair, unscheduled maintenance, and renewal and replacement.

4. Generate per square foot estimates of sustainment and operations costs for the sample and extrapolate to the project inventory

Study Sample

NASA has over 450 buildings at 24 sites globally in the selected inventory. Complete inspection of each site to estimate O&M requirements is impractical and costly. This project generated sustainment and operations estimates for a sample of buildings and extrapolated the costs to a selected NASA inventory.

The Statement of Work called for a sample that included one small building (approximately 10,000 square feet) and one large building (approximately 100,000 square feet) from four Classification types. The sample included two buildings from Administration Buildings, Propulsion Buildings, Communications Buildings, and Space Science (R&D and Test) Buildings. The project inventory excluded other Classification types in the NASA inventory, such as Warehouses and Wind Tunnels. CBRE | Whitestone proposed buildings at the Goddard Space Flight Center and the Marshall Space Flight Center to minimize travel costs.

Table 1 shows the building detail for the inspected Administration Buildings.

| Table 1. Administration Buildings Inspection Sample | | | | | | | | | | | |
|---|--------------------------|-------------|-----------------|------------|---------|--------------|--|--|--|--|--|
| Site | Classification | Property ID | Property Name | Year Built | Size | CRV | | | | | |
| Marshall Space Flight Center | Administration Buildings | 1045/62/212 | OFFICE BUILDING | 1943 | 11,050 | \$3,332,663 | | | | | |
| | Administration Buildings | 1045/62/178 | OFFICE BUILDING | 1964 | 110,929 | \$20,520,846 | | | | | |
| Total | | | | | 121,979 | \$23,853,509 | | | | | |

There are a number of variables that drive O&M costs. The project sampling plan only controls for size and Classification type. An alternative sample may control for current replacement value (CRV), age, and location.

The inspected sample was mapped to the remaining inventory by size and type. The 11k gross square foot (GSFT) building was mapped to the smaller half of the inventory, while the 111k GSFT building was mapped to the larger half. Square foot estimates were generated by MARS and then extrapolated to the inventory. All costs were indexed for location.

Administration Buildings represent the largest Classification type (67.6 percent) in the selected NASA inventory, totaling 8.5 million GSFT and 198 buildings with a \$2.2 billion CRV. Table 2 shows the Administration Buildings inventory by Site.

| | anigen | , | |
|--|--------|-----------|-----------------|
| Site | Count | Size | CRV |
| AMES Research Center | 10 | 302,101 | \$321,088,766 |
| CAPE | 3 | 42,369 | \$9,512,716 |
| Dryden Flight Research Center | 10 | 59,741 | \$12,756,692 |
| Ellington Field (JSC) | 2 | 18,535 | \$2,379,585 |
| Glenn Research Center | 2 | 119,003 | \$26,375,803 |
| Goddard Space Flight Center | 6 | 479,804 | \$148,913,686 |
| Jet Propulsion Laboratory | 33 | 1,370,645 | \$411,155,281 |
| Johnson Space Center | 16 | 947,871 | \$192,137,133 |
| JPL/Table Mtn Observatory | 1 | 6,954 | \$2,332,116 |
| Kennedy Space Center | 28 | 1,214,905 | \$222,579,596 |
| Langley Research Center | 13 | 473,920 | \$157,119,882 |
| Marshall Space Flight Center | 18 | 1,312,798 | \$254,344,864 |
| Michoud Assembly Facility | 3 | 740,110 | \$133,768,613 |
| Moffett Federal Airfield | 12 | 297,292 | \$108,443,659 |
| NASA/JSC/White Sands Test Facility | 9 | 85,820 | \$10,969,492 |
| Palestine, TX - Form 1018-Ledger 1621/1631 | 2 | 13,660 | \$1,374,281 |
| Plum Brook Station | 1 | 57,625 | \$12,719,276 |
| Stennis Space Center | 13 | 453,553 | \$90,051,838 |
| Stennis Space Center (MSAAP) | 4 | 244,292 | \$17,164,735 |
| Stennis Space Center (Tenants) | 11 | 237,537 | \$37,020,080 |
| Wallops Flight Facility | 1 | 14,613 | \$3,551,579 |
| Total | 198 | 8,493,148 | \$2,175,759,673 |

Table 2. NASA Administration Buildings by Site

Detailed cost models were developed for the two buildings using CBRE | Whitestone's MARS Facility Cost Forecast System.

Description of the MARS Model

CBRE | Whitestone used MARS to estimate preventative maintenance, unscheduled maintenance, repair, and renewal/replacement costs for this project. MARS is an asset management system that estimates both deferred maintenance and future requirements on the basis of asset components and their scheduled maintenance and repair. It also estimates costs for ten operations types in the typical commercial chart of accounts. MARS was originally developed in 1996, and is currently in its eighth version. It is used by many government agencies and commercial concerns.

| Sustainment | Preventive Maintenance & Minor Repair Unscheduled Maintenance Renewal & Replacement |
|-------------|--|
| Operations | Custodial Energy Grounds Management Pest Control Refuse Road Clearance Security Telecom Water/Sewer |

Note that the definition of future M&R requirements is the same as the "sustainment" requirements used for programming by DoD and an approach endorsed in a National Research Council (NRC) study of Department of Energy facility practices.² Among other agencies, the MARS Facility Cost Forecast System has been used to forecast budgets for the IRS, FAA, USDA, and CDC. It was recently used to benchmark costs for the Department of State Overseas Embassies. MARS is also the basis for the DoD Sustainment Model and a study for NNSA validating total life-cycle facility costs at eight nuclear weapons production and research sites.³ The model is used continuously to simulate alternative facility costs for the U.S. nuclear complex.

The MARS process begins with a component inventory of a building or structure. Derived from building plans, equipment inventory data, and on-site inspections, these components are organized into UNIFORMAT category level three elements and are identified specifically in terms of product characteristics, quantity, and output level; e.g. "Single-Ply Modified Bituminous/Thermoplastic Roof," "Condenser, Air-Cooled, 60 Ton," or "Pipe & Fittings, ³/₄" Copper."


Once the component inventory is completed, the MARS system relates maintenance tasks from a pre-defined task library to each selected component. New components and related tasks are defined as necessary. The frequency of each task determines the forecast of future required maintenance. MARS estimates four types of maintenance: preventative maintenance, unscheduled maintenance (service calls), repair, and renewal/replacement tasks. Tasks and their labor and material requirements are pre-defined by CBRE | Whitestone, but are also editable.

² National Research Council, Intelligent Sustainment and Renewal of Department of Energy Facilities and Infrastructure, 2004. P. 44.

³ Jacobs Facilities and Whitestone Research, *Implementation of the Department of Defense Sustainment Model, Final Report*, May 2002.

Other calibration steps include modifying default values for contract and in-house labor rates, specifying site-typical mark-up for contract expenditures, and identifying the utilization characteristics for each asset.

The sources for local wage rates and benefits are primarily the U.S. Department of Labor and Davis-Bacon Act labor agreements, and private sector employers. Both union and non-union wages are considered in determining prevailing rates by locality. State and local wage surveys are also used when available.



MARS Facility Cost Forecast System

MARS is also used to estimate operations costs other than maintenance and repair. These are based on the Facilities Operation Model developed jointly by the Department of Defense (DOD) and CBRE | Whitestone. This model provides costs for ten services, including those mentioned in the Federal Real Property Council (FRPC) guidance—utilities, cleaning and janitorial, and roads and grounds.⁴ Each operation type for an asset can be calibrated for a level of service (low, medium, high) to reflect the level of demand or frequency at which certain operations task are performed.

The CBRE | Whitestone operations cost models provides estimates for the following services:

Custodial. The custodial function represents the expense of cleaning offices, work areas, restrooms and common areas. Costs include local wage rates and benefits, task productivity, mark-ups for equipment, materials, supervision, and assumptions concerning the level of service. Trash removal costs are not included. Custodial service levels are defined by altering the combination and frequency of common tasks.

⁴ Federal Real Property Council. *Guidance for Real Property Inventory Reporting.* Washington, D.C. August, 2012.

Energy. Energy includes all expenses related to the purchase, generation, distribution, and conservation of energy and source fuels necessary to operate an asset. The main energy sources considered are electricity and natural gas. Not included are utilities maintenance and supervision, and utility tax rates. Service levels vary according to estimated commodity demand by asset use type.

Grounds. The grounds function includes any expense related to the maintenance of exterior landscaping. It does not include sweeping or the maintenance of signage, parking lots and roadways. Costs are estimated using local wage rates and benefits, task productivity, mark-ups for equipment, materials and supervision, and assumptions concerning the level of service. Service levels are defined by altering the combination and frequency of common tasks.

Management. The real property management function describes all costs associated with facility management, including: public works, contracts, material procurement, facility data, furnishings, real estate, and engineering services. Costs are expressed as a fixed percentage of Plant Replacement Value. Service levels are based on the distribution of costs found in institutional and commercial settings. For this project, the level of service for all NASA buildings was set to low to reflect economies of scale in a campus environment.

Pest Control. Pest control expenses cover indoor and outdoor pest control programs, separate from the grounds function. Costs are based on the frequency of common tasks for rodent and insect abatement and inspections. Costs include prevailing labor and material rates. Service levels are defined by altering the combination and frequency of common tasks.

Refuse. Refuse costs include all expenses related to trash collection and disposal, pickup services, fees, recycling operations and administration, composting, etc. Costs exclude handling and disposal of HAZMAT materials. Service levels vary according to estimated demand by asset use type.

Road Clearance. The road clearance function includes all expenses related to sweeping paved areas including sidewalks, walkways, and parking lots. Costs include prevailing labor and material rates, and climatic variables. Service levels are defined by altering the combination and frequency of common tasks.

Security. Security expenses relate to the physical security of assets and occupants, and include personnel, operating and monitoring security equipment. Costs include relevant prevailing labor and material rates. Service levels are defined by altering the combination and frequency of common tasks and services.

Telecommunications. Telecommunication expenses cover the purchase of all the services ordinarily associated with commercial activities, such as voice and data equipment and service subscription. The level of telecommunications is defined by the combination of services selected.

Water and Sewer. Water and Sewer expenses include all costs related to providing the asset with potable water, irrigation water, and sewage service. Estimates include local commodity costs. Service levels vary according to estimated commodity demand by asset use type.

Data Collection and Calibration

MARS Model Development

The technical work for this task involved the definition of the component inventory for the two sample Administration Buildings. Marshall Space Flight Center staff supplied existing equipment inventories and construction design documents before the inspection. Jacobs Facilities inspected the buildings and created draft models in MARS. In total, 314 MARS components were defined for the two facilities.

Jacobs submitted the MARS database to CBRE | Whitestone for a detailed component-bycomponent review. Three areas of focus included:

- 1) <u>Check for completeness</u>. Review the wall finishes (exterior and interior), roofing, plumbing, HVAC, fire protection, and electrical data to ensure the building model contains the appropriate components in each category.
- 2) <u>Check for consistency</u>. Review the building gross square feet for accuracy. Ensure the square footage of structural components (exterior walls, roofing system, interior finishes) are reasonable compared to building GSFT. Verify the capacity of the following is consistent with the building type and size:
 - Heating, cooling, and air distribution
 - Electrical service, distribution, and lighting
 - Plumbing fixtures and water distribution
 - Fire protection
- **3)** <u>Forecast review</u>. Run the following building-level MARS reports and look for extraordinary costs (high or low) illustrating an error in the building model:
 - Average M&R Costs
 - Most Costly M&R Tasks
 - Deferred Maintenance Detail
 - Operation Cost Summary

We also compared the costs with known resources (*The Whitestone Facility Maintenance and Repair* and *Operations Cost References*, comparable CBRE | Whitestone project work with federal agencies, and third party sources).

Attachment A and B provide detailed MARS component lists for the two inspected Administration Buildings at MSFC.

CBRE | Whitestone also collected information to calibrate the models for local site values.

Local Calibration of MARS

While the MARS system has pre-defined building models, labor and material costs, utility rates, and an extensive component library, all of these values can be changed or supplemented to reflect the actual site practices.

Calibration data was gathered to adjust MARS factors at both the site and the building level. Site-level information, such as labor and utility rates, was directly used to estimate O&M costs for the remaining non-inspected buildings at GSFC and MSFC.

Building-level calibration data was applied to the sample models and then extrapolated to the remaining NASA inventory by Classification type and size.

The following data was collected to calibrate the building models:

<u>Maintenance and Repair</u>. The sites provided contract labor rates and labor rate mark-ups. A default assumption in MARS assigns in-house labor to preventative maintenance, minor repair, and unscheduled maintenance, while contract labor performs major repair and replacement tasks. Goddard Space Flight Center and the Marshall Space Flight Center staff indicated all maintenance was performed by contract laborers. CBRE | Whitestone adjusted the MARS database accordingly.

NASA personnel specified laborers must be paid prevailing wages for the area. We used the default MARS wage rates for this study, and included a 30 percent mark-up for contract overhead.

Table 3 shows the source of the maintenance and repair factors for each site.

| Table 3. Data Sources by Site, Maintenance & Repair | | | | | | | | | | |
|---|------------------------|--------------------------|-------------------------|----------------------------|--------------|--|--|--|--|--|
| Site | In-house Shop Rates | In-house Markup Rates | Contract Labor Rates | Contract Overhead Rates | Utilization | | | | | |
| Goddard Space Flight Center Marshall Space Flight Center | N/A N/A | N/A N/A | WST WST | WST WST | Site Site | | | | | |
| WST=Whitestone, Site = Resp | ective NASA S | ite | | | | | | | | |

MARS estimates also can be adjusted to reflect utilization factors that impact M&R. For example, many NASA facilities have special safety requirements which increase costs relative to conventional commercial practice. Other special requirements include high or low hours of operation and security. The two sites defined utilization factors for the eight buildings.

Table 4 displays the average utilization multipliers by site used to adjust for these requirements.

| Table 4. Average Utilization Adjustment by Site ^A | | | | | | | | | | |
|--|---|---|---|--------------------------------------|--|--|--|--|--|--|
| Site | Hours of Operation ^B | Security ^c | Safety & Permitting ^D | Sum ^E | | | | | | |
| Goddard Space Flight Center Marshall Space Flight Center | 1.37 1.07 | 1.05 1.01 | 1.04 1.03 | 1.45 1.11 | | | | | | |
| ^A Calculated from individual as ^B Hours of Operation rates bui 0.80 = 40 hours, 1.00 = 41 to 8 ^C Security is defined as follow daily check-in, 1.15 = full cont ^D Safety & Permitting is defined activity, 1.07 = non-specific la 3.00 = nuclear facility. ^E In combination the multipliers w here β = the multiplier value. | lding use on a 80 hours, 1.37 s: 1.00 = free ractor accomp d as follow s: boratory, 1.75 are additive s | w eekly bas = 80+ hours access, 1.0 panyment. 1.00 = typica = radiologic | is and is defined s. D1 = contractor f al commercial & al or life science | training & service e research, | | | | | | |

<u>Operations</u>. MARS also estimates operations costs for ten services including: custodial, energy, grounds, management, pest control, refuse, road clearance, security, telecommunications, and water & sewer. We requested utility rates, operations labor rates, and mark-ups. In addition, individual building models are calibrated in terms of level of service (low, medium, high, or none).

Each site defined levels of service for all operation types and provided several utility rates. As with M&R, CBRE | Whitestone used the default MARS wage rates and a 30 percent mark-up for contract overhead.

The utility rates provided by the two sites were significantly lower than the default MARS commercial rates. These discounts are often provided to large federal property holders like NASA. CBRE | Whitestone applied the average discounts for the calibrated sites (GSFC and MSFC) to the remaining sites in the inventory.

Table 5 shows the source of the operations calibration data.

| Table 5. Data Sources by Site, Operations | | | | | | | | | | | |
|---|----------|-----------|--------|--------|-------------|---------------|--------------|----------------|----------|------------|---------|
| Site | Level of | Custodial | Refuse | Energy | Water/Sewer | Groundskeeper | Pest Control | Road Clearance | Security | Property | Telecom |
| | Service | Wage | Rates | Rates | Rates | Wage | Wage | Wage | Rates | Management | Rates |
| Goddard Space Flight Center | Site | WST | Site | Site | Site | WST | WST | WST | WST | Site | WST |
| Marshall Space Flight Center | Site | WST | WST | Site | Site | WST | WST | WST | WST | Site | WST |
| WST=Whitestone, Site = Respective NASA Site | | | | | | | | | | | |

Cost Estimates for Administration Buildings

Sustainment Costs

The final sustainment estimate for the smaller MSFC Administration Building (Property ID 1045/62/212) is an average of \$7.45 per GSFT over a 50-year period. The larger building (Property ID 1045/62/178) is \$4.77 per GSFT over the same period.

The sample estimates were extrapolated to the population. Table 6 shows sustainment costs by site for all Administration Buildings. Sustainment estimates are expressed as 30, 40, and 50-year averages. While Whitestone computes annual requirements, average costs are presented to smooth the annual oscillations. Overall, the sustainment requirements are an average of \$46.9 million per year over 50 years, or \$5.52 per GSFT. Expressed another way, this amounts to 2.2 percent of the \$2.2 billion replacement value.

| | | | | | | Susta | ainmen | t ^A | | | |
|--|-----------|-----------------|-------------------------|-------------|----------------|-------------------------|-------------|----------------|-------------------------|-------------|----------------|
| | | | 30-Year | Estima | tes | 40-Year | Estima | tes | 50-Year | Estimat | tes |
| Site | GSFT | CRV | Avg. Annual Estimate | Per GSFT | Percent CRV | Avg. Annual Estimate | Per GSFT | Percent CRV | Avg. Annual Estimate | Per GSFT | Percent CRV |
| AMES Research Center | 302,101 | \$321,088,766 | \$2,368,882 | \$7.84 | 0.7% | \$2,377,371 | \$7.87 | 0.7% | \$2,387,862 | \$7.90 | 0.7% |
| CAPE | 42,369 | \$9,512,716 | \$260,226 | \$6.14 | 2.7% | \$278,150 | \$6.56 | 2.9% | \$269,610 | \$6.36 | 2.8% |
| Dryden Flight Research Center | 59,741 | \$12,756,692 | \$495,545 | \$8.29 | 3.9% | \$529,677 | \$8.87 | 4.2% | \$513,414 | \$8.59 | 4.0% |
| Ellington Field (JSC) | 18,535 | \$2,379,585 | \$128,816 | \$6.95 | 5.4% | \$137,688 | \$7.43 | 5.8% | \$133,461 | \$7.20 | 5.6% |
| Glenn Research Center | 119,003 | \$26,375,803 | \$746,024 | \$6.27 | 2.8% | \$739,591 | \$6.21 | 2.8% | \$748,090 | \$6.29 | 2.8% |
| Goddard Space Flight Center | 479,804 | \$148,913,686 | \$2,683,396 | \$5.59 | 1.8% | \$2,557,789 | \$5.33 | 1.7% | \$2,646,811 | \$5.52 | 1.8% |
| Jet Propulsion Laboratory | 1,370,645 | \$411,155,281 | \$8,946,282 | \$6.53 | 2.2% | \$8,793,967 | \$6.42 | 2.1% | \$8,938,764 | \$6.52 | 2.2% |
| Johnson Space Center | 947,871 | \$192,137,133 | \$4,718,570 | \$4.98 | 2.5% | \$4,450,789 | \$4.70 | 2.3% | \$4,634,088 | \$4.89 | 2.4% |
| JPL/Table Mtn Observatory | 6,954 | \$2,332,116 | \$52,441 | \$7.54 | 2.2% | \$56,053 | \$8.06 | 2.4% | \$54,332 | \$7.81 | 2.3% |
| Kennedy Space Center | 1,214,905 | \$222,579,596 | \$5,450,619 | \$4.49 | 2.4% | \$5,188,160 | \$4.27 | 2.3% | \$5,373,162 | \$4.42 | 2.4% |
| Langley Research Center | 473,920 | \$157,119,882 | \$2,770,306 | \$5.85 | 1.8% | \$2,842,952 | \$6.00 | 1.8% | \$2,819,443 | \$5.95 | 1.8% |
| Marshall Space Flight Center | 1,312,798 | \$254,344,864 | \$6,785,948 | \$5.17 | 2.7% | \$6,409,752 | \$4.88 | 2.5% | \$6,668,280 | \$5.08 | 2.6% |
| Michoud Assembly Facility | 740,110 | \$133,768,613 | \$3,441,791 | \$4.65 | 2.6% | \$3,169,937 | \$4.28 | 2.4% | \$3,347,296 | \$4.52 | 2.5% |
| Moffett Federal Airfield | 297,292 | \$108,443,659 | \$2,355,733 | \$7.92 | 2.2% | \$2,373,569 | \$7.98 | 2.2% | \$2,378,643 | \$8.00 | 2.2% |
| NASA/JSC/White Sands Test Facility | 85,820 | \$10,969,492 | \$561,156 | \$6.54 | 5.1% | \$599,807 | \$6.99 | 5.5% | \$581,391 | \$6.77 | 5.3% |
| Palestine, TX - Form 1018-Ledger 1621/1631 | 13,660 | \$1,374,281 | \$91,873 | \$6.73 | 6.7% | \$98,201 | \$7.19 | 7.1% | \$95,186 | \$6.97 | 6.9% |
| Plum Brook Station | 57,625 | \$12,719,276 | \$449,519 | \$7.80 | 3.5% | \$480,481 | \$8.34 | 3.8% | \$465,728 | \$8.08 | 3.7% |
| Stennis Space Center | 453,553 | \$90,051,838 | \$2,365,730 | \$5.22 | 2.6% | \$2,343,668 | \$5.17 | 2.6% | \$2,371,566 | \$5.23 | 2.6% |
| Stennis Space Center (MSAAP) | 244,292 | \$17,164,735 | \$1,094,229 | \$4.48 | 6.4% | \$1,012,860 | \$4.15 | 5.9% | \$1,066,360 | \$4.37 | 6.2% |
| Stennis Space Center (Tenants) | 237,537 | \$37,020,080 | \$1,277,869 | \$5.38 | 3.5% | \$1,281,324 | \$5.39 | 3.5% | \$1,287,625 | \$5.42 | 3.5% |
| Wallops Flight Facility | 14,613 | \$3,551,579 | \$96,908 | \$6.63 | 2.7% | \$103,583 | \$7.09 | 2.9% | \$100,403 | \$6.87 | 2.8% |
| Total ^B | 8,493,148 | \$2,175,759,673 | \$47,141,862 | \$5.55 | 2.2% | \$45,825,370 | \$5.40 | 2.1% | \$46,881,512 | \$5.52 | 2.2% |

^B All costs expressed in \$2012.

Operation Costs

Final estimates of ten operation costs are shown in Table 7. In total, the operation requirements for the selected Administration Buildings are an annual average of \$50.5 million, or \$5.94 per GSFT and 2.3 percent of replacement value. Note that in commercial accounting M&R (sustainment) is often included as an operating cost, but is reported separately above.

| | | | | | | | Operation | s Type^ | | | | | _ | | |
|--|-----------|-----------------|-------------|-------------|-------------|-------------|--------------|-----------|-------------------|-------------|--------------|-------------|--------------|-------------|--------------|
| Site | GSFT | CRV | Custodial | Energy | Grounds | Management | Pest Control | Refuse | Road Clearance | Security | Telecom | Water/Sewer | Total Costs | Per GSFT | Perce CRV |
| AMES Research Center | 302,101 | \$321,088,766 | \$291,061 | \$281,845 | \$52,808 | \$802,722 | \$45,010 | \$10,972 | \$0 | \$267,516 | \$718,562 | \$51,793 | \$2,522,288 | \$8.35 | 0.8% |
| CAPE | 42,369 | \$9,512,716 | \$28,550 | \$39,743 | \$5,250 | \$23,782 | \$4,293 | \$1,337 | \$0 | \$45,441 | \$93,216 | \$10,016 | \$251,628 | \$5.94 | 2.6% |
| Dryden Flight Research Center | 59,741 | \$12,756,692 | \$54,048 | \$55,836 | \$11,027 | \$31,892 | \$5,770 | \$2,016 | \$0 | \$69,708 | \$131,436 | \$11,461 | \$373,193 | \$6.25 | 2.9% |
| Ellington Field (JSC) | 18,535 | \$2,379,585 | \$12,727 | \$21,019 | \$2,255 | \$5,949 | \$1,750 | \$1,758 | \$0 | \$20,057 | \$40,779 | \$5,130 | \$111,425 | \$6.01 | 4.7% |
| Glenn Research Center | 119,003 | \$26,375,803 | \$100,098 | \$98,972 | \$12,658 | \$65,940 | \$9,376 | \$1,056 | \$9,531 | \$90,825 | \$286,245 | \$26,519 | \$701,219 | \$5.89 | 2.7% |
| Goddard Space Flight Center | 479,804 | \$148,913,686 | \$507,526 | \$477,928 | \$60,365 | \$372,284 | \$65,435 | \$15,792 | \$7,419 | \$350,408 | \$1,189,659 | \$145,956 | \$3,192,773 | \$6.65 | 2.1% |
| Jet Propulsion Laboratory | 1,370,645 | \$411,155,281 | \$1,248,074 | \$1,281,057 | \$252,940 | \$1,027,888 | \$132,425 | \$46,262 | \$0 | \$981,317 | \$3,320,897 | \$262,959 | \$8,553,818 | \$6.24 | 2.1% |
| Johnson Space Center | 947,871 | \$192,137,133 | \$656,494 | \$762,427 | \$115,302 | \$480,343 | \$89,558 | \$28,704 | \$0 | \$498,073 | \$2,366,516 | \$181,141 | \$5,178,559 | \$5.46 | 2.7% |
| JPL/Table Mtn Observatory | 6,954 | \$2,332,116 | \$4,792 | \$10,397 | \$945 | \$5,830 | \$547 | \$559 | \$0 | \$7,926 | \$15,299 | \$1,381 | \$47,677 | \$6.86 | 2.0% |
| Kennedy Space Center | 1,214,905 | \$222,579,596 | \$825,371 | \$1,139,604 | \$150,493 | \$556,449 | \$123,147 | \$38,350 | \$0 | \$666,235 | \$3,015,197 | \$287,216 | \$6,802,061 | \$5.60 | 3.1% |
| Langley Research Center | 473,920 | \$157,119,882 | \$347,482 | \$350,577 | \$52,092 | \$392,800 | \$49,041 | \$14,795 | \$2,877 | \$419,126 | \$1,101,393 | \$67,607 | \$2,797,788 | \$5.90 | 1.8% |
| Marshall Space Flight Center | 1,312,798 | \$254,344,864 | \$964,701 | \$1,373,197 | \$164,624 | \$635,862 | \$87,842 | \$43,571 | \$2,998 | \$798,569 | \$3,274,693 | \$108,132 | \$7,454,190 | \$5.68 | 2.9% |
| Michoud Assembly Facility | 740,110 | \$133,768,613 | \$596,808 | \$804,476 | \$97,049 | \$334,422 | \$71,408 | \$68,558 | \$0 | \$362,712 | \$1,874,304 | \$162,380 | \$4,372,116 | \$5.91 | 3.3% |
| Moffett Federal Airfield | 297,292 | \$108,443,659 | \$286,352 | \$277,358 | \$51,967 | \$271,109 | \$44,293 | \$10,797 | \$0 | \$269,297 | \$704,408 | \$50,968 | \$1,966,551 | \$6.61 | 1.8% |
| NASA/JSC/White Sands Test Facility | 85,820 | \$10,969,492 | \$62,401 | \$66,885 | \$8,241 | \$27,424 | \$8,537 | \$1,351 | \$614 | \$94,222 | \$188,812 | \$4,328 | \$462,815 | \$5.39 | 4.2% |
| Palestine, TX - Form 1018-Ledger 1621/1631 | 13,660 | \$1,374,281 | \$9,191 | \$15,470 | \$1,451 | \$3,436 | \$1,211 | \$1,313 | \$0 | \$14,820 | \$30,053 | \$2,446 | \$79,391 | \$5.81 | 5.8% |
| Plum Brook Station | 57,625 | \$12,719,276 | \$48,182 | \$47,926 | \$6,131 | \$31,798 | \$4,538 | \$511 | \$4,615 | \$68,296 | \$126,780 | \$12,841 | \$351,619 | \$6.10 | 2.8% |
| Stennis Space Center | 453,553 | \$90,051,838 | \$369,136 | \$391,375 | \$53,632 | \$225,130 | \$37,371 | \$13,217 | \$0 | \$339,241 | \$1,091,635 | \$39,467 | \$2,560,204 | \$5.64 | 2.8% |
| Stennis Space Center (MSAAP) | 244,292 | \$17,164,735 | \$199,505 | \$210,802 | \$28,884 | \$42,912 | \$20,133 | \$7,119 | \$0 | \$124,188 | \$616,912 | \$21,258 | \$1,271,713 | \$5.21 | 7.4% |
| Stennis Space Center (Tenants) | 237,537 | \$37,020,080 | \$193,179 | \$204,973 | \$28,089 | \$92,550 | \$19,571 | \$6,922 | \$0 | \$190,312 | \$565,466 | \$20,670 | \$1,321,732 | \$5.56 | 3.6% |
| Wallops Flight Facility | 14,613 | \$3,551,579 | \$10,676 | \$15,324 | \$1,606 | \$8,879 | \$1,512 | \$1,429 | \$89 | \$16,462 | \$32,150 | \$4,427 | \$92,553 | \$6.33 | 2.6% |
| Total ^B | 8,493,148 | \$2,175,759,673 | \$6,816,354 | \$7,927,191 | \$1,157,808 | \$5,439,399 | \$822,767 | \$316,388 | \$28,143 | \$5,694,751 | \$20,784,412 | \$1,478,099 | \$50,465,313 | \$5.94 | 2.3% |

Total O&M Costs

Table 7 Annual Estimates of Onevations Costs by Site Administration Buildin

Estimated total annual Administration Building costs are shown in Table 8. A combination of maintenance and repair (sustainment) and operations, these costs represent an annual average for the next 50 years. Total costs are an estimated \$97.3 million per year, or can also be expressed as \$11.46 per GSFT and 4.5 percent of CRV.

Table 8. Total Annual Costs by Site, Administration Buildings

| | | | O&M Est | timates | - | | |
|--|-----------|-----------------|--|-----------------------------------|--------------|-------------|---------------|
| Site | GSFT | CRV | 50-Year Avg. Sustainment ^a | Annual Operations ^B | Total Costs | Per GSFT | Percen CRV |
| AMES Research Center | 302,101 | \$321,088,766 | \$2,387,862 | \$2,522,288 | \$4,910,149 | \$16.25 | 1.5% |
| CAPE | 42,369 | \$9,512,716 | \$269,610 | \$251,628 | \$521,237 | \$12.30 | 5.5% |
| Dryden Flight Research Center | 59,741 | \$12,756,692 | \$513,414 | \$373,193 | \$886,607 | \$14.84 | 7.0% |
| Ellington Field (JSC) | 18,535 | \$2,379,585 | \$133,461 | \$111,425 | \$244,885 | \$13.21 | 10.3% |
| Glenn Research Center | 119,003 | \$26,375,803 | \$748,090 | \$701,219 | \$1,449,309 | \$12.18 | 5.5% |
| Goddard Space Flight Center | 479,804 | \$148,913,686 | \$2,646,811 | \$3,192,773 | \$5,839,584 | \$12.17 | 3.9% |
| Jet Propulsion Laboratory | 1,370,645 | \$411,155,281 | \$8,938,764 | \$8,553,818 | \$17,492,582 | \$12.76 | 4.3% |
| Johnson Space Center | 947,871 | \$192,137,133 | \$4,634,088 | \$5,178,559 | \$9,812,648 | \$10.35 | 5.1% |
| JPL/Table Mtn Observatory | 6,954 | \$2,332,116 | \$54,332 | \$47,677 | \$102,008 | \$14.67 | 4.4% |
| Kennedy Space Center | 1,214,905 | \$222,579,596 | \$5,373,162 | \$6,802,061 | \$12,175,224 | \$10.02 | 5.5% |
| Langley Research Center | 473,920 | \$157,119,882 | \$2,819,443 | \$2,797,788 | \$5,617,231 | \$11.85 | 3.6% |
| Marshall Space Flight Center | 1,312,798 | \$254,344,864 | \$6,668,280 | \$7,454,190 | \$14,122,470 | \$10.76 | 5.6% |
| Michoud Assembly Facility | 740,110 | \$133,768,613 | \$3,347,296 | \$4,372,116 | \$7,719,412 | \$10.43 | 5.8% |
| Moffett Federal Airfield | 297,292 | \$108,443,659 | \$2,378,643 | \$1,966,551 | \$4,345,193 | \$14.62 | 4.0% |
| NASA/JSC/White Sands Test Facility | 85,820 | \$10,969,492 | \$581,391 | \$462,815 | \$1,044,206 | \$12.17 | 9.5% |
| Palestine, TX - Form 1018-Ledger 1621/1631 | 13,660 | \$1,374,281 | \$95,186 | \$79,391 | \$174,577 | \$12.78 | 12.7% |
| Plum Brook Station | 57,625 | \$12,719,276 | \$465,728 | \$351,619 | \$817,348 | \$14.18 | 6.4% |
| Stennis Space Center | 453,553 | \$90,051,838 | \$2,371,566 | \$2,560,204 | \$4,931,770 | \$10.87 | 5.5% |
| Stennis Space Center (MSAAP) | 244,292 | \$17,164,735 | \$1,066,360 | \$1,271,713 | \$2,338,073 | \$9.57 | 13.6% |
| Stennis Space Center (Tenants) | 237,537 | \$37,020,080 | \$1,287,625 | \$1,321,732 | \$2,609,357 | \$10.99 | 7.0% |
| Wallops Flight Facility | 14,613 | \$3,551,579 | \$100,403 | \$92,553 | \$192,956 | \$13.20 | 5.4% |
| Total ^c | 8,493,148 | \$2,175,759,673 | \$46,881,512 | \$50,465,313 | \$97,346,825 | \$11.46 | 4.5% |

^A Sustainment is the average annual sum of preventative maintenance, unscheduled maintenance, and major repair and replacement tasks.

^B Operations include custodial (cleaning, pest control, and trash collection), utilities (energy, water, and sew er), grounds (landscape care, mowing, and snow removal), security, telecommunications, and management.

^B All costs expressed in \$2012.

Included in Attachment A and B are detailed MARS reports for the two sample Marshall Space Flight Center Administration Buildings.

Attachment A: Detailed MARS Reports for MSFC Property ID 1045/62/212

Building Component List

Whitestone Research

| Building: Office Building | Year Built: 1943 | | Building Type: Engineering Office |
|--|--------------------------------|---------------|-----------------------------------|
| Facility: Marshall Space Flight Center | Original Cost: \$1 | | Building Num: 1045/62/212 |
| City: Huntsville, AL | Replacement Value: \$3,332,663 | per SF: \$302 | Building Gsft: 11,050 |

| Uniformat | Asset Description | Component | Date | Quantity | Location | Notes |
|-----------|-------------------|--|------|--------------|----------|-------|
| B1010 | | Concrete Ramp | 2011 | 250 Sq Ft | | |
| B1020 | | Steel Roof Access Ladder | 1995 | 20 Ln Ft | | |
| B2010 | | Aluminum Louver, 1st Floor | 1995 | 2 Each | | |
| B2010 | | Aluminum Louver, 2nd Floor | 2011 | 1 Each | | |
| B2010 | | Clay Brick, Painted, Exterior, 1st Floor | 1943 | 215 Sq Ft | | |
| B2010 | | Concrete Block, Painted, Exterior, 1st Floor | 1943 | 7700 Sq Ft | | |
| B2010 | | Concrete Block, Painted, Exterior, 2nd Floor | 1943 | 700 Sq Ft | | |
| B2020 | | Aluminum Fixed Window w/ Thermal Break, Double Glaze | 2011 | 7 Each | | |
| B2020 | | Aluminum Fixed Window w/ Thermal Break, Double Glaze | 2011 | 2 Each | | |
| B2020 | | Glass Curtain Wall | 1989 | 85 Sq Ft | | |
| B2030 | | Aluminum Frame, Fully Glazed, Exterior Door | 1989 | 2 Each | | |
| B2030 | | Steel w/ Safety Glass, Painted, Exterior Door | 1943 | 2 Each | | |
| B2030 | | Wood, Solid Core, Painted, Exterior Door | 1970 | 2 Each | | |
| B3010 | | Aluminum Gutter, Downspouts, Fittings | 2011 | 0.61 K Ln Ft | | |
| B3010 | | Concrete Roof | 1943 | 40 Sq Ft | | |
| B3010 | | Metal Canopy | 2011 | 80 Sq Ft | | |
| B3010 | | Metal Roof | 2011 | 12680 Sq Ft | | |
| C1010 | | Movable Partitions, Office, Fabric, 6' | 2011 | 390 Ln Ft | | |
| C1010 | | Toilet Partitions, Painted Metal, Overhead Braced | 2011 | 3 Each | | |
| C1020 | | Steel, Painted, Interior Door | 2011 | 1 Each | | |
| C1020 | | Wood, Solid Core, Painted, Interior Door | 1989 | 2 Each | | |
| C1020 | | Wood, Solid Core, Painted, Interior Door | 2011 | 17 Each | | |
| C2010 | | Concrete, Exterior Stairs | 2011 | 200 Sq Ft | | |
| C2010 | | Metal, Painted, Exterior Railing | 1989 | 135 Ln Ft | | |
| C2010 | | Metal, Painted, Interior Railing | 2011 | 32 Ln Ft | | |
| C2010 | | Metal, Painted, Interior Stairs | 2011 | 42 Sq Ft | | |
| C3010 | | Ceramic Tile, 4"x4", Interior Wall Finish | 1995 | 1600 Sq Ft | | |
| C3010 | | Clay Brick, Painted, Interior Wall Finish | 1943 | 360 Sq Ft | | |
| | | | | | | |

| Uniformat | Asset Description | Component | Date | Quantity | Location | Notes |
|-----------|-------------------|---|------|---------------|----------|-------|
| C3010 | | Concrete Block, Painted, Interior Wall Finish | 1943 | 3660 Sq Ft | | |
| C3010 | | Gypsum Board, Interior Wall Finish | 2011 | 9290 Sq Ft | | |
| C3010 | | Plate Glass Interior Wall | 2011 | 45 Sq Ft | | |
| C3010 | | Vinyl, Interior Wall Finish | 2011 | 290 Sq Ft | | |
| C3020 | | Carpet, Nylon 20 oz., Low Traffic | 2011 | 8323 Sq Ft | | |
| C3020 | | Ceramic Tile Flooring | 1943 | 712 Sq Ft | | |
| C3020 | | Concrete Flooring | 1943 | 571 Sq Ft | | |
| C3020 | | Concrete, Painted Flooring | 1943 | 1000 Sq Ft | | |
| C3020 | | Vinyl Tile Flooring | 2011 | 444 Sq Ft | | |
| C3030 | | Acoustical Tile, Dropped Ceiling | 2011 | 8355 Sq Ft | | |
| C3030 | | Concrete, Painted Ceiling | 1943 | 1190 Sq Ft | | |
| C3030 | | Gypsum Board, Finished Ceiling | 1989 | 200 Sq Ft | | |
| C3030 | | Metal, Painted Ceiling | 2011 | 305 Sq Ft | | |
| D2010 | | Drinking Fountain, Refrigerated | 2011 | 2 Each | | |
| D2010 | | Lavatory, Vitreous China | 2011 | 6 Each | | |
| D2010 | | Service Sink, Iron, Enamel | 2011 | 1 Each | | |
| D2010 | | Sink, Stainless Steel | 2011 | 1 Each | | |
| D2010 | | Tankless Water Closet | 2011 | 5 Each | | |
| D2010 | | Urinal, Vitreous China | 2011 | 2 Each | | |
| D2020 | | Hose Bib | 2011 | 1 Each | | |
| D2020 | | Pipe & Fittings, 2" Copper, Cold Water | 1990 | 0.1 K Ln Ft | | |
| D2020 | | Pipe & Fittings, 2" Copper, Hot Water | 1990 | 0.1 K Ln Ft | | |
| D2020 | | Pipe & Fittings, 3/4" Copper, Cold Water | 1990 | 0.175 K Ln Ft | | |
| D2020 | | Pipe & Fittings, 3/4" Copper, Cold Water | 2011 | 0.05 K Ln Ft | | |
| D2020 | | Pipe & Fittings, 3/4" Copper, Hot Water | 1990 | 0.175 K Ln Ft | | |
| D2020 | | Pipe & Fittings, 3/4" Copper, Hot Water | 2011 | 0.05 K Ln Ft | | |
| D2020 | | Pipe Insulation, Fiberglass, Cold Water | 2011 | 0.2 K Ln Ft | | |
| D2020 | | Pipe Insulation, Fiberglass, Hot Water | 2011 | 0.2 K Ln Ft | | |
| D2020 | | Water Heater, Electric, 80 Gal. | 2011 | 1 Each | | |
| D2030 | | Backflow Preventer, 1" | 2011 | 1 Each | | |
| D2030 | | Floor Drain | 2011 | 4 Each | | |
| D2030 | | Pipe & Fittings, 2" PVC | 2011 | 0.05 K Ln Ft | | |
| D2030 | | Pipe & Fittings, 3" Cast Iron | 1943 | 0.1 K Ln Ft | | |
| D2030 | | Pipe & Fittings, 3" Cast Iron | 2011 | 0.15 K Ln Ft | | |
| D2030 | | Pipe & Fittings, 4" Cast Iron | 1943 | 0.1 K Ln Ft | | |
| D2030 | | Pipe & Fittings, 4" Cast Iron | 2011 | 0.05 K Ln Ft | | |

| Uniformat | Asset Description | Component | Date | Quantity | Location | Notes | |
|-----------|-------------------|--|------|--------------|----------|------------|--|
| D2030 | | Pipe & Fittings, 4" PVC | 2011 | 0.05 K Ln Ft | | | |
| D2030 | | Pipe & Fittings, 6" Cast Iron | 1943 | 0.05 K Ln Ft | | | |
| D3020 | | Pipe & Fittings, 2" Steel | 2011 | 0.3 K Ln Ft | | | |
| D3020 | | Pipe Insulation, Fiberglass, Heating Water/Steam | 2011 | 0.45 K Ln Ft | | | |
| D3020 | | Steam Trap, F&T, 2" | 2011 | 8 Each | | | |
| D3030 | | Ball Valve, 4" | 2011 | 4 Each | | 3" | |
| D3030 | | Circulator Pump, 1/6 HP, Chilled Water | 2011 | 2 Each | | | |
| D3030 | | Flow Control Valve, Motorized, 4" | 2011 | 2 Each | | 3" | |
| D3030 | | Pipe & Fittings, 2" Steel | 2011 | 0.3 K Ln Ft | | | |
| D3030 | | Pipe & Fittings, 4" Steel | 2011 | 0.15 K Ln Ft | | | |
| D3030 | | Pipe Insulation, Fiberglass, Chilled Water | 2011 | 0.45 K Ln Ft | | | |
| D3040 | AHU-1 | Air Handler, Single Zone, 15,000 Cfm | 2011 | 1 Each | | ~12,000cfm | |
| D3040 | | Duct Insulation, Fiberglass Blanket | 1989 | 1000 Sq Ft | | | |
| D3040 | | Duct Insulation, Fiberglass Blanket | 2011 | 2000 Sq Ft | | | |
| D3040 | | Ductwork | 1989 | 2000 Lbs | | | |
| D3040 | | Ductwork | 2011 | 2500 Lbs | | | |
| D3040 | | Exhaust Fan, Ceiling, 200-500 Cfm | 2011 | 3 Each | | | |
| D3040 | | Exhaust Fan, Centrifugal, 800 Cfm | 2011 | 3 Each | | | |
| D3040 | | Variable Air Volume Box, 1,300 Cfm | 2011 | 4 Each | | | |
| D3040 | | Variable Air Volume Box, 2,500 Cfm | 2011 | 2 Each | | | |
| D3040 | | Variable Air Volume Box, 400 Cfm | 2011 | 1 Each | | | |
| D3040 | | Variable Air Volume Box, 800 Cfm | 2011 | 2 Each | | | |
| D3050 | | Fan Coil Unit, 2 Ton | 2011 | 1 Each | | | |
| D3050 | | Fan Coil Unit, 5 Ton | 1989 | 1 Each | | | |
| D3050 | | Unit Heater, 480v, 5kW | 2011 | 2 Each | | | |
| D3060 | | Direct Digital Controls, System Points | 2011 | 112 Each | | | |
| D3060 | | Thermostat | 2011 | 25 Each | | | |
| D4010 | | Fire Alarm Control Panel | 2011 | 1 Each | | | |
| D4010 | | Fire Department Connection, Siamese, 3" | 2011 | 1 Each | | | |
| D4010 | | Fire Sprinkler Head | 2011 | 60 Each | | | |
| D4010 | | Fire Sprinkler System | 2011 | 1 Each | | | |
| D4010 | | Pipe & Fittings, 2" Steel | 1989 | 0.5 K Ln Ft | | | |
| D4010 | | Pipe & Fittings, 3" Steel | 1989 | 0.15 K Ln Ft | | | |
| D5010 | | Disconnect Switch, 30 Amp. | 2011 | 1 Each | | | |
| D5010 | | Motor Starter, <5HP, <600V | 2011 | 1 Each | | | |
| D5010 | | Power Panel Board, 208 Y/120 V, 100 Amp. | 2011 | 1 Each | | | |

| Uniformat | Asset Description | Component | Date | Quantity | Location | Notes | |
|-----------|-------------------|---|------|---------------|----------|-------|--|
| D5010 | | Power Panel Board, 208 Y/120 V, 200 Amp. | 2011 | 4 Each | | | |
| D5010 | | Power Panel Board, 208 Y/120 V, 225 Amp | 2011 | 1 Each | | | |
| D5010 | | Power Panel Board, 208 Y/120 V, 400 Amp. | 2011 | 1 Each | | | |
| D5010 | | Power Panel Board, 480 V, 100 Amp. | 2011 | 1 Each | | | |
| D5010 | | Power Panel Board, 480 V, 200 Amp. | 2011 | 1 Each | | | |
| D5010 | | Power Panel Board, 480 V, 400 Amp. | 2011 | 1 Each | | 600 A | |
| D5010 | | Secondary Transformer, Dry, 30 kVA | 2011 | 1 Each | | | |
| D5010 | | Secondary Transformer, Dry, 45 kVA | 2011 | 1 Each | | | |
| D5010 | | Variable Frequency Drive, <600 V | 2011 | 3 Each | | | |
| D5020 | | Compact Fluorescent Lighting Fixture, 32 w | 2011 | 6 Each | | | |
| D5020 | | Emergency Lighting Pack, 2 Light w/ Battery | 2011 | 2 Each | | | |
| D5020 | | Fluorescent Lighting Fixture, T8, 2-32w | 2011 | 36 Each | | | |
| D5020 | | Fluorescent Lighting Fixture, T8, 4-32 w | 2011 | 205 Each | | | |
| D5020 | | Grounded Fault Circuit Interruptor, 15 Amp. | 2011 | 2 Each | | | |
| D5020 | | High Pressure Sodium Lighting Fixture, 250 w | 2002 | 12 Each | | | |
| D5020 | | Lighting Control Panel | 2011 | 1 Each | | | |
| D5020 | | Occupancy Sensors, Indoor Lighting | 2011 | 29 Each | | | |
| D5020 | | Receptacle, 120 V, 20 Amp. | 2011 | 180 Each | | | |
| D5020 | | Wiring Device, Switch | 2011 | 45 Each | | | |
| D5030 | | Camera, Exterior, Closed Circuit, PTZ Color | 2011 | 5 Each | | | |
| D5030 | | Camera, Interior, Closed Circuit, PTZ Color | 2011 | 9 Each | | | |
| D5030 | | Card Reader | 2011 | 5 Each | | | |
| D5030 | | Electric Lock | 2011 | 9 Each | | | |
| D5030 | | Fire Alarm Horn & Strobe | 2011 | 13 Each | | | |
| D5030 | | Handicap Door Access Interface | 2011 | 3 Each | | | |
| D5030 | | Headend Panel, Closed Circuit | 2011 | 1 Each | | | |
| D5030 | | Heat Detector | 2011 | 8 Each | | | |
| D5030 | | Intrusion Detection Motion Detector, Interior | 2011 | 5 Each | | | |
| D5030 | | Keypad | 2011 | 4 Each | | | |
| D5030 | | Manual Pull Station | 2011 | 5 Each | | | |
| D5030 | | Monitor, Medium, Closed Circuit | 2011 | 3 Each | | | |
| D5030 | | Public Address Speaker | 2011 | 2 Each | | | |
| D5030 | | Security System Panel | 2011 | 1 Each | | | |
| D5030 | | Smoke Detector | 2011 | 27 Each | | | |
| D5030 | | Smoke Detector, Duct | 2011 | 1 Each | | | |
| D5090 | | Grounding System | 2011 | 0.625 K Ln Ft | | | |

| Uniformat | Asset Description | Component | Date | Quantity | Location | Notes |
|-----------|-------------------|---------------------------------------|------|----------|----------|-------|
| D5090 | | Meter, Electrical, 208 Volt, 600 Amp. | 2011 | 1 Each | | |
| E1010 | | Icemaker, Commercial | 2011 | 1 Each | | |
| E1010 | | Kitchen Exhaust Hood, Commercial | 2011 | 1 Each | | |

[§] Indicates Component set to have PM Tasks coincide with Replacement Task.

Whitestone Research

Average M&R Costs


| Building: | Office Building | GSFT: 1 [*] | 1,050 |
|------------------|------------------------------|-----------------------------|-----------|
| Building Number: | 1045/62/212 | PRV: \$3 | 3,332,663 |
| Facility: | Marshall Space Flight Center | Built Date: 19 | 943 |
| City: | Huntsville, AL | | |

| _ | Μ | &R Average Annual (| Cost Forecasts | |
|--------------------------|--------------|---------------------|----------------|----------|
| _ | Current Year | 5 Year | 20 Year | 50 Year |
| PM & Minor Repair: | \$17,458 | \$17,508 | \$16,791 | \$16,567 |
| Unscheduled Maintenance: | \$12,276 | \$12,301 | \$11,673 | \$11,534 |
| Renewal & Replacement: | \$16,730 | \$6,376 | \$47,639 | \$54,271 |
| Total M&R Costs: | \$46,464 | \$36,185 | \$76,103 | \$82,372 |
| Per GSFT: | \$4.20 | \$3.27 | \$6.89 | \$7.45 |
| As % of PRV: | 1.39% | 1.09% | 2.28% | 2.47% |

M&R Costs by System per Year Chart

Whitestone Research 05-Mar-13


| Building: Office | Build | ing | | | | | | F | acili | t y : № | larsha | all Sp | ace F | light | Cent | er | | С | ity: I | Hunts | sville, | AL | | | |
|-------------------------------|--------|------|------|------|------|-------|------|------|-------|----------------|--------|--------|-------|-------|------|------|------|------|--------|-------|---------|------|------|------|------|
| Building Num: 1045/6 | 62/212 | 2 | | | | | | | GSF | T: 1 | 1050 | | | | | | | | | | | | | | |
| Forecast Year: | 2013 | 4 | 5 | 6 | 7 | 2018 | 9 | 0 | 1 | 2 | 2023 | 4 | 5 | 6 | 7 | 2028 | 9 | 0 | 1 | 2 | 2033 | 4 | 5 | 6 | 7 |
| A10 Foundations | | | | | | | | | | | | | | | | | | | | | | | | | |
| A20 Basement Construction | | | | | | | | | | | | | | | | | | | | | | | | | |
| B10 Super Structure | | | | | | | | | 0.02 | | | | 0.04 | 0.01 | | | | | 0.02 | | | | 0.14 | | |
| B20 Exterior Enclosure | 1.01 | 0.02 | 0.02 | | | 2.45 | 0.40 | 0.10 | 0.01 | | 0.89 | 0.02 | 0.05 | 0.00 | | 0.10 | 0.08 | 0.10 | 0.02 | | 0.93 | 0.02 | 0.02 | | 0.03 |
| B30 Roofing | 0.29 | 0.29 | 0.30 | 0.53 | 0.29 | 0.29 | 0.29 | 0.29 | 0.54 | 0.29 | 0.29 | 0.29 | 0.29 | 0.53 | 0.30 | 0.29 | 0.29 | 0.29 | 1.05 | 0.29 | 0.30 | 0.29 | 0.29 | 0.53 | 0.29 |
| C10 Interior Construction | 0.00 | 0.01 | 0.04 | 0.10 | 0.00 | | 0.11 | | 0.61 | | 0.04 | 0.01 | 0.00 | 0.10 | 0.04 | | 0.24 | | 0.86 | | 0.00 | 0.01 | 0.04 | 0.80 | 0.00 |
| C20 Stairs | | | 0.01 | | | | 0.56 | | | | 0.01 | | | 0.05 | 0.01 | | 0.01 | | 0.01 | | | 0.02 | 0.01 | | |
| C30 Interior Finishes | 0.50 | 0.00 | 0.03 | 0.11 | | 7.28 | 0.02 | 0.04 | 0.85 | | | | 0.03 | 5.47 | | 0.50 | 0.23 | | 0.89 | | 0.04 | | 0.03 | 0.13 | |
| D10 Conveying | | | | | | | | | | | | | | | | | | | | | | | | | |
| D20 Plumbing | 0.08 | 0.04 | 0.37 | 0.04 | 0.09 | 0.33 | 0.09 | 0.04 | 0.44 | 0.03 | 0.09 | 0.03 | 0.16 | 0.53 | 0.09 | 0.03 | 0.09 | 0.04 | 0.44 | 0.08 | 0.10 | 0.03 | 0.14 | 0.10 | 0.08 |
| D30 HVAC | 1.23 | 1.23 | 1.51 | 1.26 | 1.23 | 1.23 | 1.56 | 1.86 | 7.89 | 1.23 | 1.82 | 7.63 | 1.23 | 1.34 | 1.51 | 1.23 | 1.59 | 1.23 | 8.50 | 1.23 | 1.86 | 1.89 | 2.87 | 1.33 | 8.09 |
| D40 Fire Protection | 0.22 | 0.21 | 0.21 | 0.22 | 0.21 | 0.21 | 0.21 | 0.21 | 0.43 | 0.21 | 0.21 | 0.21 | 0.22 | 0.47 | 0.21 | 0.21 | 0.21 | 0.21 | 0.43 | 0.21 | 0.21 | 0.21 | 0.21 | 0.22 | 0.22 |
| D50 Electrical | 0.71 | 0.71 | 0.72 | 1.00 | 0.73 | 0.70 | 0.72 | 0.71 | 10.09 | 1.78 | 0.73 | 0.70 | 0.72 | 3.66 | 0.71 | 0.70 | 4.45 | 0.70 | 12.74 | 1.10 | 0.71 | 0.73 | 0.74 | 1.39 | 0.71 |
| E10 Equipment | 0.16 | 0.16 | 0.16 | 0.16 | 0.16 | 0.16 | 0.16 | 0.16 | 1.52 | 0.16 | 0.16 | 0.16 | 0.16 | 0.84 | 0.16 | 0.16 | 0.16 | 0.16 | 1.52 | 0.16 | 0.16 | 0.16 | 0.16 | 0.16 | 0.16 |
| E20 Furnishings | | | | | | | | | | | | | | | | | | | | | | | | | |
| F10 Special Construction | | | | | | | | | | | | | | | | | | | | | | | | | |
| F20 Selective Bldg Demolition | | | | | | | | | | | | | | | | | | | | | | | | | |
| G10 Site Preparation | | | | | | | | | | | | | | | | | | | | | | | | | |
| G20 Site Improvements | | | | | | | | | | | | | | | | | | | | | | | | | |
| G30 Site Mechanical Utilities | | | | | | | | | | | | | | | | | | | | | | | | | |
| G40 Site Electrical Utilities | | | | | | | | | | | | | | | | | | | | | | | | | |
| G90 Other Site Construction | | | | | | | | | | | | | | | | | | | | | | | | | |
| Total | 4.20 | 2.68 | 3.37 | 3.42 | 2.71 | 12.64 | 4.14 | 3.42 | 22.41 | 3.70 | 4.24 | 9.04 | 2.91 | 13.00 | 3.03 | 3.21 | 7.35 | 2.73 | 26.49 | 3.06 | 4.32 | 3.36 | 4.64 | 4.65 | 9.59 |



M&R Costs by System per Year Chart

Whitestone Research 05-Mar-13

| Building: Office B Building Num: 1045/6 | | • | | | | | | | | | larsha 1050 | all Sp | ace F | light | Cent | er | | Ci | ity: I | Hunts | sville, | AL | | | | |
|--|------|------|--------|--------------|------|-------|------|------|------|------|----------------|--------|-------|-------|------|------|------|------|--------|-------|---------|---------|-------|--------|--------|--------|
| Forecast Year: | | | 0 | 1 | 2 | 2043 | 4 | 5 | 6 | 7 | 2048 | 9 | 0 | 1 | 2 | 2053 | 4 | 5 | 6 | 7 | 2058 | 9 | 0 | 1 | 2 | Total |
| Ado Faundations | | | | | | | | | | | | | | | | | | | | | | | | | | 0.00 |
| A10 Foundations A20 Basement Construction | | | | | | | | | | | | | | | | | | | | | | | | | | 0.00 |
| | | | | 0.00 | | | | | | | | | 0.04 | 0.00 | | | | | 0.04 | | | | | 0.00 | | 0.00 |
| B10 Super Structure | 0.40 | 0.00 | | 0.03 | | 0.00 | 0.00 | 0.00 | | 0.00 | 0.40 | 0.40 | | 0.02 | | 0.00 | 0.00 | 0.40 | 0.01 | 0.00 | 0.40 | 0.00 | 0.40 | 0.02 | | 0.35 |
| B20 Exterior Enclosure | 0.10 | | - | 0.01 0.79 | 0.00 | 9.03 | 0.02 | | 0.50 | 0.00 | | 0.40 | | | 0.20 | 0.89 | 0.02 | 0.10 | 0.50 | 0.00 | | 0.08 | | | 0.00 | 17.86 |
| B30 Roofing | 0.29 | 0.30 | | | 0.29 | | 0.29 | | 0.53 | | 0.29 | | 0.29 | | 0.29 | 0.29 | | | | | 0.29 | | 0.29 | 0.55 | 0.29 | 28.54 |
| C10 Interior Construction | | •••• | | 0.61 | | 0.04 | 0.01 | 0.00 | 0.10 | | | 0.07 | | 2.32 | | 0.00 | 0.01 | 0.04 | | 0.00 | | 0.11 | | 1.31 | | 7.95 |
| C20 Stairs | 0.54 | 0.02 | | 0.05 | | 0.01 | | 0.00 | 0.40 | 0.01 | 0.50 | 0.56 | | 0.01 | | | | | 0.05 | | 0.50 | | | 0.61 | | 2.00 |
| C30 Interior Finishes | 0.54 | 0.02 | | 6.21 | | 1.66 | | 0.03 | 2.10 | 0.17 | 0.52 | 0.02 | | 0.89 | | | | 0.07 | 5.47 | | 0.52 | 0.02 | | 1.26 | | 35.69 |
| D10 Conveying | 0.04 | 0.40 | 0.04 | 0.07 | 0.04 | 0.40 | 0.04 | 0.00 | 0.70 | 0.00 | 0.00 | 0.05 | 0.00 | 0.47 | 0.07 | 0.40 | 0.00 | 0.07 | 0.00 | 0.05 | 0.07 | 0.07 | 0.4.4 | 0.07 | 0.00 | 0.00 |
| D20 Plumbing | 0.04 | 0= | 0.0. | 0.0. | 0.04 | 00 | 0.0. | 0.08 | 0.78 | 0.00 | 0.09 | | 0.09 | | | 0.10 | | | | | 0.07 | 0.07 | | 0.37 | 0.08 | 8.62 |
| D30 HVAC | 1.23 | | - | | 1.23 | | 1.23 | 1.23 | | 1.82 | - | | 7.63 | | | - | - | 1.51 | - | - | 1.49 | 3.24 | | 7.95 | 1.23 | 126.96 |
| D40 Fire Protection | 0.21 | 0.21 | | | 0.21 | •••=• | 0.21 | 0.21 | - | 0.21 | - | - | - | | 0.21 | - | - | - | 0.47 | - | 0.21 | 0.21 | 0.21 | | 0.21 | 12.60 |
| D50 Electrical | 0.71 | | | | | - | | - | | | | - | - | | | 0.73 | | | | | | • • • • | 0.70 | | 1.83 | 115.27 |
| E10 Equipment | 0.16 | 0.16 | 0.16 | 2.20 | 0.16 | 0.16 | 0.16 | 0.16 | 0.16 | 0.16 | 0.16 | 0.16 | 0.16 | 1.52 | 0.16 | 0.16 | 0.16 | 0.16 | 0.84 | 0.16 | 0.16 | 0.16 | 0.16 | 1.52 | 0.16 | 16.89 |
| E20 Furnishings | | | | | | | | | | | | | | | | | | | | | | | | | | 0.00 |
| F10 Special Construction | | | | | | | | | | | | | | | | | | | | | | | | | | 0.00 |
| F20 Selective Bldg Demolition | | | | | | | | | | | | | | | | | | | | | | | | | | 0.00 |
| G10 Site Preparation | | | | | | | | | | | | | | | | | | | | | | | | | | 0.00 |
| G20 Site Improvements | | | | | | | | | | | | | | | | | | | | | | | | | | 0.00 |
| G30 Site Mechanical Utilities | | | | | | | | | | | | | | | | | | | | | | | | | | 0.00 |
| G40 Site Electrical Utilities | | | | | | | | | | | | | | | | | | | | | | | | | | 0.00 |
| G90 Other Site Construction | | | | | | | | | | | | | | | | | | | | | | | | | | 0.00 |
| Total | 3.28 | 3.45 | 3.02 3 | 38.10 | 3.71 | 13.78 | 2.70 | 2.74 | 6.75 | 7.20 | 3.37 | 3.80 | 9.37 | 38.99 | 3.07 | 3.61 | 2.70 | 3.19 | 13.0 | 1 3.0 | OC 3.5 | 3 4.9 | 3 3.1 | 2 24.2 | 1 3.80 | 372.73 |



| M&R Costs by Task | | | | | | | | | W | hites | stone | Resea | arch | | | | | 05 | ō-Mar | -1: |
|--|-------|----|----|-----------|-------|---------|-------|-----------|-----|-------|-------|--------|------|-----|-----|--------|----|-------|-------|-----|
| Building: Office Building | | | | Facility: | Marsh | nall Sp | ace F | light Cen | ter | | | | | | | | | | | |
| Building Num: 1045/62/212 | | | | Citv: | Hunts | ville. | AL. | | | | | | | | | | | | | |
| Forecast Year: | 2013 | 4 | 5 | 6 7 2 | | | 1 | 2 2023 | 4 | 5 | 6 | 7 2028 | 39 | 0 | 1 | 2 2033 | 4 | 5 | 6 | |
| B10 Super Structure | | | | | | | | | | | | | | | | | | | | |
| Repair Concrete Ramp (2% of Ramp) | | | | | | | | | | | 96 | | | | | | | | | |
| Finish Repaired Concrete Ramp | | | | | | | | | | | 4 | | | | | | | | | |
| Repair Steel Roof Access Ladder | | | | | | | | | | 461 | | | | | | | | | | |
| Replace Steel Roof Access Ladder | | | | | | | | | | | | | | | | | | 1,525 | | |
| Refinish Concrete Ramp | | | | | | | 216 | | | | | | | | 216 | | | ., | | |
| Reministr Concrete Ramp | | | | | | | 210 | | | | | | | | 210 | | | | | |
| B20 Exterior Enclosure | | | | | | | | | | | | | | | | | | | | |
| Maintain Wood, Solid Core, Painted, Exterior Door Locks | | | 44 | | | 44 | | | | 44 | | | | 44 | | | | 44 | | |
| Minor Repair, Glass Curtain Wall (2% of Walls) | | 78 | | | | | | | 78 | | | | 78 | | | | 78 | | | |
| Replace Glass Curtain Wall | | | | | 3,645 | 5 | | | | | | | | | | | | | | |
| Maintain Aluminum Frame, Fully Glazed, Exterior Door Locks | | 44 | | | 44 | Ļ | | | 44 | | | | 44 | | | | 44 | | | |
| Replace Aluminum Frame, Fully Glazed, Exterior Door Locks | | | | | 657 | , | | | | | | | 657 | | | | | | | |
| Repair Aluminum Frame, Fully Glazed, Exterior Door | 347 | | | | | | | | | 347 | | | | | | | | | | 3 |
| Replace Aluminum Frame, Fully Glazed, Exterior Door | | | | | | | | | | | | | | | | | | | | |
| Maintain Steel w/ Safety Glass, Painted, Exterior Door Locks | 44 | | | | | | | 44 | | | | 44 | ļ. | | | 44 | | | | |
| Replace Steel w/ Safety Glass, Painted, Exterior Door Locks | 657 | | | | | | | | | | | 657 | • | | | | | | | |
| Refinish Steel w/ Safety Glass, Painted, Exterior Door | 46 | | | | | | | | | | | 46 | 5 | | | | | | | |
| Repair Steel w/ Safety Glass, Painted, Exterior Door | | | | | | | | | | | | | | | | 347 | | | | |
| Repair Aluminum Fixed Window w/ Thermal Break, Dbl Glazed, | | | | | | | | | | | | | | | 138 | | | | | |
| Finish Replaced Steel w/ Safety Glass, Painted, Exterior Door | | | | | 46 | | | | | | | | | | | | | | | |
| Replace Concrete Block, Painted, Exterior, 2nd Floor | | | | | | | | | | | | | | | | | | | | |
| Refinish Wood, Solid Core, Painted, Exterior Door | | | | | 46 | 5 | | | | | 46 | | | | | 46 | | | | |
| Replace Wood, Solid Core, Painted, Exterior Door Locks | | | | | | 657 | | | | | | | | 657 | | | | | | |
| Repair Wood, Solid Core, Painted, Exterior Door | | | | | | 347 | | | | | | | | 347 | | | | | | |
| Replace Wood, Solid Core, Painted, Exterior Door | | | | | | | | | | | | | | | | | | | | |
| Finish Replaced Wood, Solid Core, Painted, Exterior Door | | | | | | | | | | | | | | | | | | | | |
| Replace Steel w/ Safety Glass, Painted, Exterior Door | | | | 2 | ,368 | | | | | | | | | | | | | | | |
| Refinish Concrete Block, Painted, Exterior, 1st Floor | 8,552 | | | | | | | 8,552 | | | | | | | | 8,552 | | | | |
| Refinish Aluminum Louver, 1st Floor | | | 85 | | | | | | | 85 | | | | | | | | 85 | | |
| Replace Aluminum Louver, 1st Floor | | | | | | | | | | | | | | | | | | | | |
| Refinish Aluminum Louver, 2nd Floor | | | | | | | 73 | | | | | | | | 73 | | | | | |
| Refinish Clay Brick, Painted, Exterior, 1st Floor | 239 | | | | | | | | | | | 239 |) | | | | | | | |
| Repair Clay Brick, Painted, Exterior, 1st Floor (2% of Walls) | | | | | | | | | | | | | | | | | | | | |
| Repoint (50% surface) Clay Brick, Painted, Exterior, 1st Floor | | | | | | | | | | | | | | | | | | | | |
| Finish Repaired Clay Brick, Painted, Exterior, 1st Floor | | | | | | | | | | | | | | | | | | | | |
| Repair Aluminum Fixed Window w/ Thermal Break, Dbl Glazed, | | | | | | | | | | | | | | | 39 | | | | | |

| M&R Costs by Task | | | | | | | | W | hites | tone | Resear | ch | | | | | 0 | 5-Ma | ır-13 |
|--|------|-----|-----|------------|-----------------|---------|------------|-------|-------|------|--------|----|-------|----|-------|-----|-----|------|-------|
| Building: Office Building | | | Fa | cility: Ma | arshall | Space F | light Cent | er | | | | | | | | | | | |
| Building Num: 1045/62/212 | | | | City: Hu | untsville | e Al | | | | | | | | | | | | | |
| Forecast Year: | 2038 | 0 | 0 1 | 2 2043 | 4 I I CO VIII C | 5 6 | 7 2048 | 9 | 0 | 1 | 2 2053 | | 5 | 6 | 7 205 | 8 9 | 0 | 1 | 2 |
| | 2038 | 9 | 0 1 | 2 2043 | 4 | 5 0 | 7 2048 | э | U | 1 | 2 2053 | 4 | 5 | o | 7 205 | 5 9 | U | 1 | |
| B10 Super Structure | | | | | | | | | | | | | | | | | | | |
| Repair Concrete Ramp (2% of Ramp) | | | 96 | | | | | | | | | | | 96 | | | | | |
| Finish Repaired Concrete Ramp | | | 4 | | | | | | | | | | | 4 | | | | | |
| Repair Steel Roof Access Ladder | | | | | | | | | 461 | | | | | | | | | | |
| Replace Steel Roof Access Ladder | | | | | | | | | | | | | | | | | | | |
| Refinish Concrete Ramp | | | 216 | | | | | | | 216 | | | | | | | | 216 | |
| B20 Exterior Enclosure | | | | | | | | | | | | | | | | | | | |
| Maintain Wood, Solid Core, Painted, Exterior Door Locks | | 4 | 4 | | | 44 | | | | | | | 44 | | | | 44 | | |
| | | 70 | + | | 78 | 44 | | | | | | 78 | 44 | | | 78 | 44 | | |
| Minor Repair, Glass Curtain Wall (2% of Walls) | | 70 | | | 70 | | | 3,645 | | | | 70 | | | | 78 | | | |
| Replace Glass Curtain Wall Maintain Aluminum Frame, Fully Glazed, Exterior Door Locks | | | | | 44 | | | 44 | | | | 44 | | | | 44 | | | |
| Replace Aluminum Frame, Fully Glazed, Exterior Door Locks | | | | | 44 | | | 657 | | | | 44 | | | | 657 | | | |
| Repair Aluminum Frame, Fully Glazed, Exterior Door | | | | | | | | 007 | | 347 | | | | | | 057 | | | |
| Replace Aluminum Frame, Fully Glazed, Exterior Door | 2,4 | 07 | | | | | | | | 547 | | | | | | | | | |
| Maintain Steel w/ Safety Glass, Painted, Exterior Door Locks | 44 | .51 | | 44 | | | 44 | | | | 44 | | | | 4 | 1 | | | |
| Replace Steel w/ Safety Glass, Painted, Exterior Door Locks | 657 | | | 44 | | | 657 | | | | 44 | | | | 65 | | | | |
| | 46 | | | | | | 46 | | | | | | | | 4 | | | | |
| Refinish Steel w/ Safety Glass, Painted, Exterior Door | 40 | | | | | | 347 | | | | | | | | 4 | , | | | |
| Repair Steel w/ Safety Glass, Painted, Exterior Door | | | | | | | 347 | | | 120 | | | | | | | | | |
| Repair Aluminum Fixed Window w/ Thermal Break, Dbl Glaze | | | | | | | | | | 130 | | | | | | | | | |
| Finish Replaced Steel w/ Safety Glass, Painted, Exterior Door | | | | 0.470 | | | | | | | | | | | | | | | |
| Replace Concrete Block, Painted, Exterior, 2nd Floor | | 4 | _ | 8,172 | | | 46 | | | | | | | | 46 | | | | |
| Refinish Wood, Solid Core, Painted, Exterior Door | | | - | | | | 40 | | | | | | | | 40 | | 657 | | |
| Replace Wood, Solid Core, Painted, Exterior Door Locks | | 65 | | | | | | | | | | | | | | | | | |
| Repair Wood, Solid Core, Painted, Exterior Door | | 34 | / | | | | | | | | | | | | | | 347 | | |
| Replace Wood, Solid Core, Painted, Exterior Door | | | | | | | | à | 2,547 | | | | | | | | | | |
| Finish Replaced Wood, Solid Core, Painted, Exterior Door | | | | | | | | | 46 | | | | | | | | | | |
| Replace Steel w/ Safety Glass, Painted, Exterior Door | | | | | | | | | | | 0.550 | | | | | | | | |
| Refinish Concrete Block, Painted, Exterior, 1st Floor | | | | | | | | | | | 8,552 | | | | | | | | |
| Refinish Aluminum Louver, 1st Floor | | | | | | 85 | | | | | | | | | | | | | |
| Replace Aluminum Louver, 1st Floor | | | | | | | | | | | | | 1,005 | | | | | | |
| Refinish Aluminum Louver, 2nd Floor | 005 | | 73 | | | | | | | 73 | | | | | | | | 73 | |
| Refinish Clay Brick, Painted, Exterior, 1st Floor | 239 | | | | | | 239 | | | | | | | | 23 | 9 | | | |
| Repair Clay Brick, Painted, Exterior, 1st Floor (2% of Walls) | | | | 110 | | | | | | | | | | | | | | | |
| Repoint (50% surface) Clay Brick, Painted, Exterior, 1st Floor | | | | 547 | | | | | | | | | | | | | | | |
| Finish Repaired Clay Brick, Painted, Exterior, 1st Floor | | | | 5 | | | | | | | | | | | | | | | |
| Repair Aluminum Fixed Window w/ Thermal Break, Dbl Glaze | | | | | | | | | | 39 | | | | | | | | | |

Whitestone Research

05-Mar-13

| Building: Office Building | | | | Fa | acilit | y: M | arsha | all Sp | ace | Fligh | t Cen | ter | | | | | | | | | | | | | |
|---|-------|-------|-------|-------|--------|-------------|-------|---------|-------|-------|-------|-------|-------|-------|-------|-------|-------|-------|-------|-------|-------|-------|-------|-------|------|
| Building Num: 1045/62/212 | | | | | Cit | у: Н | untsv | ille, / | ۹L | | | | | | | | | | | | | | | | |
| Forecast Year: | 2013 | 4 | 5 | 6 | 7 | 2018 | 9 | 0 | 1 | 2 | 2023 | 4 | 5 | 6 | 7 | 2028 | 9 | 0 | 1 | 2 | 2033 | 4 | 5 | 6 | |
| Finish Replaced Clay Brick, Painted, Exterior, 1st Floor | | | | | | 239 | | | | | | | | | | | | | | | | | | | |
| Finish Replaced Concrete Block, Painted, Exterior, 2nd Floor | | | | | | | | | | | | | | | | | | | | | | | | | |
| Repair Concrete Block, Painted, Exterior, 1st Floor (2% of Wall | | | | | | 1,739 | | | | | | | | | | | | | | | | | | | |
| Repoint (50% surface) Concrete Block, Painted, Exterior, 1st Fl | | | | | | 15,183 | | | | | | | | | | | | | | | | | | | |
| Finish Repaired Concrete Block, Painted, Exterior, 1st Floor | | | | | | 172 | | | | | | | | | | | | | | | | | | | |
| Replace Concrete Block, Painted, Exterior, 1st Floor | | | | | | | | | | | | | | | | | | | | | | | | | |
| Finish Replaced Concrete Block, Painted, Exterior, 1st Floor | | | | | | | | | | | | | | | | | | | | | | | | | |
| Refinish Concrete Block, Painted, Exterior, 2nd Floor | 1,167 | | | | | | | | | | 1,167 | | | | | | | | | | 1,167 | | | | |
| Repair Concrete Block, Painted, Exterior, 2nd Floor (2% of Wall | | | | | | 166 | | | | | | | | | | | | | | | | | | | |
| Repoint (50% surface) Concrete Block, Painted, Exterior, 2nd F | | | | | | 1,577 | | | | | | | | | | | | | | | | | | | |
| Finish Repaired Concrete Block, Painted, Exerior, 2nd Floor | | | | | | 23 | | | | | | | | | | | | | | | | | | | |
| Replace Clay Brick, Painted, Exterior, 1st Floor | | | | | | 5,505 | | | | | | | | | | | | | | | | | | | |
| B30 Roofing | | | | | | | | | | | | | | | | | | | | | | | | | |
| Repair Metal Canopy | | | | | | | | | | | | | | | | | | | 126 | | | | | | |
| Replace Metal Canopy | | | | | | | | | | | | | | | | | | | 120 | | | | | | |
| Replace Metal Roof | | | | | | | | | | | | | | | | | | | | | | | | | |
| Minor Replacement, Metal Roof (2% of Roof) | | | | | | | | | | | | | | | | | | | 2,413 | | | | | | |
| Repair Metal Roof | | | | 2,593 | | | | | 2,593 | | | | | 2,593 | | | | | 2,593 | | | | | 2,593 | |
| Maintain Aluminum Gutter, Downspouts, Fittings | 201 | 201 | 201 | 201 | 201 | 201 | 201 | 201 | 201 | 201 | 201 | 201 | 201 | 201 | 201 | 201 | 201 | 201 | 2,000 | 201 | 201 | 201 | 201 | 201 | 20 |
| Replace Concrete Roof | 201 | 201 | 201 | 201 | 201 | 201 | 201 | 201 | 201 | 201 | 201 | 201 | 201 | 201 | 201 | 201 | 201 | 201 | | 201 | 201 | 201 | 201 | 201 | 20 |
| | | | | | | | | | 126 | | | | | | | | | | 126 | | | | | | |
| Refinish Metal Canopy Repair Concrete Roof | | | | | | 6 | | | 120 | | | | | | | | | | 120 | | | | | | |
| | | | 37 | | | 0 | | | 37 | | | | | | 37 | | | | | | 37 | | | | |
| Clean & Seal Concrete Roof | | | 37 | | | | | | 31 | | | | | | 37 | | | | 3,512 | | 37 | | | | |
| Replace Aluminum Gutter, Downspouts, Fittings | 1 050 | 1.050 | 1.050 | 4 050 | 4 050 | 4 050 | 4 050 | 1 050 | 1.050 | 4.050 | 4.050 | 4 050 | 4 050 | 4.050 | 4.050 | 4 050 | 4 050 | 1 050 | | 4 050 | 1.050 | 4 050 | 4.050 | 4.050 | 4.05 |
| Maintain Metal Roof | 1,352 | 1,352 | 1,352 | 1,352 | 1,352 | 1,352 | 1,352 | 1,352 | 1,352 | 1,352 | 1,352 | 1,352 | 1,352 | 1,352 | 1,352 | 1,352 | 1,352 | 1,352 | 1,352 | 1,352 | 1,352 | 1,352 | 1,352 | 1,352 | 1,35 |
| C10 Interior Construction | | | | | | | | | | | | | | | | | | | | | | | | | |
| Maintain Steel, Painted, Interior Door Locks | | | | 22 | | | | | 22 | | | | | 22 | | | | | 22 | | | | | 22 | |
| Finish Replaced Wood, Solid Core, Painted, Interior Door | | | | | | | | | | | | | | | | | 46 | | | | | | | | |
| Replace Wood, Solid Core, Painted, Interior Door | | | | | | | | | | | | | | | | | 2,639 | | | | | | | | |
| Replace Wood, Solid Core, Painted, Interior Door Locks | | | | | | | 627 | | 5,331 | | | | | | | | | | 5,331 | | | | | | |
| Maintain Wood, Solid Core, Painted, Interior Door Locks | | 44 | | 379 | | | 44 | | 379 | | | 44 | | 379 | | | | | 379 | | | 44 | | 379 | |
| Replace Steel, Painted, Interior Door Locks | | | | | | | | | 313 | | | | | | | | | | 313 | | | | | | |
| Refinish Steel, Painted, Interior Door | | | 23 | | | | 23 | | | | 23 | | | | 23 | | | | 23 | | | | 23 | | |
| Replace Toilet Partitions, Painted Metal, Overhead Braced | | | | | | | | | | | | | | | | | | | 2,372 | | | | | | |
| Refinish Toilet Partitions, Painted Metal, Overhead Braced | | | 70 | | | | 70 | | | | 70 | | | | 70 | | | | | | | | 70 | | |
| | | | | | | | | | | | | | | | | | | | | | | | | 7,742 | |

Tasks ordered by UNIFORMAT II Classifications. Unscheduled Maintenance Costs are not included. Based on a 50-Year Forecast.

| M&R Costs by Task | | | | | | | | | | | | V | Vhite | estor | ne R | lesea | arch | | | | | | 0 |)5-Ma | ar-13 |
|---|-------|-------|-------|-------|--------|-------------|-------|-----------------|-------|--------|-------|-------|-------|---------|-------|--------|-------|-------|-------|-------|-------|-------|-------|-------|-------|
| Building: Office Building | | | | Fa | acilit | y: M | arsha | all Sp | ace | Flight | t Cen | ter | | | | | | | | | | | | | |
| Building Num: 1045/62/212 | | | | | Cit | y: H | untsv | ville, <i>i</i> | ۹L | | | | | | | | | | | | | | | | |
| Forecast Year: | 2038 | 9 | 0 | 1 | | 2043 | 4 | 5 | 6 | 7 | 2048 | 9 | 0 | 1 | 2 | 2 2053 | 4 | 5 | 6 | 7 | 2058 | 9 | 0 | 1 | 2 |
| Finish Replaced Clay Brick, Painted, Exterior, 1st Floor | | | | | | | | | | | | | | | | | | | | | | | | | |
| Finish Replaced Concrete Block, Painted, Exterior, 2nd Floor | | | | | | 1,167 | | | | | | | | | | | | | | | | | | | |
| Repair Concrete Block, Painted, Exterior, 1st Floor (2% of Wa | | | | | | | | | | | | | | | | | | | | | | | | | |
| Repoint (50% surface) Concrete Block, Painted, Exterior, 1st | | | | | | | | | | | | | | | | | | | | | | | | | |
| Finish Repaired Concrete Block, Painted, Exterior, 1st Floor | | | | | | | | | | | | | | | | | | | | | | | | | |
| Replace Concrete Block, Painted, Exterior, 1st Floor | | | | | | 81,078 | | | | | | | | | | | | | | | | | | | |
| Finish Replaced Concrete Block, Painted, Exterior, 1st Floor | | | | | | 8,552 | | | | | | | | | | | | | | | | | | | |
| Refinish Concrete Block, Painted, Exterior, 2nd Floor | | | | | | | | | | | | | | | | 1,167 | | | | | | | | | |
| Repair Concrete Block, Painted, Exterior, 2nd Floor (2% of W | | | | | | | | | | | | | | | | | | | | | | | | | |
| Repoint (50% surface) Concrete Block, Painted, Exterior, 2nd | | | | | | | | | | | | | | | | | | | | | | | | | |
| Finish Repaired Concrete Block, Painted, Exerior, 2nd Floor | | | | | | | | | | | | | | | | | | | | | | | | | |
| Replace Clay Brick, Painted, Exterior, 1st Floor | | | | | | | | | | | | | | | | | | | | | | | | | |
| 330 Roofing | | | | | | | | | | | | | | | | | | | | | | | | | |
| Repair Metal Canopy | | | | | | | | | | | | | | | | | | | | | | | | 126 | |
| Replace Metal Canopy | | | | 2,895 | | | | | | | | | | | | | | | | | | | | | |
| Replace Metal Roof | | | | | | | | | | | | | | 120,666 | | | | | | | | | | | |
| Minor Replacement, Metal Roof (2% of Roof) | | | | | | | | | | | | | | | | | | | | | | | | | |
| Repair Metal Roof | | | | 2,593 | | | | | 2,593 | | | | | | | | | | 2,593 | | | | | 2,593 | |
| Maintain Aluminum Gutter, Downspouts, Fittings | 201 | 201 | 201 | 201 | 201 | 201 | 201 | 201 | 201 | 201 | 201 | 201 | 201 | | 201 | 201 | 201 | 201 | 201 | 201 | 201 | 201 | 201 | 201 | 201 |
| Replace Concrete Roof | | | | | | 684 | | | | | | | | | | | | | | | | | | | |
| Refinish Metal Canopy | | | | | | | | | | | | | | 126 | | | | | | | | | | 126 | |
| Repair Concrete Roof | | | | | | | | | | | | | | | | | | | | | | | | | |
| Clean & Seal Concrete Roof | | 37 | | | | | | | | | | 37 | | | | | | 37 | | | | | | 37 | |
| Replace Aluminum Gutter, Downspouts, Fittings | | | | | | | | | | | | | | 3,512 | | | | | | | | | | | |
| Maintain Metal Roof | 1,352 | 1,352 | 1,352 | 1,352 | 1,352 | 1,352 | 1,352 | 1,352 | 1,352 | 1,352 | 1,352 | 1,352 | 1,352 | | 1,352 | 1,352 | 1,352 | 1,352 | 1,352 | 1,352 | 1,352 | 1,352 | 1,352 | 1,352 | 1,352 |
| C10 Interior Construction | | | | | | | | | | | | | | | | | | | | | | | | | |
| Maintain Steel, Painted, Interior Door Locks | | | | 22 | | | | | 22 | | | | | 22 | | | | | 22 | | | | | 22 | |
| Finish Replaced Wood, Solid Core, Painted, Interior Door | | | | | | | | | | | | | | 395 | | | | | | | | | | | |
| Replace Wood, Solid Core, Painted, Interior Door | | | | | | | | | | | | | | 22,430 | | | | | | | | | | | |
| Replace Wood, Solid Core, Painted, Interior Door Locks | | 627 | | 5,331 | | | | | | | | 627 | | | | | | | | | | 627 | | 5,331 | |
| Maintain Wood, Solid Core, Painted, Interior Door Locks | | 44 | | 379 | | | 44 | | 379 | | | 44 | | | | | 44 | | 379 | | | 44 | | 379 | |
| Replace Steel, Painted, Interior Door Locks | | | | 313 | | | | | | | | | | 313 | | | | | | | | | | 313 | |
| Refinish Steel, Painted, Interior Door | | 23 | | | | 23 | | | | 23 | | | | 23 | | | | 23 | | | | 23 | | | |
| Replace Toilet Partitions, Painted Metal, Overhead Braced | | | | | | | | | | | | | | 2,372 | | | | | | | | | | | |
| Refinish Toilet Partitions, Painted Metal, Overhead Braced | | 70 | | | | 70 | | | | 70 | | | | | | | | 70 | | | | 70 | | | |
| Replace Movable Partitions, Office, Fabric, 6' | | | | | | | | | | | | | | | | | | | | | | | | 7,742 | |

Tasks ordered by UNIFORMAT II Classifications. Unscheduled Maintenance Costs are not included. Based on a 50-Year Forecast.

| M&R Costs by Task | | | | | | | | W | hitest | tone | Resea | rch | | | | | 05 | -Mar | -13 |
|---|----------------|-------------------|-----|--------------|-----------------|------------------|---------------|-----|----------------|------|---------------|-------|---|-----------------|---------------------|-----|-----------------|------|----------------|
| Building: Office Building | | | Fac | ility: Ma | arshall S | Space I | -light Cen | ter | | | | | | | | | | | |
| Building Num: 1045/62/212 | | | | City: Hu | Inteville | Δι | | | | | | | | | | | | | |
| - | | | | - | | | | | | | | | | | | | | | |
| Forecast Year: Refinish Wood, Solid Core, Painted, Interior Door | 2013 46 | 4 5 395 | 6 | 7 2018 46 | 9 395 | 0 1 46 | 2 2023 395 | 4 | 5 46 | 6 | 7 2028 395 | 9 | 0 | 1 395 | 2 2033 46 | 4 | 5 395 | 6 | 7 46 |
| C20 Stairs | | | | | | | | | | | | | | | | | | | |
| Refinish Metal, Painted, Interior Railing | | 27 | | | 27 | | 27 | | | | 27 | | | 27 | | | 27 | | |
| Finish Repaired Metal, Painted, Interior Railing | | | | | | | | | | 1 | | | | | | | | | |
| Repair Metal, Painted, Interior Stairs | | | | | | | | | | 96 | | | | | | | | | |
| Refinish Metal, Painted, Interior Stairs | | 35 | | | 35 | | 35 | | | | 35 | | | 35 | | | 35 | | |
| Replace Metal, Painted, Interior Railing | | | | | | | | | | | | | | | | | | | |
| Finish Repaired Metal, Painted, Interior Stairs | | | | | | | | | | 1 | | | | | | | | | |
| Repair Metal, Painted, Interior Railing | | | | | | | | | | 39 | | | | | | | | | |
| Replace Metal, Painted, Exterior Railing | | | | | 6,043 | | | | | | | | | | | | | | |
| Finish Repaired Metal, Painted, Exterior Railing | | | | | | | | | | | | | | | | 3 | | | |
| Repair Metal, Painted, Exterior Railing | | | | | | | | | | | | | | | | 168 | | | |
| Refinish Metal, Painted, Exterior Railing | | | | | | | | | | | | 126 | | | | | | | |
| Replace Concrete, Exterior Stairs | | | | | | | | | | | | | | | | | | | |
| Repair Concrete, Exterior Stairs | | | | | | | | | | 437 | | | | | | | | | |
| Finish Replaced Metal, Painted, Interior Railing | | | | | | | | | | | | | | | | | | | |
| Finish Replaced Metal, Painted, Exterior Railing | | | | | 114 | | | | | | | | | | | | | | |
| C30 Interior Finishes | | | | | | | | | | | | | | | | | | | |
| Refinish Concrete, Painted Flooring | 688 | | | | | | | | | | 688 | | | | | | | | |
| Repair Acoustic Tile, Dropped Ceiling (2% of Ceiling) | | | | | 43 | Э | | | | | | 439 | | | | | | | |
| Replace Vinyl Tile Flooring | | | | | | | | | | | | 1,881 | | | | | | | |
| Repair Vinyl Tile Flooring (2% of Floors) | | | | | 2 | 7 | | | | | | | | | | | | | |
| Finish Replaced Concrete, Painted Flooring | | | | 688 | | | | | | | | | | | | | | | |
| Replace Concrete, Painted Flooring | | | | 6,537 | | | | | | | | | | | | | | | |
| Replace Acoustical Tile, Dropped Ceiling | | | | | | | | | | | | | | | | | | | |
| Repair Concrete, Painted Flooring (2% of Floors) | | | | | | | | | | | | | | | 130 | | | | |
| Refinish Gypsum Board, Finished Ceiling | | | | | 226 | | | | | | | 226 | | | | | | | |
| Replace Concrete Flooring | | | | 3,733 | | | | | | | | | | | | | | | |
| Finish Repaired Concrete, Painted Flooring | | | | | | | | | | | | | | | 14 | | | | |
| Refinish Concrete, Painted Ceiling | 1,374 | | | | | | | | | | 1,374 | | | | | | | | |
| Repair Concrete, Painted Ceiling (2% of Ceiling) | | | | | | | | | | | | | | | | | | | |
| Finish Repaired Concrete, Painted Ceiling | | | | | | | | | | | | | | | | | | | |
| Finish Replaced Concrete, Painted Ceiling | | | | 1,374 | | | | | | | | | | | | | | | |
| Repair Gypsum Board, Finished Ceiling (2% of Ceiling) | 16 | 5 | | | | | | | | | | | | | | | | | |
| Finish Repaired Gypsum Board, Finished Ceiling | 4 | Ļ | | | | | | | | | | | | | | | | | |
| Refinish Metal, Painted Ceiling | | | | | | 344 | | | | | | | | 344 | | | | | |

Tasks ordered by UNIFORMAT II Classifications. Unscheduled Maintenance Costs are not included. Based on a 50-Year Forecast.

Whitestone Research

05-Mar-13

| Building: Office Building | | | | Fac | :ility: Ma | arshal | l Spac | ce Fl | ight Ce | enter | | | | | | | | | | | |
|---|-------|-----|---|-----|-------------------|---------|--------|-------|---------|-------|------------|-----|-----|-----|-----|-----|----|-------|-----|---|-------|
| Building Num: 1045/62/212 | | | | | City: Hu | Intsvil | le, AL | | | | | | | | | | | | | | |
| Forecast Year: | 2038 | 9 | 0 | 1 | 2 2043 | 4 | 5 | 6 | 7 204 | 8 8 |) 0 | 1 | 2 2 | 053 | 4 5 | 6 | 7 | 2058 | 9 | 0 | 1 |
| Refinish Wood, Solid Core, Painted, Interior Door | | 395 | | 46 | 395 | | 46 | | 395 | 46 | | | | 46 | 395 | | 46 | | 395 | | 46 |
| C20 Stairs | | | | | | | | | | | | | | | | | | | | | |
| Refinish Metal, Painted, Interior Railing | | 27 | | | 27 | | | | 27 | | | 27 | | | 27 | | | | 27 | | |
| Finish Repaired Metal, Painted, Interior Railing | | | | 1 | | | | | | | | | | | | 1 | | | | | |
| Repair Metal, Painted, Interior Stairs | | | | 96 | | | | | | | | | | | | 96 | | | | | |
| Refinish Metal, Painted, Interior Stairs | | 35 | | | 35 | | | | 35 | | | 35 | | | 35 | | | | 35 | | |
| Replace Metal, Painted, Interior Railing | | | | | | | | | | | | | | | | | | | | | 831 |
| Finish Repaired Metal, Painted, Interior Stairs | | | | 1 | | | | | | | | | | | | 1 | | | | | |
| Repair Metal, Painted, Interior Railing | | | | 39 | | | | | | | | | | | | 39 | | | | | |
| Replace Metal, Painted, Exterior Railing | | | | | | | | | | 6,043 | | | | | | | | | | | |
| Finish Repaired Metal, Painted, Exterior Railing | | | | | | | | | | | | | | | | | | | | | |
| Repair Metal, Painted, Exterior Railing | | | | | | | | | | | | | | | | | | | | | |
| Refinish Metal, Painted, Exterior Railing | | 126 | | | | | | | | | | | | | | | | | 126 | | |
| Replace Concrete, Exterior Stairs | | | | | | | | | | | | | | | | | | | | 5 | 5,872 |
| Repair Concrete, Exterior Stairs | | | | 437 | | | | | | | | | | | | 437 | | | | | |
| Finish Replaced Metal, Painted, Interior Railing | | | | | | | | | | | | | | | | | | | | | 27 |
| Finish Replaced Metal, Painted, Exterior Railing | | | | | | | | | | 114 | | | | | | | | | | | |
| C30 Interior Finishes | | | | | | | | | | | | | | | | | | | | | |
| Refinish Concrete, Painted Flooring | 688 | | | | | | | | 68 | 8 | | | | | | | | 688 | | | |
| Repair Acoustic Tile, Dropped Ceiling (2% of Ceiling) | 439 | | | | | | | | | | | | | | 439 | | | | | | |
| Replace Vinyl Tile Flooring | | | | | | | | 1 | 1,881 | | | | | | | | | | | | |
| Repair Vinyl Tile Flooring (2% of Floors) | 27 | | | | | | | | | | | | | | | 27 | | | | | |
| Finish Replaced Concrete, Painted Flooring | | | | | | | | | | | | | | | | | | | | | |
| Replace Concrete, Painted Flooring | | | | | | | | | | | | | | | | | | | | | |
| Replace Acoustical Tile, Dropped Ceiling | | | | | | | 21, | ,996 | | | | | | | | | | | | | |
| Repair Concrete, Painted Flooring (2% of Floors) | | | | | | | | | 13 | 0 | | | | | | | | | | | |
| Refinish Gypsum Board, Finished Ceiling | | 226 | | | | | | | | 226 | | | | | | | | | 226 | | |
| Replace Concrete Flooring | | | | | | | | | | | | | | | | | | | | | |
| Finish Repaired Concrete, Painted Flooring | | | | | | | | | 1 | 4 | | | | | | | | | | | |
| Refinish Concrete, Painted Ceiling | 1,374 | | | | | | | | 1,37 | 4 | | | | | | | | 1,374 | | | |
| Repair Concrete, Painted Ceiling (2% of Ceiling) | | | | | 485 | | | | | | | | | | | | | | | | |
| Finish Repaired Concrete, Painted Ceiling | | | | | 27 | | | | | | | | | | | | | | | | |
| Finish Replaced Concrete, Painted Ceiling | | | | | | | | | | | | | | | | | | | | | |
| Repair Gypsum Board, Finished Ceiling (2% of Ceiling) | | 16 | | | | | | | | | | | | | | | | | | | |
| Finish Repaired Gypsum Board, Finished Ceiling | | 4 | | | | | | | | | | | | | | | | | | | |
| Refinish Metal, Painted Ceiling | | | | 344 | | | | | | | | 344 | | | | | | | | | 344 |

Tasks ordered by UNIFORMAT II Classifications. Unscheduled Maintenance Costs are not included. Based on a 50-Year Forecast.

| M&R Costs by Task | | | | | | | | | | W | hites | tone | Re | sear | ch | | | | | | 05 | -Mai | r-1 |
|---|-------|----|-----|-------|-----------|--------|----------|-------|---------|----|-------|-------|----|-------|----|----|-------|----|------|----|-----|----------|-----|
| Building: Office Building | | | | Fa | cility: M | arsha | ll Space | Fligh | nt Cent | er | | | | | | | | | | | | | |
| Building Num: 1045/62/212 | | | | | City: H | intsvi | lle Al | | | | | | | | | | | | | | | | |
| - | | | _ | | • | | | | | | _ | | _ | | | | | | | | _ | | |
| Forecast Year: Repair Metal, Painted Ceiling (2% of Ceiling) | 2013 | 4 | 5 | 6 | 7 2018 | 9 | 0 1 | 1 2 | 2023 | 4 | 5 | 6 | 7 | 2028 | 9 | 0 | 1 | 2 | 2033 | 4 | 5 | 6 137 | |
| Finish Repaired Metal, Painted Ceiling | | | | | | | | | | | | | | | | | | | | | | 7 | |
| epoint (50% of surface) Clay Brick, Interior Wall Finish | | | | | | | | | | | | | | | | | | | | | | ' | |
| | | | | | | | | | | | | | | | | | | | 75 | | | | |
| epair Concrete Flooring (2% of Floors) | | | | | 24,600 | | | | | | | | | | | | | | 75 | | | | |
| eplace Concrete, Painted Ceiling | | | | | 24,600 | | | | | | | | | | | | | | | | | | |
| epair Clay Brick, Interior Wall Finish (2% of Walls) | | | | | 5 507 | | | | | | | | | | | | | | | | | | |
| Replace Clay Brick, Interior Wall Finish | | | | | 5,527 | | | | | | | | | | | | | | | | | | |
| Replace Ceramic Tile Flooring | | | | | | | | | | | | | | | | | | | | | | | |
| tefinish Clay Brick, Painted, Interior Wall Finish | 311 | | | | | | | | | | | | | 311 | | | | | | | | | |
| inish Repaired Clay Brick, Painted, Interior Wall Finish | | | | | | | | | | | | | | | | | | | | | | | |
| Repair Ceramic Tile, 4"x4", Interior Wall Finish (2% of Walls) | | | 321 | | | | | | | | 321 | | | | | | | | | | 321 | | |
| inish Replaced Clay Brick, Painted, Interior Wall Finish | | | | | 311 | | | | | | | | | | | | | | | | | | |
| efinish Concrete Block, Painted, Interior Wall Finish | 3,167 | | | | | | | | | | | | | 3,167 | | | | | | | | | |
| epair Concrete Block, Painted, Interior Wall Finish (2% of Wal | | | | | | | | | | | | | | | | | | | | | | | |
| epoint (50% surface) Concrete Block, Painted, Interior Wall Fi | | | | | | | | | | | | | | | | | | | | | | | |
| inish Repaired Concrete Block, Painted, Interior Wall Finish | | | | | | | | | | | | | | | | | | | | | | | |
| eplace Concrete Block, Painted, Interior Wall Finish | | | | | 34,310 | | | | | | | | | | | | | | | | | | |
| epair Carpet, Nylon 20 oz., Low Traffic (2% of Carpet) | | | | 1,199 | | | 1,199 | | | | | | | | | | 1,199 | | | | 1 | ,199 | |
| efinish Gypsum Board, Interior Wall Finish | | | | | | | 7,816 | | | | | | | | | | 7,816 | | | | | | |
| epair Gypsum Board, Interior Wall Finish (2% of Walls) | | | | | | | | | | | | | | | | | 362 | | | | | | |
| inish Repaired Gypsum Board, Interior Wall Finish | | | | | | | | | | | | | | | | | 157 | | | | | | |
| epair Plate Glass Interior Wall | | | | | | | | | | | | | | | | | | | | | | 75 | |
| Replace Plate Glass Interior Wall | | | | | | | | | | | | | | | | | | | | | | | |
| Repair Vinyl, Interior Wall Finish (2% of Walls) | | | | 10 | | | 10 | | | | | | | | | | 10 | | | | | 10 | |
| eplace Vinyl, Interior Wall Finish | | | | | | | | | | | | 516 | | | | | | | | | | | |
| Repair Ceramic Tile Flooring (2% of Floors) | | | | | 253 | | | | | | | | | | | | | | 253 | | | | |
| Replace Carpet, Nylon 20 oz., Low Traffic | | | | | | | | | | | 59 | 9,952 | | | | | | | | | | | |
| inish Replaced Concrete Block, Painted, Interior Wall Finish | | | | | 3,167 | | | | | | | | | | | | | | | | | | |
| 20 Plumbing | | | | | | | | | | | | | | | | | | | | | | | |
| Replace Pipe Insulation, Fiberglass, Cold Water (20% of Insula | | | | | | | | | | | | | | | | | | | | | | 157 | |
| e-tape Pipe Insulation, Fiberglass, Cold Water | | | | 52 | | | 52 | | | | | 52 | | | | | 52 | | | | | | |
| eplace Pipe & Fittings, 2" Copper, Hot Water (20% of Pipe) | | | 888 | | | | | | | | | | | | | | | | | | | | |
| eplace 10' Section, Pipe & Fittings, 2" Copper, Hot Water | | | | | | | | | | | | | | | | | | | | | 44 | | |
| esolder Joint, Pipe & Fittings, 2" Copper, Hot Water | | | | | | | | | | | 35 | | | | | | | | | | 35 | | |
| eplace Pipe & Fittings, 2" Copper, Cold Water (20% of Pipe) | | | 888 | | | | | | | | | | | | | | | | | | | | |
| Resolder Joint, Pipe & Fittings, 2" Copper, Cold Water | | | | | | | | | | | 35 | | | | | | | | | | 35 | | |
| Aaintain Backflow Preventer, 1" | 46 | 46 | 46 | 46 | 46 46 | 46 | 46 | 40 | 10 | | 46 | 46 | 46 | 46 | 10 | 10 | | 10 | 46 | 46 | 46 | 46 | |

Tasks ordered by UNIFORMAT II Classifications. Unscheduled Maintenance Costs are not included. Based on a 50-Year Forecast.

Whitestone Research

05-Mar-13

| Building: Office Building | | | | Fa | cility: | Mar | rshal | l Spa | ce Fl | light (| Cente | er | | | | | | | | | | | | |
|--|-------|----|-----|-------|---------|-----|--------|--------|-------|---------|-------|----|----|-------|----|------|----|-----|-------|----|-------|----|-----|-----|
| Building Num: 1045/62/212 | | | | | City: | Hur | ntsvil | le, AL | _ | | | | | | | | | | | | | | | |
| Forecast Year: | 2038 | 9 | 0 | 1 | 2 20 | | 4 | 5 | 6 | 72 | 048 | 9 | 0 | 1 | 2 | 2053 | 4 | 5 | 6 | 7 | 2058 | 9 | 0 | 1 |
| Repair Metal, Painted Ceiling (2% of Ceiling) | | | | | | | | | | | | | | | | | | | | | | | | 137 |
| Finish Repaired Metal, Painted Ceiling | | | | | | | | | | | | | | | | | | | | | | | | 7 |
| Repoint (50% of surface) Clay Brick, Interior Wall Finish | | | | | 1, | 233 | | | | | | | | | | | | | | | | | | |
| Repair Concrete Flooring (2% of Floors) | | | | | | | | | | | 75 | | | | | | | | | | | | | |
| Replace Concrete, Painted Ceiling | | | | | | | | | | | | | | | | | | | | | | | | |
| Repair Clay Brick, Interior Wall Finish (2% of Walls) | | | | | | 110 | | | | | | | | | | | | | | | | | | |
| Replace Clay Brick, Interior Wall Finish | | | | | | | | | | | | | | | | | | | | | | | | |
| Replace Ceramic Tile Flooring | | | | | 8, | 515 | | | | | | | | | | | | | | | | | | |
| Refinish Clay Brick, Painted, Interior Wall Finish | 311 | | | | | | | | | | 311 | | | | | | | | | | 311 | | | |
| Finish Repaired Clay Brick, Painted, Interior Wall Finish | | | | | | 6 | | | | | | | | | | | | | | | | | | |
| Repair Ceramic Tile, 4"x4", Interior Wall Finish (2% of Walls) | | | | | | | | 321 | | | | | | | | | | 321 | | | | | | |
| Finish Replaced Clay Brick, Painted, Interior Wall Finish | | | | | | | | | | | | | | | | | | | | | | | | |
| Refinish Concrete Block, Painted, Interior Wall Finish | 3,167 | | | | | | | | | 3 | ,167 | | | | | | | | | | 3,167 | | | |
| Repair Concrete Block, Painted, Interior Wall Finish (2% of W | | | | | | 686 | | | | | | | | | | | | | | | | | | |
| Repoint (50% surface) Concrete Block, Painted, Interior Wall | | | | | 7, | 251 | | | | | | | | | | | | | | | | | | |
| Finish Repaired Concrete Block, Painted, Interior Wall Finish | | | | | | 64 | | | | | | | | | | | | | | | | | | |
| Replace Concrete Block, Painted, Interior Wall Finish | | | | | | | | | | | | | | | | | | | | | | | | |
| Repair Carpet, Nylon 20 oz., Low Traffic (2% of Carpet) | | | | | | | | 1 | ,199 | | | | | 1,199 | | | | | | | | | 1, | 199 |
| Refinish Gypsum Board, Interior Wall Finish | | | | 7,816 | | | | | | | | | | 7,816 | | | | | | | | | 7, | 816 |
| Repair Gypsum Board, Interior Wall Finish (2% of Walls) | | | | | | | | | | | | | | 362 | | | | | | | | | | |
| Finish Repaired Gypsum Board, Interior Wall Finish | | | | | | | | | | | | | | 157 | | | | | | | | | | |
| Repair Plate Glass Interior Wall | | | | | | | | | | | | | | | | | | | | | | | | |
| Replace Plate Glass Interior Wall | | | | | | | | | | | | | | | | | | | | | | | 4,4 | 414 |
| Repair Vinyl, Interior Wall Finish (2% of Walls) | | | | | | | | | 10 | | | | | 10 | | | | | | | | | | 10 |
| Replace Vinyl, Interior Wall Finish | | | | 516 | | | | | | | | | | | | | | | 516 | | | | | |
| Repair Ceramic Tile Flooring (2% of Floors) | | | | | | | | | | | | | | | | | | | | | 253 | | | |
| Replace Carpet, Nylon 20 oz., Low Traffic | | | 5 | 9,952 | | | | | | | | | | | | | | 5 | 9,952 | | | | | |
| Finish Replaced Concrete Block, Painted, Interior Wall Finish | | | | | | | | | | | | | | | | | | | | | | | | |
| D20 Plumbing | | | | | | | | | | | | | | | | | | | | | | | | |
| Replace Pipe Insulation, Fiberglass, Cold Water (20% of Insul | | | | | | | | | | | | | | | | | | | | | | | | 157 |
| Re-tape Pipe Insulation, Fiberglass, Cold Water | | | | 52 | | | | | 52 | | | | | 52 | | | | | 52 | | | | | |
| Replace Pipe & Fittings, 2" Copper, Hot Water (20% of Pipe) | | | 888 | | | | | | | | | | | | | | | | | | | | | |
| Replace 10' Section, Pipe & Fittings, 2" Copper, Hot Water | | | | | | | | | | | | | | | | | | | | | | | 44 | |
| Resolder Joint, Pipe & Fittings, 2" Copper, Hot Water | | | | | | | | | | | | | 35 | | | | | | | | | | 35 | |
| Replace Pipe & Fittings, 2" Copper, Cold Water (20% of Pipe) | | | 888 | | | | | | | | | | | | | | | | | | | | | |
| Resolder Joint, Pipe & Fittings, 2" Copper, Cold Water | | | | | | | | | | | | | 35 | | | | | | | | | | 35 | |
| Maintain Backflow Preventer, 1" | 46 | 46 | 46 | | 46 | 46 | 46 | 46 | 46 | 46 | 46 | 46 | 46 | | 46 | 46 | 46 | 46 | 46 | 46 | 46 | 46 | 46 | 4 |

Tasks ordered by UNIFORMAT II Classifications. Unscheduled Maintenance Costs are not included. Based on a 50-Year Forecast. All costs expressed in (\$) 2012.

Page 4, Year 26-50

Whitestone Research

05-Mar-13

| Building: Office Building | | | | Fac | cility | : Ma | irshal | II Spa | ace F | light | t Cent | er | | | | | | | | | | | | | |
|---|------|----|-----|-----|--------|------|--------|--------|-------|-------|--------|----|-----|-------|-----|------|-----|----|-------|-----|------|----|-----|-----|-----|
| Building Num: 1045/62/212 | | | | | City | : Hu | ntsvil | le, A | L | | | | | | | | | | | | | | | | |
| Forecast Year: | 2013 | 4 | 5 | 6 | 7 3 | 2018 | 9 | 0 | 1 | 2 | 2023 | 4 | 5 | 6 | 7 | 2028 | 9 | 0 | 1 | 2 | 2033 | 4 | 5 | 6 | 7 |
| Replace Pipe & Fittings, 3/4" Copper, Hot Water (20% of Pipe) | | | 663 | | | | | | | | | | | | | | | | | | | | | 190 | |
| Replace 10' Section, Pipe & Fittings, 2" Copper, Cold Water | | | | | | | | | | | | | | | | | | | | | | | 44 | | |
| Re-tape Pipe Insulation, Fiberglass, Hot Water | | | | 52 | | | | | 52 | | | | | 52 | | | | | 52 | | | | | | |
| Replace Pipe Insulation, Fiberglass, Hot Water (20% of Insulati | | | | | | | | | | | | | | | | | | | | | | | | 157 | |
| Check Operation, Water Heater, Electric, 80 Gal. | | 19 | | | 19 | | | 19 | | | 19 | | | | | | 19 | | | 19 | | | 19 | | |
| Replace 10' Section, Pipe & Fittings, 3" Cast Iron | | | 33 | | | | | | | | 51 | | | | | | | 33 | | | | | 51 | | |
| Replace Water Heater, Electric, 80 Gal. | | | | | | | | | | | | | | 5,405 | | | | | | | | | | | |
| Replace Backflow Preventer, 1" | | | | | | | | | 992 | | | | | | | | | | 992 | | | | | | |
| Maintain Floor Drain | 92 | 92 | 92 | 92 | 92 | 92 | 92 | 92 | 92 | 92 | 92 | 92 | 92 | 92 | 92 | 92 | 92 | 92 | 92 | 92 | 92 | 92 | 92 | 92 | 92 |
| Replace Floor Drain | | | | | | | | | | | | | | | | | | | | | | | | | |
| Replace 10' Section, Pipe & Fittings, 3/4" Copper, Hot Water | | | | | | | | | | | | | | | | | | | 9 | | | | 33 | | |
| Replace Faucet Washer & Clean Trap, Sink, Stainless Steel | 20 | | 20 | | 20 | | 20 | | 20 | | 20 | | 20 | | 20 | | 20 | | 20 | | 20 | | 20 | | 20 |
| Install New Gasket & Bolts, Pipe & Fittings, 3" Cast Iron | | | | | | | | | | | | | | | | | | | | | | | | 18 | |
| Drain & Flush Water Heater, Electric, 80 Gal. | | | | | | 236 | | | | | | | 236 | | | | | | | | 236 | | | | |
| Replace Service Sink, Iron, Enamel | | | | | | | | | | | | | | | | | | | | | | | | | |
| Replace 10' Section, Pipe & Fittings, 4" Cast Iron | | | 57 | | | | | | | | 28 | | | | | | | 57 | | | | | 28 | | |
| Install New Gasket & Bolts, Pipe & Fittings, 4" Cast Iron | | | | | | | | | | | | | | | | | | | | | | | | 8 | |
| Replace Coolant & Adjust Drinking Fountain, Refrigerated | 48 | | 48 | | 48 | | 48 | | | | 48 | | 48 | | 48 | | 48 | | | | 48 | | 48 | | 48 |
| Replace Drinking Fountain, Refrigerated | | | | | | | | | 1,893 | | | | | | | | | | 1,893 | | | | | | |
| Replace Faucet Washer & Clean Trap, Lavatory, Vitreous Chin | 119 | | 119 | | 119 | | 119 | | 119 | | 119 | | 119 | | 119 | | 119 | | 119 | | 119 | | 119 | | 119 |
| Replace Washer & Spud Connection, Lavatory, Vitreous China | | | | | | 218 | | | | | | | 218 | | | | | | | 218 | | | | | |
| Replace Valve Set, Lavatory, Vitreous China | | | | | | | | | 742 | | | | | | | | | | 742 | | | | | | |
| Replace Lavatory, Vitreous China | | | | | | | | | | | | | | | | | | | | | | | | | |
| Replace Faucet Washer & Clean Trap, Sink, Iron, Enamel | 20 | | 20 | | 20 | | 20 | | 20 | | 20 | | 20 | | 20 | | 20 | | 20 | | 20 | | 20 | | 20 |
| Replace Valve Set, Sink, Stainless Steel | | | | | | | | | 124 | | | | | | | | | | 124 | | | | | | |
| Replace Valve Set, Service Sink, Iron, Enamel | | | | | | | | | 124 | | | | | | | | | | 124 | | | | | | |
| Resolder Joint, Pipe & Fittings, 3/4" Copper, Hot Water | | | | | | | | | 17 | | | | 62 | | | | | | 17 | | | | 62 | | |
| Repair Strainer, Sink, Stainless Steel | | | | | | | 58 | | | | | | | | 58 | | | | | | | | 58 | | |
| Replace Sink, Stainless Steel | | | | | | | | | | | | | | | | | | | | | | | | | |
| Replace Flush Valve, Tankless Water Closet | | | | | | | | | 97 | | | | | | | | | | 97 | | | | | | |
| Replace Tankless Water Closet | | | | | | | | | | | | | | | | | | | | | | | | | |
| Replace Flush Valve, Urinal, Vitreous China | | | | | | 260 | | | | | | | 260 | | | | | | | 260 | | | | | |
| Replace Urinal, Vitreous China | | | | | | | | | | | | | | | | | | | | | | | | | |
| Replace Valve, Hose Bib | | | | | | | | | 53 | | | | | | | | | | 53 | | | | | | |
| Resolder Joint, Pipe & Fittings, 3/4" Copper, Cold Water | | | | | | | | | 17 | | | | 62 | | | | | | 17 | | | | 62 | | |
| Replace 10' Section, Pipe & Fittings, 3/4" Copper, Cold Water | | | | | | | | | | | | | | | | | | | 9 | | | | 33 | | |
| Replace Pipe & Fittings, 3/4" Copper, Cold Water (20% of Pipe) | | | 663 | | | | | | | | | | | | | | | | | | | | | 190 | |

Whitestone Research

05-Mar-13

| Reprise 16 stating. 36" Copyon. Lisk Vance (2004)Image 1000000000000000000000000000000000000 | Building: Office Building | | | | Fa | cility | : Ma | rsha | ll Spa | ace F | light | Cente | er | | | | | | | | | | | | | |
|---|---|------|-----|-----|-------|--------|------|-------|--------|-------|-------|-------|----|-----|-------|-----|------|-----|-----|-------|----|------|----|-----|-------|-----|
| Applic by Eak ming, 3d Corpor, 1dV were (2) were and 3d | Building Num: 1045/62/212 | | | | | City | : Hu | ntsvi | lle, A | L | | | | | | | | | | | | | | | | |
| NameN | Forecast Year: | 2038 | 9 | 0 | 1 | 2 | 2043 | 4 | 5 | 6 | 7 | 2048 | 9 | 0 | 1 | 2 | 2053 | 4 | 5 | 6 | 7 | 2058 | 9 | 0 | 1 | 2 |
| namen | Replace Pipe & Fittings, 3/4" Copper, Hot Water (20% of Pipe | | | 663 | | | | | | | | | | | | | | | | | | | | | 190 | |
| Probability of the series of | Replace 10' Section, Pipe & Fittings, 2" Copper, Cold Water | | | | | | | | | | | | | | | | | | | | | | | 44 | | |
| 1013 <td>Re-tape Pipe Insulation, Fiberglass, Hot Water</td> <td></td> <td></td> <td></td> <td>52</td> <td></td> <td></td> <td></td> <td></td> <td></td> <td></td> | Re-tape Pipe Insulation, Fiberglass, Hot Water | | | | 52 | | | | | 52 | | | | | 52 | | | | | 52 | | | | | | |
| Appende 20Set of the set of t | Replace Pipe Insulation, Fiberglass, Hot Water (20% of Insula | | | | | | | | | | | | | | | | | | | | | | | | 157 | |
| Physical Register of the set of the se | Check Operation, Water Heater, Electric, 80 Gal. | 19 | | | | | | 19 | | | 19 | | | 19 | | | 19 | | | | | | 19 | | | 19 |
| Particity <td>Replace 10' Section, Pipe & Fittings, 3" Cast Iron</td> <td></td> <td></td> <td></td> <td></td> <td>33</td> <td></td> <td></td> <td></td> <td></td> <td>51</td> <td></td> <td></td> <td></td> <td></td> <td></td> <td></td> <td>33</td> <td></td> <td></td> <td></td> <td></td> <td>51</td> <td></td> <td></td> <td></td> | Replace 10' Section, Pipe & Fittings, 3" Cast Iron | | | | | 33 | | | | | 51 | | | | | | | 33 | | | | | 51 | | | |
| Manine DorbinNo <td>Replace Water Heater, Electric, 80 Gal.</td> <td></td> <td></td> <td>:</td> <td>5,405</td> <td></td> <td>5,405</td> <td></td> <td></td> <td></td> <td></td> <td></td> <td></td> | Replace Water Heater, Electric, 80 Gal. | | | : | 5,405 | | | | | | | | | | | | | | | 5,405 | | | | | | |
| | Replace Backflow Preventer, 1" | | | | 992 | | | | | | | | | | 992 | | | | | | | | | | 992 | |
| Application Open & Fittings. 3/4" Coopen. Fitting. 3/4" Scalenes and a scale and a sc | Maintain Floor Drain | 92 | 92 | 92 | 92 | 92 | 92 | 92 | 92 | 92 | 92 | 92 | 92 | 92 | | 92 | 92 | 92 | 92 | 92 | 92 | 92 | 92 | 92 | 92 | 92 |
| Replace Yaucet Washe & Clean Trap, Sink, Stainless Steel CP 20 <td< td=""><td>Replace Floor Drain</td><td></td><td></td><td></td><td></td><td></td><td></td><td></td><td></td><td></td><td></td><td></td><td></td><td></td><td>1,134</td><td></td><td></td><td></td><td></td><td></td><td></td><td></td><td></td><td></td><td></td><td></td></td<> | Replace Floor Drain | | | | | | | | | | | | | | 1,134 | | | | | | | | | | | |
| | Replace 10' Section, Pipe & Fittings, 3/4" Copper, Hot Water | | | | | | | | | | | | | | | | | | | 9 | | | | 33 | | |
| | Replace Faucet Washer & Clean Trap, Sink, Stainless Steel | | 20 | | 20 | | 20 | | 20 | | 20 | | 20 | | | | 20 | | 20 | | 20 | | 20 | | 20 | |
| Replace Service Site with the service of the set | Install New Gasket & Bolts, Pipe & Fittings, 3" Cast Iron | | | | | | 12 | | | | | | | | | | | | | | | | | | 18 | |
| <table-container>Papea 0 section page 4 fittings, 4° calt inon1000<th< td=""><td>Drain & Flush Water Heater, Electric, 80 Gal.</td><td></td><td></td><td>236</td><td></td><td></td><td></td><td></td><td></td><td></td><td></td><td>236</td><td></td><td></td><td></td><td></td><td></td><td></td><td>236</td><td></td><td></td><td></td><td></td><td></td><td></td><td></td></th<></table-container> | Drain & Flush Water Heater, Electric, 80 Gal. | | | 236 | | | | | | | | 236 | | | | | | | 236 | | | | | | | |
| Instal Nord Gasket & Bolic, Pipe & Fittings, 4° cast Iron | Replace Service Sink, Iron, Enamel | | | | | | | | | 964 | | | | | | | | | | | | | | | | |
| Papase Coolant & Adjust Drinking Fournian, Refingerated48484848484848484848484848Replace Durking Fournian, Refingerated118118119 | Replace 10' Section, Pipe & Fittings, 4" Cast Iron | | | | | 57 | | | | | 28 | | | | | | | 57 | | | | | 28 | | | |
| Replace Drinking Fourtian, Refrigerated Replace Drinking Fourtian, Refrigerated 1.883 1.883 1.883 1.883 1.99 119 | Install New Gasket & Bolts, Pipe & Fittings, 4" Cast Iron | | | | | | 17 | | | | | | | | | | | | | | | | | | 8 | |
| Replace Tange Lavadory, Vitreous China 119< | Replace Coolant & Adjust Drinking Fountain, Refrigerated | | 48 | | | | 48 | | 48 | | 48 | | 48 | | | | 48 | | 48 | | 48 | | 48 | | | |
| Replace Washer & Spud Connection, Lawardny, Vitreous China 218 218 Replace Washer & Spud Connection, Lawardny, Vitreous China | Replace Drinking Fountain, Refrigerated | | | | 1,893 | | | | | | | | | | 1,893 | | | | | | | | | | 1,893 | |
| Replace Valve Set, Lavatory, Vitreous China 6 Replace Lavatory, Vitreous China 20 | Replace Faucet Washer & Clean Trap, Lavatory, Vitreous Chi | | 119 | | 119 | | 119 | | 119 | | | 119 | | 119 | | 119 | | 119 | | 119 | | 119 | | 119 | | 119 |
| Replace Lavatory, Vircours China 20 <td>Replace Washer & Spud Connection, Lavatory, Vitreous Chin</td> <td></td> <td>218</td> <td></td> <td>218</td> <td></td> <td></td> <td></td> <td></td> <td></td> <td></td> <td>218</td> <td></td> <td></td> | Replace Washer & Spud Connection, Lavatory, Vitreous Chin | | 218 | | | | | | | | | | | | | | 218 | | | | | | | 218 | | |
| Replace Fauce Washer & Clean Trap, Sink, Iron, Enamel 20 | Replace Valve Set, Lavatory, Vitreous China | | | | 742 | | | | | | | | | | | | | | | 742 | | | | | | |
| Replace Value Sets, Sink, Stainless Steel 124 Replace Value Sets, Sink, Iron, Enamel 124 Replace Value Sets, Sink, Iron, Enamel 124 Replace Value Sets, Sink, Iron, Enamel 124 Replace Value Sets, Stainless Steel 124 Replace Sink, Stainless Steel 126 Replace Flush Valve, Tankless Water Closet 942 Replace Flush Valve, Urinal, Vitreous China 260 Replace Valve, Hose Bib 260 Replace Valve, Hose Bib 263 Replace Valve, Hose Bib 53 Replace Valve, Pipe & Fittings, 34" Copper, Cold Water 53 Replace Valve, Pipe & Fittings, 34" Copper, Cold Water 53 | Replace Lavatory, Vitreous China | | | | | | | | | 2,607 | | | | | | | | | | | | | | | | |
| Replace Valve Set, Service Sink, Iron, Enamel 124 Replace Valve Set, Service Sink, Iron, Enamel 124 124 Replace Valve Set, Service Sink, Iron, Enamel 124 124 Replace Valve Set, Service Sink, Iron, Enamel 17 62 17 62 | Replace Faucet Washer & Clean Trap, Sink, Iron, Enamel | | 20 | | 20 | | 20 | | 20 | | | 20 | | 20 | | 20 | | 20 | | 20 | | 20 | | 20 | | 20 |
| Reader Joint, Pipe & Fittings, 3/4" Copper, Hot Water 17 62 Repix Strainer, Sink, Stainless Steel 58 58 Replace Sink, Stainless Steel 94 58 Replace Sink, Stainless Steel 94 58 Replace Flush Valve, Tankless Water Closet 97 94 Replace Flush Valve, Tankless Water Closet 97 97 Replace Flush Valve, Urinal, Vitreous China 260 260 Replace Flush Valve, Urinal, Vitreous China 260 260 Replace Valve, Hose Bib 6 53 53 Resolder Joint, Pipe & Fittings, 3/4" Copper, Cold Wate 6 53 53 Replace 10' Section, Pipe & Fittings, 3/4" Copper, Cold Wate 6 53 53 Replace 10' Section, Pipe & Fittings, 3/4" Copper, Cold Wate 6 62 53 | Replace Valve Set, Sink, Stainless Steel | | | | 124 | | | | | | | | | | | | | | | | | | | | 124 | |
| Replace Stanleys Steel 58 Replace Sink, Stainless Steel 942 Replace Flush Valve, Tankless Water Closet 97 Replace Tankless Water Closet 97 Replace Tankless Water Closet 97 Replace Flush Valve, Urinal, Vitreous China 260 Replace Flush Valve, Urinal, Vitreous China 260 Replace Valve, Hose Bib 6 Replace Valve, Hose Bib 53 Resolder Joint, Pipe & Fittings, 3/4" Copper, Cold Water 6 Replace 10' Section, Pipe & Fittings, 3/4" Copper, Cold Water 33 | Replace Valve Set, Service Sink, Iron, Enamel | | | | 124 | | | | | | | | | | | | | | | 124 | | | | | | |
| Replace Sink, Stainless Steel 942 Replace Flush Valve, Tankless Water Closet 97 Replace Tankless Water Closet 97 Replace Flush Valve, Urinal, Vitreous China 260 Replace Flush Valve, Urinal, Vitreous China 260 Replace Urinal, Vitreous China 260 Replace Valve, Hose Bib 61 Resolder Joint, Pipe & Fittings, 3/4" Copper, Cold Water 61 Replace 10' Section, Pipe & Fittings, 3/4" Copper, Cold Water 61 | Resolder Joint, Pipe & Fittings, 3/4" Copper, Hot Water | | | | | | | | | 17 | | | | 62 | | | | | | 17 | | | | 62 | | |
| Replace Flush Valve, Tankless Water Closet 97 Replace Flush Valve, Tankless Water Closet 97 Replace Tankless Water Closet 3.054 Replace Flush Valve, Urinal, Vitreous China 260 Replace Urinal, Vitreous China 260 Replace Urinal, Vitreous China 1.469 Replace Valve, Hose Bib 53 Resolder Joint, Pipe & Fittings, 3/4° Copper, Cold Water 62 Replace 10' Section, Pipe & Fittings, 3/4° Copper, Cold Water 1 | Repair Strainer, Sink, Stainless Steel | | | | | | 58 | | | | | | | | | | | | | | | | 58 | | | |
| Replace Tankless Water Closet3.054Replace Flush Valve, Urinal, Vitreous China260260Replace Urinal, Vitreous China260260Replace Valve, Hose Bib635353Resolder Joint, Pipe & Fittings, 3/4° Copper, Cold Water616233Replace 10° Section, Pipe & Fittings, 3/4° Copper, Cold Water933 | Replace Sink, Stainless Steel | | | | | | | | | | | | | | 942 | | | | | | | | | | | |
| Replace Flush Valve, Urinal, Vitreous China 260 260 Replace Flush Valve, Urinal, Vitreous China 260 260 Replace Urinal, Vitreous China 1.469 53 Replace Valve, Hose Bib 53 53 Resolder Joint, Pipe & Fittings, 3/4° Copper, Cold Water 62 17 62 Replace 10' Section, Pipe & Fittings, 3/4° Copper, Cold Water 9 33 | Replace Flush Valve, Tankless Water Closet | | | | 97 | | | | | | | | | | | | | | | 97 | | | | | | |
| Replace Urinal, Vitreous China 1.469 Replace Urinal, Vitreous China 1.469 Replace Valve, Hose Bib 53 53 Resolder Joint, Pipe & Fittings, 3/4° Copper, Cold Water 62 17 62 Replace 10' Section, Pipe & Fittings, 3/4° Copper, Cold Water 9 33 | Replace Tankless Water Closet | | | | | | | | | 3,054 | | | | | | | | | | | | | | | | |
| Replace Valve, Hose Bib 53 53 Resolder Joint, Pipe & Fittings, 3/4" Copper, Cold Water 17 62 Replace 10' Section, Pipe & Fittings, 3/4" Copper, Cold Water 9 33 | Replace Flush Valve, Urinal, Vitreous China | | 260 | | | | | | | | | | | | | | 260 | | | | | | | 260 | | |
| Resolder Joint, Pipe & Fittings, 3/4" Copper, Cold Water 17 62 17 62 Replace 10' Section, Pipe & Fittings, 3/4" Copper, Cold Water 9 33 | Replace Urinal, Vitreous China | | | | | | | | | 1,469 | | | | | | | | | | | | | | | | |
| Replace 10' Section, Pipe & Fittings, 3/4" Copper, Cold Water 9 33 | Replace Valve, Hose Bib | | | | 53 | | | | | | | | | | 53 | | | | | | | | | | 53 | |
| | Resolder Joint, Pipe & Fittings, 3/4" Copper, Cold Water | | | | | | | | | 17 | | | | 62 | | | | | | 17 | | | | 62 | | |
| Replace Pine & Fittings 3/4" Conner Cold Water (20% of Pin 663 190 | Replace 10' Section, Pipe & Fittings, 3/4" Copper, Cold Water | | | | | | | | | | | | | | | | | | | 9 | | | | 33 | | |
| Noplace Lipe at Italings, or Copper, Cold Water (2070 of Lipe 100 | Replace Pipe & Fittings, 3/4" Copper, Cold Water (20% of Pip | | | 663 | | | | | | | | | | | | | | | | | | | | | 190 | |

Whitestone Research

05-Mar-13

| Building: Office Buildin | g | | | | Fé | acilit | y: IVI | arsha | iii Sp | ace | Fiight | t Cen | ter | | | | | | | | | | | | | |
|---|--------------|-------|-------|-------|-------|--------|---------------|--------|---------|-----------|--------|-------|--------|-------|-------|-------|-------|-------|-------|--------|-------|-------|-------|-------|-------|-----|
| Building Num: 1045/62/212 | 2 | | | | | City | y: H | untsvi | ille, A | ۱L | | | | | | | | | | | | | | | | |
| Fo | recast Year: | 2013 | 4 | 5 | 6 | 7 | 2018 | 9 | 0 | 1 | 2 | 2023 | 4 | 5 | 6 | 7 | 2028 | 9 | 0 | 1 | 2 | 2033 | 4 | 5 | 6 | |
| Repair Strainer, Sink, Iron, Enamel | | | | | | | | 59 | | | | | | | | 59 | | | | | | | | 59 | | |
| Replace Pipe & Fittings, 4" Cast Iron (20% of Pipe |) | | | | | | 1,133 | | | | | | | | | | | | | | | | | | | |
| Replace 10' Section, Pipe & Fittings, 6" Cast Iron | | | | 36 | | | | | | | | | | | | | | | 36 | | | | | | | |
| nstall New Gasket & Bolts, Pipe & Fittings, 6" Cas | st Iron | | | | | | | | | | | | | | | | | | | | | | | | | |
| Replace Pipe & Fittings, 6" Cast Iron (20% of Pipe |) | | | | | | 734 | | | | | | | | | | | | | | | | | | | |
| Replace 10' Section, Pipe & Fittings, 2" DWV PVC | ; | | | | | | | | | 13 | | | | | | | | | | 13 | | | | | | |
| Replace Pipe & Fittings, 2" DWV PVC (20% of Pip | e) | | | | | | | | | | | | | | | | | | | | | | | | | |
| eplace 10' Section, Pipe & Fittings, 4" DWV PVC | ; | | | | | | | | | 16 | | | | | | | | | | 16 | | | | | | |
| Replace Pipe & Fittings, 4" DWV PVC (20% of Pip | e) | | | | | | | | | | | | | | | | | | | | | | | | | |
| Replace Pipe & Fittings, 3" Cast Iron (20% of Pipe |) | | | | | | 673 | | | | | | | | | | | | | | | | | | | |
| 30 HVAC | | | | | | | | | | | | | | | | | | | | | | | | | | |
| epair Exhaust Fan, Centrifugal, 800 Cfm | | | | | | | | | | | | | 575 | | | | | | | | | | | | | |
| Leplace Variable Air Volume Box, 1,300 Cfm | | | | | | | | | | | | | 19,281 | | | | | | | | | | | | | 19, |
| Lepair Variable Air Volume Box, 1,300 Cfm | | | | | | | | | 2,409 | | | | 10,201 | | | | | | | | | 2,409 | | | | , |
| laintain Variable Air Volume Box, 1,300 Cfm | | 1,422 | 1,422 | 1,422 | 1.422 | 1,422 | 1,422 | 1,422 | 1,422 | 1,422 | 1,422 | 1,422 | | 1,422 | 1,422 | 1,422 | 1,422 | 1,422 | 1,422 | 1,422 | 1,422 | 1,422 | 1,422 | 1,422 | 1 422 | |
| eplace Variable Air Volume Box, 800 Cfm | | 1,422 | 1,422 | 1,422 | 1,422 | 1,422 | 1,422 | 1,422 | 1,422 | 1,422 | 1,422 | 1,422 | 7,733 | 1,422 | 1,422 | 1,422 | 1,422 | 1,422 | 1,422 | 1,422 | 1,422 | 1,422 | 1,422 | 1,422 | 1,422 | 7, |
| epair Variable Air Volume Box, 800 Cfm | | | | | | | | | 1,021 | | | | 1,100 | | | | | | | | | 1,021 | | | | |
| laintain Variable Air Volume Box, 600 Cfm | | 683 | 683 | 683 | 683 | 683 | 683 | 683 | 683 | 683 | 683 | 683 | | 683 | 683 | 683 | 683 | 683 | 683 | 683 | 683 | 683 | 683 | 683 | 683 | |
| Replace Variable Air Volume Box, 400 Cfm | | 000 | 000 | 000 | 000 | 000 | 000 | 000 | 000 | 000 | 000 | 000 | 3,105 | 000 | 000 | 000 | 000 | 000 | 000 | 000 | 000 | 000 | 000 | 000 | 000 | 3, |
| Lepair Variable Air Volume Box, 400 Cfm | | | | | | | | | 508 | | | | 0,100 | | | | | | | | | 508 | | | | 0, |
| Iaintain Variable Air Volume Box, 400 Chm | | 737 | 737 | 737 | 737 | 737 | 737 | 737 | 737 | 737 | 737 | 737 | | 737 | 737 | 737 | 737 | 737 | 737 | 737 | 737 | 737 | 737 | 737 | 737 | |
| Replace Exhaust Fan, Centrifugal, 800 Cfm | | 101 | 101 | 101 | 101 | 101 | 101 | 101 | 101 | 101 | 101 | 101 | | 101 | 101 | 101 | 101 | 101 | 101 | 101 | 101 | 101 | 101 | 3,799 | 101 | |
| faintain Fan Coil Unit, 5 Ton | | 234 | 234 | 234 | 234 | 234 | 234 | 234 | 234 | 234 | 234 | 234 | 234 | 234 | 234 | 234 | 234 | 234 | 234 | 234 | 234 | 234 | 234 | 0,100 | 234 | |
| /aintain Pari Coli Onit, 5 Ton /aintain Variable Air Volume Box, 400 Cfm | | 334 | 334 | 334 | 334 | 334 | 334 | 334 | 334 | 334 | 334 | 334 | 2.54 | 334 | 334 | 334 | 334 | 334 | 334 | 334 | 334 | 334 | 334 | 334 | 334 | |
| | | 554 | 554 | 554 | 554 | 554 | 554 | 554 | 1,043 | 554 | 554 | 554 | | 554 | 554 | 554 | 554 | 554 | 554 | 554 | 554 | 1,043 | 554 | 554 | 554 | |
| Repair Variable Air Volume Box, 2,500 Cfm Replace Variable Air Volume Box, 2,500 Cfm | | | | | | | | | 1,043 | | | | 14,217 | | | | | | | | | 1,043 | | | | 14, |
| | | 234 | 234 | 234 | 234 | 234 | 234 | 234 | 234 | 234 | 234 | 234 | 234 | 234 | 234 | 234 | 234 | 234 | 234 | 234 | 234 | 234 | | 234 | 234 | 14, |
| laintain Fan Coil Unit, 2 Ton | | | | | | | | | | | | | | | | | | | | | | 234 | 070 | 234 | | |
| laintain Exhaust Fan, Centrifugal, 800 Cfm | | 278 | 278 | 278 | 278 | 278 | 278 | 278 | 278 | 278 | 278 | 278 | 278 | 278 | 278 | 278 | 278 | 278 | 278 | 278 | 278 | 278 | 278 | | 278 | |
| teplace Fan Coil Unit, 2 Ton | | | | | | | | | | ~ ~ ~ ~ ~ | | | | | | | | | | | | | 2,326 | | | |
| Replace Direct Digital Controls, System Points | | | | | | | | | | 69,093 | | | | | | | | | | 69,093 | | | | | | |
| Lepair Fan Coil Unit, 5 Ton | | | | | | | | 611 | | | | | | | | | | | | | | | 611 | | | |
| eplace Fan Coil Unit, 5 Ton | | | | | | | | | | | | | | | | | | | | | | | | 3,313 | | |
| laintain Unit Heater, 480v, 5kW | | 238 | 238 | 238 | 238 | 238 | 238 | 238 | 238 | 238 | 238 | 238 | 238 | 238 | 238 | 238 | 238 | 238 | 238 | 238 | 238 | 238 | | 238 | 238 | |
| epair Unit Heater, 480v, 5kW | | | | | | | | | | | | | | | 264 | | | | | | | | | | | |
| Replace Unit Heater, 480v, 5kW | | | | | | | | | | | | | | | | | | | | | | | 1,830 | | | |
| Ionitor Direct Digital Controls, System Points | | 2,189 | 2,189 | 2,189 | 2,189 | 2,189 | 2,189 | 2,189 | 2,189 | | 2,189 | 2,189 | 2,189 | 2,189 | 2,189 | 2,189 | 2,189 | 2,189 | 2,189 | | 2,189 | 2,189 | 2,189 | 2,189 | 2,189 | 2, |
| laintain Thermostat | | 489 | 489 | 489 | 489 | 489 | 489 | 489 | 489 | | 489 | 489 | 489 | 489 | 489 | 489 | 489 | 489 | 489 | | 489 | 489 | 489 | 489 | 489 | 4 |

Based on a 50-Year Forecast.

Whitestone Research

05-Mar-13

| Building: Office Building | | | | Fa | acilit | y: M | arsha | all Sp | ace l | Flight | t Cen | ter | | | | | | | | | | | | | |
|---|--------|-------|-------|--------|--------|-------------|-------|----------|-------|--------|-------|-------|--------|--------|-------|-------|-------|-------|-------|-------|-------|-------|-------|--------|-----|
| Building Num: 1045/62/212 | | | | | Cit | у: Н | untsv | ville, A | ۱L | | | | | | | | | | | | | | | | |
| Forecast Year | : 2038 | 9 | 0 | 1 | 2 | 2043 | 4 | 5 | 6 | 7 | 2048 | 9 | 0 | 1 | 2 | 2053 | 4 | 5 | 6 | 7 | 2058 | 9 | 0 | 1 | |
| Repair Strainer, Sink, Iron, Enamel | | | | | | 59 | | | | | | | | | | | 59 | | | | | | | | |
| Replace Pipe & Fittings, 4" Cast Iron (20% of Pipe) | | | | | | | | | | | | | | | | | | | | | | | | | |
| Replace 10' Section, Pipe & Fittings, 6" Cast Iron | | | | | 36 | | | | | | | | | | | | 36 | | | | | | | | |
| Install New Gasket & Bolts, Pipe & Fittings, 6" Cast Iron | | | | | | 9 | | | | | | | | | | | | | | | | | | | |
| Replace Pipe & Fittings, 6" Cast Iron (20% of Pipe) | | | | | | | | | | | | | | | | | | | | | | | | | |
| Replace 10' Section, Pipe & Fittings, 2" DWV PVC | | | | | | | | | | | | | | 13 | | | | | | | | | | 13 | |
| Replace Pipe & Fittings, 2" DWV PVC (20% of Pipe) | | | | 256 | | | | | | | | | | | | | | | | | | | | | |
| Replace 10' Section, Pipe & Fittings, 4" DWV PVC | | | | | | | | | | | | | | 16 | | | | | | | | | | 16 | |
| Replace Pipe & Fittings, 4" DWV PVC (20% of Pipe) | | | | 311 | | | | | | | | | | | | | | | | | | | | | |
| Replace Pipe & Fittings, 3" Cast Iron (20% of Pipe) | | | | | | | | | | | | | | | | | | | | | | | | | |
| 030 HVAC | | | | | | | | | | | | | | | | | | | | | | | | | |
| Repair Exhaust Fan, Centrifugal, 800 Cfm | | | | | | | | | | | 575 | | | | | | | | | | | | | | |
| Replace Variable Air Volume Box, 1,300 Cfm | | | | | | | | | | | | | 19,281 | | | | | | | | | | | | |
| Repair Variable Air Volume Box, 1,300 Cfm | | | | | | | | | 2,409 | | | | | | | | | | | | | 2,409 | | | |
| Maintain Variable Air Volume Box, 1,300 Cfm | 1,422 | 1,422 | 1,422 | 1,422 | 1,422 | 1,422 | 1,422 | 1,422 | 1,422 | 1,422 | 1,422 | 1,422 | | 1,422 | 1,422 | 1,422 | 1,422 | 1,422 | 1,422 | 1,422 | 1,422 | 1,422 | 1,422 | 1,422 | 1,4 |
| Replace Variable Air Volume Box, 800 Cfm | | | | | | | | | | | | | 7,733 | | | | | | | | | | | | |
| Repair Variable Air Volume Box, 800 Cfm | | | | | | | | | 1,021 | | | | | | | | | | | | | 1,021 | | | |
| Maintain Variable Air Volume Box, 800 Cfm | 683 | 683 | 683 | 683 | 683 | 683 | 683 | 683 | 683 | 683 | 683 | 683 | | 683 | 683 | 683 | 683 | 683 | 683 | 683 | 683 | 683 | 683 | 683 | 6 |
| Replace Variable Air Volume Box, 400 Cfm | | | | | | | | | | | | | 3,105 | | | | | | | | | | | | |
| Repair Variable Air Volume Box, 400 Cfm | | | | | | | | | 508 | | | | | | | | | | | | | 508 | | | |
| Maintain Variable Air Volume Box, 2,500 Cfm | 737 | 737 | 737 | 737 | 737 | 737 | 737 | 737 | 737 | 737 | 737 | 737 | | 737 | 737 | 737 | 737 | 737 | 737 | 737 | 737 | 737 | 737 | 737 | 7 |
| Replace Exhaust Fan, Centrifugal, 800 Cfm | | | | | | | | | | | | | | | | | | | | | | 3,799 | | | |
| Maintain Fan Coil Unit, 5 Ton | 234 | 234 | 234 | 234 | 234 | 234 | 234 | 234 | 234 | 234 | 234 | 234 | 234 | 234 | 234 | 234 | 234 | 234 | 234 | 234 | | 234 | 234 | 234 | 2 |
| Maintain Variable Air Volume Box, 400 Cfm | 334 | 334 | 334 | 334 | 334 | 334 | 334 | 334 | 334 | 334 | 334 | 334 | | 334 | 334 | 334 | 334 | 334 | 334 | 334 | 334 | 334 | 334 | 334 | 3 |
| Repair Variable Air Volume Box, 2,500 Cfm | | | | | | | | | 1,043 | | | | | | | | | | | | | 1,043 | | | |
| Replace Variable Air Volume Box, 2,500 Cfm | | | | | | | | | | | | | 14,217 | | | | | | | | | | | | |
| Maintain Fan Coil Unit, 2 Ton | 234 | 234 | 234 | 234 | 234 | 234 | 234 | 234 | 234 | 234 | 234 | 234 | 234 | 234 | 234 | 234 | 234 | 234 | 234 | | 234 | 234 | 234 | 234 | 2 |
| Maintain Exhaust Fan, Centrifugal, 800 Cfm | 278 | 278 | 278 | 278 | 278 | 278 | 278 | 278 | 278 | 278 | 278 | 278 | 278 | 278 | 278 | 278 | 278 | 278 | 278 | 278 | 278 | | 278 | 278 | 2 |
| Replace Fan Coil Unit, 2 Ton | | | | | | | | | | | | | | | | | | | | 2,326 | | | | | |
| Replace Direct Digital Controls, System Points | | | | 69,093 | | | | | | | | | | 69,093 | | | | | | | | | | 69,093 | |
| Repair Fan Coil Unit, 5 Ton | | | | | | | | | | | | | 611 | | | | | | | | | | | | |
| Replace Fan Coil Unit, 5 Ton | | | | | | | | | | | | | | | | | | | | | 3,313 | | | | |
| Maintain Unit Heater, 480v, 5kW | 238 | 238 | 238 | 238 | 238 | 238 | 238 | 238 | 238 | 238 | 238 | 238 | 238 | 238 | 238 | 238 | 238 | 238 | 238 | | 238 | 238 | 238 | 238 | 2 |
| Repair Unit Heater, 480v, 5kW | | | | | | | | | | | | 264 | | | | | | | | | | | | | |
| Replace Unit Heater, 480v, 5kW | | | | | | | | | | | | | | | | | | | | 1,830 | | | | | |
| Monitor Direct Digital Controls, System Points | 2,189 | 2,189 | 2,189 | | 2,189 | 2,189 | 2,189 | 2,189 | 2,189 | 2,189 | 2,189 | 2,189 | 2,189 | | 2,189 | 2,189 | 2,189 | 2,189 | 2,189 | 2,189 | 2,189 | 2,189 | 2,189 | | 2,1 |
| Maintain Thermostat | 489 | 489 | 489 | | 489 | 489 | 489 | 489 | 489 | 489 | 489 | 489 | 489 | | 489 | 489 | 489 | 489 | 489 | 489 | 489 | 489 | 489 | | 4 |

Tasks ordered by UNIFORMAT II Classifications. Unscheduled Maintenance Costs are not included. Based on a 50-Year Forecast. All costs expressed in (\$) 2012.

Page 6, Year 26-50

Whitestone Research

05-Mar-13

| Building: Office Building | | | | Fa | cility | y: M | arsha | all Sp | ace F | -light | Cen | ter | | | | | | | | | | | | | |
|--|------|-----|-------|-----|--------|--------------|-------|---------|-------|--------|-------|--------|-----|-----|-------|------|-------|-----|-------|-----|-------|-------|-------|-----|-------|
| Building Num: 1045/62/212 | | | | | City | y: Hu | untsv | ille, A | L | | | | | | | | | | | | | | | | |
| Forecast Year: | 2013 | 4 | 5 | 6 | 7 | 2018 | 9 | 0 | 1 | 2 | 2023 | 4 | 5 | 6 | 7 | 2028 | 9 | 0 | 1 | 2 | 2033 | 4 | 5 | 6 | |
| Repair Fan Coil Unit, 2 Ton | | | | | | | | | | | | | | 563 | | | | | | | | | | | |
| Replace Valve Actuator, 4" | | | | | | | | | | | | | | | | | | | | | | 3,295 | | | |
| Replace Fan & Motor, Exhaust Fan, Ceiling 200-500 Cfm | | | | | | | | | | | | | | | | | | | | | | | 2,152 | | |
| Replace Thermostat | | | | | | | | | 8,866 | | | | | | | | | | 8,866 | | | | | | |
| Install New Gasket & Bolts, Pipe & Fittings, 2" Steel | | | | | | | | | | | | | | | | | | | | | | | | 31 | |
| Replace 10' Section, Pipe & Fittings, 2" Steel | | | | | | | | | | | 57 | | | | | | | | | | | | 57 | | |
| Re-tape Pipe Insulation, Fiberglass, Heating Water/Steam | | | | 116 | | | | | 116 | | | | | 116 | | | | | 116 | | | | | | |
| Replace Pipe Insulation, Fiberglass, Heating Water/Steam (20 | | | | | | | | | | | | | | | | | | | | | | | | 493 | |
| Maintain Steam Trap, F&T, 2" | 237 | 237 | 237 | 237 | 237 | 237 | 237 | 237 | 237 | 237 | | 237 | 237 | 237 | 237 | 237 | 237 | 237 | 237 | 237 | 237 | 237 | | 237 | 23 |
| Repair Steam Trap, F&T, 2" | | | 3,098 | | | | 3,098 | | | | | | | | 3,098 | | | | 3,098 | | | | | | |
| Replace Steam Trap, F&T, 2" | | | | | | | | | | | 6,809 | | | | | | | | | | | | 6,809 | | |
| Lubricate, Repack Gland, Ball Valve, 4" | 279 | 279 | 279 | 279 | 279 | 279 | 279 | 279 | 279 | 279 | 279 | 279 | 279 | 279 | 279 | 279 | 279 | 279 | 279 | 279 | 279 | 279 | | 279 | 2 |
| Maintain Flow Control Valve & Actuator, 4" | 157 | 157 | 157 | 157 | 157 | 157 | 157 | 157 | 157 | 157 | 157 | 157 | 157 | 157 | 157 | 157 | 157 | 157 | 157 | 157 | 157 | 157 | 157 | 157 | |
| Replace Flow Control Valve, Motorized, 4" | | | | | | | | | | | | | | | | | | | | | | | | | 5,90 |
| Inspect & Lubricate Circulator Pump, 1/6 HP, Chilled Water | 46 | 46 | 46 | 46 | 46 | 46 | 46 | 46 | 46 | 46 | 46 | 46 | 46 | 46 | 46 | 46 | 46 | 46 | | 46 | 46 | 46 | 46 | 46 | 4 |
| Maintain Air Handler, Single Zone, 15,000 Cfm | 844 | 844 | 844 | 844 | 844 | 844 | 844 | 844 | 844 | 844 | 844 | | 844 | 844 | 844 | 844 | 844 | 844 | 844 | 844 | 844 | 844 | 844 | 844 | |
| Maintain Fan & Motor, Exhaust Fan, Ceiling 200-500 Cfm | 162 | 162 | 162 | 162 | 162 | 162 | 162 | 162 | 162 | 162 | 162 | 162 | 162 | 162 | 162 | 162 | 162 | 162 | 162 | 162 | 162 | 162 | | 162 | 16 |
| Replace Existing Ductwork (20% of Ductwork) | | | | | | | | | | | | | | | | | 3,210 | | | | | | | | |
| Replace Duct Insulation (20% of Insulation) | | | | | | | | | | | | | | | | | 825 | | | | | | | | |
| Replace Ball Valve, 4" | | | | | | | | | | | | | | | | | | | | | | | 3,841 | | |
| Repair Air Handler, Single Zone, 15,000 Cfm | | | | | | | | 2,033 | | | | | | | | | | | | | 2,033 | | | | |
| Overhaul Circulator Pump, 1/6 HP, Chilled Water | | | | 92 | | | | | 92 | | | | | 92 | | | | | | | | | | 92 | |
| Replace Pipe Insulation, Fiberglass, Chilled Water (20% of Ins | | | | | | | | | | | | | | | | | | | | | | | | 354 | |
| Re-tape Pipe Insulation, Fiberglass, Chilled Water | | | | 116 | | | | | 116 | | | | | 116 | | | | | 116 | | | | | | |
| Install New Gasket & Bolts, Pipe & Fittings, 4" Steel | | | | | | | | | | | | | | | | | | | | | | | | 25 | |
| Replace 10' Section, Pipe & Fittings, 4" Steel | | | | | | | | | | | 60 | | | | | | | | | | | | 60 | | |
| Install New Gasket & Bolts, Pipe & Fittings, 2" Steel | | | | | | | | | | | | | | | | | | | | | | | | 31 | |
| Replace 10' Section, Pipe & Fittings, 2" Steel | | | | | | | | | | | 57 | | | | | | | | | | | | 57 | | |
| Replace Circulator Pump, 1/6 HP, Chilled Water | | | | | | | | | | | | | | | | | | | 3,938 | | | | | | |
| Replace Air Handler, Single Zone, 20,000 Cfm | | | | | | | | | | | | 31,592 | | | | | | | | | | | | | 31,59 |
| D40 Fire Protection | | | | | | | | | | | | | | | | | | | | | | | | | |
| Maintain Fire Sprinkler System | 768 | 768 | 768 | 768 | 768 | 768 | 768 | 768 | 768 | 768 | 768 | 768 | 768 | 768 | 768 | 768 | 768 | 768 | 768 | 768 | 768 | 768 | 768 | 768 | 76 |
| Repair Fire Alarm Control Panel | | | | 114 | | | | | 114 | | | | | | | | | | 114 | | | | | 114 | |
| Install New Gasket & Bolts, Pipe & Fittings, 3" Steel | | 18 | | | | | | | | | | | | | | | | | | | | | | | |
| Replace 10' Section, Pipe & Fittings, 3" Steel | 43 | | | | | | | | | | | | 43 | | | | | | | | | | | | 4 |
| Install New Gasket & Bolts, Pipe & Fittings, 2" Steel | | 53 | | | | | | | | | | | | | | | | | | | | | | | |
| | 93 | | | | | | | | | | | | 93 | | | | | | | | | | | | g |

Tasks ordered by UNIFORMAT II Classifications. Unscheduled Maintenance Costs are not included. Based on a 50-Year Forecast. All costs expressed in (\$) 2012.

Page 7, Year 1-25

Whitestone Research

05-Mar-13

| Building Num: 1045/62/212 Forecast Year: Repair Fan Coil Unit, 2 Ton Replace Valve Actuator, 4" Replace Fan & Motor, Exhaust Fan, Ceiling 200-500 Cfm Replace Thermostat Install New Gasket & Bolts, Pipe & Fittings, 2" Steel Replace 10' Section, Pipe & Fittings, 2" Steel | 2038 | 9 | 0 | 1 | | y: Hu 2043 | ıntsvi ₄ | lle, A ₅ | L 6 | 7 | 2048 | | | | | | | | | 7 | 2058 | 9 | • | | |
|--|------|-------|-----|-------|-----|---------------|-------------|-------------|-------|-------|------|-----|--------|-------|-----|------|-----|-------|-----|-----|------|-------|-------|-------|---|
| Repair Fan Coil Unit, 2 Ton Replace Valve Actuator, 4" Replace Fan & Motor, Exhaust Fan, Ceiling 200-500 Cfm Replace Thermostat Install New Gasket & Bolts, Pipe & Fittings, 2" Steel | 2038 | 9 | 0 | | 2 | 2043 | 4 | 5 | 6 | 7 | 2048 | • | • | | | | | | • | 7 | 2059 | • | • | | |
| Replace Valve Actuator, 4" Replace Fan & Motor, Exhaust Fan, Ceiling 200-500 Cfm Replace Thermostat Install New Gasket & Bolts, Pipe & Fittings, 2" Steel | | | | 0.055 | | | | | | | 2040 | 9 | 0 | 1 | 2 | 2053 | 4 | 5 | 6 | ' | 2008 | э | 0 | 1 | |
| Replace Fan & Motor, Exhaust Fan, Ceiling 200-500 Cfm Replace Thermostat Install New Gasket & Bolts, Pipe & Fittings, 2" Steel | | | | 0.005 | | | | | | | | 563 | | | | | | | | | | | | | |
| Replace Thermostat Install New Gasket & Bolts, Pipe & Fittings, 2" Steel | | | | 0.055 | | | | | | | | | | | | | | | | | | | 3,295 | | |
| Install New Gasket & Bolts, Pipe & Fittings, 2" Steel | | | | 0.000 | | | | | | | | | | | | | | | | | | 2,152 | | | |
| | | | | 8,866 | | | | | | | | | | 8,866 | | | | | | | | | | 8,866 | |
| Replace 10' Section Pine & Fittings 2" Steel | | | | | | | | | | | | | | | | | | | | | | | | 31 | |
| | | | | | | | | | | 57 | | | | | | | | | | | | 57 | | | |
| Re-tape Pipe Insulation, Fiberglass, Heating Water/Steam | | | | 116 | | | | | 116 | | | | | 116 | | | | | 116 | | | | | | |
| Replace Pipe Insulation, Fiberglass, Heating Water/Steam (20 | | | | | | | | | | | | | | | | | | | | | | | | 493 | |
| Maintain Steam Trap, F&T, 2" | 237 | 237 | 237 | 237 | 237 | 237 | 237 | 237 | 237 | | 237 | 237 | 237 | 237 | 237 | 237 | 237 | 237 | 237 | 237 | 237 | | 237 | 237 | : |
| Repair Steam Trap, F&T, 2" | | 3,098 | | | | 3,098 | | | | | | | | 3,098 | | | | 3,098 | | | | | | | |
| Replace Steam Trap, F&T, 2" | | | | | | | | | | 6,809 | | | | | | | | | | | | 6,809 | | | |
| Lubricate, Repack Gland, Ball Valve, 4" | 279 | 279 | 279 | 279 | 279 | 279 | 279 | 279 | 279 | 279 | 279 | 279 | 279 | 279 | 279 | 279 | 279 | 279 | 279 | 279 | 279 | | 279 | 279 | |
| Maintain Flow Control Valve & Actuator, 4" | 157 | 157 | 157 | 157 | 157 | 157 | 157 | 157 | 157 | 157 | 157 | 157 | 157 | 157 | 157 | 157 | 157 | 157 | 157 | 157 | 157 | 157 | 157 | 157 | |
| Replace Flow Control Valve, Motorized, 4" | | | | | | | | | | | | | | | | | | | | | | | | | |
| Inspect & Lubricate Circulator Pump, 1/6 HP, Chilled Water | 46 | 46 | 46 | 46 | 46 | 46 | 46 | 46 | 46 | 46 | 46 | 46 | 46 | | 46 | 46 | 46 | 46 | 46 | 46 | 46 | 46 | 46 | 46 | |
| Maintain Air Handler, Single Zone, 15,000 Cfm | 844 | 844 | 844 | 844 | 844 | 844 | 844 | 844 | 844 | 844 | 844 | 844 | | 844 | 844 | 844 | 844 | 844 | 844 | 844 | 844 | 844 | 844 | 844 | |
| Maintain Fan & Motor, Exhaust Fan, Ceiling 200-500 Cfm | 162 | 162 | 162 | 162 | 162 | 162 | 162 | 162 | 162 | 162 | 162 | 162 | 162 | 162 | 162 | 162 | 162 | 162 | 162 | 162 | 162 | | 162 | 162 | |
| Replace Existing Ductwork (20% of Ductwork) | | | | | | | | | | | | | | 4,013 | | | | | | | | | | | |
| Replace Duct Insulation (20% of Insulation) | | | | | | | | | | | | | | 1,650 | | | | | | | | | | | |
| Replace Ball Valve, 4" | | | | | | | | | | | | | | | | | | | | | | 3,841 | | | |
| Repair Air Handler, Single Zone, 15,000 Cfm | | | | | | | | | 2,033 | | | | | | | | | | | | | 2,033 | | | |
| Overhaul Circulator Pump, 1/6 HP, Chilled Water | | | | 92 | | | | | 92 | | | | | | | | | | 92 | | | | | 92 | |
| Replace Pipe Insulation, Fiberglass, Chilled Water (20% of In | | | | | | | | | | | | | | | | | | | | | | | | 354 | |
| Re-tape Pipe Insulation, Fiberglass, Chilled Water | | | | 116 | | | | | 116 | | | | | 116 | | | | | 116 | | | | | | |
| Install New Gasket & Bolts, Pipe & Fittings, 4" Steel | | | | | | | | | | | | | | | | | | | | | | | | 25 | |
| Replace 10' Section, Pipe & Fittings, 4" Steel | | | | | | | | | | 60 | | | | | | | | | | | | 60 | | | |
| Install New Gasket & Bolts, Pipe & Fittings, 2" Steel | | | | | | | | | | | | | | | | | | | | | | | | 31 | |
| Replace 10' Section, Pipe & Fittings, 2" Steel | | | | | | | | | | 57 | | | | | | | | | | | | 57 | | | |
| Replace Circulator Pump, 1/6 HP, Chilled Water | | | | | | | | | | | | | | 3,938 | | | | | | | | | | | |
| Replace Air Handler, Single Zone, 20,000 Cfm | | | | | | | | | | | | : | 31,592 | | | | | | | | | | | | |
| 40 Fire Protection | | | | | | | | | | | | | | | | | | | | | | | | | |
| Maintain Fire Sprinkler System | 768 | 768 | 768 | 768 | 768 | 768 | 768 | 768 | 768 | 768 | 768 | 768 | 768 | 768 | 768 | 768 | 768 | 768 | 768 | 768 | 768 | 768 | 768 | 768 | |
| Repair Fire Alarm Control Panel | | | | | | | | | 114 | | | | | 114 | | | | | | | | | | 114 | |
| Install New Gasket & Bolts, Pipe & Fittings, 3" Steel | | 18 | | | | | | | | | | | | | | | | | | | | | | | |
| Replace 10' Section, Pipe & Fittings, 3" Steel | | | | | | | | | | | | 43 | | | | | | | | | | | | 43 | |
| Install New Gasket & Bolts, Pipe & Fittings, 2" Steel | | 53 | | | | | | | | | | 10 | | | | | | | | | | | | FO | |
| Replace 10' Section, Pipe & Fittings, 2' Steel | | 00 | | | | | | | | | | 93 | | | | | | | | | | | | 93 | |

Tasks ordered by UNIFORMAT II Classifications. Unscheduled Maintenance Costs are not included. Based on a 50-Year Forecast. All costs expressed in (\$) 2012.

Page 7, Year 26-50

Whitestone Research

05-Mar-13

| Building: Office Building | | | | Fa | cility | y: Ma | arsha | ll Sp | ace F | Flight | Cent | ter | | | | | | | | | | | | | |
|--|------|-----|-----|-------|--------|--------------|-------|---------|--------|--------|------|-----|-----|--------|-----|------|-----|-----|--------|-----|------|-----|-----|-------|-----|
| Building Num: 1045/62/212 | | | | | City | y։ Hւ | Intsv | ille, A | ۱L | | | | | | | | | | | | | | | | |
| - Forecast Year: | 2013 | 4 | 5 | 6 | 7 | 2018 | 9 | 0 | 1 | 2 | 2023 | 4 | 5 | 6 | 7 | 2028 | 9 | 0 | 1 | 2 | 2033 | 4 | 5 | 6 | 7 |
| Test Gages & Valves, Fire Sprinkler System | 708 | 708 | 708 | 708 | 708 | 708 | 708 | 708 | 708 | 708 | 708 | 708 | 708 | 708 | 708 | 708 | 708 | 708 | 708 | 708 | 708 | 708 | 708 | 708 | 708 |
| Replace Fire Department Connection, Siamese, 3" | | | | | | | | | | | | | | | | | | | | | | | | | |
| Test Fire Sprinkler Head | | | | | | | | | 1,770 | | | | | | | | | | 1,770 | | | | | | |
| Inspect Fire Sprinkler Head | 35 | 35 | 35 | 35 | 35 | 35 | 35 | 35 | 35 | 35 | 35 | 35 | 35 | 35 | 35 | 35 | 35 | 35 | 35 | 35 | 35 | 35 | 35 | 35 | 35 |
| Replace Fire Alarm Control Panel | | | | | | | | | | | | | | 3,011 | | | | | | | | | | | |
| Inspect & Test Fire Alarm Control Panel | 122 | 122 | 122 | 122 | 122 | 122 | 122 | 122 | 122 | 122 | 122 | 122 | 122 | | 122 | 122 | 122 | 122 | 122 | 122 | 122 | 122 | 122 | 122 | 122 |
| Inspect & Maintain Fire Department Connection, Siamese, 3" | 115 | 115 | 115 | 115 | 115 | 115 | 115 | 115 | 115 | 115 | 115 | 115 | 115 | 115 | 115 | 115 | 115 | 115 | 115 | 115 | 115 | 115 | 115 | 115 | 115 |
| Replace Fire Sprinkler Head | | | | | | | | | | | | | | | | | | | | | | | | | |
| | | | | | | | | | | | | | | | | | | | | | | | | | |
| D50 Electrical | | | | | | | | | | | | | | | | | | | | | | | | | |
| Maintain Card Reader | 286 | 286 | 286 | 286 | 286 | 286 | 286 | 286 | | 286 | 286 | 286 | 286 | 286 | 286 | 286 | 286 | 286 | | 286 | 286 | 286 | 286 | 286 | 286 |
| Replace Card Reader | | | | | | | | | 4,346 | | | | | | | | | | 4,346 | | | | | | |
| Replace Electric Lock | | | | | | | | | 2,257 | | | | | | | | | | 2,257 | | | | | | |
| Replace Fire Alarm Horn & Strobe | | | | | | | | | | | | | | | | | | | 1,800 | | | | | | |
| Replace Camera, Interior, Closed Circuit, PTZ Color | | | | | | | | | 26,321 | | | | | | | | | | 26,321 | | | | | | |
| Replace Handicap Door Access Interface | | | | | | | | | 698 | | | | | | | | | | 698 | | | | | | |
| Replace Wiring Device, Switch | | | | | | | | | | | | | | 1,486 | | | | | | | | | | | |
| Maintain Headend Panel, Closed Circuit | 19 | 19 | 19 | 19 | 19 | 19 | 19 | 19 | | 19 | 19 | 19 | 19 | 19 | 19 | 19 | 19 | 19 | | 19 | 19 | 19 | 19 | 19 | 19 |
| Replace Headend Panel, Closed Circuit | | | | | | | | | 2,215 | | | | | | | | | | 2,215 | | | | | | |
| Check Operation, Heat Detector | 150 | 150 | 150 | 150 | 150 | 150 | 150 | 150 | 150 | 150 | 150 | 150 | 150 | | 150 | 150 | 150 | 150 | 150 | 150 | 150 | 150 | 150 | 150 | 150 |
| Maintain Handicap Door Access Interface | 86 | 86 | 86 | 86 | 86 | 86 | 86 | 86 | | 86 | 86 | 86 | 86 | 86 | 86 | 86 | 86 | 86 | | 86 | 86 | 86 | 86 | 86 | 86 |
| Maintain Camera, Interior, Closed Circuit, PTZ Color | 514 | 514 | 514 | 514 | 514 | 514 | 514 | 514 | | 514 | 514 | 514 | 514 | 514 | 514 | 514 | 514 | 514 | | 514 | 514 | 514 | 514 | 514 | 514 |
| Inspect & Maintain Lighting Control Panel | 30 | 30 | 30 | 30 | 30 | 30 | 30 | 30 | 30 | 30 | 30 | 30 | 30 | | 30 | 30 | 30 | 30 | 30 | 30 | 30 | 30 | 30 | 30 | 30 |
| Maintain Camera, Exterior, Closed Circuit, PTZ Color | 286 | 286 | 286 | 286 | 286 | 286 | 286 | 286 | | 286 | 286 | 286 | 286 | 286 | 286 | 286 | 286 | 286 | | 286 | 286 | 286 | 286 | 286 | 286 |
| Repair Wiring Device, Switch | | | | | | | | | 1,412 | | | | | | | | | | | | | | | 1,412 | |
| Replace Receptacle, 120 V, 20 Amp. | | | | | | | | | | | | | | | | | | | 13,992 | | | | | | |
| Replace Occupancy Sensors, Indoor Lighting | | | | | | | | | | | | | | 25,937 | | | | | | | | | | | |
| Replace Lighting Control Panel | | | | | | | | | | | | | | 1,028 | | | | | | | | | | | |
| Replace Control Unit, Occupancy Sensors, Indoor Lighting | | | | 2,966 | | | | | 2,966 | | | | | | | | | | 2,966 | | | | | 2,966 | |
| Inspect & Maintain Occupancy Sensor, Indoor Lighting | 879 | 879 | 879 | 879 | 879 | 879 | 879 | 879 | 879 | 879 | 879 | 879 | 879 | | 879 | 879 | 879 | 879 | 879 | 879 | 879 | 879 | 879 | 879 | 879 |
| Replace Lightning Protection General Wiring | | | | | | | | | | | | | | | | | | | | | | | | 1,761 | |
| Repair Heat Detector | | | | | | | | | 332 | | | | | | | | | | | | | | | 332 | |
| Replace Camera, Exterior, Closed Circuit, PTZ Color | | | | | | | | | 22,862 | | | | | | | | | | 22,862 | | | | | | |
| Replace Security System Panel | | | | | | | | | 433 | | | | | | | | | | 433 | | | | | | |
| Replace Power Panel Board, 208 Y/120 V, 100 Amp. | | | | | | | | | | | | | | | | | | | | | | | | | |
| Replace HP Sodium Lighting Fixture, 250 w | | | | | | | | | | 11,962 | | | | | | | | | | | | | | | |
| Annual PM, Grounding System | 42 | 42 | 42 | 42 | 42 | 42 | 42 | 42 | 42 | 42 | 42 | 42 | 42 | 42 | 42 | 42 | 42 | 42 | 42 | 42 | 42 | 42 | 42 | | 42 |
| Maintain & Repair, Grounding System | 41 | 41 | 41 | 41 | 41 | 41 | 41 | 41 | 41 | 41 | 41 | 41 | 41 | 41 | 41 | 41 | 41 | 41 | 41 | 41 | 41 | 41 | 41 | | 41 |

Tasks ordered by UNIFORMAT II Classifications. Unscheduled Maintenance Costs are not included. Based on a 50-Year Forecast. All costs expressed in (\$) 2012.

Whitestone Research

05-Mar-13

| Building: Office Building | | | | Fa | cility | /: Ma | arsha | II Spa | ace F | light | Cent | ter | | | | | | | | | | | | | |
|--|------|-----|-----|--------|--------|--------------|--------|--------|-------|-------|------|-----|-----|--------|-----|------|-----|-----|--------|-----|------|-----|-----|--------|------|
| Building Num: 1045/62/212 | | | | | City | /: Hu | intsvi | lle, A | L | | | | | | | | | | | | | | | | |
| Forecast Year: | 2038 | 9 | 0 | 1 | 2 | 2043 | 4 | 5 | 6 | 7 | 2048 | 9 | 0 | 1 | 2 | 2053 | 4 | 5 | 6 | 7 | 2058 | 9 | 0 | 1 | |
| Test Gages & Valves, Fire Sprinkler System | 708 | 708 | 708 | 708 | 708 | 708 | 708 | 708 | 708 | 708 | 708 | 708 | 708 | 708 | 708 | 708 | 708 | 708 | 708 | 708 | 708 | 708 | 708 | 708 | 70 |
| Replace Fire Department Connection, Siamese, 3" | | | | | | | | | | | | | | | | | | | | | | | | 1,131 | |
| Test Fire Sprinkler Head | | | | 1,770 | | | | | | | | | | 1,770 | | | | | | | | | | | |
| Inspect Fire Sprinkler Head | 35 | 35 | 35 | 35 | 35 | 35 | 35 | 35 | 35 | 35 | 35 | 35 | 35 | 35 | 35 | 35 | 35 | 35 | 35 | 35 | 35 | 35 | 35 | | 3 |
| Replace Fire Alarm Control Panel | | | | 3,011 | | | | | | | | | | | | | | | 3,011 | | | | | | |
| Inspect & Test Fire Alarm Control Panel | 122 | 122 | 122 | | 122 | 122 | 122 | 122 | 122 | 122 | 122 | 122 | 122 | 122 | 122 | 122 | 122 | 122 | | 122 | 122 | 122 | 122 | 122 | 12 |
| Inspect & Maintain Fire Department Connection, Siamese, 3" | 115 | 115 | 115 | 115 | 115 | 115 | 115 | 115 | 115 | 115 | 115 | 115 | 115 | 115 | 115 | 115 | 115 | 115 | 115 | 115 | 115 | 115 | 115 | | 1 |
| Replace Fire Sprinkler Head | | | | | | | | | | | | | | | | | | | | | | | | 3,861 | |
| D50 Electrical | | | | | | | | | | | | | | | | | | | | | | | | | |
| Maintain Card Reader | 286 | 286 | 286 | | 286 | 286 | 286 | 286 | 286 | 286 | 286 | 286 | 286 | | 286 | 286 | 286 | 286 | 286 | 286 | 286 | 286 | 286 | | 28 |
| Replace Card Reader | | | | 4,346 | | | | | | | | | | 4,346 | | | | | | | | | | 4,346 | |
| Replace Electric Lock | | | | 2,257 | | | | | | | | | | 2,257 | | | | | | | | | | 2,257 | |
| Replace Fire Alarm Horn & Strobe | | | | | | | | | | | | | | 1,800 | | | | | | | | | | | |
| Replace Camera, Interior, Closed Circuit, PTZ Color | | | : | 26,321 | | | | | | | | | | 26,321 | | | | | | | | | | 26,321 | |
| Replace Handicap Door Access Interface | | | | 698 | | | | | | | | | | 698 | | | | | | | | | | 698 | |
| Replace Wiring Device, Switch | | | | 1,486 | | | | | | | | | | | | | | | 1,486 | | | | | | |
| Maintain Headend Panel, Closed Circuit | 19 | 19 | 19 | | 19 | 19 | 19 | 19 | 19 | 19 | 19 | 19 | 19 | | 19 | 19 | 19 | 19 | 19 | 19 | 19 | 19 | 19 | | 1 |
| Replace Headend Panel, Closed Circuit | | | | 2,215 | | | | | | | | | | 2,215 | | | | | | | | | | 2,215 | |
| Check Operation, Heat Detector | 150 | 150 | 150 | | 150 | 150 | 150 | 150 | 150 | 150 | 150 | 150 | 150 | 150 | 150 | 150 | 150 | 150 | | 150 | 150 | 150 | 150 | 150 | 15 |
| Maintain Handicap Door Access Interface | 86 | 86 | 86 | | 86 | 86 | 86 | 86 | 86 | 86 | 86 | 86 | 86 | | 86 | 86 | 86 | 86 | 86 | 86 | 86 | 86 | 86 | | 8 |
| Maintain Camera, Interior, Closed Circuit, PTZ Color | 514 | 514 | 514 | | 514 | 514 | 514 | 514 | 514 | 514 | 514 | 514 | 514 | | 514 | 514 | 514 | 514 | 514 | 514 | 514 | 514 | 514 | | 51 |
| Inspect & Maintain Lighting Control Panel | 30 | 30 | 30 | | 30 | 30 | 30 | 30 | 30 | 30 | 30 | 30 | 30 | 30 | 30 | 30 | 30 | 30 | | 30 | 30 | 30 | 30 | 30 | 3 |
| Maintain Camera, Exterior, Closed Circuit, PTZ Color | 286 | 286 | 286 | | 286 | 286 | 286 | 286 | 286 | 286 | 286 | 286 | 286 | | 286 | 286 | 286 | 286 | 286 | 286 | 286 | 286 | 286 | | 28 |
| Repair Wiring Device, Switch | | | | | | | | | | | | | | 1,412 | | | | | | | | | | | |
| Replace Receptacle, 120 V, 20 Amp. | | | | | | | | | | | | | | 13,992 | | | | | | | | | | | |
| Replace Occupancy Sensors, Indoor Lighting | | | : | 25,937 | | | | | | | | | | | | | | | 25,937 | | | | | | |
| Replace Lighting Control Panel | | | | 1,028 | | | | | | | | | | | | | | | 1,028 | | | | | | |
| Replace Control Unit, Occupancy Sensors, Indoor Lighting | | | | | | | | | 2,966 | | | | | 2,966 | | | | | | | | | | 2,966 | |
| Inspect & Maintain Occupancy Sensor, Indoor Lighting | 879 | 879 | 879 | | 879 | 879 | 879 | 879 | 879 | 879 | 879 | 879 | 879 | 879 | 879 | 879 | 879 | 879 | | 879 | 879 | 879 | 879 | 879 | 87 |
| Replace Lightning Protection General Wiring | | | | | | | | | | | | | | | | | | | | | | | | 1,761 | |
| Repair Heat Detector | | | | | | | | | | | | | | 332 | | | | | | | | | | | |
| Replace Camera, Exterior, Closed Circuit, PTZ Color | | | : | 22,862 | | | | | | | | | | 22,862 | | | | | | | | | | 22,862 | |
| Replace Security System Panel | | | | 433 | | | | | | | | | | 433 | | | | | | | | | | 433 | |
| Replace Power Panel Board, 208 Y/120 V, 100 Amp. | | | | 3,899 | | | | | | | | | | | | | | | | | | | | | |
| Replace HP Sodium Lighting Fixture, 250 w | | | | | 11,962 | | | | | | | | | | | | | | | | | | | | 11,9 |
| Annual PM, Grounding System | 42 | 42 | 42 | 42 | 42 | 42 | 42 | 42 | 42 | 42 | 42 | 42 | 42 | 42 | 42 | 42 | 42 | 42 | 42 | 42 | 42 | 42 | 42 | | |
| Maintain & Repair, Grounding System | 41 | 41 | 41 | 41 | 41 | 41 | 41 | 41 | 41 | 41 | 41 | 41 | 41 | 41 | 41 | 41 | 41 | 41 | 41 | 41 | 41 | 41 | 41 | | |

All costs expressed in (\$) 2012.

Page 8, Year 26-50

Whitestone Research

05-Mar-13

| Building: Office Building | | | | Fa | cility | y: Ma | arsha | ll Sp | ace F | -light | Cent | ter | | | | | | | | | | | | | |
|---|------|-----|-----|-----|--------|--------------|--------|---------|-------|--------|------|-----|-----|-------|-----|------|-----|-----|-------|-------|------|-----|-----|-------|-----|
| Building Num: 1045/62/212 | | | | | City | /: Hu | intsvi | ille, A | L | | | | | | | | | | | | | | | | |
| - Forecast Year: | 2013 | 4 | 5 | 6 | - | 2018 | 9 | 0 | 1 | 2 | 2023 | 4 | 5 | 6 | 7 | 2028 | 9 | 0 | 1 | 2 | 2033 | 4 | 5 | 6 | 7 |
| Replace Meter, Electrical, 208 Volt, 600 Amp. | | | | | | | | | | | | | | | | | | | | | | | | | |
| Replace Smoke Detector, Duct | | | | | | | | | | | | | | 479 | | | | | | | | | | | |
| Replace Smoke Detector | | | | | | | | | | | | | | 3,963 | | | | | | | | | | | |
| Repair Smoke Detector, Duct | | | | | | | | | 39 | | | | | | | | | | | | | | | 39 | |
| Repair Smoke Detector | | | | | | | | | 1,069 | | | | | | | | | | | | | | | 1,069 | |
| Inspect and Test Meter, Electrical, 208 Volt, 600 Amp. | 19 | 19 | 19 | 19 | 19 | 19 | 19 | 19 | 19 | 19 | 19 | 19 | 19 | 19 | 19 | 19 | 19 | 19 | 19 | 19 | 19 | 19 | 19 | 19 | 19 |
| Replace Batteries & Check Operation, Smoke Detector | 485 | 485 | 485 | 485 | 485 | 485 | 485 | 485 | 485 | 485 | 485 | 485 | 485 | | 485 | 485 | 485 | 485 | 485 | 485 | 485 | 485 | 485 | 485 | 485 |
| Replace Heat Detector | | | | | | | | | | | | | | 1,005 | | | | | | | | | | | |
| Maintain Security System Panel | | | 58 | | | | 58 | | | | | | 58 | | | | 58 | | | | | | 58 | | |
| Replace Public Address Speaker | | | | | | | | | | | | | | 547 | | | | | | | | | | | |
| Maintain Public Address Speaker | 37 | 37 | 37 | 37 | 37 | 37 | 37 | 37 | 37 | 37 | 37 | 37 | 37 | | 37 | 37 | 37 | 37 | 37 | 37 | 37 | 37 | 37 | 37 | 3 |
| Replace Monitor, Medium, Closed Circuit | | | | | | | | | 8,906 | | | | | | | | | | 8,906 | | | | | | |
| Replace Manual Pull Station | | | | | | | | | | | | | | 567 | | | | | | | | | | | |
| Check & Repair Manual Pull Station | | | | | | | | | 245 | | | | | | | | | | | | | | | 245 | |
| Replace Access Keypad | | | | | | | | | 1,970 | | | | | | | | | | 1,970 | | | | | | |
| Maintain Keypad | 228 | 228 | 228 | 228 | 228 | 228 | 228 | 228 | | 228 | 228 | 228 | 228 | 228 | 228 | 228 | 228 | 228 | | 228 | 228 | 228 | 228 | 228 | 228 |
| Replace Intrusion Detection Motion Detector, Interior | | | | | | | | | 3,051 | | | | | | | | | | 3,051 | | | | | | |
| Maintain Intrusion Detection Motion Detector, Interior | 142 | 142 | 142 | 142 | 142 | 142 | 142 | 142 | | 142 | 142 | 142 | 142 | 142 | 142 | 142 | 142 | 142 | | 142 | 142 | 142 | 142 | 142 | 142 |
| Replace Batteries & Check Operation, Smoke Detector, Duct | 18 | 18 | 18 | 18 | 18 | 18 | 18 | 18 | 18 | 18 | 18 | 18 | 18 | | 18 | 18 | 18 | 18 | 18 | 18 | 18 | 18 | 18 | 18 | 18 |
| Replace Power Panel Board, 208 Y/120 V, 200 Amp. | | | | | | | | | | | | | | | | | | | | | | | | | |
| Replace Ballast & Lamp, HP Sodium Lighting Fixture, 250 w | | | | | | | | | | | | | | | | | | | | 4,223 | | | | | |
| Maintain Power Panel Board, 480 V, 200 Amp. | 58 | 58 | 58 | 58 | 58 | 58 | 58 | 58 | 58 | 58 | 58 | 58 | 58 | 58 | 58 | 58 | 58 | 58 | 58 | 58 | 58 | 58 | 58 | 58 | 58 |
| Repair Power Panel Board, 208 Y/120 V, 200 Amp. | | | | | | | | | 367 | | | | | | | | | | 367 | | | | | | |
| Repair Power Panel Board, 480 V, 100 Amp. | | | | | | | | | 92 | | | | | | | | | | 92 | | | | | | |
| Maintain Power Panel Board, 480 V, 100 Amp. | 58 | 58 | 58 | 58 | 58 | 58 | 58 | 58 | 58 | 58 | 58 | 58 | 58 | 58 | 58 | 58 | 58 | 58 | 58 | 58 | 58 | 58 | 58 | 58 | 58 |
| Replace Power Panel Board, 208 Y/120 V, 400 Amp. | | | | | | | | | | | | | | | | | | | | | | | | | |
| Repair Power Panel Board, 208 Y/120 V, 400 Amp. | | | | | | | | | 92 | | | | | | | | | | 92 | | | | | | |
| Maintain Power Panel Board, 208 Y/120 V, 400 Amp. | 58 | 58 | 58 | 58 | 58 | 58 | 58 | 58 | 58 | 58 | 58 | 58 | 58 | 58 | 58 | 58 | 58 | 58 | 58 | 58 | 58 | 58 | 58 | 58 | 58 |
| Replace Power Panel Board, 208 Y/120 V, 225 Amp. | | | | | | | | | | | | | | | | | | | | | | | | | |
| Replace Power Panel Board, 480 V, 200 Amp. | | | | | | | | | | | | | | | | | | | | | | | | | |
| Maintain Power Panel Board, 208 Y/120 V, 225 Amp. | 58 | 58 | 58 | 58 | 58 | 58 | 58 | 58 | 58 | 58 | 58 | 58 | 58 | 58 | 58 | 58 | 58 | 58 | 58 | 58 | 58 | 58 | 58 | 58 | 58 |
| Repair Power Panel Board, 480 V, 200 Amp. | | | | | | | | | 92 | | | | | | | | | | 92 | | | | | | |
| Maintain Power Panel Board, 208 Y/120 V, 200 Amp. | 228 | 228 | 228 | 228 | 228 | 228 | 228 | 228 | 228 | 228 | 228 | 228 | 228 | 228 | 228 | 228 | 228 | 228 | 228 | 228 | 228 | 228 | 228 | 228 | 228 |
| Repair Power Panel Board, 208 Y/120 V, 100 Amp. | | | | | | | | | 92 | | | | | | | | | | 92 | | | | | | |
| Maintain Power Panel Board, 208 Y/120 V, 100 Amp. | 58 | 58 | 58 | 58 | 58 | 58 | 58 | 58 | 58 | 58 | 58 | 58 | 58 | 58 | 58 | 58 | 58 | 58 | 58 | 58 | 58 | 58 | 58 | 58 | 58 |
| Replace Motor Starter, <5HP, <600V | | | | | | | | | | | | | | | | | 532 | | | | | | | | |
| Replace Coil, Motor Starter, <5HP, <600V | | 188 | | | 188 | | | 188 | | | 188 | | | 188 | | | | | | 188 | | | 188 | | |

Whitestone Research

05-Mar-13

| Building: Office Building | | | | Fa | cility | /: Ma | arsha | ll Spa | ace F | Flight | Cent | er | | | | | | | | | | | | | |
|---|------|-----|-----|--------|--------|--------------|-------|--------|-------|--------|------|-----|-----|-------|-------|------|-----|-----|-------|-----|------|-----|-----|-------|-----|
| Building Num: 1045/62/212 | | | | | City | /: Hu | ntsvi | lle, A | L | | | | | | | | | | | | | | | | |
| Forecast Year: | 2038 | 9 | 0 | 1 | 2 | 2043 | 4 | 5 | 6 | 7 | 2048 | 9 | 0 | 1 | 2 | 2053 | 4 | 5 | 6 | 7 | 2058 | 9 | 0 | 1 | 2 |
| Replace Meter, Electrical, 208 Volt, 600 Amp. | | | | 441 | | | | | | | | | | | | | | | | | | | | | |
| Replace Smoke Detector, Duct | | | | 479 | | | | | | | | | | | | | | | 479 | | | | | | |
| Replace Smoke Detector | | | | 3,963 | | | | | | | | | | | | | | | 3,963 | | | | | | |
| Repair Smoke Detector, Duct | | | | | | | | | | | | | | 39 | | | | | | | | | | | |
| Repair Smoke Detector | | | | | | | | | | | | | | 1,069 | | | | | | | | | | | |
| Inspect and Test Meter, Electrical, 208 Volt, 600 Amp. | 19 | 19 | 19 | | 19 | 19 | 19 | 19 | 19 | 19 | 19 | 19 | 19 | 19 | 19 | 19 | 19 | 19 | 19 | 19 | 19 | 19 | 19 | 19 | 19 |
| Replace Batteries & Check Operation, Smoke Detector | 485 | 485 | 485 | | 485 | 485 | 485 | 485 | 485 | 485 | 485 | 485 | 485 | 485 | 485 | 485 | 485 | 485 | | 485 | 485 | 485 | 485 | 485 | 485 |
| Replace Heat Detector | | | | 1,005 | | | | | | | | | | | | | | | 1,005 | | | | | | |
| Maintain Security System Panel | | 58 | | | | | | 58 | | | | 58 | | | | | | 58 | | | | 58 | | | |
| Replace Public Address Speaker | | | | 547 | | | | | | | | | | | | | | | 547 | | | | | | |
| Maintain Public Address Speaker | 37 | 37 | 37 | | 37 | 37 | 37 | 37 | 37 | 37 | 37 | 37 | 37 | 37 | 37 | 37 | 37 | 37 | | 37 | 37 | 37 | 37 | 37 | 37 |
| Replace Monitor, Medium, Closed Circuit | | | | 8,906 | | | | | | | | | | 8,906 | | | | | | | | | | 8,906 | |
| Replace Manual Pull Station | | | | 567 | | | | | | | | | | | | | | | 567 | | | | | | |
| Check & Repair Manual Pull Station | | | | | | | | | | | | | | 245 | | | | | | | | | | | |
| Replace Access Keypad | | | | 1,970 | | | | | | | | | | 1,970 | | | | | | | | | | 1,970 | |
| Maintain Keypad | 228 | 228 | 228 | | 228 | 228 | 228 | 228 | 228 | 228 | 228 | 228 | 228 | | 228 | 228 | 228 | 228 | 228 | 228 | 228 | 228 | 228 | | 228 |
| Replace Intrusion Detection Motion Detector, Interior | | | | 3,051 | | | | | | | | | | 3,051 | | | | | | | | | | 3,051 | |
| Maintain Intrusion Detection Motion Detector, Interior | 142 | 142 | 142 | | 142 | 142 | 142 | 142 | 142 | 142 | 142 | 142 | 142 | | 142 | 142 | 142 | 142 | 142 | 142 | 142 | 142 | 142 | | 142 |
| Replace Batteries & Check Operation, Smoke Detector, Duct | 18 | 18 | 18 | | 18 | 18 | 18 | 18 | 18 | 18 | 18 | 18 | 18 | 18 | 18 | 18 | 18 | 18 | | 18 | 18 | 18 | 18 | 18 | 18 |
| Replace Power Panel Board, 208 Y/120 V, 200 Amp. | | | | 22,445 | | | | | | | | | | | | | | | | | | | | | |
| Replace Ballast & Lamp, HP Sodium Lighting Fixture, 250 w | | | | | | | | | | | | | | | 4,223 | | | | | | | | | | |
| Maintain Power Panel Board, 480 V, 200 Amp. | 58 | 58 | 58 | | 58 | 58 | 58 | 58 | 58 | 58 | 58 | 58 | 58 | 58 | 58 | 58 | 58 | 58 | 58 | 58 | 58 | 58 | 58 | 58 | 58 |
| Repair Power Panel Board, 208 Y/120 V, 200 Amp. | | | | | | | | | | | | | | 367 | | | | | | | | | | 367 | |
| Repair Power Panel Board, 480 V, 100 Amp. | | | | | | | | | | | | | | 92 | | | | | | | | | | 92 | |
| Maintain Power Panel Board, 480 V, 100 Amp. | 58 | 58 | 58 | | 58 | 58 | 58 | 58 | 58 | 58 | 58 | 58 | 58 | 58 | 58 | 58 | 58 | 58 | 58 | 58 | 58 | 58 | 58 | 58 | 58 |
| Replace Power Panel Board, 208 Y/120 V, 400 Amp. | | | | 7,099 | | | | | | | | | | | | | | | | | | | | | |
| Repair Power Panel Board, 208 Y/120 V, 400 Amp. | | | | | | | | | | | | | | 92 | | | | | | | | | | 92 | |
| Maintain Power Panel Board, 208 Y/120 V, 400 Amp. | 58 | 58 | 58 | | 58 | 58 | 58 | 58 | 58 | 58 | 58 | 58 | 58 | 58 | 58 | 58 | 58 | 58 | 58 | 58 | 58 | 58 | 58 | 58 | 58 |
| Replace Power Panel Board, 208 Y/120 V, 225 Amp. | | | | 5,971 | | | | | | | | | | | | | | | | | | | | | |
| Replace Power Panel Board, 480 V, 200 Amp. | | | | 7,632 | | | | | | | | | | | | | | | | | | | | | |
| Maintain Power Panel Board, 208 Y/120 V, 225 Amp. | 58 | 58 | 58 | | 58 | 58 | 58 | 58 | 58 | 58 | 58 | 58 | 58 | 58 | 58 | 58 | 58 | 58 | 58 | 58 | 58 | 58 | 58 | 58 | 58 |
| Repair Power Panel Board, 480 V, 200 Amp. | | | | | | | | | | | | | | 92 | | | | | | | | | | 92 | |
| Maintain Power Panel Board, 208 Y/120 V, 200 Amp. | 228 | 228 | 228 | | 228 | 228 | 228 | 228 | 228 | 228 | 228 | 228 | 228 | 228 | 228 | 228 | 228 | 228 | 228 | 228 | 228 | 228 | 228 | 228 | 228 |
| Repair Power Panel Board, 208 Y/120 V, 100 Amp. | | | | | | | | | | | | | | 92 | | | | | | | | | | 92 | |
| Maintain Power Panel Board, 208 Y/120 V, 100 Amp. | 58 | 58 | 58 | | 58 | 58 | 58 | 58 | 58 | 58 | 58 | 58 | 58 | 58 | 58 | 58 | 58 | 58 | 58 | 58 | 58 | 58 | 58 | 58 | 58 |
| Replace Motor Starter, <5HP, <600V | | | | | | | | | | 532 | | | | | | | | | | | | | | | |
| Replace Coil, Motor Starter, <5HP, <600V | 188 | | | 188 | | | 188 | | | | | | 188 | | | 188 | | | 188 | | | 188 | | | 188 |

Whitestone Research

05-Mar-13

| Building: Office Building | | | | Fa | cility | /: Ma | arsha | ll Sp | ace F | Flight | Cent | er | | | | | | | | | | | | | |
|--|---------|-----|-----|-----|--------|-------|--------|--------|--------|--------|------|-----|-----|-------|-----|------|--------|-----|--------|-----|------|-----|-----|-----|-----|
| Building Num: 1045/62/212 | | | | | City | /: Hu | intsvi | lle, A | L | | | | | | | | | | | | | | | | |
| Forecast Yea | r: 2013 | 4 | 5 | 6 | 7 | 2018 | 9 | 0 | 1 | 2 | 2023 | 4 | 5 | 6 | 7 | 2028 | 9 | 0 | 1 | 2 | 2033 | 4 | 5 | 6 | 7 |
| Inspect & Clean Motor Starter, <5HP, <600V | 38 | 38 | 38 | 38 | 38 | 38 | 38 | 38 | 38 | 38 | 38 | 38 | 38 | 38 | 38 | 38 | | 38 | 38 | 38 | 38 | 38 | 38 | 38 | 38 |
| Replace Disconnect Switch, 30 Amp. | | | | | | | | | | | | | | | | | | | | | | | | | |
| Repair Disconnect Switch, 30 Amp. | | | | | | | | | 119 | | | | | | | | | | 119 | | | | | | |
| Maintain Disconnect Switch, 30 Amp. | 19 | 19 | 19 | 19 | 19 | 19 | 19 | 19 | 19 | 19 | 19 | 19 | 19 | 19 | 19 | 19 | 19 | 19 | 19 | 19 | 19 | 19 | 19 | 19 | 19 |
| Repair Power Panel Board, 208 Y/120 V, 225 Amp. | | | | | | | | | 92 | | | | | | | | | | 92 | | | | | | |
| Replace Ballast & Lamps, Compact Fluorescent Lighting Fix | ur | | | | | | | | 469 | | | | | | | | | | | | | | | | |
| Replace Grounded Fault Circuit Interruptor, 15 Amp. | | | | | | | | | | | | | | | | | | | 118 | | | | | | |
| Replace Fluorescent Lighting Fixture, T8, 4-32 w | | | | | | | | | | | | | | | | | | | 33,982 | | | | | | |
| Replace Fluorescent Lighting Fixture, T8, 2-32 w | | | | | | | | | | | | | | | | | | | 5,968 | | | | | | |
| Replace Ballast & Lamps, Fluorescent Lighting Fixture, T8, 4 | -3 | | | | | | | | 21,254 | | | | | | | | | | | | | | | | |
| Replace Ballast & Lamps, Fluorescent Lighting Fixture, T8, 2 | -3 | | | | | | | | 3,732 | | | | | | | | | | | | | | | | |
| Replace Emergency Lighting Pack, 2 Light w/ Battery | | | | | | | | | | | | | | | | | | | 2,011 | | | | | | |
| Replace Lens, Replace Emergency Lighting Pack, 2 Light w/ | Ва | | | | | | | | 63 | | | | | | | | | | | | | | | | |
| Replace Lamp, Replace Emergency Lighting Pack, 2 Light w | B 126 | | 126 | | 126 | | 126 | | 126 | | 126 | | 126 | | 126 | | 126 | | | | 126 | | 126 | | 126 |
| Replace Power Panel Board, 480 V, 100 Amp. | | | | | | | | | | | | | | | | | | | | | | | | | |
| Replace Compact Fluorescent Lighting Fixture, 32 w | | | | | | | | | | | | | | | | | | | 529 | | | | | | |
| Maintain Power Panel Board, 480 V, 400 Amp. | 58 | 58 | 58 | 58 | 58 | 58 | 58 | 58 | 58 | 58 | 58 | 58 | 58 | 58 | 58 | 58 | 58 | 58 | 58 | 58 | 58 | 58 | 58 | 58 | 58 |
| Replace Variable Frequency Drive, <600V | | | | | | | | | | | | | | | | | 41,054 | | | | | | | | |
| Replace Coil, Variable Frequency Drive, <600V | | | | 399 | | | | | 399 | | | | | 399 | | | | | | | | 399 | | | |
| Inspect & Clean Variable Frequency Drive, <600 V | 172 | 172 | 172 | 172 | 172 | 172 | 172 | 172 | 172 | 172 | 172 | 172 | 172 | 172 | 172 | 172 | | 172 | 172 | 172 | 172 | 172 | 172 | 172 | 172 |
| Replace Secondary Transformer, Dry, 45 kVA | | | | | | | | | | | | | | | | | | | | | | | | | |
| Repair Secondary Transformer, Dry, 45 kVA | | | | | | | | | 265 | | | | | | | | | | 265 | | | | | | |
| Maintain Secondary Transformer, Dry, 45 kVA | 58 | 58 | 58 | 58 | 58 | 58 | 58 | 58 | 58 | 58 | 58 | 58 | 58 | 58 | 58 | 58 | 58 | 58 | 58 | 58 | 58 | 58 | 58 | 58 | 58 |
| Replace Secondary Transformer, Dry, 30 kVA | | | | | | | | | | | | | | | | | | | | | | | | | |
| Repair Secondary Transformer, Dry, 30 kVA | | | | | | | | | 265 | | | | | | | | | | 265 | | | | | | |
| Maintain Secondary Transformer, Dry, 30 kVA | 58 | 58 | 58 | 58 | 58 | 58 | 58 | 58 | 58 | 58 | 58 | 58 | 58 | 58 | 58 | 58 | 58 | 58 | 58 | 58 | 58 | 58 | 58 | 58 | 58 |
| Replace Power Panel Board, 480 V, 400 Amp. | | | | | | | | | | | | | | | | | | | | | | | | | |
| Repair Power Panel Board, 480 V, 400 Amp. | | | | | | | | | 127 | | | | | | | | | | 127 | | | | | | |
| E10 Equipment | | | | | | | | | | | | | | | | | | | | | | | | | |
| Maintain Icemaker, Commercial | 826 | 826 | 826 | 826 | 826 | 826 | 826 | 826 | | 826 | 826 | 826 | 826 | 826 | 826 | 826 | 826 | 826 | | 826 | 826 | 826 | 826 | 826 | 826 |
| Replace Icemaker, Commercial | | | | | | | | | 16,699 | | | | | | | | | | 16,699 | | | | | | |
| Maintain Kitchen Exhaust Hood, Commercial | 68 | 68 | 68 | 68 | 68 | 68 | 68 | 68 | 68 | 68 | 68 | 68 | 68 | | 68 | 68 | 68 | 68 | 68 | 68 | 68 | 68 | 68 | 68 | 68 |
| Replace Kitchen Exhaust Hood, Commercial | | | | | | | | | | | | | | 7,628 | | | | | | | | | | | |

Whitestone Research

05-Mar-13

| Building: Office Building | | | | Fa | cility | /: Ma | arsha | ll Spa | ace F | Flight | Cent | er | | | | | | | | | | | | | |
|---|------|-----|-----|-------|--------|--------------|--------|--------|-------|--------|------|-----|-----|--------|-----|------|-----|-----|-----|-----|------|-----|-----|--------|-----|
| Building Num: 1045/62/212 | | | | | City | /: Hu | intsvi | lle, A | L | | | | | | | | | | | | | | | | |
| Forecast Year: | 2038 | 9 | 0 | 1 | 2 | 2043 | 4 | 5 | 6 | 7 | 2048 | 9 | 0 | 1 | 2 | 2053 | 4 | 5 | 6 | 7 | 2058 | 9 | 0 | 1 | 2 |
| Inspect & Clean Motor Starter, <5HP, <600V | 38 | 38 | 38 | 38 | 38 | 38 | 38 | 38 | 38 | | 38 | 38 | 38 | 38 | 38 | 38 | 38 | 38 | 38 | 38 | 38 | 38 | 38 | 38 | 38 |
| Replace Disconnect Switch, 30 Amp. | | | | | | | | | | | | | | | | | | | | | | | | 326 | |
| Repair Disconnect Switch, 30 Amp. | | | | 119 | | | | | | | | | | 119 | | | | | | | | | | | |
| Maintain Disconnect Switch, 30 Amp. | 19 | 19 | 19 | 19 | 19 | 19 | 19 | 19 | 19 | 19 | 19 | 19 | 19 | 19 | 19 | 19 | 19 | 19 | 19 | 19 | 19 | 19 | 19 | | 19 |
| Repair Power Panel Board, 208 Y/120 V, 225 Amp. | | | | | | | | | | | | | | 92 | | | | | | | | | | 92 | |
| Replace Ballast & Lamps, Compact Fluorescent Lighting Fixtu | | | | 469 | | | | | | | | | | | | | | | | | | | | 469 | |
| Replace Grounded Fault Circuit Interruptor, 15 Amp. | | | | | | | | | | | | | | 118 | | | | | | | | | | | |
| Replace Fluorescent Lighting Fixture, T8, 4-32 w | | | | | | | | | | | | | : | 33,982 | | | | | | | | | | | |
| Replace Fluorescent Lighting Fixture, T8, 2-32 w | | | | | | | | | | | | | | 5,968 | | | | | | | | | | | |
| Replace Ballast & Lamps, Fluorescent Lighting Fixture, T8, 4- | | | 2 | 1,254 | | | | | | | | | | | | | | | | | | | | 21,254 | |
| Replace Ballast & Lamps, Fluorescent Lighting Fixture, T8, 2- | | | | 3,732 | | | | | | | | | | | | | | | | | | | | 3,732 | |
| Replace Emergency Lighting Pack, 2 Light w/ Battery | | | | | | | | | | | | | | 2,011 | | | | | | | | | | | |
| Replace Lens, Replace Emergency Lighting Pack, 2 Light w/ | | | | 63 | | | | | | | | | | | | | | | | | | | | 63 | |
| Replace Lamp, Replace Emergency Lighting Pack, 2 Light w/ | | 126 | | 126 | | 126 | | 126 | | 126 | | 126 | | | | 126 | | 126 | | 126 | | 126 | | 126 | |
| Replace Power Panel Board, 480 V, 100 Amp. | | | | 5,500 | | | | | | | | | | | | | | | | | | | | | |
| Replace Compact Fluorescent Lighting Fixture, 32 w | | | | | | | | | | | | | | 529 | | | | | | | | | | | |
| Maintain Power Panel Board, 480 V, 400 Amp. | 58 | 58 | 58 | | 58 | 58 | 58 | 58 | 58 | 58 | 58 | 58 | 58 | 58 | 58 | 58 | 58 | 58 | 58 | 58 | 58 | 58 | 58 | 58 | 58 |
| Replace Variable Frequency Drive, <600V | | | | | | | | | | 41,054 | | | | | | | | | | | | | | | |
| Replace Coil, Variable Frequency Drive, <600V | | 399 | | | | | 399 | | | | | | | | 399 | | | | | 399 | | | | | 399 |
| Inspect & Clean Variable Frequency Drive, <600 V | 172 | 172 | 172 | 172 | 172 | 172 | 172 | 172 | 172 | | 172 | 172 | 172 | 172 | 172 | 172 | 172 | 172 | 172 | 172 | 172 | 172 | 172 | 172 | 172 |
| Replace Secondary Transformer, Dry, 45 kVA | | | | 5,165 | | | | | | | | | | | | | | | | | | | | | |
| Repair Secondary Transformer, Dry, 45 kVA | | | | | | | | | | | | | | 265 | | | | | | | | | | 265 | |
| Maintain Secondary Transformer, Dry, 45 kVA | 58 | 58 | 58 | | 58 | 58 | 58 | 58 | 58 | 58 | 58 | 58 | 58 | 58 | 58 | 58 | 58 | 58 | 58 | 58 | 58 | 58 | 58 | 58 | 58 |
| Replace Secondary Transformer, Dry, 30 kVA | | | | 4,456 | | | | | | | | | | | | | | | | | | | | | |
| Repair Secondary Transformer, Dry, 30 kVA | | | | | | | | | | | | | | 265 | | | | | | | | | | 265 | |
| Maintain Secondary Transformer, Dry, 30 kVA | 58 | 58 | 58 | | 58 | 58 | 58 | 58 | 58 | 58 | 58 | 58 | 58 | 58 | 58 | 58 | 58 | 58 | 58 | 58 | 58 | 58 | 58 | 58 | 58 |
| Replace Power Panel Board, 480 V, 400 Amp. | | | | 8,911 | | | | | | | | | | | | | | | | | | | | | |
| Repair Power Panel Board, 480 V, 400 Amp. | | | | | | | | | | | | | | 127 | | | | | | | | | | 127 | |
| E10 Equipment | | | | | | | | | | | | | | | | | | | | | | | | | |
| Maintain Icemaker, Commercial | 826 | 826 | 826 | | 826 | 826 | 826 | 826 | 826 | 826 | 826 | 826 | 826 | | 826 | 826 | 826 | 826 | 826 | 826 | 826 | 826 | 826 | | 826 |
| Replace Icemaker, Commercial | | | 1 | 6,699 | | | | | | | | | | 16,699 | | | | | | | | | | 16,699 | |
| Maintain Kitchen Exhaust Hood, Commercial | 68 | 68 | 68 | | 68 | 68 | 68 | 68 | 68 | 68 | 68 | 68 | 68 | 68 | 68 | 68 | 68 | 68 | | 68 | 68 | 68 | 68 | 68 | 68 |
| | | | | | | | | | | | | | | | | | | | | | | | | | |

Operation Costs Summary

Whitestone Research

Building: Office Building

Building Number: 1045/62/212


Facility: Marshall Space Flight Center

City: Huntsville, AL

Built Date: 1943

GSFT: 11,050 Replacement Value: \$3,332,663 Building Use: Office Building Type: Engineering Office

| Operation | Annual Cost/GSFT | Annual Total | Percent |
|----------------|---------------------|-----------------|---------|
| Custodial | \$0.729 | \$8,051 | 5.3% |
| Energy | \$1.046 | \$11,558 | 7.6% |
| Grounds | \$0.125 | \$1,386 | 0.9% |
| M&R | \$7.455 | \$82,372 | 54.3% |
| Management | \$0.754 | \$8,332 | 5.5% |
| Pest Control | \$0.067 | \$739 | 0.5% |
| Refuse | \$0.033 | \$367 | 0.2% |
| Road Clearance | \$0.002 | \$25 | 0.0% |
| Security | \$1.243 | \$13,733 | 9.0% |
| Telecom | \$2.200 | \$24,311 | 16.0% |
| Water/Sewer | \$0.082 | \$910 | 0.6% |
| Building Total | \$13.74 | \$151,784 | 100.0% |



Building Operations Task Details

Whitestone Research

| Building: Office E | Building | Year Built: 1943 | Building Ty | be: Engineering | Office |
|------------------------|-------------|--|-------------|-----------------------|----------|
| Facility: Marsha | all Space I | Flight Center Original Cost: \$1 | Building Nu | m: 1045/62/212 | |
| City: Huntsv | ille, AL | Replacement Value: \$3,332,663 per SF: \$302 | Building G | sft: 11,050 | |
| Functional Area | FA GSFT | Task | Labor Cost | Material Cost | Task Cos |
| Operation: Custodial | | Level of Service: Low | | | |
| Office | 6630 | Vacuum Carpet with 14" Upright Vacuum | \$2,317 | \$376 | \$2,693 |
| Office | 6630 | Empty Trash; Wipe Clean & Re-line Basket | \$662 | \$108 | \$770 |
| Office | 6630 | Clean and Wipe Furniture with Trigger Sprayer & Cloth | \$406 | \$66 | \$472 |
| Office | 6630 | Dust Surfaces with Duster | \$306 | \$50 | \$355 |
| Office | 6630 | Vacuum Upholstered Furniture with Tank or Canister Vacuum | \$254 | \$41 | \$296 |
| Office | 6630 | Dust Window Blinds | \$147 | \$24 | \$170 |
| Storage | 1878 | Sweep Hard Floor with 48" Push Broom | \$34 | \$5 | \$39 |
| Storage | 1878 | Empty Trash; Wipe Clean & Re-line Basket | \$22 | \$4 | \$25 |
| Common/Circulation Are | 552 | Vacuum Carpet with 14" Upright Vacuum | \$386 | \$63 | \$448 |
| Conference Room | 552 | Vacuum Carpet with 14" Upright Vacuum | \$193 | \$31 | \$224 |
| Conference Room | 552 | Clean and Wipe Furniture with Trigger Sprayer & Cloth | \$73 | \$12 | \$85 |
| Common/Circulation Are | 552 | Empty Trash; Wipe Clean & Re-line Basket | \$55 | \$9 | \$64 |
| Common/Circulation Are | 552 | Vacuum Upholstered Furniture with Tank or Canister Vacuum | \$42 | \$7 | \$49 |
| Conference Room | 552 | Empty Trash; Wipe Clean & Re-line Basket | \$28 | \$4 | \$32 |
| Restroom | 442 | Service Restroom: Empty Trash, Clean & Disinfect Fixtures, Wipe Mirrors, Replace Supplies, Wet | \$927 | \$151 | \$1,077 |
| Restroom | 442 | Service Restroom: Empty Trash, Replace Supplies & Touch Up as Needed | \$142 | \$23 | \$165 |
| Mechanical/Equipment | 442 | Sweep Hard Floor with 48" Push Broom | \$8 | \$1 | \$9 |
| Mechanical/Equipment | 442 | Empty Trash; Wipe Clean & Re-line Basket | \$5 | \$1 | \$6 |
| Laboratory | 331 | Wet Mop & Rinse Hard Floor with 32 oz. Mop Using Single Bucket & Wringer | \$99 | \$16 | \$115 |
| Laboratory | 331 | Empty Trash; Wipe Clean & Re-line Basket | \$33 | \$5 | \$38 |
| Laboratory | 331 | Clean and Wipe Furniture with Trigger Sprayer & Cloth | \$20 | \$3 | \$24 |
| Laboratory | 331 | Dust Surfaces with Duster | \$15 | \$2 | \$18 |
| Laboratory | 331 | Dust Window Blinds | \$7 | \$1 | \$9 |
| Kitchen | 221 | Scrub and Damp Wipe Sinks | \$177 | \$29 | \$205 |
| Kitchen | 221 | Wet Mop & Rinse Hard Floor with 32 oz. Mop Using Double Bucket & Wringer | \$165 | \$27 | \$192 |
| Kitchen | 221 | Clean and Polish Metal Surfaces with Trigger Sprayer & Cloth | \$132 | \$22 | \$154 |
| Kitchen | 221 | Wash Fatigue Mats with Pressure Washer | \$88 | \$14 | \$103 |

| Functional Area | FA GSFT | Task | Labor Cost | Material Cost | Task Cost |
|----------------------|---------|--|------------|---------------|-----------|
| Kitchen | 221 | Clean Oven | \$42 | \$7 | \$49 |
| Kitchen | 221 | Empty, Clean and Disinfect Refrigerator | \$42 | \$7 | \$49 |
| Kitchen | 221 | Clean Stovetop | \$37 | \$6 | \$43 |
| Kitchen | 221 | Empty Trash; Wipe Clean & Re-line Basket | \$33 | \$5 | \$38 |
| Kitchen | 221 | Damp Wipe Interior and Exterior Cupboard | \$27 | \$4 | \$32 |
| Total: | | | \$6,926 | \$1,125 | \$8,051 |
| Operation: Grounds | | Level of Service: Low | | | |
| Grounds, Improved | 6630 | Mow Turfgrass with 21" Power Mower | \$245 | \$102 | \$347 |
| Grounds, Improved | 6630 | Aerate Improved Grounds | \$190 | \$79 | \$269 |
| Grounds, Improved | 6630 | Clear Shrubs | \$159 | \$66 | \$225 |
| Grounds, Improved | 6630 | Edge Clean & Trim Walks with Gas Powered Edger | \$102 | \$42 | \$144 |
| Grounds, Improved | 6630 | Overseed, Improved Grounds | \$95 | \$40 | \$134 |
| Grounds, Improved | 6630 | Vacuum with 30" Billy Goat | \$63 | \$26 | \$90 |
| Grounds, Improved | 6630 | Clear Crabgrass | \$47 | \$20 | \$67 |
| Grounds, Improved | 6630 | Clear Weeds with 15" Boom, Improved Grounds | \$25 | \$11 | \$36 |
| Grounds, Improved | 6630 | Trim Around Raised Objects with String Edger | \$21 | \$9 | \$29 |
| Grounds, Improved | 6630 | Fertilize Improved Grounds | \$19 | \$8 | \$27 |
| Grounds, Improved | 6630 | Sweep with 30" Power Rake | \$13 | \$5 | \$18 |
| Grounds, Improved | 6630 | Fertilize Using Power Take Off Broadcast | \$0 | \$0 | \$0 |
| Total: | | | \$979 | \$407 | \$1,386 |
| Operation: Pest Cont | rol | Level of Service: Medium | | | |
| Pest Controlled | 11050 | Install, or Check and Re-Bait 5 Rodent Boxes | \$255 | \$106 | \$362 |
| Pest Controlled | 11050 | Perform Crawling Insect Abatement | \$192 | \$80 | \$271 |
| Pest Controlled | 11050 | Inspect Building for Pests | \$107 | \$0 | \$107 |
| Total: | | | \$554 | \$186 | \$739 |
| Operation: Road Clea | irance | Level of Service: Medium | | | |
| Pavement NASA | 8840 | Plow Paved Area | \$19 | \$6 | \$25 |
| Total: | | | \$19 | \$6 | \$25 |
| Operation: Security | | Level of Service: Medium | | | |
| Secured Area | 11050 | Patrol Building Perimeter | \$2,100 | \$341 | \$2,442 |
| Secured Area | 11050 | Guard Lobby/Parking | \$0 | \$0 | \$0 |
| Total: | | | \$2,100 | \$341 | \$2,442 |

Building Operations Utility Details

Whitestone Research

| Building | : Office Building | Year Bui | lt: 1943 | | Building Typ | be: Engineering | Office |
|------------|-------------------|----------------------------|-----------------------|---------------|--------------|------------------------|----------|
| Facility | : Marshall Space | Flight Center Original Cos | st: \$1 | | Building Nu | m: 1045/62/212 | |
| City | : Huntsville, AL | Replacement Valu | e: \$3,332,663 | per SF: \$302 | Building G | sft: 11,050 | |
| | | Utility | GSFT | Demand | UM | Rate | Cost |
| Operation: | Energy | Level of Service: Medium | | | | | |
| | | Electricity | 11050 | 11.027 | kWh | \$0.0833 | \$10,150 |
| | | Natural Gas | 11050 | 0.161 | Thm | \$0.7900 | \$1,408 |
| | | Diesel | 11050 | 0.000 | Gal | \$3.2100 | \$0 |
| | | Total: | | 11.189 | | | \$11,558 |
| Operation: | Refuse | Level of Service: Medium | | | | | |
| | | Municipal Solid Waste | 11050 | 0.370 | Lbs | \$0.0717 | \$293 |
| | | Recycling | 11050 | 0.180 | Lbs | \$0.0370 | \$74 |
| | | Total: | | 0.550 | | | \$367 |
| Operation: | Water/Sewer | Level of Service: Medium | | | | | |
| | | Sewer | 11050 | 17.160 | Gal | \$0.0034 | \$645 |
| | | Water | 11050 | 21.840 | Gal | \$0.0011 | \$265 |
| | | Total: | | 39.000 | | | \$910 |

| Building | Operation | ns Manage | ment De | etails | | | Whiteston | e Researc |
|---------------|-----------------|-----------------|------------|--------------------------------|---------------|------------|-------------------------|-----------|
| Building: | Office Building | 9 | | Year Built: 1943 | | Building 1 | ype: Engineering | Office |
| Facility: | Marshall Spac | e Flight Center | | Original Cost: \$1 | | Building I | Num: 1045/62/212 | 2 |
| City: | Huntsville, AL | | | Replacement Value: \$3,332,663 | per SF: \$302 | Building | Gsft: 11,050 | |
| | | | Service | | Demand | UM | PRV | Cost |
| Operation: Ma | anagement | Level of Serv | /ice: Low | | | | | |
| | | | Management | | 0.3% | PRV | \$3,332,663 | \$8,332 |
| | | | Total: | | | | | \$8,332 |

| Building | : Office Building | | Year Built: | 1943 | FTEs: 27 | Building | Type: Engineerin | g Office |
|------------|-------------------|-------------------|---------------------|-------------|-----------------|----------|-----------------------|----------|
| Facility | : Marshall Space | Flight Center | Original Cost: | \$1 | | Building | Num: 1045/62/2 | 12 |
| City | : Huntsville, AL | | Replacement Value: | \$3,332,663 | per SF: \$302 | Building | g Gsft: 11,050 | |
| | | Service | 3* | | | Quantity | Rate | Cost |
| Operation: | Security | Level of Service: | Medium | | | | | |
| | | Intrusio | n Detection Systems | | | 1 | \$4,986 | \$4,986 |
| | | System | Monitoring | | | 1 | \$3,615 | \$3,615 |
| | | Access | Control | | | 1 | \$2,690 | \$2,690 |
| | | Total: | | | | | | \$11,291 |
| Operation: | Telecom | Level of Service: | High | | | | | |
| | | Local T | elephone | | | 27 | \$468 | \$12,636 |
| | | Data | | | | 27 | \$3,588 | \$6,491 |
| | | Long Di | istance Telephone | | | 27 | \$192 | \$5,184 |
| | | Total: | | | | | | \$24,311 |

Building Operations Service Details

Whitestone Research

Attachment B: Detailed MARS Reports for MSFC Property ID 1045/62/178

Building Component List

Whitestone Research

| Building: Office Building | Year Built: 1964 | | Building Type: Engineering Office |
|--|---------------------------------|----------------------|-----------------------------------|
| Facility: Marshall Space Flight Center | Original Cost: \$1 | | Building Num: 1045/62/178 |
| City: Huntsville, AL | Replacement Value: \$20,520,846 | per SF: \$185 | Building Gsft: 110,929 |

| Uniformat | Asset Description | Component | Date | Quantity | Location | Notes | |
|-----------|-------------------|--|------|-------------|----------|-------------|--|
| B1020 | | Steel Roof Access Ladder | 1964 | 15 Ln Ft | | | |
| B2010 | | Aluminum Louver, 3rd Floor | 1964 | 1 Each | | | |
| B2010 | | Concrete, Exterior, 1st Floor | 1964 | 600 Sq Ft | | | |
| B2010 | | Concrete, Exterior, 2nd Floor | 1964 | 600 Sq Ft | | | |
| B2010 | | Concrete, Painted, Exterior, 3rd+ Floor | 1964 | 3200 Sq Ft | | | |
| B2010 | | Steel, Painted, Exterior, 3rd+ Floor | 1964 | 1920 Sq Ft | | | |
| B2020 | | Glass Curtain Wall | 1964 | 45320 Sq Ft | | | |
| B2030 | | Aluminum Frame, Fully Glazed, Sliding Exterior Door | 1990 | 3 Each | | | |
| B2030 | | Steel, Painted, Exterior Door | 1964 | 1 Each | | | |
| B2030 | | Vault Door | 1964 | 1 Each | | | |
| B3010 | | Metal Canopy | 1964 | 2640 Sq Ft | | | |
| B3010 | | Single-Ply Roof w/ Thermoplastic Olefin (TPO) Membrane | 2008 | 15620 Sq Ft | | | |
| C1010 | | Toilet Partitions, Painted Metal, Overhead Braced | 2000 | 50 Each | | | |
| C1020 | | Aluminum Frame, Fully Glazed, Sliding Interior Door | 1990 | 2 Each | | | |
| C1020 | | Aluminum, Fully Glazed, Interior Door | 1964 | 2 Each | | | |
| C1020 | | Aluminum, Fully Glazed, Interior Door | 1990 | 1 Each | | | |
| C1020 | | Aluminum, Fully Glazed, Interior Door | 2005 | 1 Each | | | |
| C1020 | | Aluminum, Fully Glazed, Interior Door | 1964 | 2 Each | | Double door | |
| C1020 | | Steel, Painted, Interior Door | 1964 | 13 Each | | | |
| C1020 | | Steel, Painted, Interior Double Door | 1964 | 1 Each | | | |
| C1020 | | Wood, Hollow Core, Painted, Interior Door | 1964 | 80 Each | | | |
| C1020 | | Wood, Hollow Core, Painted, Interior Door | 1995 | 345 Each | | | |
| C1020 | | Wood, Hollow Core, Painted, Interior Door | 1964 | 6 Each | | Double Door | |
| C1020 | | Wood, Painted, Fully Glazed, Interior Door | 1990 | 5 Each | | | |
| C1020 | | Wood, Painted, Fully Glazed, Interior Door | 1964 | 4 Each | | | |
| C1020 | | Wood, Painted, Fully Glazed, Interior Door | 2000 | 6 Each | | | |
| C1020 | | Wood, Painted, Fully Glazed, Interior Door | 2005 | 3 Each | | | |
| C2010 | | Metal, Painted, Interior Railing | 1964 | 650 Ln Ft | | | |

| Uniformat | Asset Description | Component | Date | Quantity | Location | Notes |
|-----------|-------------------|--|------|--------------|----------|-------|
| C2010 | | Metal, Painted, Interior Stairs | 1964 | 2592 Sq Ft | | |
| C3010 | | Ceramic Tile, 4"x4", Interior Wall Finish | 1990 | 1782 Sq Ft | | |
| C3010 | | Ceramic Tile, 4"x4", Interior Wall Finish | 1990 | 2160 Sq Ft | | |
| C3010 | | Concrete, Painted, Interior Wall Finish | 1964 | 9990 Sq Ft | | |
| C3010 | | Fabric, Interior Wall Finish | 1995 | 1300 Sq Ft | | |
| C3010 | | Gypsum Board, Interior Wall Finish | 1964 | 103950 Sq Ft | | |
| C3010 | | Gypsum Board, Interior Wall Finish | 1995 | 93100 Sq Ft | | |
| C3010 | | Steel, Interior Wall Finish | 1964 | 504 Sq Ft | | |
| C3010 | | Wallpaper, Interior Wall Finish | 2000 | 3330 Sq Ft | | |
| C3010 | | Wallpaper, Interior Wall Finish | 1995 | 864 Sq Ft | | |
| C3010 | | Wallpaper, Interior Wall Finish | 2005 | 1080 Sq Ft | | |
| C3020 | | Carpet, Nylon 20 oz., Low Traffic | 2000 | 38408 Sq Ft | | |
| C3020 | | Carpet, Nylon 20 oz., Low Traffic | 1995 | 50585 Sq Ft | | |
| C3020 | | Carpet, Nylon 20 oz., Low Traffic | 2010 | 4060 Sq Ft | | |
| C3020 | | Carpet, Nylon 20 oz., Low Traffic | 2005 | 5135 Sq Ft | | |
| C3020 | | Ceramic Tile Flooring | 1964 | 3500 Sq Ft | | |
| C3020 | | Ceramic Tile Flooring | 2000 | 1000 Sq Ft | | |
| C3020 | | Concrete Flooring | 1964 | 6556 Sq Ft | | |
| C3020 | | Vinyl Tile Flooring | 1995 | 1685 Sq Ft | | |
| C3030 | | Acoustical Tile, Dropped Ceiling | 2000 | 40854 Sq Ft | | |
| C3030 | | Acoustical Tile, Dropped Ceiling | 1995 | 45750 Sq Ft | | |
| C3030 | | Acoustical Tile, Dropped Ceiling | 2010 | 760 Sq Ft | | |
| C3030 | | Acoustical Tile, Dropped Ceiling | 1964 | 10700 Sq Ft | | |
| C3030 | | Acoustical Tile, Dropped Ceiling | 2005 | 500 Sq Ft | | |
| C3030 | | Concrete Ceiling | 1964 | 72 Sq Ft | | |
| C3030 | | Gypsum Board, Finished Ceiling | 2000 | 3841 Sq Ft | | |
| C3030 | | Metal Ceiling | 1964 | 183 Sq Ft | | |
| D1010 | | Elevator, Geared, 3,500 lbs, 6-15 Floor, 350 fpm | 1964 | 3 Each | | |
| D1010 | | Elevator, Hydraulic, 2,500 lbs, 3-5 Floor, 200 fpm | 1964 | 1 Each | | |
| D2010 | | Drinking Fountain, Refrigerated | 2000 | 12 Each | | |
| D2010 | | Lavatory, Vitreous China | 2000 | 38 Each | | |
| D2010 | | Service Sink, Floor | 1964 | 5 Each | | |
| D2010 | | Tankless Water Closet | 2000 | 56 Each | | |
| D2010 | | Urinal, Vitreous China | 2000 | 19 Each | | |
| D2020 | | Ball Valve, 4" | 1990 | 4 Each | | |
| D2020 | PMP-005 | Booster Pump, 1 1/2 HP | 2000 | 1 Each | | |

| Uniformat As | Asset Description | Component | Date | Quantity | Location | Notes | |
|--------------|-------------------|--|------|---------------|----------|-------|--|
| D2020 | | Circulator Pump, 1/2 HP, Hot Water | 1990 | 1 Each | | | |
| D2020 | | Circulator Pump, 3 HP, Cold Water | 2010 | 2 Each | | | |
| D2020 | | Circulator Pump, 3 HP, Hot Water | 1990 | 1 Each | | | |
| D2020 | | Pipe & Fittings, 2" Copper, Cold Water | 1964 | 0.244 K Ln Ft | | | |
| D2020 | | Pipe & Fittings, 2" Copper, Hot Water | 1964 | 0.168 K Ln Ft | | | |
| D2020 | | Pipe & Fittings, 3/4" Copper, Cold Water | 1964 | 0.072 K Ln Ft | | | |
| D2020 | | Pipe & Fittings, 3/4" Copper, Hot Water | 1964 | 0.216 K Ln Ft | | | |
| D2020 | | Pipe & Fittings, 4" Copper, Cold Water | 1964 | 0.288 K Ln Ft | | | |
| D2020 | | Pipe Insulation, Fiberglass, Cold Water | 1964 | 0.604 K Ln Ft | | | |
| D2020 | | Pipe Insulation, Fiberglass, Hot Water | 1964 | 0.384 K Ln Ft | | | |
| D2020 | | Water Heater, Electric, 120 Gal. | 2010 | 1 Each | | | |
| D2020 | | Water Storage Tank, 500 Gal. | 1964 | 1 Each | | | |
| D2030 | | Backflow Preventer, 2" | 1964 | 2 Each | | | |
| D2030 | | Floor Drain | 1964 | 20 Each | | | |
| D2030 | | Pipe & Fittings, 4" Cast Iron | 1964 | 0.288 K Ln Ft | | | |
| D2030 | | Pipe & Fittings, 6" Cast Iron | 1964 | 0.12 K Ln Ft | | | |
| D2030 | | Pipe & Fittings, 8" PVC | 1964 | 0.192 K Ln Ft | | | |
| D2040 | | Pipe & Fittings, 4" PVC | 1964 | 0.12 K Ln Ft | | | |
| D2040 | | Pipe & Fittings, 6" PVC | 1964 | 0.168 K Ln Ft | | | |
| D2040 | | Roof Drain, 4-6" | 1964 | 6 Each | | | |
| D2040 | | Sump Pump, 3 HP | 1995 | 2 Each | | 2 HP | |
| D2040 | | Sump Pump, 3 HP | 2010 | 2 Each | | 2 HP | |
| D2090 A0 | AC-1, 2 | Air Compressor, 5 HP | 2010 | 2 Each | | | |
| D2090 | | Compressed Air Dryer | 2005 | 2 Each | | | |
| D3020 | | Expansion Tank, 10 Gal. | 2000 | 1 Each | | DHW | |
| D3020 | | Pipe & Fittings, 2" Steel | 1964 | 0.55 K Ln Ft | | | |
| D3020 | | Pipe & Fittings, 3" Steel | 1964 | 0.25 K Ln Ft | | | |
| D3020 | | Pipe & Fittings, 6" Steel | 1964 | 0.25 K Ln Ft | | | |
| D3020 | | Pipe Insulation, Fiberglass, Heating Water/Steam | 1964 | 1 K Ln Ft | | | |
| D3030 | | Ball Valve, 4" | 1990 | 4 Each | | | |
| D3030 Cł | CHWP-1, 2 | Circulation Pump, 10 HP, Chiller & Condenser Water | 2010 | 2 Each | | | |
| D3030 | | Pipe & Fittings, 2" Steel | 1964 | 0.75 K Ln Ft | | | |
| D3030 | | Pipe & Fittings, 4" Steel | 1964 | 0.25 K Ln Ft | | | |
| D3030 | | Pipe & Fittings, 6" Steel | 1964 | 0.1 K Ln Ft | | | |
| D3030 | | Pipe & Fittings, 8" Steel | 1964 | 0.05 K Ln Ft | | | |
| D3030 | | Pipe Insulation, Fiberglass, Chilled Water | 1964 | 1.15 K Ln Ft | | | |

| Uniformat | Asset Description | Component | Date | Quantity | Location | Notes |
|-----------|-------------------|---|------|--------------|----------|-------------------|
| D3040 | AHU-1, 2 | Air Handler, Multizone, 100,000 Cfm | 1964 | 2 Each | Basement | Includes SAF-1, 2 |
| D3040 | | Duct Insulation, Fiberglass Blanket | 1964 | 49950 Sq Ft | | |
| D3040 | | Ductwork | 1964 | 66600 Lbs | | |
| D3040 | EF-6 | Exhaust Fan, Centrifugal, 10,000 Cfm | 1964 | 1 Each | | |
| D3040 | EF-1 | Exhaust Fan, Centrifugal, 5,000 Cfm | 1964 | 1 Each | | |
| D3040 | EF-3, 4, 5, 8 | Exhaust Fan, Roof Mounted, 1,500 Cfm | 1964 | 4 Each | | |
| D3040 | EF-2 | Exhaust Fan, Roof Mounted, 8,500 Cfm | 1964 | 1 Each | | |
| D3040 | EF-7 | Exhaust Fan, Roof Mounted, 800 Cfm | 1964 | 1 Each | | |
| D3040 | RAF-1, 2 | Supply Fan, Centrifugal, 60,000 Cfm | 1964 | 2 Each | | |
| D3040 | | Variable Air Volume Control Box | 1964 | 177 Each | | |
| D3060 | | Direct Digital Controls, System Points | 1999 | 114 Each | | |
| D3060 | | HVAC Control Panel | 1964 | 1 Each | | |
| D3060 | | Thermostat | 1964 | 150 Each | | |
| D3060 | | Thermostat | 2005 | 95 Each | | |
| D4010 | | Fire Alarm Control Panel | 2000 | 1 Each | | |
| D4010 | | Fire Department Connection, Siamese, 3" | 1995 | 12 Each | | Interior |
| D4010 | | Fire Sprinkler Head | 1995 | 640 Each | | |
| D4010 | | Fire Sprinkler System | 1995 | 1 Each | | |
| D4010 | | Fire Suppression System Water Pump, 10 HP | 2000 | 1 Each | | 15 hp |
| D4010 | | Pipe & Fittings, 2" Steel | 1995 | 5.1 K Ln Ft | | |
| D4010 | | Pipe & Fittings, 3" Steel | 1995 | 1.2 K Ln Ft | | |
| D4010 | | Pipe & Fittings, 4" Steel | 1995 | 0.15 K Ln Ft | | |
| D4010 | | Valves & Components, Sprinkler System, 3" | 1995 | 4 Each | | |
| D5010 | | Bus Duct & Fittings, AL, 800-4,000 Amp. | 1964 | 84 Ln Ft | | |
| D5010 | | Disconnect Switch, 100 Amp. | 1990 | 4 Each | | |
| D5010 | | Disconnect Switch, 30 Amp. | 1964 | 3 Each | | |
| D5010 | | Disconnect Switch, 30 Amp. | 1990 | 3 Each | | |
| D5010 | | Disconnect Switch, 400 Amp. | 1964 | 1 Each | | |
| D5010 | | Disconnect Switch, 60 Amp. | 1964 | 3 Each | | |
| D5010 | | Motor Starter, <5HP, <600V | 1995 | 3 Each | | |
| D5010 | | Motor Starter, 5-20 HP, <600 V | 1995 | 2 Each | | |
| D5010 | | Power Panel Board, 208 Y/120 V, 100 Amp. | 1990 | 5 Each | | |
| D5010 | | Power Panel Board, 208 Y/120 V, 100 Amp. | 2000 | 2 Each | | |
| D5010 | | Power Panel Board, 208 Y/120 V, 100 Amp. | 1964 | 1 Each | | |
| D5010 | | Power Panel Board, 208 Y/120 V, 100 Amp. | 2000 | 1 Each | | 125A |
| D5010 | | Power Panel Board, 208 Y/120 V, 200 Amp. | 1990 | 1 Each | | 150A |

| Uniformat | Asset Description | Component | Date | Quantity | Location | Notes | |
|-----------|-------------------|--|------|-----------|----------|-------|--|
| D5010 | | Power Panel Board, 208 Y/120 V, 225 Amp | 1964 | 15 Each | | | |
| D5010 | | Power Panel Board, 480 V, 100 Amp. | 1964 | 1 Each | | | |
| D5010 | | Power Panel Board, 480 V, 200 Amp. | 1964 | 5 Each | | 225A | |
| D5010 | | Power Panel Board, 480 V, 400 Amp. | 1964 | 3 Each | | 300A | |
| D5010 | | Secondary Transformer, Dry, 2 kVA | 1964 | 1 Each | | | |
| D5010 | | Secondary Transformer, Dry, 30 kVA | 1964 | 1 Each | | | |
| D5010 | | Secondary Transformer, Dry, 75 kVA | 1964 | 3 Each | | | |
| D5010 | | Switchgear, Indoor, 600 V | 1964 | 1 Each | | | |
| D5010 | | Variable Frequency Drive, <600 V | 1995 | 5 Each | | | |
| D5020 | | Compact Fluorescent Lighting Fixture, 32 w | 2000 | 146 Each | | | |
| D5020 | | Emergency Lighting Pack, 2 Light w/ Battery | 1995 | 20 Each | | | |
| D5020 | | Exit Lighting Fixture, w/ Battery | 2000 | 3 Each | | | |
| D5020 | | Fluorescent Lighting Fixture, T8, 2-32w | 1964 | 12 Each | | | |
| D5020 | | Fluorescent Lighting Fixture, T8, 2-32w | 1990 | 348 Each | | | |
| D5020 | | Fluorescent Lighting Fixture, T8, 4-32 w | 1990 | 1410 Each | | | |
| D5020 | | Incandescent Lighting Fixture, Basic, 100 w | 1964 | 13 Each | | | |
| D5020 | | Incandescent Lighting Fixture, Basic, 100 w | 1995 | 30 Each | | | |
| D5020 | | Metal Halide Lighting Fixture, Wall Mount, 150 w | 1990 | 4 Each | | | |
| D5020 | | Receptacle, 120 V, 15 Amp. | 2005 | 200 Each | | | |
| D5020 | | Receptacle, 120 V, 15 Amp. | 1995 | 1200 Each | | | |
| D5020 | | Receptacle, 120 V, 15 Amp. | 1964 | 200 Each | | | |
| D5020 | | Receptacle, 120 V, 15 Amp. | 2005 | 350 Each | | | |
| D5020 | | Wiring Device, Switch | 1964 | 250 Each | | | |
| D5020 | | Wiring Device, Switch | 1995 | 350 Each | | | |
| D5030 | | Camera, Exterior, Closed Circuit, PTZ B/W | 2006 | 2 Each | | | |
| D5030 | | Camera, Interior, Closed Circuit, Fixed B/W | 2006 | 9 Each | | | |
| D5030 | | Camera, Interior, Closed Circuit, PTZ B/W | 2006 | 7 Each | | | |
| D5030 | | Card Reader | 2006 | 4 Each | | | |
| D5030 | | Electric Lock | 2006 | 4 Each | | | |
| D5030 | | Fire Alarm Horn & Strobe | 2000 | 46 Each | | | |
| D5030 | | Heat Detector | 2000 | 2 Each | | | |
| D5030 | | Manual Pull Station | 2000 | 26 Each | | | |
| D5030 | | Motion Detector | 2000 | 40 Each | | | |
| D5030 | | Public Address Speaker | 1964 | 10 Each | | | |
| D5030 | | Public Address Speaker | 1995 | 21 Each | | | |
| D5030 | | Smoke Detector | 2000 | 315 Each | | | |

| Uniformat | Asset Description | Component | Date | Quantity | Location | Notes |
|-----------|-------------------|-----------------------------|------|--------------|----------|-------|
| D5090 | | Grounding System | 1964 | 1 K Ln Ft | | |
| D5090 | | Lightning Protection System | 2006 | 1.18 K Ln Ft | | |
| E1010 | | Icemaker, Commercial | 2000 | 1 Each | | |

[§] Indicates Component set to have PM Tasks coincide with Replacement Task.

Average M&R Costs

| Building: | Office Building |
|------------------|------------------------------|
| Building Number: | 1045/62/178 |
| Facility: | Marshall Space Flight Center |
| City: | Huntsville, AL |


GSFT: 110,929 PRV: \$20,520,846 Built Date: 1964

M&R Average Annual Cost Forecasts **Current Year** 5 Year 20 Year 50 Year PM & Minor Repair: \$106,648 \$96,610 \$105,176 \$105,687 **Unscheduled Maintenance:** \$40,810 \$41,943 \$43,153 \$43,375 **Renewal & Replacement:** \$82,714 \$461,066 \$398,144 \$380,355 **Total M&R Costs:** \$230,172 \$599,619 \$546,473 \$529,417 Per GSFT: \$2.07 \$5.41 \$4.93 \$4.77 As % of PRV: 1.12% 2.92% 2.66% 2.58%

M&R Costs by System per Year Chart

Whitestone Research 05-Mar-13

| Building: Office | Forecast Year: 2013 4 5 6 7 2018 9 0 Foundations Image: Segment Construction Image: Segment Construction | | | | | | | | | | | | | Cente | er | | С | ity: | Hunts | sville, | AL | | | |
|-------------------------------|--|------|------|------|------|------|------|------|------|------|------------|------|------|-------|------|------|------|------|-------|---------|------|------|------|------|
| | | | | | | | | | | 1 | 10929 | | | | | | | | | | | | | |
| Forecast Year: | 2013 | 4 | 5 | 6 | 7 | 2018 | 9 | 0 | 1 | 2 | 2023 4 | 5 | 6 | 7 | 2028 | 9 | 0 | 1 | 2 | 2033 | 4 | 5 | 6 | 7 |
| A10 Foundations | | | | | | | | | | | | | | | | | | | | | | | | |
| A20 Basement Construction | | | | | | | | | | | | | | | | | | | | | | | | |
| B10 Super Structure | | | | | | | | | | | 0.00 | | | | | | | | | | | | | |
| B20 Exterior Enclosure | 0.00 | 0.58 | 0.00 | 0.00 | 0.00 | 0.00 | 0.38 | 0.01 | 0.00 | 0.00 | 0.0017.68 | 0.00 | 0.01 | 0.00 | 0.00 | 0.38 | 0.01 | 0.00 | 0.00 | 0.00 | 0.53 | 0.00 | 0.00 | 0.00 |
| B30 Roofing | 0.04 | 0.06 | 0.02 | 0.02 | 0.02 | 0.06 | 0.02 | 0.02 | 0.02 | 0.02 | 0.04 0.88 | 0.02 | 0.02 | 0.02 | 0.06 | 0.02 | 0.02 | 0.02 | 0.02 | 0.04 | 0.06 | 0.02 | 0.02 | 0.02 |
| C10 Interior Construction | 0.00 | 0.48 | 1.26 | 0.03 | 0.00 | 0.00 | 0.13 | 0.62 | 0.00 | 0.00 | 0.07 0.50 | 1.69 | 0.01 | | 0.03 | 0.13 | 0.24 | | 0.03 | 0.07 | 0.37 | 1.18 | 0.03 | 0.07 |
| C20 Stairs | | 0.16 | | 0.02 | | 0.00 | | 0.02 | | 0.00 | 0.07 | | 0.00 | | 0.02 | 0.01 | 0.00 | | 0.02 | | 0.00 | | 0.02 | |
| C30 Interior Finishes | 0.09 | 1.28 | 3.34 | 0.00 | | 0.02 | 0.00 | 0.55 | 0.00 | 0.02 | 0.00 0.93 | 4.35 | | 0.02 | 0.00 | 0.01 | 3.71 | 0.06 | 0.00 | 0.00 | 1.12 | 2.19 | 0.00 | 0.00 |
| D10 Conveying | 0.75 | 1.77 | 0.75 | 0.75 | 4.16 | 0.75 | 0.75 | 0.75 | 0.75 | 0.75 | 0.75 0.75 | 0.75 | 0.75 | 0.75 | 0.75 | 0.75 | 0.75 | 0.75 | 0.75 | 0.75 | 0.75 | 0.75 | 0.75 | 0.75 |
| D20 Plumbing | 0.03 | 0.26 | 0.09 | 0.06 | 0.04 | 0.07 | 0.04 | 0.35 | 0.07 | 0.07 | 0.03 0.20 | 0.13 | 0.07 | 0.03 | 0.10 | 0.04 | 0.51 | 0.03 | 0.06 | 0.03 | 0.16 | 0.86 | 0.04 | 0.05 |
| D30 HVAC | 0.28 | 0.77 | 0.56 | 5.16 | 0.28 | 0.28 | 0.89 | 0.28 | 0.28 | 0.28 | 0.28 1.42 | 0.72 | 0.28 | 0.28 | 0.28 | 5.77 | 0.28 | 0.28 | 0.28 | 0.36 | 0.72 | 0.56 | 1.18 | 0.28 |
| D40 Fire Protection | 0.05 | 0.05 | 0.45 | 0.05 | 0.05 | 0.05 | 0.06 | 0.05 | 0.05 | 0.05 | 0.05 0.05 | 0.27 | 0.05 | 0.05 | 0.05 | 0.05 | 0.11 | 0.06 | 0.05 | 0.05 | 0.05 | 0.39 | 0.05 | 0.05 |
| D50 Electrical | 0.82 | 0.37 | 1.30 | 0.51 | 0.18 | 0.17 | 0.19 | 2.45 | 0.18 | 0.17 | 0.19 2.09 | 0.68 | 0.51 | 0.18 | 0.18 | 0.18 | 3.62 | 0.91 | 0.17 | 0.18 | 0.79 | 0.93 | 0.51 | 0.19 |
| E10 Equipment | 0.01 | 0.01 | 0.01 | 0.01 | 0.01 | 0.01 | 0.01 | 0.15 | 0.01 | 0.01 | 0.01 0.01 | 0.01 | 0.01 | 0.01 | 0.01 | 0.01 | 0.15 | 0.01 | 0.01 | 0.01 | 0.01 | 0.01 | 0.01 | 0.01 |
| E20 Furnishings | | | | | | | | | | | | | | | | | | | | | | | | |
| F10 Special Construction | | | | | | | | | | | | | | | | | | | | | | | | |
| F20 Selective Bldg Demolition | | | | | | | | | | | | | | | | | | | | | | | | |
| G10 Site Preparation | | | | | | | | | | | | | | | | | | | | | | | | |
| G20 Site Improvements | | | | | | | | | | | | | | | | | | | | | | | | |
| G30 Site Mechanical Utilities | | | | | | | | | | | | | | | | | | | | | | | | |
| G40 Site Electrical Utilities | | | | | | | | | | | | | | | | | | | | | | | | |
| G90 Other Site Construction | | | | | | | | | | | | | | | | | | | | | | | | |
| Total | 2.07 | 5.78 | 7.80 | 6.63 | 4.74 | 1.44 | 2.47 | 5.25 | 1.37 | 1.40 | 1.43 24.61 | 8.63 | 1.72 | 1.36 | 1.49 | 7.35 | 9.42 | 2.14 | 1.40 | 1.51 | 4.57 | 6.90 | 2.63 | 1.44 |
| ¢20.0 | | | | | | | | | | | | | | | | | | | | | | | | |




Notes: A value of "0.00" means cost of more than \$.000 but less than \$.005 per gsft. All costs expressed in (\$) 2012 per gsft. Based on a 50-Year Forecast.

M&R Costs by System per Year Chart

Whitestone Research 05-Mar-13

| Building: Office I | Buildi | ng | | | | | | Fa | acility | /: M | arsha | all Sp | ace F | light | Cent | er | | С | ity: | Hunts | sville, | AL | | | | |
|-------------------------------|--------|-------|------|------|------|------|------|------|---------|--------------|-------|--------|-------|-------|------|------|-------|-------|------|-------|---------|-------|-------|-------|--------|--------|
| Building Num: 1045/6 | 2/178 | | | | | | | | GSF | Г: 11 | 10929 | 9 | | | | | | | | | | | | | | |
| Forecast Year: | 2038 | 9 | 0 | 1 | 2 | 2043 | 4 | 5 | 6 | 7 | 2048 | 9 | 0 | 1 | 2 | 2053 | 4 | 5 | 6 | 7 | 2058 | 9 | 0 | 1 | 2 | Tota |
| A10 Foundations | | | | | | | | | | | | | | | | | | | | | | | | | | 0.00 |
| A20 Basement Construction | | | | | | | | | | | | | | | | | | | | | | | | | | 0.00 |
| B10 Super Structure | | 0.00 | | | | | 0.01 | | | | | | | | | | | | | | | 0.00 | | | | 0.02 |
| B20 Exterior Enclosure | 0.01 | 1.12 | 0.05 | 0.00 | 0.00 | 0.00 | 0.48 | 0.00 | 0.00 | 0.00 | 0.00 | 0.43 | 0.01 | 0.00 | 0.01 | 0.00 | 17.63 | 0.00 | 0.00 | 0.00 | 0.00 | 0.43 | 0.01 | 0.00 | 0.00 | 39.84 |
| B30 Roofing | 0.06 | 0.02 | 0.02 | 0.02 | 0.02 | 1.85 | 0.10 | 0.02 | 0.02 | 0.02 | 0.04 | 0.02 | 0.02 | 0.02 | 0.02 | 0.06 | 0.88 | 0.02 | 0.02 | 0.02 | 0.04 | 0.02 | 0.02 | 0.02 | 0.02 | 5.11 |
| C10 Interior Construction | 0.01 | 0.17 | 0.72 | 0.07 | 0.00 | 0.00 | 0.36 | 1.26 | 0.00 | 0.00 | 0.03 | 0.17 | 0.32 | 0.00 | 0.03 | 0.07 | 0.45 | 1.75 | 0.01 | | 0.02 | 0.17 | 0.59 | | 0.02 | 13.20 |
| C20 Stairs | 0.00 | 0.72 | | | 0.00 | 0.02 | 0.01 | | 0.00 | 0.02 | | | 0.00 | 0.02 | | | 0.06 | 0.02 | | | 0.00 | 0.03 | | | 0.00 | 1.29 |
| C30 Interior Finishes | | 4.96 | 3.71 | 0.00 | | 0.01 | 0.03 | 3.31 | | 0.00 | 0.02 | 0.93 | 0.61 | 0.00 | 0.01 | 0.02 | 0.01 | 4.39 | 0.00 | 0.02 | 0.00 | 0.93 | 2.66 | 0.01 | 0.02 | 39.35 |
| D10 Conveying | 0.75 | 1.77 | 0.75 | 0.75 | 4.16 | 0.75 | 0.75 | 0.75 | 0.75 | 0.75 | 0.75 | 0.75 | 0.75 | 0.75 | 0.75 | 0.75 | 0.75 | 0.75 | 0.75 | 0.75 | 0.75 | 0.75 | 0.75 | 0.75 | 0.75 | 46.56 |
| D20 Plumbing | 0.04 | 0.23 | 0.29 | 0.08 | 0.08 | 0.06 | 0.17 | 0.14 | 0.04 | 0.07 | 0.04 | 0.09 | 0.48 | 0.07 | 0.04 | 0.05 | 0.11 | 0.24 | 0.08 | 0.05 | 0.08 | 0.07 | 0.36 | 0.05 | 0.04 | 6.49 |
| D30 HVAC | 0.47 | 1.04 | 0.28 | 0.28 | 5.13 | 0.28 | 2.72 | 0.56 | 0.28 | 0.28 | 0.28 | 0.92 | 0.29 | 0.45 | 0.28 | 0.28 | 0.75 | 5.40 | 0.36 | 0.28 | 0.28 | 0.89 | 1.17 | 0.28 | 0.31 | 45.61 |
| D40 Fire Protection | 0.05 | 0.05 | 0.05 | 0.05 | 0.05 | 0.06 | 0.05 | 0.59 | 0.05 | 0.05 | 0.05 | 0.05 | 0.05 | 0.05 | 0.05 | 0.05 | 0.05 | 0.40 | 0.05 | 0.05 | 0.05 | 0.05 | 0.11 | 0.05 | 0.05 | 4.33 |
| D50 Electrical | 0.17 | 0.30 | 2.55 | 0.19 | 0.17 | 0.19 | 0.35 | 0.77 | 0.52 | 0.18 | 0.17 | 0.89 | 3.46 | 0.18 | 0.17 | 0.18 | 1.97 | 1.12 | 0.60 | 0.18 | 0.17 | 0.19 | 2.70 | 0.19 | 0.17 | 35.41 |
| E10 Equipment | 0.01 | 0.01 | 0.15 | 0.01 | 0.01 | 0.01 | 0.01 | 0.01 | 0.01 | 0.01 | 0.01 | 0.01 | 0.15 | 0.01 | 0.01 | 0.01 | 0.01 | 0.01 | 0.01 | 0.01 | 0.01 | 0.01 | 0.15 | 0.01 | 0.01 | 1.42 |
| E20 Furnishings | | | | | | | | | | | | | | | | | | | | | | | | | | 0.00 |
| F10 Special Construction | | | | | | | | | | | | | | | | | | | | | | | | | | 0.00 |
| F20 Selective Bldg Demolition | | | | | | | | | | | | | | | | | | | | | | | | | | 0.00 |
| G10 Site Preparation | | | | | | | | | | | | | | | | | | | | | | | | | | 0.00 |
| G20 Site Improvements | | | | | | | | | | | | | | | | | | | | | | | | | | 0.00 |
| G30 Site Mechanical Utilities | | | | | | | | | | | | | | | | | | | | | | | | | | 0.00 |
| G40 Site Electrical Utilities | | | | | | | | | | | | | | | | | | | | | | | | | | 0.00 |
| G90 Other Site Construction | | | | | | | | | | | | | | | | | | | | | | | | | | 0.00 |
| Total | 1.58 | 10.39 | 8.59 | 1.47 | 9.62 | 3.25 | 5.04 | 7.43 | 1.69 | 1.39 | 1.40 | 4.28 | 6.15 | 1.56 | 1.38 | 1.49 | 22.68 | 14.10 | 1.8 | 9 1.: | 38 1.4 | 1 3.5 | 5 8.5 | 5 1.3 | 7 1.41 | 238.63 |



Notes: A value of "0.00" means cost of more than \$.000 but less than \$.005 per gsft. All costs expressed in (\$) 2012 per gsft. Based on a 50-Year Forecast.

| M&R Costs by Task | | | | | | | | | W | /hites | stone | Res | sear | ch | | | | | | 05 | 5-Mai | -13 |
|---|---------|-----|-----|-----------|---------|----------|--------------------|--------|--------|--------|-------|-----|------|--------|-----|-----|-----|------|--------|-----|-------|-----|
| Building: Office Building | | | Fa | cility: N | /larsha | II Spac | e Flig | ht Cen | ter | | | | | | | | | | | | | |
| Building Num: 1045/62/178 | | | | City: ⊦ | luntsv | ille. AL | | | | | | | | | | | | | | | | |
| Forecast Year: | 2013 4 | 5 | 6 | 7 2018 | | 0 | 1 : | 2 2023 | 4 | 5 | 6 | 7 | 2028 | 9 | 0 | 1 | 2 | 2033 | 4 | 5 | 6 | 7 |
| B10 Super Structure | | | | | | | | | | | | | | | | | | | | | | |
| Replace Steel Roof Access Ladder | | | | | | | | | | | | | | | | | | | | | | |
| Repair Steel Roof Access Ladder | | | | | | | | | 345 | | | | | | | | | | | | | |
| | | | | | | | | | 010 | | | | | | | | | | | | | |
| B20 Exterior Enclosure | | | | | | | | | | | | | | | | | | | | | | |
| Repair Steel, Painted, Exterior Door | | | | | | | | | 174 | | | | | | | | | | | | | |
| Maintain Aluminum Frame, Fully Glazed, Sliding Exterior Door | | 67 | | | | 67 | | | | 67 | | | | | 67 | | | | | 67 | | |
| Replace Aluminum Frame, Fully Glazed, Sliding Exterior Door L | | | | | | 985 | | | | | | | | | 985 | | | | | | | |
| Repair Aluminum Frame, Fully Glazed, Sliding Exterior Door | 705 | | | | | | | | | | 705 | | | | | | | | | | | |
| Replace Aluminum Frame, Fully Glazed, Sliding Exterior Door | | | | | | | | | | | | | | | | | | | | | | |
| Maintain Steel, Painted, Exterior Door Locks | 22 | | | | 22 | | | | 22 | | | | | 22 | | | | | 22 | | | |
| Replace Glass Curtain Wall | | | | | | | | ,9 | 43,522 | | | | | | | | | | | | | |
| Refinish Steel, Painted, Exterior Door | 23 | | | | | | | | 23 | | | | | | | | | | 23 | | | |
| Replace Steel, Painted, Exterior Door | | | | | | | | | | | | | | | | | | | | | | |
| Finish Replaced Steel, Painted, Exterior Door | | | | | | | | | | | | | | | | | | | | | | |
| Replace Digital Lock, Vault Door | 1,460 | | | | | | | | 1,460 | | | | | | | | | | 1,460 | | | |
| Repair Vault Door | 1,208 | | | | | | | | | | | | | | | | | | | | | |
| Replace Vault Door | | | | | | | | | | | | | | | | | | | | | | |
| Replace Steel, Painted, Exterior Door Locks | 328 | | | | | | | | 328 | | | | | | | | | | 328 | | | |
| Refinish Concrete, Painted, Exterior, 3rd+ Floor | 7,068 | | | | | | | | 7,068 | | | | | | | | | | 7,068 | | | |
| Maintain Vault Door Locks | 101 101 | 101 | 101 | 101 101 | 101 | 101 10 | D1 10 ⁻ | 1 101 | 101 | 101 | 101 | 101 | 101 | 101 | 101 | 101 | 101 | 101 | 101 | 101 | 101 | 101 |
| Replace Aluminum Louver, 3rd Floor | | | | | | | | | 544 | | | | | | | | | | | | | |
| Clean & Seal Concrete, Exterior, 1st Floor | 818 | | | | | | | | 818 | | | | | | | | | | 818 | | | |
| Repair Concrete, Exterior, 1st Floor (2% of Walls) | 194 | | | | | | | | | | | | | | | | | | | | | |
| Clean & Seal Concrete, Exterior, 2nd Floor | 1,151 | | | | | | | | 1,151 | | | | | | | | | | 1,151 | | | |
| Minor Repair, Glass Curtain Wall (2% of Walls) | 41,494 | | | | 41,494 | | | | | | | | | 41,494 | | | | | 41,494 | | | |
| Repair Concrete, Exterior, 2nd Floor (2% of Walls) | 210 | | | | | | | | | | | | | | | | | | | | | |
| Repair Concrete, Painted, Exterior, 3rd+ Floor (2% of Walls) | 1,210 | | | | | | | | | | | | | | | | | | | | | |
| Finish Repaired Concrete, Painted, Exterior, 3rd+ Floor | 141 | | | | | | | | | | | | | | | | | | | | | |
| Refinish Steel, Painted, Exterior, 3rd+ Floor | 4,055 | | | | | | | | 4,055 | | | | | | | | | | 4,055 | | | |
| Repair Steel, Painted, Exterior, 3rd+ Floor (2% of Walls) | 1,155 | | | | | | | | | | | | | | | | | | | | | |
| Finish Repaired Steel, Painted, Exterior, 3rd Floor | 81 | | | | | | | | | | | | | | | | | | | | | |
| Replace Steel, Painted, Exterior, 3rd+ Floor | | | | | | | | | | | | | | | | | | | | | | |
| Finish Replaced Steel, Painted, Exterior, 3rd+ Floor | | | | | | | | | | | | | | | | | | | | | | |
| Refinish Aluminum Louver, 3rd Floor | 103 | | | | | | | | | | | | | | | | | | 103 | | | |
| R20 Reading | | | | | | | | | | | | | | | | | | | | | | |
| B30 Roofing Replace Metal Canopy | | | | | | | | | 95,521 | | | | | | | | | | | | | |

| M&R Costs by Task | | | | | | | | | | | W | /hite | ston | e Re | esea | rch | | | | | | 0 | 5-Ma | r-13 |
|--|------|------|----|-----|--------|--------|------------|-------|-------|------|--------|-------|------|------|------|---------|-----|-----|-----|------|--------|-----|------|------|
| Building: Office Building | | | | Fac | ility: | Marsha | all Spa | ace F | light | Cent | er | | | | | | | | | | | | | |
| Building Num: 1045/62/178 | | | | | City: | Huntev | illo A | ı I | | | | | | | | | | | | | | | | |
| Forecast Year: | 2038 | 9 | 0 | 1 | 2 204 | | ше, л 5 | 6 | 7 | 2048 | 9 | 0 | 1 | • | 2053 | | 5 | 6 | 7 | 2058 | 9 | 0 | 1 | 2 |
| | 2030 | 9 | U | 1 | 2 204 | 5 4 | 5 | 0 | ' | 2040 | 9 | U | | 2 | 2055 | 4 | 5 | 0 | ' | 2000 | 9 | U | • | 4 |
| B10 Super Structure | | | | | | | | | | | | | | | | | | | | | | | | |
| Replace Steel Roof Access Ladder | | | | | | 1,143 | | | | | | | | | | | | | | | | | | |
| Repair Steel Roof Access Ladder | | 345 | | | | | | | | | | | | | | | | | | | 345 | | | |
| B20 Exterior Enclosure | | | | | | | | | | | | | | | | | | | | | | | | |
| Repair Steel, Painted, Exterior Door | | | | | | | | | | | | | | | | 174 | | | | | | | | |
| Maintain Aluminum Frame, Fully Glazed, Sliding Exterior Door | | | | | | | 67 | | | | | 67 | | | | | 67 | | | | | 67 | | |
| Replace Aluminum Frame, Fully Glazed, Sliding Exterior Door | | | | | | | | | | | | 985 | | | | | | | | | | 985 | | |
| Repair Aluminum Frame, Fully Glazed, Sliding Exterior Door | 705 | | | | | | | | | | | | | 705 | | | | | | | | | | |
| Replace Aluminum Frame, Fully Glazed, Sliding Exterior Door | | 5,3 | 86 | | | | | | | | | | | | | | | | | | | | | |
| Maintain Steel, Painted, Exterior Door Locks | | | | | | 22 | | | | | 22 | | | | | 22 | | | | | 22 | | | |
| Replace Glass Curtain Wall | | | | | | | | | | | | | | | | 943,522 | | | | | | | | |
| Refinish Steel, Painted, Exterior Door | | | | | | | | | | | 23 | | | | | | | | | | 23 | | | |
| Replace Steel, Painted, Exterior Door | | 859 | | | | | | | | | | | | | | | | | | | | | | |
| Finish Replaced Steel, Painted, Exterior Door | | 23 | | | | | | | | | | | | | | | | | | | | | | |
| Replace Digital Lock, Vault Door | | | | | | | | | | | 1,460 | | | | | | | | | | 1,460 | | | |
| Repair Vault Door | | | | | | | | | | | | | | | | | | | | | | | | |
| Replace Vault Door | 16 | ,166 | | | | | | | | | | | | | | | | | | | | | | |
| Replace Steel, Painted, Exterior Door Locks | | | | | | | | | | | 328 | | | | | | | | | | 328 | | | |
| Refinish Concrete, Painted, Exterior, 3rd+ Floor | | | | | | 7,068 | | | | | | | | | | 7,068 | | | | | | | | |
| Maintain Vault Door Locks | 101 | 1 | 01 | 101 | 101 10 | 1 101 | 101 | 101 | 101 | 101 | 101 | 101 | 101 | 101 | 101 | 101 | 101 | 101 | 101 | 101 | 101 | 101 | 101 | 101 |
| Replace Aluminum Louver, 3rd Floor | | | | | | | | | | | | | | | | | | | | | | | | |
| Clean & Seal Concrete, Exterior, 1st Floor | | | | | | 818 | | | | | | | | | | 818 | | | | | | | | |
| Repair Concrete, Exterior, 1st Floor (2% of Walls) | | 194 | | | | | | | | | | | | | | | | | | | | | | |
| Clean & Seal Concrete, Exterior, 2nd Floor | | | | | | 1,151 | | | | | | | | | | 1,151 | | | | | | | | |
| Minor Repair, Glass Curtain Wall (2% of Walls) | 41 | ,494 | | | | 41,494 | | | | 4 | 41,494 | | | | | | | | | | 41,494 | | | |
| Repair Concrete, Exterior, 2nd Floor (2% of Walls) | | 210 | | | | | | | | | | | | | | | | | | | | | | |
| Repair Concrete, Painted, Exterior, 3rd+ Floor (2% of Walls) | 1 | ,210 | | | | | | | | | | | | | | | | | | | | | | |
| Finish Repaired Concrete, Painted, Exterior, 3rd+ Floor | | 141 | | | | | | | | | | | | | | | | | | | | | | |
| Refinish Steel, Painted, Exterior, 3rd+ Floor | | | | | | | | | | | 4,055 | | | | | | | | | | 4,055 | | | |
| Repair Steel, Painted, Exterior, 3rd+ Floor (2% of Walls) | | | | | | | | | | | | | | | | | | | | | | | | |
| Finish Repaired Steel, Painted, Exterior, 3rd Floor | | | | | | | | | | | | | | | | | | | | | | | | |
| Replace Steel, Painted, Exterior, 3rd+ Floor | 57 | ,768 | | | | | | | | | | | | | | | | | | | | | | |
| Finish Replaced Steel, Painted, Exterior, 3rd+ Floor | 6 | ,126 | | | | | | | | | | | | | | | | | | | | | | |
| Refinish Aluminum Louver, 3rd Floor | | | | | | 103 | | | | | | | | | | 103 | | | | | | | | |
| B30 Poofing | | | | | | | | | | | | | | | | | | | | | | | | |
| B30 Roofing Replace Metal Canopy | | | | | | | | | | | | | | | | 95,521 | | | | | | | | |

Tasks ordered by UNIFORMAT II Classifications. Unscheduled Maintenance Costs are not included. Based on a 50-Year Forecast. All costs expressed in (\$) 2012.

Whitestone Research

05-Mar-13

| Building: Office Building | | | | Fa | acilit | t y : M | arsh | all Sp | ace | Fligh | t Cen | ter | | | | | | | | | | | | | |
|--|-------|--------|---------|-------|--------|----------------|-------|----------|-------|-------|-------|--------|---------|-------|-------|-------|-------|-------|-------|-------|-------|--------|---------|-------|------|
| Building Num: 1045/62/178 | | | | | Cit | t y: H | untsv | ville, J | ۹L | | | | | | | | | | | | | | | | |
| Forecast Year: | 2013 | 4 | 5 | 6 | | 2018 | 9 | | 1 | 2 | 2023 | 4 | 5 | 6 | 7 | 2028 | 9 | 0 | 1 | 2 | 2033 | 4 | 5 | 6 | |
| Replace Membrane, Single-Ply Roof w/ TPO Membrane | | | - | - | | | - | - | | _ | | - | - | - | | | - | - | | _ | | | - | - | |
| Minor Replacement, Single-Ply Roof w/ TPO (2% of Roof) | | | | | | 2,793 | | | | | | | | | | 2,793 | | | | | | | | | |
| Repair Metal Canopy | | | | | | | | | | | | | | | | | | | | | | | | | |
| Refinish Metal Canopy | | 4,160 | | | | | | | | | | | | | | | | | | | | 4,160 | | | |
| Maintain Single-Ply Roof w/ TPO Membrane | 1,733 | 1,733 | 1,733 | 1,733 | 1,733 | 1,733 | 1,733 | 1,733 | 1,733 | 1,733 | 1,733 | 1,733 | 1,733 | 1,733 | 1,733 | 1,733 | 1,733 | 1,733 | 1,733 | 1,733 | 1,733 | 1,733 | 1,733 | 1,733 | 1,73 |
| Non-Destructive Moisture Inspection | 1,689 | | | | | 1,689 | | | | | 1,689 | | | | | 1,689 | | | | | 1,689 | | | | |
| C10 Interior Construction | | | | | | | | | | | | | | | | | | | | | | | | | |
| Refinish Wood, Hollow Core, Painted, Interior Door | | | 8,023 | 2,000 | | | 8,023 | 2,000 | | | 8,023 | | | | | 2,000 | 8,023 | | | 2,000 | 8,023 | | | 2,000 | 8,02 |
| Replace Steel, Painted, Interior Double Door Locks | | 313 | | | | | | | | | | 313 | | | | | | | | | | 313 | | | |
| Replace Steel, Painted, Interior Double Door | | | | | | | | | | | | | | | | | | | | | | | | | |
| Finish Replaced Steel, Painted, Interior Double Doors | | | | | | | | | | | | | | | | | | | | | | | | | |
| Refinish Wood, Painted, Fully Glazed, Interior Door | 70 | 116 | | 139 | 70 | 209 | | 139 | 70 | 209 | | 139 | 70 | 209 | | 139 | 70 | 209 | | 139 | 70 | 209 | | 139 | i |
| Replace Aluminum, Fully Glazed, Interior Door Locks | | | 313 | | | | | 313 | | | | 1,254 | 313 | | | | | 313 | | | | 1,254 | 313 | | |
| Maintain Wood, Painted, Fully Glazed, Interior Door Locks | | | 311 | | | | 89 | 311 | | | | 89 | 311 | | | | 89 | 311 | | | | 89 | 311 | | |
| Replace Wood, Painted, Fully Glazed, Interior Door Locks | | | 940 | | | | | 3,449 | | | | 1,254 | 940 | | | | | 3,449 | | | | 1,254 | 940 | | |
| Finish Replaced Wood, Painted, Fully Glazed, Interior Door | | 93 | | | | | | | | | | | | | | | | | | | | | | | |
| Maintain Wood, Hollow Core, Painted, Interior Door Locks | | 1,915 | 7,685 | | | | 1,915 | 7,685 | | | | | | | | | 1,915 | 7,685 | | | | 1,915 | 7,685 | | |
| Replace Wood, Hollow Core, Painted, Interior Door Locks | | 26,966 | 108,175 | | | | | | | | | | | | | | | | | | | 26,966 | 108,175 | | |
| Replace Wood, Hollow Core, Painted, Interior Door | | | | | | | | | | | | 44,113 | 176,965 | | | | | | | | | | | | |
| Finish Replaced Wood, Hollow Core, Painted, Interior Door | | | | | | | | | | | | 2,000 | 8,023 | | | | | | | | | | | | |
| Maintain Steel, Painted, Interior Double Door Locks | | 22 | | | | | 22 | | | | | 22 | | | | | 22 | | | | | 22 | | | |
| Replace Wood, Painted, Fully Glazed, Interior Door | | 7,430 | | | | | | | | | | | | | | | | | | | | | | | |
| Replace Aluminum Frame, Fully Glazed, Sliding Interior Door | | | | | | | | | | | | | | | | | | | | | | | | | |
| Refinish Steel, Painted, Interior Door | | | | 302 | | | | 302 | | | | 302 | | | | 302 | | | | 302 | | | | 302 | |
| Refinish Toilet Partitions, Painted Metal, Overhead Braced | | | | 1,163 | | | | | | | | 1,163 | | | | 1,163 | | | | 1,163 | | | | 1,163 | |
| Replace Toilet Partitions, Painted Metal, Overhead Braced | | | | | | | | 39,535 | | | | | | | | | | | | | | | | | |
| Maintain Aluminum Frame, Fully Glazed, Sliding Interior Door | | | 44 | | | | | 44 | | | | | 44 | | | | | 44 | | | | | 44 | | |
| Refinish Steel, Painted, Interior Double Door | | | | 45 | | | | 45 | | | | 45 | | | | 45 | | | | 45 | | | | 45 | |
| Repair Aluminum Frame, Fully Glazed, Sliding Interior Door | | 459 | | | | | | | | | | | | 459 | | | | | | | | | | | |
| Maintain Aluminum, Fully Glazed, Interior Door Locks | | | 44 | | | | 89 | 44 | | | | 89 | 44 | | | | 89 | 44 | | | | 89 | 44 | | |
| Replace Aluminum, Fully Glazed, Interior Door | | 7,947 | | | | | | | | | | | | | | | | | | | | | | | |
| Maintain Steel, Painted, Interior Door Locks | | 290 | | | | | 290 | | | | | 290 | | | | | 290 | | | | | 290 | | | |
| Replace Steel, Painted, Interior Door Locks | | 4,076 | | | | | | | | | | 4,076 | | | | | | | | | | 4,076 | | | |
| Replace Steel, Painted, Interior Door | | | | | | | | | | | | | | | | | | | | | | | | | |
| Finish Replaced Steel, Painted, Interior Door | | | | | | | | | | | | | | | | | | | | | | | | | |
| Replace Door Locks Aluminum Frame, Fully Glazed, Sliding Int | | | | | | | | 651 | | | | | | | | | | 651 | | | | | | | |

Whitestone Research

05-Mar-13

| Building: Office Building | | | | Fa | acility: N | larsh | all Sp | ace | Fligh | t Cen | ter | | | | | | | | | | | | | |
|--|-------|--------|--------|-------|------------|--------|----------|-------|-------|-------|-------|--------|-------|-------|-------|----------|--------|-------|-------|-------|-------|--------|-------|-----|
| Building Num: 1045/62/178 | | | | | City: H | luntsv | /ille, / | ۹L | | | | | | | | | | | | | | | | |
| Forecast Year: | 2038 | 9 | 0 | 1 | 2 2043 | 4 | 5 | 6 | 7 | 2048 | 9 | 0 | 1 | 2 | 2053 | 4 | 5 | 6 | 7 | 2058 | 9 | 0 | 1 | |
| Replace Membrane, Single-Ply Roof w/ TPO Membrane | | | | | 205,685 | | | | | | | | | | | | | | | | | | | |
| Minor Replacement, Single-Ply Roof w/ TPO (2% of Roof) | 2,793 | | | | | | | | | | | | | | 2,793 | | | | | | | | | |
| Repair Metal Canopy | | | | | | 4,171 | | | | | | | | | | | | | | | | | | |
| Refinish Metal Canopy | | | | | | 4,160 | | | | | | | | | | | | | | | | | | |
| Maintain Single-Ply Roof w/ TPO Membrane | 1,733 | 1,733 | 1,733 | 1,733 | 1,733 | 1,733 | 1,733 | 1,733 | 1,733 | 1,733 | 1,733 | 1,733 | 1,733 | 1,733 | 1,733 | 1,733 | 1,733 | 1,733 | 1,733 | 1,733 | 1,733 | 1,733 | 1,733 | 1,7 |
| Non-Destructive Moisture Inspection | 1,689 | | | | | | | | | 1,689 | | | | | 1,689 | | | | | 1,689 | | | | |
| C10 Interior Construction | | | | | | | | | | | | | | | | | | | | | | | | |
| Refinish Wood, Hollow Core, Painted, Interior Door | | | 2,000 | 8,023 | | 2,000 | 8,023 | | | 2,000 | 8,023 | | | 2,000 | 8,023 | | | | | 2,000 | 8,023 | | | 2,0 |
| Replace Steel, Painted, Interior Double Door Locks | | | | | | | | | | | 313 | | | | | | | | | | 313 | | | |
| Replace Steel, Painted, Interior Double Door | | 1,801 | | | | | | | | | | | | | | | | | | | | | | |
| Finish Replaced Steel, Painted, Interior Double Doors | | 45 | | | | | | | | | | | | | | | | | | | | | | |
| Refinish Wood, Painted, Fully Glazed, Interior Door | 209 | | 139 | 70 | 93 | 256 | 70 | 93 | | 256 | 70 | 93 | | 116 | 70 | 232 | | 116 | | 232 | 70 | 116 | | 2 |
| Replace Aluminum, Fully Glazed, Interior Door Locks | | | | | | 1,254 | 313 | | | | | 313 | | | | 1,254 | | | | | | 313 | | |
| Maintain Wood, Painted, Fully Glazed, Interior Door Locks | | 89 | 200 | | | 89 | 311 | | | | 89 | 178 | | | | 89 | 244 | | | | 89 | 311 | | |
| Replace Wood, Painted, Fully Glazed, Interior Door Locks | | | 1,882 | | | 1,254 | 940 | | | | | 1,568 | | | | 1,254 | | | | | | 3,449 | | |
| Finish Replaced Wood, Painted, Fully Glazed, Interior Door | | | 116 | | | | | | | | | 139 | | | | | 70 | | | | | | | |
| Maintain Wood, Hollow Core, Painted, Interior Door Locks | | 1,915 | 7,685 | | | 1,915 | 7,685 | | | | 1,915 | 7,685 | | | | | | | | | 1,915 | 7,685 | | |
| Replace Wood, Hollow Core, Painted, Interior Door Locks | | | | | | 26,966 | 108,175 | | | | | | | | | | | | | | | | | |
| Replace Wood, Hollow Core, Painted, Interior Door | | | | | | | | | | | | | | | | 44,113 1 | 76,965 | | | | | | | |
| Finish Replaced Wood, Hollow Core, Painted, Interior Door | | | | | | | | | | | | | | | | 2,000 | 8,023 | | | | | | | |
| Maintain Steel, Painted, Interior Double Door Locks | | | | | | 22 | | | | | 22 | | | | | 22 | | | | | 22 | | | |
| Replace Wood, Painted, Fully Glazed, Interior Door | | | 9,288 | | | | | | | | | 11,145 | | | | | 5,572 | | | | | | | |
| Replace Aluminum Frame, Fully Glazed, Sliding Interior Door | | | 4,037 | | | | | | | | | | | | | | | | | | | | | |
| Refinish Steel, Painted, Interior Door | | | | | 302 | | | | 302 | | | | 302 | | | | 302 | | | | 302 | | | |
| Refinish Toilet Partitions, Painted Metal, Overhead Braced | | | | | | 1,163 | | | | 1,163 | | | | 1,163 | | | | 1,163 | | | | | | |
| Replace Toilet Partitions, Painted Metal, Overhead Braced | | | 39,535 | | | | | | | | | | | | | | | | | | | 39,535 | | |
| Maintain Aluminum Frame, Fully Glazed, Sliding Interior Door | | | | | | | 44 | | | | | 44 | | | | | 44 | | | | | 44 | | |
| Refinish Steel, Painted, Interior Double Door | | | | | 45 | | | | 45 | | | | 45 | | | | 45 | | | | 45 | | | |
| Repair Aluminum Frame, Fully Glazed, Sliding Interior Door | 459 | | | | | | | | | | | | | 459 | | | | | | | | | | |
| Maintain Aluminum, Fully Glazed, Interior Door Locks | | 89 | 22 | | | 89 | 44 | | | | 89 | 44 | | | | 89 | 22 | | | | 89 | 44 | | |
| Replace Aluminum, Fully Glazed, Interior Door | | | 1,987 | | | | | | | | | | | | | | 1,987 | | | | | | | |
| Maintain Steel, Painted, Interior Door Locks | | | | | | 290 | | | | | 290 | | | | | 290 | | | | | 290 | | | |
| Replace Steel, Painted, Interior Door Locks | | | | | | | | | | | 4,076 | | | | | | | | | | 4,076 | | | |
| Replace Steel, Painted, Interior Door | | 10,772 | | | | | | | | | | | | | | | | | | | | | | |
| Finish Replaced Steel, Painted, Interior Door | | 302 | | | | | | | | | | | | | | | | | | | | | | |
| Replace Door Locks Aluminum Frame, Fully Glazed, Sliding I | | | | | | | | | | | | 651 | | | | | | | | | | 651 | | |

| M&R Costs by Task | | | | | | | | | W | hites | tone | Resea | rch | | | | | 0 | 5-Mai | r-1: |
|--|-------|----------|--------|-------|-----------|---------------------|----------|--------|----------|-------|------|--------|-------|---------|-------|-------|--------|---------|-------|------|
| Building: Office Building | | | | Fac | ility: Ma | arshall Sp | ace Flig | ht Ce | enter | | | | | | | | | | | |
| Building Num: 1045/62/178 | | | | (| City: H | untsville, <i>I</i> | 21 | | | | | | | | | | | | | |
| Forecast Year: | 2013 | 4 | 5 | 6 | 7 2018 | 9 0 | | 2 202: | 34 | 5 | 6 | 7 2028 | 9 | 0 | 1 | 2 20 | 33 4 | 5 | 6 | |
| C20 Stairs | | | | | | | | | | | | | | | | | | | | |
| Refinish Metal, Painted, Interior Stairs | | | | 2,201 | | 2,201 | | | 2,201 | | | 2,201 | | | | 2,201 | | | 2,201 | |
| Finish Replaced Metal, Painted, Interior Stairs | | | | | | | | | | | | | | | | | | | | |
| Replace Metal, Painted, Interior Stairs | | | | | | | | | | | | | | | | | | | | |
| Repair Metal, Painted, Interior Stairs | | | | | | | | | 5,916 | | | | | | | | | | | |
| Replace Metal, Painted, Interior Railing | | 16,876 | | | | | | | | | | | | | | | | | | |
| Finish Repaired Metal, Painted, Interior Railing | | | | | | | | | | | | | 16 | | | | | | | |
| Repair Metal, Painted, Interior Railing | | | | | | | | | | | | | 806 | | | | | | | |
| Refinish Metal, Painted, Interior Railing | | | | | 551 | | 55 | 1 | | | 551 | | | 551 | | | 551 | | | |
| Finish Replaced Metal, Painted, Interior Railing | | 551 | | | | | | | | | | | | | | | | | | |
| Finish Repaired Metal, Painted, Interior Stairs | | | | | | | | | 64 | | | | | | | | | | | |
| 30 Interior Finishes | | | | | | | | | | | | | | | | | | | | |
| Refinish Gypsum Board, Finished Ceiling | | | | | | 4,343 | | | | | | | | 4,343 | | | | | | |
| Replace Carpet, Nylon 20 oz., Low Traffic | | 27 | 76,657 | | | 36,988 | | | 39 | 3,614 | | | : | 276,657 | | | | 36,988 | | |
| Repair Ceramic Tile Flooring (2% of Floors) | | | 355 | | | | | | | | | | 1,240 | 355 | | | | | | |
| Replace Ceramic Tile Flooring | | 41,857 | | | | | | | | | | | | | | | | | | |
| Repair Concrete Flooring (2% of Floors) | | | | | | | | | 857 | | | | | | | | | | | |
| Replace Concrete Flooring | | | | | | | | | | | | | | | | | | | | |
| Repair Vinyl Tile Flooring (2% of Floors) | | | | | | | 10 | 4 | | | | | | | | | | | | |
| Replace Vinyl Tile Flooring | 7,138 | | | | | | | | | | | | | | 7,138 | | | | | |
| Repair Acoustic Tile, Dropped Ceiling (2% of Ceiling) | 2,406 | 26 | | | 2,711 | 40 | 2,40 | 6 26 | 6 | | 2, | 711 40 | | | | 26 | | | | |
| Replace Acoustical Tile, Dropped Ceiling | | | | | | | | | | | | | | 120,441 | | | 28,169 | 107,553 | | |
| Replace Concrete Ceiling | | | | | | | | | | | | | | | | | | | | |
| Repair Gypsum Board, Finished Ceiling (2% of Ceiling) | | | | | | | | | | 308 | | | | | | | | | | |
| Finish Repaired Gypsum Board, Finished Ceiling | | | | | | | | | | 87 | | | | | | | | | | |
| Repair Metal Ceiling (2% of Ceiling) | | | | | | 82 | | | | | | 82 | | | | | | | 82 | |
| Replace Metal Ceiling | | | | | | | | | | | | | | | | | | | | |
| Repair Wallpaper, Interior Wall Finish (2% of Walls) | 35 | | | 108 | | | 35 | 28 | 3 | | | 108 | | | 28 | | 35 | | 108 | |
| Repair Concrete Ceiling (2% of Ceiling) | | 29 | | | | | | | | | | | | | | | | | | |
| Refinish Gypsum Board, Interior Wall Finish | | 87,459 7 | 78,331 | | | | | | 87,459 7 | 8,331 | | | | | | | 87,459 | 78,331 | | |
| Repair Carpet, Nylon 20 oz., Low Traffic (2% of Carpet) | | | 8,611 | | | 13,405 | | | | 6,272 | | | | 8,611 | | | | 13,405 | | |
| Repair Ceramic Tile, 4"x4", Interior Wall Finish (2% of Walls) | | | | | | 791 | | | | | | | | 791 | | | | | | |
| Refinish Concrete, Painted, Interior Wall Finish | | 8,646 | | | | | | | 8,646 | | | | | | | | 8,646 | | | |
| Repair Concrete, Painted, Interior Wall Finish (2% of Walls) | | 3,713 | | | | | | | | | | | | | | | | | | |
| Finish Repaired Concrete, Painted, Interior Wall Finish | | 174 | | | | | | | | | | | | | | | | | | |
| Replace Concrete, Painted, Interior Wall Finish | | | | | | | | | | | | | | | | | | | | |

| M&R Costs by Task | | | | | | | | | Whi | testo | one R | lesea | rch | | | | | 05 | 5-Ma | r-1 |
|---|--------|---------|-------|---------|-----------|---------|-------|-------|-------|-------|-------|--------|-------|-------|-------|------|--------|---------|------|------|
| Building: Office Building | | | Facil | ity: Ma | arshall S | Space F | light | Cente | r | | | | | | | | | | | |
| Building Num: 1045/62/178 | | | С | itv: Hu | untsville | AI | | | | | | | | | | | | | | |
| Forecast Year: | 2038 9 | 0 | | 2 2043 | | 56 | 7 | 2048 | 9 | 0 | 1 2 | 2 2053 | 4 | 5 | 6 7 | 2058 | 9 | 0 | 1 | |
| | | | | | | | | | | | | | | | | | | | | |
| C20 Stairs Refinish Metal, Painted, Interior Stairs | | | | 2,201 | | | 2,201 | | | 2,20 | 1 | | | 2,201 | | | 2,201 | | | |
| Finish Replaced Metal, Painted, Interior Stairs | 2,201 | | | 2,201 | | | 2,201 | | | 2,20 | /1 | | 4 | 2,201 | | | 2,201 | | | |
| Replace Metal, Painted, Interior Stairs | 78,083 | | | | | | | | | | | | | | | | | | | |
| Repair Metal, Painted, Interior Stairs | 10,000 | | | | | | | | | | | | 5,916 | | | | | | | |
| Replace Metal, Painted, Interior Railing | | | | | | | | | | | | | 5,510 | | | | | | | |
| | | | | | 16 | | | | | | | | | | | | 16 | | | |
| Finish Repaired Metal, Painted, Interior Railing Repair Metal, Painted, Interior Railing | | | | | 806 | | | | | | | | | | | | 806 | | | |
| Refinish Metal, Painted, Interior Railing | 551 | | 55 | 1 | 000 | 551 | | | 55 | 1 | | | 551 | | | 551 | 000 | | | 5 |
| Finish Replaced Metal, Painted, Interior Railing | 351 | | | 1 | | 551 | | | | | | | 551 | | | 551 | | | | 5. |
| Finish Repaired Metal, Painted, Interior Stairs | | | | | | | | | | | | | 64 | | | | | | | |
| | | | | | | | | | | | | | | | | | | | | |
| <u>30 Interior Finishes</u> | | | | | | | | | | | | | | | | | | | | |
| Refinish Gypsum Board, Finished Ceiling | | 4,343 | | | | | | | 4,34 | | | | | | | | | 4,343 | | |
| Replace Carpet, Nylon 20 oz., Low Traffic | | 393,614 | | | 276,65 | | | | 36,98 | 8 | | | 393 | 3,614 | | | 1 | 276,657 | | |
| Repair Ceramic Tile Flooring (2% of Floors) | | | | | 1,240 35 | 55 | | | | | | | | | | | 1,240 | | | |
| Replace Ceramic Tile Flooring | | | | | | | | | 11,95 | 9 | | | | | | | | | | |
| Repair Concrete Flooring (2% of Floors) | | | | | | | | | | | | | 857 | | | | | | | |
| Replace Concrete Flooring | 42,857 | | | | | | | | | | | | | | | | | | | |
| Repair Vinyl Tile Flooring (2% of Floors) | | 104 | | | | | | | | | | | | | | 104 | | | | |
| Replace Vinyl Tile Flooring | | | | | | | | | 138 | | | | | | | | | | | |
| Repair Acoustic Tile, Dropped Ceiling (2% of Ceiling) | 2,406 | | | 563 | 2,148 | | | 2,406 | 26 | | 563 | 2,148 | 40 | | 2,406 | 26 | | | 563 | 2,14 |
| Replace Acoustical Tile, Dropped Ceiling | | 1,316 | | | 2,00 |)1 | | | | | | | | | | | | | | |
| Replace Concrete Ceiling | 1,489 | | | | | | | | | | | | | | | | | | | |
| Repair Gypsum Board, Finished Ceiling (2% of Ceiling) | | | | | | | | | 30 | | | | | | | | | | | |
| Finish Repaired Gypsum Board, Finished Ceiling | | | | | | | | | 8 | 7 | | | | | | | | | | |
| Repair Metal Ceiling (2% of Ceiling) | | | | | | | 82 | | | | | | | 82 | | | | | | |
| Replace Metal Ceiling | 4,143 | | | | | | | | | | | | | | | | | | | |
| Repair Wallpaper, Interior Wall Finish (2% of Walls) | | | 35 | 28 | | | | 108 | | 2 | 28 | 35 | | | 108 | | | | 35 | |
| Repair Concrete Ceiling (2% of Ceiling) | | | | | | | | | | | | | | | | | | | | |
| Refinish Gypsum Board, Interior Wall Finish | | | | | 78,33 | | | 87,4 | | | | | | 3,331 | | | 87,459 | | | |
| Repair Carpet, Nylon 20 oz., Low Traffic (2% of Carpet) | | 6,272 | | | 8,61 | 1 | | | 13,40 | | | | 6 | 6,272 | | | | 8,611 | | |
| Repair Ceramic Tile, 4"x4", Interior Wall Finish (2% of Walls) | | 791 | | | | | | | 79 | 1 | | | | | | | | 791 | | |
| Refinish Concrete, Painted, Interior Wall Finish | | | | | | | | 8, | 646 | | | | | | | | 8,646 | | | |
| Repair Concrete, Painted, Interior Wall Finish (2% of Walls) | | | | | | | | | | | | | | | | | | | | |
| Finish Repaired Concrete, Painted, Interior Wall Finish | | | | | | | | | | | | | | | | | | | | |

Whitestone Research

05-Mar-13

| Building: Office Building | | | | Fa | acilit | : y: № | larsh | all Sp | bace | Fligh | t Cer | nter | | | | | | | | | | | | | |
|---|--------|---------|--------|--------|---------|---------------|--------|----------|--------|--------|--------|--------|--------|--------|--------|--------|--------|--------|--------|--------|--------|--------|--------|--------|--------|
| Building Num: 1045/62/178 | | | | | Cit | у: Н | unts | /ille, / | AL | | | | | | | | | | | | | | | | |
| Forecast Year: | 2013 | 4 | 5 | 6 | 7 | 2018 | 9 | 0 | 1 | 2 | 2023 | 4 | 5 | 6 | 7 | 2028 | 9 | 0 | 1 | 2 | 2033 | 4 | 5 | 6 | 7 |
| Finish Replaced Concrete, Painted, Interior Wall Finish | | | | | | | | | | | | | | | | | | | | | | | | | |
| Replace Fabric, Interior Wall Finish | | | | | | | | | | | | | 1,822 | | | | | | | | | | | | |
| Repair Gypsum Board, Interior Wall Finish (2% of Walls) | | | 3,621 | | | | | | | | | 4,043 | | | | | | | | | | | 3,621 | | |
| Finish Repaired Gypsum Board, Interior Wall Finish | | | 1,566 | | | | | | | | | 1,748 | | | | | | | | | | | 1,566 | | |
| Replace Gypsum Board, Interior Wall Finish | | | | | | | | | | | | | | | | | | | | | | | | | |
| Finish Replaced Gypsum Board, Interior Wall Finish | | | | | | | | | | | | | | | | | | | | | | | | | |
| Repair Steel, Interior Wall Finish (2% of Walls) | | 290 | | | | | | | | | | | | | | | | | | | | | | | |
| Replace Steel, Interior Wall Finish | | | | | | | | | | | | | | | | | | | | | | | | | |
| Replace Wallpaper, Interior Wall Finish | | | 1,342 | | | | | 5,174 | | | | | 1,679 | | | | | | | | | | 1,342 | | |
| Repair Fabric, Interior Wall Finish (2% of Walls) | | | 38 | | | | | | | | | | | | | | | | | | | | 38 | | |
| D10 Conveying | | | | | | | | | | | | | | | | | | | | | | | | | |
| Renovate Elevator, Geared, 3,500 lbs, 6-15 Floor, 350 fpm | | | | | 449,857 | | | | | | | | | | | | | | | | | | | | |
| Maintain Elevator, Hydraulic, 2,500 lbs, 3-5 Floor, 200 fpm | 9,202 | | 9,202 | 9,202 | 9,202 | 9,202 | 9,202 | 9,202 | 9,202 | 9,202 | 9,202 | 9,202 | 9,202 | 9,202 | 9,202 | 9,202 | 9,202 | 9,202 | 9,202 | 9,202 | 9,202 | 9,202 | 9,202 | 9,202 | 9,202 |
| Maintain Elevator, Geared, 3,500 lbs, 6-15 Floor, 350 fpm | 58,541 | 58,541 | 58,541 | 58,541 | | 58,541 | 58,541 | 58,541 | 58,541 | 58,541 | 58,541 | 58,541 | 58,541 | 58,541 | 58,541 | 58,541 | 58,541 | 58,541 | 58,541 | 58,541 | 58,541 | 58,541 | 58,541 | 58,541 | 58,541 |
| Renovate Elevator, Hydraulic, 2,500 lbs, 3-5 Floor, 200 fpm | | 123,352 | | | | | | | | | | | | | | | | | | | | | | | |
| D20 Plumbing | | | | | | | | | | | | | | | | | | | | | | | | | |
| Maintain Backflow Preventer, 2" | 211 | | 211 | 211 | 211 | 211 | 211 | 211 | 211 | 211 | 211 | | 211 | 211 | 211 | 211 | 211 | 211 | 211 | 211 | 211 | | 211 | 211 | 211 |
| Replace Water Storage Tank, 500 Gal. | | | | | | | | | | | | 3,808 | | | | | | | | | | | | | |
| Maintain Water Storage Tank, 500 Gal. | 87 | 87 | 87 | 87 | 87 | 87 | 87 | 87 | 87 | 87 | 87 | | 87 | 87 | 87 | 87 | 87 | 87 | 87 | 87 | 87 | 87 | 87 | 87 | 87 |
| Replace Water Heater, Electric, 120 Gal. | | | | | | | | | | | | | 9,775 | | | | | | | | | | | | |
| Drain & Flush Water Heater, Electric, 120 Gal. | | | | | 236 | | | | | | | 236 | | | | | | | | 236 | | | | | |
| Check Operation, Water Heater, Electric, 120 Gal. | 19 | | | 19 | | | 19 | | | 19 | | | | | | 19 | | | 19 | | | 19 | | | 19 |
| Replace Pipe Insulation, Fiberglass, Hot Water (20% of Insulati | | 302 | | | | | | | | | | | | | | | | | | | | | | | |
| Re-tape Pipe Insulation, Fiberglass, Hot Water | | | | | | | 100 | | | | | 100 | | | | | 100 | | | | | 100 | | | |
| Replace 10' Section, Pipe & Fittings, 4" DWV PVC | | 39 | | | | | | | | | | | | | | | | | | | | 39 | | | |
| Replace Pipe Insulation, Fiberglass, Cold Water (20% of Insula | | 475 | | | | | | | | | | | | | | | | | | | | | | | |
| Re-tape Pipe Insulation, Fiberglass, Cold Water | | | | | | | 157 | | | | | 157 | | | | | 157 | | | | | 157 | | | |
| Replace Pipe & Fittings, 4" Copper, Cold Water (20% of Pipe) | | 7,569 | | | | | | | | | | | | | | | | | | | | | | | |
| Replace 10' Section, Pipe & Fittings, 4" Copper, Cold Water | | | | | | | | | | | | | | | | | | | | | | 379 | | | |
| Resolder Joint, Pipe & Fittings, 4" Copper, Cold Water | | | | | | | | | | | | 101 | | | | | | | | | | 101 | | | |
| Replace Pipe & Fittings, 2" Copper, Hot Water (20% of Pipe) | | 1,492 | | | | | | | | | | | | | | | | | | | | | | | |
| Replace Backflow Preventer, 2" | | 3,560 | | | | | | | | | | 3,560 | | | | | | | | | | 3,560 | | | |
| Replace 10' Section, Pipe & Fittings, 2" Copper, Hot Water | | | | | | | | | | | | | | | | | | | | | | 75 | | | |
| Resolder Joint, Pipe & Fittings, 2" Copper, Hot Water | | | | | | | | | | | | 59 | | | | | | | | | | 59 | | | |
| Overhaul Sump Pump, 3 HP | | | 93 | | | | | 186 | | | | | 186 | | | | | 93 | | | | | 93 | | |
| Inspect & Lubricate Sump Pump, 3 HP | 93 | 93 | 46 | 93 | 93 | 93 | 93 | 93 | 93 | 93 | 93 | 93 | 93 | 93 | 93 | 93 | 93 | 46 | 93 | 93 | 93 | 93 | 46 | 93 | 93 |
| nopeo, a Labridate Gump Fump, 5 Fir | 00 | 00 | .5 | | 00 | | | 00 | 00 | 00 | | 00 | | | 00 | 00 | | .0 | 00 | | 00 | 00 | .0 | 00 | 00 |

Whitestone Research

05-Mar-13

| Building: Office Building | | | | F | acilit | : y: M | arsha | all Sp | bace | Fligh | t Cen | iter | | | | | | | | | | | | | |
|---|--------|---------|--------|--------|---------|---------------|--------|-----------------|--------|--------|--------|--------|--------|--------|--------|--------|--------|--------|--------|--------|--------|--------|--------|--------|--------|
| Building Num: 1045/62/178 | | | | | Cit | : у: Н | untsv | ville, <i>i</i> | AL | | | | | | | | | | | | | | | | |
| Forecast Year: | 2038 | 39 | 0 | 1 | | 2043 | 4 | 5 | 6 | 7 | 2048 | 9 | 0 | 1 | 2 | 2053 | 4 | 5 | 6 | 7 | 2058 | 9 | 0 | 1 | 2 |
| Finish Replaced Concrete, Painted, Interior Wall Finish | | 8,646 | | | | | | | | | | | | | | | | | | | | | | | |
| Replace Fabric, Interior Wall Finish | | | | | | | | | | | | | | | | | | 1,822 | | | | | | | |
| Repair Gypsum Board, Interior Wall Finish (2% of Walls) | | | | | | | | | | | | | | | | | | 3,621 | | | | 4,043 | | | |
| Finish Repaired Gypsum Board, Interior Wall Finish | | | | | | | | | | | | | | | | | | 1,566 | | | | 1,748 | | | |
| Replace Gypsum Board, Interior Wall Finish | | 202,434 | | | | | | | | | | | | | | | | | | | | | | | |
| Finish Replaced Gypsum Board, Interior Wall Finish | | 87,459 | | | | | | | | | | | | | | | | | | | | | | | |
| Repair Steel, Interior Wall Finish (2% of Walls) | | | | | | | | | | | | | | | | | | | | | | | | | |
| Replace Steel, Interior Wall Finish | | 11,754 | | | | | | | | | | | | | | | | | | | | | | | |
| Replace Wallpaper, Interior Wall Finish | | | 5,174 | | | | | 1,679 | | | | | | | | | | 1,342 | | | | | 5,174 | | |
| Repair Fabric, Interior Wall Finish (2% of Walls) | | | | | | | | 38 | | | | | | | | | | | | | | | | | |
| D10 Conveying | | | | | | | | | | | | | | | | | | | | | | | | | |
| Renovate Elevator, Geared, 3,500 lbs, 6-15 Floor, 350 fpm | | | | | 449,857 | | | | | | | | | | | | | | | | | | | | |
| Maintain Elevator, Hydraulic, 2,500 lbs, 3-5 Floor, 200 fpm | 9,202 | ! | 9,202 | 9,202 | 9,202 | 9,202 | 9,202 | 9,202 | 9,202 | 9,202 | 9,202 | 9,202 | 9,202 | 9,202 | 9,202 | 9,202 | 9,202 | 9,202 | 9,202 | 9,202 | 9,202 | 9,202 | 9,202 | 9,202 | 9,202 |
| Maintain Elevator, Geared, 3,500 lbs, 6-15 Floor, 350 fpm | 58,541 | 58,541 | 58,541 | 58,541 | | 58,541 | 58,541 | 58,541 | 58,541 | 58,541 | 58,541 | 58,541 | 58,541 | 58,541 | 58,541 | 58,541 | 58,541 | 58,541 | 58,541 | 58,541 | 58,541 | 58,541 | 58,541 | 58,541 | 58,541 |
| Renovate Elevator, Hydraulic, 2,500 lbs, 3-5 Floor, 200 fpm | | 123,352 | | | | | | | | | | | | | | | | | | | | | | | |
| D20 Plumbing | | | | | | | | | | | | | | | | | | | | | | | | | |
| Maintain Backflow Preventer. 2" | 211 | 211 | 211 | 211 | 211 | 211 | | 211 | 211 | 211 | 211 | 211 | 211 | 211 | 211 | 211 | | 211 | 211 | 211 | 211 | 211 | 211 | 211 | 211 |
| Replace Water Storage Tank, 500 Gal. | | | | | | | 3,808 | | | | | | | | | | | | | | | | | | |
| Maintain Water Storage Tank, 500 Gal. | 87 | 87 | 87 | 87 | 87 | 87 | | 87 | 87 | 87 | 87 | 87 | 87 | 87 | 87 | 87 | 87 | 87 | 87 | 87 | 87 | 87 | 87 | 87 | 87 |
| Replace Water Heater, Electric, 120 Gal. | | | 9,775 | | | | | | | | | | | | | | | 9,775 | | | | | | | |
| Drain & Flush Water Heater, Electric, 120 Gal. | | 236 | | | | | | | | 236 | | | | | | | 236 | | | | | | | | 236 |
| Check Operation, Water Heater, Electric, 120 Gal. | | | | | | 19 | | | 19 | | | 19 | | | 19 | | | | | | 19 | | | 19 | |
| Replace Pipe Insulation, Fiberglass, Hot Water (20% of Insula | | 302 | | | | | | | | | | | | | | | | | | | | | | | |
| Re-tape Pipe Insulation, Fiberglass, Hot Water | | | | | | | 100 | | | | | 100 | | | | | 100 | | | | | 100 | | | |
| Replace 10' Section, Pipe & Fittings, 4" DWV PVC | | | | | | | 39 | | | | | | | | | | | | | | | | | | |
| Replace Pipe Insulation, Fiberglass, Cold Water (20% of Insul | | 475 | | | | | | | | | | | | | | | | | | | | | | | |
| Re-tape Pipe Insulation, Fiberglass, Cold Water | | | | | | | 157 | | | | | 157 | | | | | 157 | | | | | 157 | | | |
| Replace Pipe & Fittings, 4" Copper, Cold Water (20% of Pipe) | | 7,569 | | | | | | | | | | | | | | | | | | | | | | | |
| Replace 10' Section, Pipe & Fittings, 4" Copper, Cold Water | | | | | | | | | | | | | | | | | | | | | | 379 | | | |
| Resolder Joint, Pipe & Fittings, 4" Copper, Cold Water | | | | | | | | | | | | 101 | | | | | | | | | | 101 | | | |
| Replace Pipe & Fittings, 2" Copper, Hot Water (20% of Pipe) | | 1,492 | | | | | | | | | | | | | | | | | | | | | | | |
| Replace Backflow Preventer, 2" | | | | | | | 3,560 | | | | | | | | | | 3,560 | | | | | | | | |
| Replace 10' Section, Pipe & Fittings, 2" Copper, Hot Water | | | | | | | | | | | | | | | | | | | | | | 75 | | | |
| Resolder Joint, Pipe & Fittings, 2" Copper, Hot Water | | | | | | | | | | | | 59 | | | | | | | | | | 59 | | | |
| Overhaul Sump Pump, 3 HP | | | 186 | | | | | 186 | | | | | 93 | | | | | 93 | | | | | 186 | | |
| Inspect & Lubricate Sump Pump, 3 HP | 93 | 93 | 93 | 93 | 93 | 93 | 93 | 93 | 93 | 93 | 93 | 93 | 46 | 93 | 93 | 93 | 93 | 46 | 93 | 93 | 93 | 93 | 93 | 93 | 93 |
| | | | | | | | | | | | | | | | | | | | | | | | | | |

Whitestone Research

05-Mar-13

| Building: Office Building | | | | Fa | cility | /: Ma | arsha | ll Sp | ace F | Flight | Cen | ter | | | | | | | | | | | | | |
|---|------|-------|-----|-----|--------|--------------|--------|--------|-------|--------|------|-------|-----|-------|-----|-------|-----|--------|-----|-----|------|-------|--------|-----|-----|
| Building Num: 1045/62/178 | | | | | City | /: Hu | untsvi | lle, A | L | | | | | | | | | | | | | | | | |
| Forecast Year: | 2013 | 4 | 5 | 6 | - | 2018 | 9 | 0 | 1 | 2 | 2023 | 4 | 5 | 6 | 7 | 2028 | 9 | 0 | 1 | 2 | 2033 | 4 | 5 | 6 | 7 |
| Replace Roof Drain, 4-6" | | • | - | - | • | | • | • | • | - | | • | - | • | • | | • | • | • | - | | • | • | • | · |
| Maintain Roof Drain, 4-6" | 141 | 141 | 141 | 141 | 141 | 141 | 141 | 141 | 141 | 141 | 141 | 141 | 141 | 141 | 141 | 141 | 141 | 141 | 141 | 141 | 141 | 141 | 141 | 141 | 141 |
| Replace Pipe & Fittings, 6" DWV PVC (20% of Pipe) | | | | | | | | | | | | 1,364 | | | | | | | | | | | | | |
| Replace 10' Section, Pipe & Fittings, 6" DWV PVC | | 73 | | | | | | | | | | | | | | | | | | | | 73 | | | |
| Replace Pipe & Fittings, 4" DWV PVC (20% of Pipe) | | | | | | | | | | | | 746 | | | | | | | | | | | | | |
| Replace 10' Section, Pipe & Fittings, 8" DWV PVC | | 103 | | | | | | | | | | | | | | | | | | | | 103 | | | |
| Replace Pipe & Fittings, 8" DWV PVC (20% of Pipe) | | | | | | | | | | | | 2,069 | | | | | | | | | | | | | |
| Maintain Floor Drain | 460 | 460 | 460 | 460 | 460 | 460 | 460 | 460 | 460 | 460 | 460 | 460 | 460 | 460 | 460 | 460 | 460 | 460 | 460 | 460 | 460 | 460 | 460 | 460 | 460 |
| Replace Pipe & Fittings, 6" Cast Iron (20% of Pipe) | | | | | | | | | | | | | | | | | | | | | | | | | |
| Install New Gasket & Bolts, Pipe & Fittings, 6" Cast Iron | | 21 | | | | | | | | | | | | | | | | | | | | | | | |
| Replace 10' Section, Pipe & Fittings, 6" Cast Iron | | | | | | | | | | | | 88 | | | | | | | | | | | | 88 | |
| Replace Pipe & Fittings, 4" Cast Iron (20% of Pipe) | | | | | | | | | | | | | | | | | | | | | | | | | |
| Install New Gasket & Bolts, Pipe & Fittings, 4" Cast Iron | | 48 | | | | | | | | | | | | | | | | | | | | | | | |
| Replace 10' Section, Pipe & Fittings, 4" Cast Iron | | | | | | | | | | | | 164 | | | | | | | | | | | | 164 | |
| Replace Floor Drain | | | | | | | | | | | | | | | | | | | | | | | | | |
| Inspect & Lubricate Circulator Pump, 3 HP, Hot Water | 23 | 23 | 23 | 23 | 23 | 23 | 23 | 23 | 23 | 23 | 23 | 23 | 23 | 23 | 23 | 23 | 23 | | 23 | 23 | 23 | 23 | 23 | 23 | 23 |
| Replace Faucet Washer & Clean Trap, Sink, Floor | | 56 | | 56 | | 56 | | 56 | | 56 | | 56 | | 56 | | 56 | | 56 | | 56 | | | | 56 | |
| Lubricate, Repack Gland, Ball Valve, 4" | 112 | 112 | 112 | 112 | 112 | 112 | 112 | 112 | 112 | 112 | 112 | | 112 | 112 | 112 | 112 | 112 | 112 | 112 | 112 | 112 | 112 | 112 | 112 | 112 |
| Replace Urinal, Vitreous China | | | | | | | | | | | | | | | | | | | | | | | 13,952 | | |
| Replace Flush Valve, Urinal, Vitreous China | | 2,466 | | | | | | | 2,466 | | | | | | | 2,466 | | | | | | | | | |
| Replace Tankless Water Closet | | | | | | | | | | | | | | | | | | | | | | | 34,211 | | |
| Replace Flush Valve, Tankless Water Closet | | | | | | | | 1,090 | | | | | | | | | | 1,090 | | | | | | | |
| Replace Sink, Enameled Steel | | | | | | | | | | | | | | | | | | | | | | 6,026 | | | |
| Replace Circulator Pump, 3 HP, Hot Water | | | | | | | | | | | | | | | | | | 7,880 | | | | | | | |
| Repair Strainer, Sink, Floor | | | | | | | | 278 | | | | | | | | 278 | | | | | | | | | |
| Overhaul Booster Pump, 1 1/2 HP | | | 109 | | | | | | | | | | 109 | | | | | 109 | | | | | 109 | | |
| Replace Lavatory, Vitreous China | | | | | | | | | | | | | | | | | | | | | | | 16,509 | | |
| Replace Valve Set, Lavatory, Vitreous China | | | | | | | | 4,703 | | | | | | | | | | 4,703 | | | | | | | |
| Replace Washer & Spud Connection, Lavatory, Vitreous China | | 1,384 | | | | | | | 1,384 | | | | | | | 1,384 | | | | | | | | | |
| Replace Faucet Washer & Clean Trap, Lavatory, Vitreous Chin | | 756 | | 756 | | 756 | | 756 | | 756 | | 756 | | 756 | | 756 | | 756 | | 756 | | 756 | | | 756 |
| Replace Drinking Fountain, Refrigerated | | | | | | | | 11,355 | | | | | | | | | | 11,355 | | | | | | | |
| Replace Coolant & Adjust Drinking Fountain, Refrigerated | | 294 | | 294 | | 294 | | | | 294 | | 294 | | 294 | | 294 | | | | 294 | | 294 | | 294 | |
| Repair Air Compressor, 5 HP | | 1,318 | | | | 1,318 | | | | 1,318 | | | | 1,318 | | | | 1,318 | | | | 1,318 | | | |
| Replace Valve Set, Sink, Enameled Steel | | 492 | | | | | | | | | | 492 | | | | | | | | | | | | | |
| Replace Circulator Pump, 3 HP, Cold Water | | | | | | | | | | | | | | | | | | 15,760 | | | | | | | |
| Replace 10' Section, Pipe & Fittings, 2" Copper, Cold Water | | | | | | | | | | | | | | | | | | | | | | 108 | | | |
| Resolder Joint, Pipe & Fittings, 2" Copper, Cold Water | | | | | | | | | | | | 85 | | | | | | | | | | 85 | | | |

Whitestone Research

05-Mar-13

| Biblic SubstrateParticityPartityParticityParticityParti | shall Space Flight Center | space Flight Ce | ility: Marshall Sp | Facility: | Building: Office Building |
|---|--|-----------------|--------------------|-------------------------------------|---|
| ProventioneProvinceProv | tsville. AL | AL | Citv: Huntsville. | Citv: | Building Num: 1045/62/178 |
| Plandscription of the series | | | • | • | - |
| Match Rad Dain, 4"Int <t< td=""><td></td><td>5 0 7 204</td><td></td><td></td><td></td></t<> | | 5 0 7 204 | | | |
| Place Probation of the probability | 141 141 141 141 141 141 141 141 141 141 | 1 141 141 14 | 141 141 141 | 141 141 141 141 141 14 ¹ | |
| Relaction Open Entings, of CMV PVC (20% of Pipe)USE USE USE USE USE USE USE USE USE USE | 1,364 | | | | |
| Papelae Pack Strains, of WVPC (20% of Pain S, T)VIETURE VIETURE VIET | 73 | | 73 | | |
| Parameter is a state of the set of th | 746 | | | | |
| Participanty of 2000 (2000)Participanty | 103 | | 103 | | |
| Maintain Floor Drain460 | 2,069 | | | | |
| Install Name Gasket & Bolls, Pipe & Fittings, 6° Cast Iron Cast Iron (20% OP Pipe) Cast Iron (20% OP Pipe)< | 460 460 460 460 460 460 460 460 460 460 | 0 460 460 46 | 460 460 460 | 460 460 460 460 460 460 | |
| Replace 0's Cention Ope 0Constrained of the constrained of the | | | | 1,761 | Replace Pipe & Fittings, 6" Cast Iron (20% of Pipe) |
| Replace 0's Cection Pipe & Fittings, 4' Cast Iron (20% OF Pipe)3.287555 </td <td></td> <td></td> <td></td> <td></td> <td></td> | | | | | |
| Replace Pipe A Strating, 4° Cast Iron3.3255 <th< td=""><td>88</td><td></td><td></td><td></td><td></td></th<> | 88 | | | | |
| Install Now Gask A Bolts, Pipe & Fittings, 4° Cast Iron | | | | 3,265 | |
| Replace Floor Drain Figure Floor Drain Sequence Floor Drain Se | | | | | |
| Replace Floor Drain | 164 | | | | |
| Replace Faucet Washer & Clean Tay, Sink, Floor 56 | 670 | | 5,670 | | |
| Lubricate, Repack Gland, Ball Valve, 4* 112 | 23 23 23 23 23 23 23 23 23 23 23 23 23 2 | 3 23 23 2 | 23 23 23 23 | 23 23 23 23 23 23 23 | Inspect & Lubricate Circulator Pump, 3 HP, Hot Water |
| Replace Unial, Vitrous ChinalGet ControlReplace Flush Valve, Unial, Vitrous Chinal2.4662.466Replace Flush Valve, Tankless Water Closet | 56 56 56 56 56 56 56 56 56 | 56 5 | 56 56 | 56 56 56 | Replace Faucet Washer & Clean Trap, Sink, Floor |
| Pelace Flush Valve, Urial, Vitreous China2,4662,466Replace Flush Valve, Tankless Water ClosetReplace Flush Valve, Tankless Water Closet1,0901,090Replace Flush Valve, Tankless Water ClosetReplace Sink, Enameled SteelReplace Circulator Pump, 3 HP, Hot Water0-Replace Sink, FloorOverhaul Booster Pump, 11/2 HPReplace Lavatory, Vitreous ChinaReplace Valve Skt, Lavatory, Vitreous ChinaReplace Valve Skt, Lavatory, Vitreous ChinaReplace Washer & Spud Connection, Lavatory, Vitreous China-1,384 | 112 112 112 112 112 112 112 112 112 112 | 2 112 112 11 | 112 112 112 112 | 112 112 112 112 112 | Lubricate, Repack Gland, Ball Valve, 4" |
| Replace Tankless Water Closet | | | | | Replace Urinal, Vitreous China |
| Replace Flush Valve, Tankless Water Closet1,000Replace Sink, Enameled Steel1,000Replace Circulator Pump, 3 HP, Hot Water7,800Repair Strainer, Sink, Floor278Overhaul Booster Pump, 1 1/2 HP100Replace Lavatory, Vitreous China100Replace Valve Set, Lavatory, Vitreous China4,703Replace Washer & Spud Connection, Lavatory, Vitreous China1,384 | 2,466 2,466 | | 466 | 2,466 | Replace Flush Valve, Urinal, Vitreous China |
| Replace Sink, Enameled Steel | | | | | Replace Tankless Water Closet |
| Reface Circulator Pump, 3 HP, Hot Water7.880Repair Strainer, Sink, Floor278278Overhaul Booster Pump, 1 1/2 HP109109Replace Lavatory, Vitreous China | 1,090 1,090 | 0 | 1,090 | | Replace Flush Valve, Tankless Water Closet |
| Repair Strainer, Sink, Floor278278Overhaul Booster Pump, 11/2 HP109109Replace Lavatory, Vitreous China109109Replace Lavatory, Vitreous China4,7034,703Replace Valve Set, Lavatory, Vitreous China1,3841,384 | | | | | Replace Sink, Enameled Steel |
| Overhaul Booster Pump, 1 1/2 HP109109Replace Lavatory, Vitreous China109109Replace Valve Set, Lavatory, Vitreous China4,7034,703Replace Washer & Spud Connection, Lavatory, Vitreous China1,3841,384 | 7,880 | | | | Replace Circulator Pump, 3 HP, Hot Water |
| Replace Lavatory, Vitreous China 4,703 4,703 Replace Valve Set, Lavatory, Vitreous China 1,384 1,384 1,384 | 278 278 | | 278 | 278 | Repair Strainer, Sink, Floor |
| Replace Valve Set, Lavatory, Vitreous China 4,703 Replace Washer & Spud Connection, Lavatory, Vitreous China 1,384 1,384 1,384 | 109 109 109 | 9 | 109 | | Overhaul Booster Pump, 1 1/2 HP |
| Replace Washer & Spud Connection, Lavatory, Vitreous Chin 1,384 1,384 1,384 | | | | | |
| | 4,703 4,703 | 3 | 4,703 | | Replace Valve Set, Lavatory, Vitreous China |
| | 1,384 1,384 | | 384 | 1,384 | Replace Washer & Spud Connection, Lavatory, Vitreous Chin |
| Replace Faucet Washer & Clean Trap, Lavatory, Vitreous Chi 756 756 756 756 756 756 756 756 756 756 | 756 756 756 756 756 756 756 756 756 756 | 6 756 | 756 756 | 756 756 756 | Replace Faucet Washer & Clean Trap, Lavatory, Vitreous Chi |
| Replace Drinking Fountain, Refrigerated 11,355 11,355 11,355 | 11,355 11,355 | | | 11,355 | Replace Drinking Fountain, Refrigerated |
| Replace Coolant & Adjust Drinking Fountain, Refrigerated 294 294 294 294 294 294 294 294 294 294 | 294 294 294 294 294 294 294 | 294 29 | 294 294 | 294 294 | Replace Coolant & Adjust Drinking Fountain, Refrigerated |
| Repair Air Compressor, 5 HP 1,318 1,318 1,318 1,318 1,318 1,318 1,318 | 1,318 1,318 1,318 1,318 | 1,318 | 1,318 | 1,318 1,318 | Repair Air Compressor, 5 HP |
| Replace Valve Set, Sink, Enameled Steel 492 492 | 492 492 | | 492 | | Replace Valve Set, Sink, Enameled Steel |
| Replace Circulator Pump, 3 HP, Cold Water 15,760 | 15,760 | | | | Replace Circulator Pump, 3 HP, Cold Water |
| Replace 10' Section, Pipe & Fittings, 2" Copper, Cold Water 108 | 108 | | | | Replace 10' Section, Pipe & Fittings, 2" Copper, Cold Water |
| Resolder Joint, Pipe & Fittings, 2" Copper, Cold Water 85 85 | 85 85 | | | | |

Tasks ordered by UNIFORMAT II Classifications. Unscheduled Maintenance Costs are not included. Based on a 50-Year Forecast. All costs expressed in (\$) 2012.

Whitestone Research

05-Mar-13

| | | | | | | | • | | iigin | Cent | 01 | | | | | | | | | | | | | |
|------|--|--|---|---|--|--|--|---|---|---|-------|--|---|---|---|---|---|---|--|---|-----|---------------------------------------|---------------------------------------|---------------------------------------|
| | | | | City | : Hu | intsvi | lle, A | L | | | | | | | | | | | | | | | | |
| 2013 | 4 | 5 | 6 | 7 | 2018 | 9 | 0 | 1 | 2 | 2023 | 4 | 5 | 6 | 7 | 2028 | 9 | 0 | 1 | 2 | 2033 | 4 | 5 | 6 | 7 |
| | 818 | | | | | | | | | | | | | | | | | | | | | | | |
| | | | | | | | | | | | | | | | | | | | | | 40 | | | |
| | | | | | | | | | | | 76 | | | | | | | | | | 76 | | | |
| | 273 | | | | | | | | | | | | | | | | | | | | | | | |
| | | | | | | | | | | | | | | | | | | | | | 13 | | | |
| | | | | | | | | | | | 3,839 | | | | | | | | | | | | | |
| | | 46 | | | | | 46 | | | | | 46 | | | | | | | | | | 46 | | |
| 23 | 23 | 23 | 23 | 23 | 23 | 23 | | 23 | 23 | 23 | 23 | 23 | 23 | 23 | 23 | 23 | 23 | 23 | 23 | 23 | 23 | 23 | 23 | 23 |
| | | 92 | | | | | 92 | | | | | 92 | | | | | | | | | | 92 | | |
| 46 | 46 | 46 | 46 | 46 | 46 | 46 | 46 | 46 | 46 | 46 | 46 | 46 | 46 | 46 | 46 | 46 | | 46 | 46 | 46 | 46 | 46 | 46 | 46 |
| | | | | | | | | | | | | | | | | | 2,863 | | | | | | | |
| | | 46 | | | | | 46 | | | | | 46 | | | | | | | | | | 46 | | |
| 23 | 23 | 23 | 23 | 23 | 23 | 23 | 23 | 23 | 23 | 23 | 23 | 23 | 23 | 23 | 23 | 23 | | 23 | 23 | 23 | 23 | 23 | 23 | 23 |
| | | | | | | | 6,131 | | | | | | | | | | | | | | | | | |
| | 2,166 | | | | | | | | | | | | | | | | | | | | | | | |
| | | | | | | | | | | | 25 | | | | | | | | | | 25 | | | |
| | | 2,819 | | | | | | | | | | | | | | | 2,819 | | | | | 2,819 | | |
| | | | | | | | | | | | | | | | | | | | | | 1 | 15,279 | | |
| 59 | 59 | 59 | 59 | 59 | 59 | 59 | | 59 | 59 | 59 | 59 | 59 | 59 | 59 | 59 | 59 | 59 | 59 | 59 | 59 | 59 | | 59 | 59 |
| | | 117 | | | | | | | | | | 117 | | | | | 117 | | | | | | | |
| | | 2,868 | | | | | | | | | | | | | | | 2,868 | | | | | | | |
| | | | | | | | 8,485 | | | | | | | | | | | | | | | 8,485 | | |
| 131 | 131 | 131 | 131 | 131 | 131 | 131 | 131 | 131 | 131 | 131 | 131 | 131 | 131 | 131 | 131 | 131 | 131 | 131 | 131 | 131 | 131 | | 131 | 131 |
| | | | | | | | | | | | | | | | | | | | | | | | | |
| | | | | | | | | | | | | | | | | | | | | | | | | |
| | | | | | | | | | | | | | | | | | | | | | | | | |
| 93 | 93 | 93 | 93 | 93 | 93 | 93 | 93 | 93 | 93 | 93 | 93 | 93 | 93 | 93 | 93 | 93 | 93 | 93 | 93 | 93 | 93 | 93 | | 93 |
| | | | | | | | | | | | | | | | | | | | | | | ε | 33,147 | |
| | | | 2,221 | | | | | | | | | | | | | 2,221 | | | | | | | | |
| 440 | 440 | 440 | 440 | 440 | 440 | 440 | 440 | 440 | 440 | 440 | 440 | 440 | 440 | 440 | 440 | 440 | 440 | 440 | 440 | 440 | 440 | 440 | | 440 |
| | | | | | | | | | | | | | | | | | | | | | | | 5,186 | |
| | | | 192 | | | | | | | | | | | | | 192 | | | | | | | | |
| 93 | 93 | 93 | 93 | 93 | 93 | 93 | 93 | 93 | 93 | 93 | 93 | 93 | 93 | 93 | 93 | 93 | 93 | 93 | 93 | 93 | 93 | 93 | | 93 |
| | | | | | | | | | | | | | | | | | | | | | | | 3,186 | |
| | | | 192 | | | | | | | | | | | | | 192 | | | | | | | | |
| | | | 192 | | | | | | | | | | | | | 192 | | | | | | | | |
| | | | | | | | | | | | | | | | | | | | | | | | | |
| 93 | 93 | 93 | 93 | 93 | 93 | 93 | 93 | 93 | 93 | 93 | 93 | 93 | 93 | 93 | 93 | 93 | 93 | 93 | 93 | 93 | 93 | 93 | | 93 |
| | 46 23 59 131 93 440 93 | 273 223 223 223 23 23 23 23 23 23 23 23 23 | 273 46 23 23 23 92 46 46 46 46 46 46 46 46 46 46 46 46 46 | 273 273 3 23 24 20 20 20 20 20 20 20 20 20 20 20 20 20 | 273 273 46 23 23 23 23 23 23 23 23 23 23 | $\begin{array}{cccccccccccccccccccccccccccccccccccc$ | $\begin{array}{cccccccccccccccccccccccccccccccccccc$ | 273 46 23 46 48 48 48 48 48 48 48 48 48 48 | $ \begin{array}{cccccccccccccccccccccccccccccccccccc$ | $ \begin{array}{cccccccccccccccccccccccccccccccccccc$ | | 121 231 241 251 251 251 251 251 251 251 25 | $ \begin{array}{cccccccccccccccccccccccccccccccccccc$ | $ \begin{array}{cccccccccccccccccccccccccccccccccccc$ | - 1 + 1 + 1 + 1 + 1 + 1 + 1 + 1 + 1 + 1 | - 1 + 1 + 1 + 1 + 1 + 1 + 1 + 1 + 1 + 1 | - 1 + 1 + 1 + 1 + 1 + 1 + 1 + 1 + 1 + 1 | - 1 + 1 + 1 + 1 + 1 + 1 + 1 + 1 + 1 + 1 | result of the series of the se | 1 1 | | + 1 + 1 + 1 + 1 + 1 + 1 + 1 + 1 + 1 + | + 1 + 1 + 1 + 1 + 1 + 1 + 1 + 1 + 1 + | s s s s s s s s s s s s s s s s s s s |

Tasks ordered by UNIFORMAT II Classifications. Unscheduled Maintenance Costs are not included. Based on a 50-Year Forecast. All costs expressed in (\$) 2012.

Maintain Exhaust Fan, Roof Mounted, 8,500 Cfm

Whitestone Research

05-Mar-13

| Building: Office Building | | | | Fa | cilit | y: Ma | arsha | ll Spa | ace F | light | Cent | er | | | | | | | | | | | | | |
|---|------|-------|-------|-------|-------|-------|--------|--------|-------|-------|------|-------|-------|-----|-----|------|-----|-------|-----|-----|-------|-----|--------|-----|-----|
| Building Num: 1045/62/178 | | | | | Cit | y: Hu | ntsvi | lle, A | L | | | | | | | | | | | | | | | | |
| Forecast Year: | 2038 | 9 | 0 | 1 | 2 | 2043 | 4 | 5 | 6 | 7 | 2048 | 9 | 0 | 1 | 2 | 2053 | 4 | 5 | 6 | 7 | 2058 | 9 | 0 | 1 | |
| Replace Pipe & Fittings, 3/4" Copper, Hot Water (20% of Pipe | | 818 | | | | | | | | | | | | | | | | | | | | | | | |
| Replace 10' Section, Pipe & Fittings, 3/4" Copper, Hot Water | | | | | | | | | | | | | | | | | | | | | | 40 | | | |
| Resolder Joint, Pipe & Fittings, 3/4" Copper, Hot Water | | | | | | | | | | | | 76 | | | | | | | | | | 76 | | | |
| Replace Pipe & Fittings, 3/4" Copper, Cold Water (20% of Pip | | 273 | | | | | | | | | | | | | | | | | | | | | | | |
| Replace 10' Section, Pipe & Fittings, 3/4" Copper, Cold Water | | | | | | | | | | | | | | | | | | | | | | 13 | | | |
| Replace Ball Valve, 4" | | | | 3,839 | | | | | | | | | | | | | | | | | 3,839 | | | | |
| Overhaul Circulator Pump, 3 HP, Hot Water | | | 46 | | | | | 46 | | | | | | | | | | 46 | | | | | 46 | | |
| Inspect & Lubricate Booster Pump, 1 1/2 HP | 23 | 23 | | 23 | 23 | 23 | 23 | 23 | 23 | 23 | 23 | 23 | 23 | 23 | 23 | 23 | 23 | 23 | 23 | 23 | 23 | 23 | | 23 | 23 |
| Overhaul Circulator Pump, 3 HP, Cold Water | | | 92 | | | | | 92 | | | | | | | | | | 92 | | | | | 92 | | |
| Inspect & Lubricate Circulator Pump, 3 HP, Cold Water | 46 | 46 | 46 | 46 | 46 | 46 | 46 | 46 | 46 | 46 | 46 | 46 | | 46 | 46 | 46 | 46 | 46 | 46 | 46 | 46 | 46 | 46 | 46 | 46 |
| Replace Circulator Pump, 1/2 HP, Hot Water | | | | | | | | | | | | | 2,863 | | | | | | | | | | | | |
| Overhaul Circulator Pump, 1/2 HP, Hot Water | | | 46 | | | | | 46 | | | | | | | | | | 46 | | | | | 46 | | |
| Inspect & Lubricate Circulator Pump, 1/2 HP, Hot Water | 23 | 23 | 23 | 23 | 23 | 23 | 23 | 23 | 23 | 23 | 23 | 23 | | 23 | 23 | 23 | 23 | 23 | 23 | 23 | 23 | 23 | 23 | 23 | 23 |
| Replace Assembly, Booster Pump, 1 1/2 HP | | | 6,131 | | | | | | | | | | | | | | | | | | | | 6,131 | | |
| Replace Pipe & Fittings, 2" Copper, Cold Water (20% of Pipe) | | 2,166 | | | | | | | | | | | | | | | | | | | | | | | |
| Resolder Joint, Pipe & Fittings, 3/4" Copper, Cold Water | | | | | | | | | | | | 25 | | | | | | | | | | 25 | | | |
| Replace Pump & Motor Assembly, Sump Pump, 3 HP | | | | | | | | | | | | | 2,819 | | | | | 2,819 | | | | | | | |
| Replace Air Compressor, 5 HP | | | | | | | | | | | | | | | | | | | | | | | 15,279 | | |
| Check & Adjust Compressed Air Dryer | 59 | 59 | 59 | 59 | 59 | 59 | 59 | 59 | 59 | 59 | 59 | 59 | | 59 | 59 | 59 | 59 | 59 | 59 | 59 | 59 | 59 | 59 | 59 | 59 |
| Recharge Compressed Air Dryer | | | 117 | | | | | 117 | | | | | | | | | | 117 | | | | | 117 | | |
| Replace Compressor, Compressed Air Dryer | | | | | | | | 2,868 | | | | | | | | | | | | | | | 2,868 | | |
| Replace Compressed Air Dryer | | | | | | | | | | | | | 8,485 | | | | | | | | | | | | |
| Check & Adjust, Air Compressor, 5 HP | 131 | 131 | 131 | 131 | 131 | 131 | 131 | 131 | 131 | 131 | 131 | 131 | 131 | 131 | 131 | 131 | 131 | 131 | 131 | 131 | 131 | 131 | | 131 | 131 |
| | | | | | | | | | | | | | | | | | | | | | | | | | |
| D30 HVAC | | | | | | | | | | | | | | | | | | | | | | | | | |
| Replace Duct Insulation (20% of Insulation) | | | | | | | 41,207 | | | | | | | | | | | | | | | | | | |
| Maintain Exhaust Fan, Roof Mounted, 800 Cfm | 93 | 93 | 93 | 93 | 93 | 93 | 93 | 93 | 93 | 93 | 93 | 93 | 93 | 93 | 93 | 93 | 93 | 93 | 93 | 93 | 93 | 93 | | 93 | 93 |
| Replace Supply Fan, Centrifugal, 60,000 Cfm | | | | | | | | | | | | | | | | | | | | | | | 83,147 | | |
| Repair Supply Fan, Centrifugal, 60,000 Cfm | | | | | | | | | | | | 2,221 | | | | | | | | | | | | | |
| Maintain Supply Fan, Centrifugal, 60,000 Cfm | 440 | 440 | 440 | 440 | 440 | 440 | 440 | 440 | 440 | 440 | 440 | 440 | 440 | 440 | 440 | 440 | 440 | 440 | 440 | 440 | 440 | 440 | | 440 | 440 |
| Replace Exhaust Fan, Centrifugal, 10,000 Cfm | | | | | | | | | | | | | | | | | | | | | | | 5,186 | | |
| Repair Exhaust Fan, Centrifugal, 10,000 Cfm | | | | | | | | | | | | 192 | | | | | | | | | | | | | |
| Maintain Exhaust Fan, Centrifugal, 10,000 Cfm | 93 | 93 | 93 | 93 | 93 | 93 | 93 | 93 | 93 | 93 | 93 | 93 | 93 | 93 | 93 | 93 | 93 | 93 | 93 | 93 | 93 | 93 | | 93 | 93 |
| Replace Exhaust Fan, Centrifugal, 5,000 Cfm | | | | | | | | | | | | | | | | | | | | | | | 3,186 | | |
| Repair Exhaust Fan, Centrifugal, 5,000 Cfm | | | | | | | | | | | | 192 | | | | | | | | | | | | | |
| Repair Exhaust Fan, Roof Mounted, 800 Cfm | | | | | | | | | | | | 192 | | | | | | | | | | | | | |
| | | | | | | | | | | | | | | | | | | | | | | | | | |

Tasks ordered by UNIFORMAT II Classifications. Unscheduled Maintenance Costs are not included. Based on a 50-Year Forecast.

All costs expressed in (\$) 2012.

Whitestone Research

05-Mar-13

| Building: Office Building | | | | Fa | acility | y: M | arsha | all Sp | ace | Flight | Cen | ter | | | | | | | | | | | | | |
|--|-------|--------|--------|---------|---------|-------------|--------|---------|-------|--------|-------|--------|--------|-------|-------|-------|---------|-------|-------|-------|-------|--------|--------|-------|-------|
| Building Num: 1045/62/178 | | | | | City | y: H | untsv | ille, A | ۹L | | | | | | | | | | | | | | | | |
| Forecast Year: | 2013 | 4 | 5 | 6 | | 2018 | 9 | 0 | 1 | 2 | 2023 | 4 | 5 | 6 | 7 | 2028 | 9 | 0 | 1 | 2 | 2033 | 4 | 5 | 6 | 7 |
| Replace Air Handler, Multizone, 100,000 Cfm | | | ŧ | 539,986 | | | | | | | | | | | | | 539,986 | | | | | | | | |
| Repair Air Handler, Multizone, 100,000 Cfm | | | | | | | | | | | | | 17,824 | | | | | | | | | | | | |
| Maintain Exhaust Fan, Centrifugal, 5,000 Cfm | 93 | 93 | 93 | 93 | 93 | 93 | 93 | 93 | 93 | 93 | 93 | 93 | 93 | 93 | 93 | 93 | 93 | 93 | 93 | 93 | 93 | 93 | 93 | | 93 |
| Maintain Variable Air Volume Control Box | 8,411 | 8,411 | 8,411 | 8,411 | 8,411 | 8,411 | 8,411 | 8,411 | 8,411 | 8,411 | 8,411 | | 8,411 | 8,411 | 8,411 | 8,411 | 8,411 | 8,411 | 8,411 | 8,411 | 8,411 | 8,411 | 8,411 | 8,411 | 8,411 |
| Replace Thermostat | | 53,197 | 33,691 | | | | | | | | | 53,197 | 33,691 | | | | | | | | | 53,197 | 33,691 | | |
| Replace HVAC Control Panel | | | | | | | | | | | | 3,354 | | | | | | | | | | | | | |
| Minor Repair, HVAC Control Panel | | 213 | | | | | 213 | | | | | | | | | | 213 | | | | | 213 | | | |
| Inspect & Maintain HVAC Control Panel | 47 | 47 | 47 | 47 | 47 | 47 | 47 | 47 | 47 | 47 | 47 | | 47 | 47 | 47 | 47 | 47 | 47 | 47 | 47 | 47 | 47 | 47 | 47 | 47 |
| Replace Direct Digital Controls, System Points | | | | | | | 70,327 | | | | | | | | | | 70,327 | | | | | | | | |
| Repair Exhaust Fan, Roof Mounted, 1,500 Cfm | | | | 777 | | | | | | | | | | | | | 777 | | | | | | | | |
| Replace Variable Air Volume Control Box | | | | | | | | | | | | 87,454 | | | | | | | | | | | | | |
| Replace Exhaust Fan, Roof Mounted, 800 Cfm | | | | | | | | | | | | | | | | | | | | | | | | 1,080 | |
| Replace Exhaust Fan, Roof Mounted, 8,500 Cfm | | | | | | | | | | | | | | | | | | | | | | | | 3,237 | |
| Repair Exhaust Fan, Roof Mounted, 8,500 Cfm | | | | 287 | | | | | | | | | | | | | 287 | | | | | | | | |
| Maintain Thermostat | 4,788 | 1,856 | 2,932 | 4,788 | 4,788 | 4,788 | 4,788 | 4,788 | 4,788 | 4,788 | 4,788 | 1,856 | 2,932 | 4,788 | 4,788 | 4,788 | 4,788 | 4,788 | 4,788 | 4,788 | 4,788 | 1,856 | 2,932 | 4,788 | 4,788 |
| Replace Exhaust Fan, Roof Mounted, 1,500 Cfm | | | | | | | | | | | | | | | | | | | | | | | | 4,866 | |
| Maintain Air Handler, Multizone, 100,000 Cfm | 1,943 | 1,943 | 1,943 | | 1,943 | 1,943 | 1,943 | 1,943 | 1,943 | 1,943 | 1,943 | 1,943 | 1,943 | 1,943 | 1,943 | 1,943 | | 1,943 | 1,943 | 1,943 | 1,943 | 1,943 | 1,943 | 1,943 | 1,943 |
| Maintain Exhaust Fan, Roof Mounted, 1,500 Cfm | 356 | 356 | 356 | 356 | 356 | 356 | 356 | 356 | 356 | 356 | 356 | 356 | 356 | 356 | 356 | 356 | 356 | 356 | 356 | 356 | 356 | 356 | 356 | | 356 |
| Monitor Direct Digital Controls, System Points | 2,228 | 2,228 | 2,228 | 2,228 | 2,228 | 2,228 | | 2,228 | 2,228 | 2,228 | 2,228 | 2,228 | 2,228 | 2,228 | 2,228 | 2,228 | | 2,228 | 2,228 | 2,228 | 2,228 | 2,228 | 2,228 | 2,228 | 2,228 |
| Replace 10' Section, Pipe & Fittings, 3" Steel | | | | | | | | | | | | 73 | | | | | | | | | | | | 73 | |
| Replace Ball Valve, 4" | | 3,841 | | | | | | | | | | | | | | | | | | | | | | | |
| Lubricate, Repack Gland, Ball Valve, 4" | 279 | | 279 | 279 | 279 | 279 | 279 | 279 | 279 | 279 | 279 | 279 | 279 | 279 | 279 | 279 | 279 | 279 | 279 | 279 | 279 | 279 | 279 | 279 | 279 |
| Replace Pipe Insulation, Fiberglass, Heating Water/Steam (20 | | 1,096 | | | | | | | | | | | | | | | | | | | | | | | |
| Replace Pipe & Fittings, 6" Steel (20% of Pipe) | | | | | | | | | | | | | | | | | | | | | | | | | |
| Replace 10' Section, Pipe & Fittings, 6" Steel | | | | | | | | | | | | 126 | | | | | | | | | | | | 126 | |
| Maintain Circulation Pump, 10 HP, Chiller & Condenser Water | 84 | 84 | 84 | 84 | 84 | 84 | 84 | 84 | 84 | 84 | 84 | 84 | 84 | 84 | 84 | 84 | 84 | 84 | 84 | 84 | | 84 | 84 | 84 | 84 |
| Install New Gasket & Bolts, Pipe & Fittings, 3" Steel | | 29 | | | | | | | | | | | | | | | | | | | | | | | |
| Re-tape Pipe Insulation, Fiberglass, Heating Water/Steam | | | | | | | 260 | | | | | 260 | | | | | 260 | | | | | 260 | | | |
| Replace Pipe & Fittings, 2" Steel (20% of Pipe) | | | | | | | | | | | | | | | | | | | | | | | | | |
| Install New Gasket & Bolts, Pipe & Fittings, 2" Steel | | 58 | | | | | | | | | | | | | | | | | | | | | | | |
| Replace 10' Section, Pipe & Fittings, 2" Steel | | | | | | | | | | | | 103 | | | | | | | | | | | | 103 | |
| Maintain Expansion Tank, 10 Gal. | 19 | 19 | 19 | 19 | 19 | 19 | 19 | 19 | 19 | 19 | 19 | 19 | 19 | 19 | 19 | 19 | 19 | 19 | 19 | 19 | 19 | 19 | 19 | 19 | 19 |
| Replace Expansion Tank, 10 Gal. | | | | | | | | | | | | | | | | | | | | | | | | | |
| Replace Pipe Insulation, Fiberglass, Chilled Water (20% of Ins | | 904 | | | | | | | | | | | | | | | | | | | | | | | |
| Replace Pipe & Fittings, 3" Steel (20% of Pipe) | | | | | | | | | | | | | | | | | | | | | | | | | |
| Replace Pipe & Fittings, 6" Steel (20% of Pipe) | | | | | | | | | | | | | | | | | | | | | | | | | |
| Re-tape Pipe Insulation, Fiberglass, Chilled Water | | | | | | | 298 | | | | | 298 | | | | | 298 | | | | | 298 | | | |

Tasks ordered by UNIFORMAT II Classifications. Unscheduled Maintenance Costs are not included. Based on a 50-Year Forecast. All costs expressed in (\$) 2012.

Whitestone Research

05-Mar-13

| Building: Office Building | | | | Fa | acilit | y: M | arsha | all Sp | ace | Flight | Cer | iter | | | | | | | | | | | | | |
|---|--------|--------|-------|-------|---------|-------------|--------|----------|-------|--------|-------|--------|-------|--------|-------|-------|--------|---------|-------|-------|-------|--------|-------|-------|-------|
| Building Num: 1045/62/178 | | | | | Cit | y: H | untsv | ville, A | ۱L | | | | | | | | | | | | | | | | |
| Forecast Year: | 2038 | 9 | 0 | 1 | 2 | 2043 | 4 | 5 | 6 | 7 | 2048 | 9 | 0 | 1 | 2 | 2053 | 4 | 5 | 6 | 7 | 2058 | 9 | 0 | 1 | 2 |
| Replace Air Handler, Multizone, 100,000 Cfm | | | | 1 | 539,986 | | | | | | | | | | | | 1 | 539,986 | | | | | | | |
| Repair Air Handler, Multizone, 100,000 Cfm | 17,824 | | | | | | | | | | | | | 17,824 | | | | | | | | | | | |
| Maintain Exhaust Fan, Centrifugal, 5,000 Cfm | 93 | 93 | 93 | 93 | 93 | 93 | 93 | 93 | 93 | 93 | 93 | 93 | 93 | 93 | 93 | 93 | 93 | 93 | 93 | 93 | 93 | 93 | | 93 | 93 |
| Maintain Variable Air Volume Control Box | 8,411 | 8,411 | 8,411 | 8,411 | 8,411 | 8,411 | | 8,411 | 8,411 | 8,411 | 8,411 | 8,411 | 8,411 | 8,411 | 8,411 | 8,411 | 8,411 | 8,411 | 8,411 | 8,411 | 8,411 | 8,411 | 8,411 | 8,411 | 8,411 |
| Replace Thermostat | | | | | | | 53,197 | 33,691 | | | | | | | | | 53,197 | 33,691 | | | | | | | |
| Replace HVAC Control Panel | | 3,354 | | | | | | | | | | | | | | | 3,354 | | | | | | | | |
| Minor Repair, HVAC Control Panel | | | | | | | 213 | | | | | 213 | | | | | | | | | | 213 | | | |
| Inspect & Maintain HVAC Control Panel | 47 | | 47 | 47 | 47 | 47 | 47 | 47 | 47 | 47 | 47 | 47 | 47 | 47 | 47 | 47 | | 47 | 47 | 47 | 47 | 47 | 47 | 47 | 47 |
| Replace Direct Digital Controls, System Points | | 70,327 | | | | | | | | | | 70,327 | | | | | | | | | | 70,327 | | | |
| Repair Exhaust Fan, Roof Mounted, 1,500 Cfm | | | | | | | | | | | | 777 | | | | | | | | | | | | | |
| Replace Variable Air Volume Control Box | | | | | | | 87,454 | | | | | | | | | | | | | | | | | | |
| Replace Exhaust Fan, Roof Mounted, 800 Cfm | | | | | | | | | | | | | | | | | | | | | | | 1,080 | | |
| Replace Exhaust Fan, Roof Mounted, 8,500 Cfm | | | | | | | | | | | | | | | | | | | | | | | 3,237 | | |
| Repair Exhaust Fan, Roof Mounted, 8,500 Cfm | | | | | | | | | | | | 287 | | | | | | | | | | | | | |
| Maintain Thermostat | 4,788 | 4,788 | 4,788 | 4,788 | 4,788 | 4,788 | 1,856 | 2,932 | 4,788 | 4,788 | 4,788 | 4,788 | 4,788 | 4,788 | 4,788 | 4,788 | 1,856 | 2,932 | 4,788 | 4,788 | 4,788 | 4,788 | 4,788 | 4,788 | 4,788 |
| Replace Exhaust Fan, Roof Mounted, 1,500 Cfm | | | | | | | | | | | | | | | | | | | | | | | 4,866 | | |
| Maintain Air Handler, Multizone, 100,000 Cfm | 1,943 | 1,943 | 1,943 | 1,943 | | 1,943 | 1,943 | 1,943 | 1,943 | 1,943 | 1,943 | 1,943 | 1,943 | 1,943 | 1,943 | 1,943 | 1,943 | | 1,943 | 1,943 | 1,943 | 1,943 | 1,943 | 1,943 | 1,943 |
| Maintain Exhaust Fan, Roof Mounted, 1,500 Cfm | 356 | 356 | 356 | 356 | 356 | 356 | 356 | 356 | 356 | 356 | 356 | 356 | 356 | 356 | 356 | 356 | 356 | 356 | 356 | 356 | 356 | 356 | | 356 | 356 |
| Monitor Direct Digital Controls, System Points | 2,228 | | 2,228 | 2,228 | 2,228 | 2,228 | 2,228 | 2,228 | 2,228 | 2,228 | 2,228 | | 2,228 | 2,228 | 2,228 | 2,228 | 2,228 | 2,228 | 2,228 | 2,228 | 2,228 | | 2,228 | 2,228 | 2,228 |
| Replace 10' Section, Pipe & Fittings, 3" Steel | | | | | | | | | | | | | | 73 | | | | | | | | | | | |
| Replace Ball Valve, 4" | 3,841 | | | | | | | | | | | | | | | | | | | | | | | | 3,841 |
| Lubricate, Repack Gland, Ball Valve, 4" | | 279 | 279 | 279 | 279 | 279 | 279 | 279 | 279 | 279 | 279 | 279 | 279 | 279 | 279 | 279 | 279 | 279 | 279 | 279 | 279 | 279 | 279 | 279 | |
| Replace Pipe Insulation, Fiberglass, Heating Water/Steam (20 | | 1,096 | | | | | | | | | | | | | | | | | | | | | | | |
| Replace Pipe & Fittings, 6" Steel (20% of Pipe) | | 2,549 | | | | | | | | | | | | | | | | | | | | | | | |
| Replace 10' Section, Pipe & Fittings, 6" Steel | | | | | | | | | | | | | | 126 | | | | | | | | | | | |
| Maintain Circulation Pump, 10 HP, Chiller & Condenser Water | 84 | 84 | 84 | 84 | 84 | 84 | 84 | 84 | 84 | 84 | 84 | 84 | 84 | 84 | 84 | 84 | 84 | 84 | | 84 | 84 | 84 | 84 | 84 | 84 |
| Install New Gasket & Bolts, Pipe & Fittings, 3" Steel | | | | | | | | | | | | | | | | | | | | | | | | | |
| Re-tape Pipe Insulation, Fiberglass, Heating Water/Steam | | | | | | | 260 | | | | | 260 | | | | | 260 | | | | | 260 | | | |
| Replace Pipe & Fittings, 2" Steel (20% of Pipe) | | 2,058 | | | | | | | | | | | | | | | | | | | | | | | |
| Install New Gasket & Bolts, Pipe & Fittings, 2" Steel | | | | | | | | | | | | | | | | | | | | | | | | | |
| Replace 10' Section, Pipe & Fittings, 2" Steel | | | | | | | | | | | | | | 103 | | | | | | | | | | | |
| Maintain Expansion Tank, 10 Gal. | 19 | 19 | 19 | 19 | 19 | 19 | 19 | 19 | 19 | 19 | 19 | 19 | | 19 | 19 | 19 | 19 | 19 | 19 | 19 | 19 | 19 | 19 | 19 | 19 |
| Replace Expansion Tank, 10 Gal. | | | | | | | | | | | | | 758 | | | | | | | | | | | | |
| Replace Pipe Insulation, Fiberglass, Chilled Water (20% of In | | 904 | | | | | | | | | | | | | | | | | | | | | | | |
| Replace Pipe & Fittings, 3" Steel (20% of Pipe) | | 1,456 | | | | | | | | | | | | | | | | | | | | | | | |
| Replace Pipe & Fittings, 6" Steel (20% of Pipe) | | 1,020 | | | | | | | | | | | | | | | | | | | | | | | |
| Re-tape Pipe Insulation, Fiberglass, Chilled Water | | | | | | | 298 | | | | | 298 | | | | | 298 | | | | | 298 | | | |

M&R Costs by Task Whitestone Research 05-Mar-13 Building: Office Building Facility: Marshall Space Flight Center City: Huntsville, AL Building Num: 1045/62/178 Forecast Year: 7 2018 2 2023 2 2033 7 2028 Replace Pipe & Fittings, 8" Steel (20% of Pipe) Install New Gasket & Bolts, Pipe & Fittings, 6" Steel Replace 10' Section, Pipe & Fittings, 8" Steel Repair Circulation Pump, 10 HP, Chiller & Condenser Water Install New Gasket & Bolts, Pipe & Fittings, 6" Steel Replace 10' Section, Pipe & Fittings, 6" Steel Replace Pipe & Fittings, 4" Steel (20% of Pipe) Replace Circulation Pump, 10 HP, Chiller & Condenser Water 9,252 Replace 10' Section, Pipe & Fittings, 4" Steel Replace Pipe & Fittings, 2" Steel (20% of Pipe) Install New Gasket & Bolts, Pipe & Fittings, 2" Steel Replace 10' Section, Pipe & Fittings, 2" Steel Install New Gasket & Bolts, Pipe & Fittings, 4" Steel Install New Gasket & Bolts, Pipe & Fittings, 8" Steel **D40** Fire Protection Inspect & Test Fire Suppression System Water Pump, 10 HP Maintain Fire Suppression System Water Pump, 10 HP 5.476 5 476 Replace Fire Suppression System Water Pump, 10 HP Replace 10' Section, Pipe & Fittings, 2" Steel Install New Gasket & Bolts, Pipe & Fittings, 2" Steel Replace 10' Section, Pipe & Fittings, 3" Steel Replace Fire Department Connection, Siamese, 3" Install New Gasket & Bolts, Pipe & Fittings, 3" Steel Test Gages & Valves, Fire Sprinkler System Replace 10' Section, Pipe & Fittings, 4" Steel Install New Gasket & Bolts, Pipe & Fittings, 4" Steel Replace Fire Sprinkler Head Test Fire Sprinkler Head 18,874 18 874 18 874 Inspect Fire Sprinkler Head Replace Fire Alarm Control Panel 3.011 3.01 Repair Fire Alarm Control Panel Inspect & Test Fire Alarm Control Panel 1,377 1,377 1,377 1,377 1,377 1,377 1,377 1,377 1,377 1,377 1,377 1,377 1,377 1,377 1,377 1,377 1,377 1,377 Inspect & Maintain Fire Department Connection, Siamese, 3" 1.377 1.377 1.377 1.377 1.377 1.377 1.377 Replace Valves & Components, Sprinkler System 12.880 12.880 Maintain Fire Sprinkler System **D50 Electrical**

Tasks ordered by UNIFORMAT II Classifications. Unscheduled Maintenance Costs are not included. Based on a 50-Year Forecast.

M&R Costs by Task Whitestone Research 05-Mar-13 Facility: Marshall Space Flight Center **Building:** Office Building Building Num: 1045/62/178 City: Huntsville, AL Forecast Year: 2 2043 7 2048 2 2053 Replace Pipe & Fittings, 8" Steel (20% of Pipe) Install New Gasket & Bolts, Pipe & Fittings, 6" Steel Replace 10' Section, Pipe & Fittings, 8" Steel Repair Circulation Pump, 10 HP, Chiller & Condenser Water Install New Gasket & Bolts, Pipe & Fittings, 6" Steel Replace 10' Section, Pipe & Fittings, 6" Steel Replace Pipe & Fittings, 4" Steel (20% of Pipe) Replace Circulation Pump, 10 HP, Chiller & Condenser Water 9.252 Replace 10' Section, Pipe & Fittings, 4" Steel Replace Pipe & Fittings, 2" Steel (20% of Pipe) 2,807 Install New Gasket & Bolts, Pipe & Fittings, 2" Steel Replace 10' Section, Pipe & Fittings, 2" Steel Install New Gasket & Bolts, Pipe & Fittings, 4" Steel Install New Gasket & Bolts, Pipe & Fittings, 8" Steel **D40** Fire Protection Inspect & Test Fire Suppression System Water Pump, 10 HP Maintain Fire Suppression System Water Pump, 10 HP 5.476 5.476 Replace Fire Suppression System Water Pump, 10 HP Replace 10' Section, Pipe & Fittings, 2" Steel Install New Gasket & Bolts, Pipe & Fittings, 2" Steel Replace 10' Section, Pipe & Fittings, 3" Steel Replace Fire Department Connection, Siamese, 3" 13.57 Install New Gasket & Bolts, Pipe & Fittings, 3" Steel Test Gages & Valves, Fire Sprinkler System Replace 10' Section, Pipe & Fittings, 4" Steel Install New Gasket & Bolts, Pipe & Fittings, 4" Steel Replace Fire Sprinkler Head 41,186 Test Fire Sprinkler Head 18 874 Inspect Fire Sprinkler Head 3,011 Replace Fire Alarm Control Panel 3.011 Repair Fire Alarm Control Panel Inspect & Test Fire Alarm Control Panel 1,377 Inspect & Maintain Fire Department Connection, Siamese, 3" 1.377 1.377 1.377 1.377 Replace Valves & Components, Sprinkler System 12 880 Maintain Fire Sprinkler System

D50 Electrical

Tasks ordered by UNIFORMAT II Classifications. Unscheduled Maintenance Costs are not included. Based on a 50-Year Forecast.

Whitestone Research

05-Mar-13

| Biological stateBiological State <th <="" colspan="2" th=""><th>Building: Office Building</th><th></th><th></th><th></th><th>Fa</th><th>cility</th><th>y: M</th><th>arsha</th><th>all Sp</th><th>ace</th><th>Flight</th><th>Cen</th><th>ter</th><th></th><th></th><th></th><th></th><th></th><th></th><th></th><th></th><th></th><th></th><th></th><th></th><th></th></th> | <th>Building: Office Building</th> <th></th> <th></th> <th></th> <th>Fa</th> <th>cility</th> <th>y: M</th> <th>arsha</th> <th>all Sp</th> <th>ace</th> <th>Flight</th> <th>Cen</th> <th>ter</th> <th></th> | | Building: Office Building | | | | Fa | cility | y: M | arsha | all Sp | ace | Flight | Cen | ter | | | | | | | | | | | | | |
|--|---|--------|---------------------------|--------|-------|-------|-------------|--------|-------------|-------|--------|-------|--------|--------|-------|-------|-------|-------|---------|--------|-------|-------|-------|--------|-------|-------|--|--|
| Repaired problem in the stratement of the stratem | Building Num: 1045/62/178 | | | | | City | y: H | untsv | ille, / | ۹L | | | | | | | | | | | | | | | | | | |
| Region lighting Range, Maine Marke, Mark | Forecast Year: | 2013 | 4 | 5 | 6 | 7 | 2018 | 9 | 0 | 1 | 2 | 2023 | 4 | 5 | 6 | 7 | 2028 | 9 | 0 | 1 | 2 | 2033 | 4 | 5 | 6 | 7 | | |
| NameN | Replace Lamp, Incandescent Lighting Fixture, Basic, 100 w | | 117 | | | | | 117 | 270 | | | | | 270 | | | | 117 | 270 | | | | 117 | | | | | |
| Repine Match | Replace Incandescent Lighting Fixture, Basic, 100 w | | | 4,082 | | | | | | | | | 1,770 | | | | | | | | | | | 4,082 | | | | |
| Repair diversion of the set of the se | Replace Lamp, Metal Halide Lighting Fixture, Wall Mount, 150 | | | 382 | | | | | 382 | | | | | 382 | | | | | | | | | | 382 | | | | |
| <table-container>NameN</table-container> | Replace Ballast, Metal Halide Lighting Fixture, Wall Mount, 150 | | | | | | | | 803 | | | | | | | | | | | | | | | | | | | |
| Repair Mind DeckRepair Mind MinistrySubstrain Mind Mind Mind Mind Mind Mind Mind Mi | Replace Metal Halide Lighting Fixture, Wall Mount, 150 w | | | | | | | | | | | | | | | | | | 2,097 | | | | | | | | | |
| Replace Number of the series of the serie | Replace Receptacle, 120 V, 15 Amp. | | | 49,042 | | | | | | | | | 8,174 | 22,478 | | | | | | | | | | 49,042 | | | | |
| Annal PM, Motion Detector C28 | Repair Wiring Device, Switch | | 7,844 | 10,981 | | | | | | | | | | | | | | | | | | | 7,844 | 10,981 | | | | |
| <table-container>Android Private with the series of the se</table-container> | Replace Fluorescent Lighting Fixture, T8, 4-32 w | | | | | | | | | | | | | | | | | 2 | 233,734 | | | | | | | | | |
| Replace Wing Device, Swith the parameter of the second se | Annual PM, Motion Detector | 228 | 228 | 228 | 228 | 228 | 228 | 228 | | 228 | 228 | 228 | 228 | 228 | 228 | 228 | 228 | 228 | | 228 | 228 | 228 | 228 | 228 | 228 | 228 | | |
| Replace Transmission of the second of the s | Replace Lamp, Exit Lighting Fixture, w/ Battery | | | 215 | | | | | | | | | | 215 | | | | | 215 | | | | | 215 | | | | |
| Preparable and the problem of the | Replace Wiring Device, Switch | | | | | | | | | | | | 8,253 | 11,553 | | | | | | | | | | | | | | |
| Replace Motion DetectorConstrained with the second of the se | Replace Fluorescent Lighting Fixture, T8, 2-32 w | | | | | | | | | | | | 1,990 | | | | | | 57,687 | | | | | | | | | |
| Arrow <th< td=""><td>Replace Ballast & Lamps, Fluorescent Lighting Fixture, T8, 4-3</td><td></td><td></td><td></td><td></td><td></td><td></td><td>1</td><td>46,187</td><td></td><td></td><td></td><td></td><td></td><td></td><td></td><td></td><td></td><td></td><td></td><td></td><td></td><td></td><td></td><td></td><td></td></th<> | Replace Ballast & Lamps, Fluorescent Lighting Fixture, T8, 4-3 | | | | | | | 1 | 46,187 | | | | | | | | | | | | | | | | | | | |
| Maintain Card Reader 228 | Replace Motion Detector | | | | | | | | 23,517 | | | | | | | | | | 23,517 | | | | | | | | | |
| Applice Company Lighting Pack Light Mathematican Sequence Sequ | Replace Exit Lighting Fixture, w/ Battery | | | | | | | | 982 | | | | | | | | | | | | | | | | | | | |
| | Maintain Card Reader | 228 | 228 | 228 | | 228 | 228 | 228 | 228 | 228 | 228 | 228 | 228 | 228 | | 228 | 228 | 228 | 228 | 228 | 228 | 228 | 228 | 228 | | 228 | | |
| | Replace Emergency Lighting Pack, 2 Light w/ Battery | | | 20,114 | | | | | | | | | | | | | | | | | | | | 20,114 | | | | |
| Replace Compact Fluorescent Lighting Fixture, 32 with Replace Calibles & Lamps, Compact Fluorescent Lighting Fixture, 32 with Replace Calibles & Lamps, Compact Fluorescent Lighting Fixture, 32 with Replace Calibles & Lamps, Compact Fluorescent Lighting Fixture, 32 with Replace Calibles & Lamps, Compact Fluorescent Lighting Fixture, 32 with Replace Calibles & Lamps, Compact Fluorescent Lighting Fixture, 32 with Replace Calibles & Lamps, Compact Fluorescent Lighting Fixture, 32 with Replace Calibles & Lamps, Fluorescent Lighting Fixture, 32 with Replace Calibles & Lamps, Fluorescent Lighting Fixture, 32 with Replace Calibles & Lamps, Fluorescent Lighting Fixture, 32 with Replace Calibles & Lamps, Fluorescent Lighting Fixture, 32 with Replace Calibles & Lamps, Fluorescent Lighting Fixture, 32 with Replace Calibration 68,42 :::::::::::::::::::::::::::::::::::: | Replace Lens, Replace Emergency Lighting Pack, 2 Light w/ Ba | | | | | | | | | | | | | 622 | | | | | | | | | | | | | | |
| Replace Ballast Lamps, Compact Fluorescent Lighting Fixed 64.24 Image: Second Sec | Replace Lamp, Replace Emergency Lighting Pack, 2 Light w/ B | 1,263 | | | | 1,263 | | 1,263 | | 1,263 | | 1,263 | | 1,263 | | 1,263 | | 1,263 | | 1,263 | | 1,263 | | | | 1,263 | | |
| Replace Variable Frequency Drive, <600V 68,47 <td>Replace Compact Fluorescent Lighting Fixture, 32 w</td> <td></td> <td></td> <td></td> <td></td> <td></td> <td></td> <td></td> <td>12,876</td> <td></td> | Replace Compact Fluorescent Lighting Fixture, 32 w | | | | | | | | 12,876 | | | | | | | | | | | | | | | | | | | |
| Replace Coil, Variable Frequency Drive, <600V (I) < | Replace Ballast & Lamps, Compact Fluorescent Lighting Fixtur | | | | | | | | | | | | | | | | | | 11,414 | | | | | | | | | |
| Replace Ballast & Lamps, Fluorescent Lighting Fixture, T8, 2-3 1.244 :::::::::::::::::::::::::::::::::::: | Replace Variable Frequency Drive, <600V | 68,424 | | | | | | | | | | | | | | | | | | 68,424 | | | | | | | | |
| Check & Repair Manual Pull Station Cell Cell< | Replace Coil, Variable Frequency Drive, <600V | | | | | | 665 | | | | | 665 | | | | | 665 | | | | | | | | 665 | | | |
| Inspect & Clean Variable Frequency Drive, <600 V 28 286 | Replace Ballast & Lamps, Fluorescent Lighting Fixture, T8, 2-3 | | 1,244 | | | | | | 36,080 | | | | | | | | | | | | | | 1,244 | | | | | |
| Replace Lightning Protection General Wring 2.819 | Check & Repair Manual Pull Station | | | | | | | | | | | | | 1,275 | | | | | | | | | | | | | | |
| Maintain & Repair, Grounding System 67 | Inspect & Clean Variable Frequency Drive, <600 V | | 286 | 286 | 286 | 286 | 286 | 286 | 286 | 286 | 286 | 286 | 286 | 286 | 286 | 286 | 286 | 286 | 286 | | 286 | 286 | 286 | 286 | 286 | 286 | | |
| Maintain & Repair General Wiring, Lightning Protection System 90 | Replace Lightning Protection General Wiring | | 2,819 | | | | | | | | | | | | | | | | | 10,585 | | | | | | | | |
| Replace Disconnect Switch, 30 Amp. 978 Replace Smoke Detector 46,238 46,238 46,238 | Maintain & Repair, Grounding System | 67 | | 67 | 67 | 67 | 67 | 67 | 67 | 67 | 67 | 67 | 67 | 67 | 67 | 67 | 67 | 67 | 67 | 67 | 67 | 67 | 67 | 67 | 67 | 67 | | |
| Replace Smoke Detector 46,238 46,238 | Maintain & Repair General Wiring, Lightning Protection System | 90 | 90 | 90 | 90 | 90 | 90 | 90 | 90 | 90 | 90 | 90 | 90 | 90 | 90 | 90 | 90 | 90 | 90 | | 90 | 90 | 90 | 90 | 90 | 90 | | |
| | Replace Disconnect Switch, 30 Amp. | | 978 | | | | | | | | | | | | | | | | | | | | | | | | | |
| Annual PM, Grounding System 68 68 68 68 68 68 68 68 68 68 68 68 68 | Replace Smoke Detector | | | 46,238 | | | | | | | | | | | | | | | 46,238 | | | | | | | | | |
| | | 68 | | 68 | 68 | 68 | 68 | 68 | 68 | 68 | 68 | 68 | 68 | 68 | 68 | 68 | 68 | 68 | 68 | 68 | 68 | 68 | 68 | 68 | 68 | 68 | | |
| Repair Smoke Detector 12,465 | | | | | | | | | | | | | | 12,465 | | | | | | | | | | | | | | |
| Replace Batteries & Check Operation, Smoke Detector 5,654 5, | | 5,654 | 5,654 | | 5,654 | 5,654 | 5,654 | 5,654 | 5,654 | 5,654 | 5,654 | 5,654 | 5,654 | 5,654 | 5,654 | 5,654 | 5,654 | 5,654 | | 5,654 | 5,654 | 5,654 | 5,654 | 5,654 | 5,654 | 5,654 | | |
| Replace Public Address Speaker 2,737 5,749 | | | | | | | | | | | | | 2,737 | 5,749 | | | | | | | | | | | | | | |
| Maintain Camera, Interior, Closed Circuit, PTZ B/W 400 400 400 400 400 400 400 400 400 40 | | 400 | 400 | 400 | | 400 | 400 | 400 | 400 | 400 | 400 | 400 | 400 | 400 | | 400 | 400 | 400 | 400 | 400 | 400 | 400 | 400 | 400 | | 400 | | |
| Replace Manual Pull Station 2,946 2,946 | | | | | | | | | | | | | | | | | | | | | | | | | | | | |

Tasks ordered by UNIFORMAT II Classifications. Unscheduled Maintenance Costs are not included. Based on a 50-Year Forecast.

Whitestone Research

05-Mar-13

| Building: Office Building | | | | Fa | acilit | y: M | arsha | all Sp | ace l | Flight | Cen | ter | | | | | | | | | | | | | |
|--|-------|-------|---------|-------|--------|--------------|-------|---------|-------|--------|-------|--------|---------|-------|-------|-------|-------|--------|--------|-------|-------|-------|--------|-------|-------|
| Building Num: 1045/62/178 | | | | | Cit | y: Hu | untsv | ille, A | ۱L | | | | | | | | | | | | | | | | |
| Forecast Year: | 2038 | 9 | 0 | 1 | 2 | 2043 | 4 | 5 | 6 | 7 | 2048 | 9 | 0 | 1 | 2 | 2053 | 4 | 5 | 6 | 7 | 2058 | 9 | 0 | 1 | 2 |
| Replace Lamp, Incandescent Lighting Fixture, Basic, 100 w | | 117 | 270 | | | | | 270 | | | | 117 | 270 | | | | 117 | | | | | 117 | 270 | | |
| Replace Incandescent Lighting Fixture, Basic, 100 w | | | | | | | 1,770 | | | | | | | | | | | 4,082 | | | | | | | |
| Replace Lamp, Metal Halide Lighting Fixture, Wall Mount, 150 | | | 382 | | | | | 382 | | | | | | | | | | 382 | | | | | 382 | | |
| Replace Ballast, Metal Halide Lighting Fixture, Wall Mount, 15 | | | 803 | | | | | | | | | | | | | | | | | | | | 803 | | |
| Replace Metal Halide Lighting Fixture, Wall Mount, 150 w | | | | | | | | | | | | | 2,097 | | | | | | | | | | | | |
| Replace Receptacle, 120 V, 15 Amp. | | | | | | | 8,174 | 22,478 | | | | | | | | | | 49,042 | | | | | | | |
| Repair Wiring Device, Switch | | | | | | | | | | | | 7,844 | 10,981 | | | | | | | | | | | | |
| Replace Fluorescent Lighting Fixture, T8, 4-32 w | | | | | | | | | | | | | 233,734 | | | | | | | | | | | | |
| Annual PM, Motion Detector | 228 | 228 | | 228 | 228 | 228 | 228 | 228 | 228 | 228 | 228 | 228 | | 228 | 228 | 228 | 228 | 228 | 228 | 228 | 228 | 228 | | 228 | 228 |
| Replace Lamp, Exit Lighting Fixture, w/ Battery | | | | | | | | 215 | | | | | 215 | | | | | 215 | | | | | | | |
| Replace Wiring Device, Switch | | 8,253 | 11,553 | | | | | | | | | | | | | | 8,253 | 11,553 | | | | | | | |
| Replace Fluorescent Lighting Fixture, T8, 2-32 w | | | | | | | 1,990 | | | | | | 57,687 | | | | | | | | | | | | |
| Replace Ballast & Lamps, Fluorescent Lighting Fixture, T8, 4- | | | 146,187 | | | | | | | | | | | | | | | | | | | 1 | 46,187 | | |
| Replace Motion Detector | | | 23,517 | | | | | | | | | | 23,517 | | | | | | | | | | 23,517 | | |
| Replace Exit Lighting Fixture, w/ Battery | | | 982 | | | | | | | | | | | | | | | | | | | | 982 | | |
| Maintain Card Reader | 228 | 228 | 228 | 228 | 228 | 228 | 228 | 228 | | 228 | 228 | 228 | 228 | 228 | 228 | 228 | 228 | 228 | | 228 | 228 | 228 | 228 | 228 | 228 |
| Replace Emergency Lighting Pack, 2 Light w/ Battery | | | | | | | | | | | | | | | | | | 20,114 | | | | | | | |
| Replace Lens, Replace Emergency Lighting Pack, 2 Light w/ | | | | | | | | 622 | | | | | | | | | | | | | | | | | |
| Replace Lamp, Replace Emergency Lighting Pack, 2 Light w/ | | 1,263 | | 1,263 | | 1,263 | | 1,263 | | 1,263 | | 1,263 | | 1,263 | | 1,263 | | | | 1,263 | | 1,263 | | 1,263 | |
| Replace Compact Fluorescent Lighting Fixture, 32 w | | | 12,876 | | | | | | | | | | | | | | | | | | | | 12,876 | | |
| Replace Ballast & Lamps, Compact Fluorescent Lighting Fixtu | | | | | | | | | | | | | 11,414 | | | | | | | | | | | | |
| Replace Variable Frequency Drive, <600V | | | | | | | | | | | | 68,424 | | | | | | | | | | | | | |
| Replace Coil, Variable Frequency Drive, <600V | | | | 665 | | | | | 665 | | | | | | | | 665 | | | | | 665 | | | |
| Replace Ballast & Lamps, Fluorescent Lighting Fixture, T8, 2- | | | 36,080 | | | | | | | | | | | | | | 1,244 | | | | | | 36,080 | | |
| Check & Repair Manual Pull Station | | | 1,275 | | | | | | | | | | | | | | | 1,275 | | | | | | | |
| Inspect & Clean Variable Frequency Drive, <600 V | 286 | 286 | 286 | 286 | 286 | 286 | 286 | 286 | 286 | 286 | 286 | | 286 | 286 | 286 | 286 | 286 | 286 | 286 | 286 | 286 | 286 | 286 | 286 | 286 |
| Replace Lightning Protection General Wiring | | 2,819 | | | | | | | | | | | | | | | | | 10,585 | | | | | | |
| Maintain & Repair, Grounding System | 67 | | 67 | 67 | 67 | 67 | 67 | 67 | 67 | 67 | 67 | 67 | 67 | 67 | 67 | 67 | 67 | 67 | 67 | 67 | 67 | 67 | 67 | 67 | 67 |
| Maintain & Repair General Wiring, Lightning Protection Syste | 90 | 90 | 90 | 90 | 90 | 90 | 90 | 90 | 90 | 90 | 90 | 90 | 90 | 90 | 90 | 90 | 90 | 90 | | 90 | 90 | 90 | 90 | 90 | 90 |
| Replace Disconnect Switch, 30 Amp. | | | 978 | | | | | | | | | | | | | | | | | | | | | | |
| Replace Smoke Detector | | | | | | | | 46,238 | | | | | | | | | | | | | | | 46,238 | | |
| Annual PM, Grounding System | 68 | | 68 | 68 | 68 | 68 | 68 | 68 | 68 | 68 | 68 | 68 | 68 | 68 | 68 | 68 | 68 | 68 | 68 | 68 | 68 | 68 | 68 | 68 | 68 |
| Repair Smoke Detector | | | 12,465 | | | | | | | | | | | | | | | 12,465 | | | | | | | |
| Replace Batteries & Check Operation, Smoke Detector | 5,654 | 5,654 | 5,654 | 5,654 | 5,654 | 5,654 | 5,654 | | 5,654 | 5,654 | 5,654 | 5,654 | 5,654 | 5,654 | 5,654 | 5,654 | 5,654 | 5,654 | 5,654 | 5,654 | 5,654 | 5,654 | | 5,654 | 5,654 |
| Replace Public Address Speaker | | 2,737 | 5,749 | | | | | | | | | | | | | | 2,737 | 5,749 | | | | | | | |
| Maintain Camera, Interior, Closed Circuit, PTZ B/W | 400 | 400 | 400 | 400 | 400 | 400 | 400 | 400 | | 400 | 400 | 400 | 400 | 400 | 400 | 400 | 400 | 400 | | 400 | 400 | 400 | 400 | 400 | 400 |
| Replace Manual Pull Station | | | | | | | | 2,946 | | | | | | | | | | | | | | | 2,946 | | |

Whitestone Research

05-Mar-13

| Building: Office Building | | | | Fa | cility | y: Ma | arsha | all Sp | ace I | Flight | t Cen | ter | | | | | | | | | | | | | |
|--|-------|-------|-----|--------|--------|--------------|-------|---------|-------|--------|-------|-------|-----|--------|-----|------|-----|--------|-------|-----|------|--------|-----|--------|-----|
| Building Num: 1045/62/178 | | | | | City | /: Hu | untsv | ille, A | L | | | | | | | | | | | | | | | | |
| Forecast Year: | 2013 | 4 | 5 | 6 | 7 | 2018 | 9 | 0 | 1 | 2 | 2023 | 4 | 5 | 6 | 7 | 2028 | 9 | 0 | 1 | 2 | 2033 | 4 | 5 | 6 | 7 |
| Maintain Camera, Exterior, Closed Circuit, PTZ B/W | 114 | 114 | 114 | | 114 | 114 | 114 | 114 | 114 | 114 | 114 | 114 | 114 | | 114 | 114 | 114 | 114 | 114 | 114 | 114 | 114 | 114 | | 114 |
| Replace Heat Detector | | | 251 | | | | | | | | | | | | | | | 251 | | | | | | | |
| Repair Heat Detector | | | | | | | | | | | | | 83 | | | | | | | | | | | | |
| Check Operation, Heat Detector | 37 | 37 | | 37 | 37 | 37 | 37 | 37 | 37 | 37 | 37 | 37 | 37 | 37 | 37 | 37 | 37 | | 37 | 37 | 37 | 37 | 37 | 37 | 37 |
| Replace Fire Alarm Horn & Strobe | | | | | | | | 6,368 | | | | | | | | | | | | | | | | | |
| Replace Electric Lock | | | | 1,004 | | | | | | | | | | 1,004 | | | | | | | | | | 1,004 | |
| Replace Card Reader | | | | 3,476 | | | | | | | | | | 3,476 | | | | | | | | | | 3,476 | |
| Replace Camera, Interior, Closed Circuit, PTZ B/W | | | | 16,875 | | | | | | | | | | 16,875 | | | | | | | | | | 16,875 | |
| Replace Camera, Interior, Closed Circuit, Fixed B/W | | | | 12,834 | | | | | | | | | | 12,834 | | | | | | | | | | 12,834 | |
| Maintain Camera, Interior, Closed Circuit, Fixed B/W | 514 | 514 | 514 | | 514 | 514 | 514 | 514 | 514 | 514 | 514 | 514 | 514 | | 514 | 514 | 514 | 514 | 514 | 514 | 514 | 514 | 514 | | 514 |
| Replace Camera, Exterior, Closed Circuit, PTZ B/W | | | | 5,858 | | | | | | | | | | 5,858 | | | | | | | | | | 5,858 | |
| Maintain Public Address Speaker | 585 | 585 | 585 | 585 | 585 | 585 | 585 | 585 | 585 | 585 | 585 | 396 | 189 | 585 | 585 | 585 | 585 | 585 | 585 | 585 | 585 | 585 | 585 | 585 | 585 |
| Replace Disconnect Switch, 400 Amp. | | 3,994 | | | | | | | | | | | | | | | | | | | | | | | |
| Repair Power Panel Board, 208 Y/120 V, 200 Amp. | | | | | | | | | | | | | | | | | | 92 | | | | | | | |
| Repair Disconnect Switch, 60 Amp. | | | | | | | | | | | | 368 | | | | | | | | | | 368 | | | |
| Replace Power Panel Board, 208 Y/120 V, 100 Amp. | | | | | | | | 19,495 | | | | 3,899 | | | | | | 11,697 | | | | | | | |
| Repair Power Panel Board, 208 Y/120 V, 100 Amp. | | 92 | | | | | | 276 | | | | | | | | | | 459 | | | | 92 | | | |
| Maintain Power Panel Board, 208 Y/120 V, 100 Amp. | 515 | 515 | 515 | 515 | 515 | 515 | 515 | 229 | 515 | 515 | 515 | 458 | 515 | 515 | 515 | 515 | 515 | 343 | 515 | 515 | 515 | 515 | 515 | 515 | 515 |
| Replace Motor Starter, 5-20 HP, <600 V | 1,357 | | | | | | | | | | | | | | | | | | 1,357 | | | | | | |
| Replace Coil, Motor Starter, 5-20 HP, <600 V | | | | 376 | | | 376 | | | 376 | | | 376 | | | 376 | | | | | | 376 | | | 376 |
| Inspect & Clean Motor Starter, 5-20 HP, <600 V | | 77 | 77 | 77 | 77 | 77 | 77 | 77 | 77 | 77 | 77 | 77 | 77 | 77 | 77 | 77 | 77 | 77 | | 77 | 77 | 77 | 77 | 77 | 77 |
| Replace Motor Starter, <5HP, <600V | 1,596 | | | | | | | | | | | | | | | | | | 1,596 | | | | | | |
| Replace Switchgear, Indoor, 600 V | | | | | | | | | | | | 4,193 | | | | | | | | | | | | | |
| Inspect & Clean Motor Starter, <5HP, <600V | | 115 | 115 | 115 | 115 | 115 | 115 | 115 | 115 | 115 | 115 | 115 | 115 | 115 | 115 | 115 | 115 | 115 | | 115 | 115 | 115 | 115 | 115 | 115 |
| Replace Power Panel Board, 208 Y/120 V, 200 Amp. | | | | | | | | 5,612 | | | | | | | | | | | | | | | | | |
| Repair Disconnect Switch, 400 Amp. | | | | | | | | | | | | 219 | | | | | | | | | | 219 | | | |
| Maintain Disconnect Switch, 400 Amp. | 54 | | 54 | 54 | 54 | 54 | 54 | 54 | 54 | 54 | 54 | 54 | 54 | 54 | 54 | 54 | 54 | 54 | 54 | 54 | 54 | 54 | 54 | 54 | 54 |
| Replace Disconnect Switch, 100 Amp. | | | | | | | | | | | | | | | | | | | | | | | | | |
| Repair Disconnect Switch, 100 Amp. | | | | | | | | 565 | | | | | | | | | | 565 | | | | | | | |
| Maintain Disconnect Switch, 100 Amp. | 213 | 213 | 213 | 213 | 213 | 213 | 213 | 213 | 213 | 213 | 213 | 213 | 213 | 213 | 213 | 213 | 213 | 213 | 213 | 213 | 213 | 213 | 213 | 213 | 213 |
| Replace Disconnect Switch, 60 Amp. | | 2,192 | | | | | | | | | | | | | | | | | | | | | | | |
| Maintain Disconnect Switch, 60 Amp. | 57 | | 57 | 57 | 57 | 57 | 57 | 57 | 57 | 57 | 57 | 57 | 57 | 57 | 57 | 57 | 57 | 57 | 57 | 57 | 57 | 57 | 57 | 57 | 57 |
| Repair Disconnect Switch, 30 Amp. | | | | | | | | 359 | | | | 359 | | | | | | 359 | | | | 359 | | | |
| Maintain Disconnect Switch, 30 Amp. | 113 | 57 | 113 | 113 | 113 | 113 | 113 | 113 | 113 | 113 | 113 | 113 | 113 | 113 | 113 | 113 | 113 | 113 | 113 | 113 | 113 | 113 | 113 | 113 | 113 |
| Replace Bus Duct & Fittings, AL, 800-4,000 Amp. | | | | | | | | | | | | | | | | | | | | | | 53,499 | | | |
| Replace Coil, Motor Starter, <5HP, <600V | | | | 565 | | | 565 | | | 565 | | | 565 | | | 565 | | | | | | 565 | | | 565 |
| Maintain Secondary Transformer, Dry, 2 kVA | 58 | 58 | 58 | 58 | 58 | 58 | 58 | 58 | 58 | 58 | 58 | | 58 | 58 | 58 | 58 | 58 | 58 | 58 | 58 | 58 | 58 | 58 | 58 | 58 |
| | | | | | | | | | | | | | | | | | | | | | | | | | |

Tasks ordered by UNIFORMAT II Classifications. Unscheduled Maintenance Costs are not included. Based on a 50-Year Forecast.

Whitestone Research

05-Mar-13

| Biblic bis |
|---|
| Animainal Camera, Exclosed Clicuit, PTZ BW 114 |
| Regiace Haddreed Detector And a |
| NameNa |
| Name Nam Name Name < |
| Replace find work \$1000000000000000000000000000000000000 |
| Replace Electric Lock Replace Electric Lock |
| Replace Card ReaderImage: Substrate Strate Stra |
| Replace Camera, Interior, Closed Circuit, Fixed B/W Fixed B/W 54* 514< |
| Replace Camera, Interior, Closed Circuit, Fixed BAWSetu<SetuSetuSetuSetuSetuSetuSetuSetuSetuSetuSetuSetuSetuSetuSetuSetuSetuSetu </td |
| Maintain Gramma, Interior, Closed Circuit, Fixed BW 514 515 515 515 515 |
| Replace Camera, Exterior, Closed Clircuit, PTZ BW 585 396 189 585 |
| Maintain Public Address Speaker 588 398 198 588 |
| Replace Disconnect Swith, 400 Amp. Figure Panel Board, 208 Y/120 V, 200 Amp. Image: Power Panel Board, 208 Y/120 V, 100 Amp. Image: Power Panel |
| Repair Power Panel Board, 208 Y/120 V, 200 Amp. 92 56 |
| Repair Disconnect Switch, 60 Amp. |
| Replace Power Panel Board, 208 Y/120 V, 100 Amp. Image: State of the state o |
| Repair Power Panel Board, 208 Y/120 V, 100 Amp. Fit Fit 92 Fit 515 |
| Maintain Power Panel Board, 208 Y/120 V, 100 Amp. 515 |
| Replace Motor Starter, 5-20 HP, <600 V 376< |
| Replace Coil, Motor Starter, 5-20 HP, <600 V 376 376 376 376 376 376 376 376 Inspect & Clean Motor Starter, 5-20 HP, <600 V |
| Inspect & Clean Motor Starter, 5-20 HP, <600 V 77 77 77 77 77 77 77 77 77 77 77 77 7 |
| |
| Replace Motor Starter, <5HP, <600V 1,596 |
| |
| Replace Switchgear, Indoor, 600 V 4,193 |
| Inspect & Clean Motor Starter, <5HP, <600V 115 115 115 115 115 115 115 115 115 11 |
| Replace Power Panel Board, 208 Y/120 V, 200 Amp. 5,612 |
| Repair Disconnect Switch, 400 Amp. 219 219 |
| Maintain Disconnect Switch, 400 Amp. 54 54 54 54 54 54 54 54 54 54 54 54 54 |
| Replace Disconnect Switch, 100 Amp. 4,850 |
| Repair Disconnect Switch, 100 Amp. 565 565 |
| Maintain Disconnect Switch, 100 Amp. 213 213 213 213 213 213 213 213 213 213 |
| Replace Disconnect Switch, 60 Amp. |
| Maintain Disconnect Switch, 60 Amp. 57 57 57 57 57 57 57 57 57 57 57 57 57 |
| Repair Disconnect Switch, 30 Amp. 359 359 359 359 359 |
| Maintain Disconnect Switch, 30 Amp. 113 113 113 113 113 113 113 113 113 11 |
| Replace Bus Duct & Fittings, AL, 800-4,000 Amp. |
| Replace Coil, Motor Starter, <5HP, <600V 565 565 565 565 565 565 565 565 |
| Maintain Secondary Transformer, Dry, 2 kVA 58 58 58 58 58 58 58 58 58 58 58 58 58 |

Tasks ordered by UNIFORMAT II Classifications. Unscheduled Maintenance Costs are not included. Based on a 50-Year Forecast.

Whitestone Research

05-Mar-13

| Building: Office Building | | | | Fa | cilit | y: Ma | arsha | ll Spa | ace F | Flight | Cen | ter | | | | | | | | | | | | | |
|--|------|-------|-----|-----|-------|--------------|-------|---------|-------|--------|------|--------|-----|-----|-----|------|-----|--------|-----|-----|------|-------|-----|-----|-----|
| Building Num: 1045/62/178 | | | | | Cit | y։ Hւ | untsv | ille, A | L | | | | | | | | | | | | | | | | |
| Forecast Year: | 2013 | 4 | 5 | 6 | 7 | 2018 | 9 | 0 | 1 | 2 | 2023 | 4 | 5 | 6 | 7 | 2028 | 9 | 0 | 1 | 2 | 2033 | 4 | 5 | 6 | 7 |
| Repair Switchgear, Indoor, 600 V (5% of total fuses) | | 410 | | | | | | | | | | | | | | | | | | | | 410 | | | |
| Maintain Switchgear, Indoor, 600 V | | | 28 | | | 28 | | | 28 | | | | | | 28 | | | 28 | | | 28 | | | 28 | |
| Replace Secondary Transformer, Dry, 75 kVA | | | | | | | | | | | | 18,985 | | | | | | | | | | | | | |
| Repair Secondary Transformer, Dry, 75 kVA | | 795 | | | | | | | | | | | | | | | | | | | | 795 | | | |
| Maintain Secondary Transformer, Dry, 75 kVA | 172 | 172 | 172 | 172 | 172 | 172 | 172 | 172 | 172 | 172 | 172 | | 172 | 172 | 172 | 172 | 172 | 172 | 172 | 172 | 172 | 172 | 172 | 172 | 172 |
| Replace Secondary Transformer, Dry, 30 kVA | | | | | | | | | | | | 4,456 | | | | | | | | | | | | | |
| Repair Secondary Transformer, Dry, 30 kVA | | 265 | | | | | | | | | | | | | | | | | | | | 265 | | | |
| Maintain Secondary Transformer, Dry, 30 kVA | 58 | 58 | 58 | 58 | 58 | 58 | 58 | 58 | 58 | 58 | 58 | | 58 | 58 | 58 | 58 | 58 | 58 | 58 | 58 | 58 | 58 | 58 | 58 | 58 |
| Maintain Power Panel Board, 208 Y/120 V, 200 Amp. | 58 | 58 | 58 | 58 | 58 | 58 | 58 | | 58 | 58 | 58 | 58 | 58 | 58 | 58 | 58 | 58 | 58 | 58 | 58 | 58 | 58 | 58 | 58 | 58 |
| Repair Secondary Transformer, Dry, 2 kVA | | 236 | | | | | | | | | | | | | | | | | | | | 236 | | | |
| Maintain Power Panel Board, 208 Y/120 V, 225 Amp. | 857 | 857 | 857 | 857 | 857 | 857 | 857 | 857 | 857 | 857 | 857 | | 857 | 857 | 857 | 857 | 857 | 857 | 857 | 857 | 857 | 857 | 857 | 857 | 857 |
| Replace Power Panel Board, 480 V, 400 Amp. | | | | | | | | | | | | 26,735 | | | | | | | | | | | | | |
| Repair Power Panel Board, 480 V, 400 Amp. | | 381 | | | | | | | | | | | | | | | | | | | | 381 | | | |
| Maintain Power Panel Board, 480 V, 400 Amp. | 172 | 172 | 172 | 172 | 172 | 172 | 172 | 172 | 172 | 172 | 172 | | 172 | 172 | 172 | 172 | 172 | 172 | 172 | 172 | 172 | 172 | 172 | 172 | 172 |
| Replace Power Panel Board, 480 V, 200 Amp. | | | | | | | | | | | | 38,159 | | | | | | | | | | | | | |
| Repair Power Panel Board, 480 V, 200 Amp. | | 459 | | | | | | | | | | | | | | | | | | | | 459 | | | |
| Maintain Power Panel Board, 480 V, 200 Amp. | 286 | 286 | 286 | 286 | 286 | 286 | 286 | 286 | 286 | 286 | 286 | | 286 | 286 | 286 | 286 | 286 | 286 | 286 | 286 | 286 | 286 | 286 | 286 | 286 |
| Replace Power Panel Board, 480 V, 100 Amp. | | | | | | | | | | | | 5,500 | | | | | | | | | | | | | |
| Repair Power Panel Board, 480 V, 100 Amp. | | 92 | | | | | | | | | | | | | | | | | | | | 92 | | | |
| Maintain Power Panel Board, 480 V, 100 Amp. | 58 | 58 | 58 | 58 | 58 | 58 | 58 | 58 | 58 | 58 | 58 | | 58 | 58 | 58 | 58 | 58 | 58 | 58 | 58 | 58 | 58 | 58 | 58 | 58 |
| Replace Power Panel Board, 208 Y/120 V, 225 Amp. | | | | | | | | | | | | 89,560 | | | | | | | | | | | | | |
| Repair Power Panel Board, 208 Y/120 V, 225 Amp. | | 1,375 | | | | | | | | | | | | | | | | | | | | 1,375 | | | |
| Replace Secondary Transformer, Dry, 2 kVA | | | | | | | | | | | | 2,191 | | | | | | | | | | | | | |
| | | | | | | | | | | | | | | | | | | | | | | | | | |
| E10 Equipment | | | | | | | | | | | | | | | | | | | | | | | | | |
| Replace Icemaker, Commercial | | | | | | | | 16,699 | | | | | | | | | | 16,699 | | | | | | | |
| Maintain Icemaker, Commercial | 826 | 826 | 826 | 826 | 826 | 826 | 826 | | 826 | 826 | 826 | 826 | 826 | 826 | 826 | 826 | 826 | | 826 | 826 | 826 | 826 | 826 | 826 | 826 |

Whitestone Research

05-Mar-13

| Building: Office Building | | | | Fa | cility | y: Ma | arsha | ll Spa | ace F | Flight | Cent | ter | | | | | | | | | | | | | |
|--|------|-----|--------|-----|--------|--------------|--------|---------|-------|--------|------|-----|--------|-----|-----|------|--------|-----|-----|-----|------|-----|--------|-----|-----|
| Building Num: 1045/62/178 | | | | | City | յ։ Hւ | intsvi | ille, A | L | | | | | | | | | | | | | | | | |
| Forecast Year: | 2038 | 9 | 0 | 1 | 2 | 2043 | 4 | 5 | 6 | 7 | 2048 | 9 | 0 | 1 | 2 | 2053 | 4 | 5 | 6 | 7 | 2058 | 9 | 0 | 1 | 2 |
| Repair Switchgear, Indoor, 600 V (5% of total fuses) | | | | | | | | | | | | | | | | | 410 | | | | | | | | |
| Maintain Switchgear, Indoor, 600 V | | 28 | | | 28 | | | | | 28 | | | 28 | | | 28 | | | 28 | | | 28 | | | 28 |
| Replace Secondary Transformer, Dry, 75 kVA | | | | | | | | | | | | | | | | | 18,985 | | | | | | | | |
| Repair Secondary Transformer, Dry, 75 kVA | | | | | | | 795 | | | | | | | | | | | | | | | | | | |
| Maintain Secondary Transformer, Dry, 75 kVA | 172 | 172 | 172 | 172 | 172 | 172 | 172 | 172 | 172 | 172 | 172 | 172 | 172 | 172 | 172 | 172 | | 172 | 172 | 172 | 172 | 172 | 172 | 172 | 172 |
| Replace Secondary Transformer, Dry, 30 kVA | | | | | | | | | | | | | | | | | 4,456 | | | | | | | | |
| Repair Secondary Transformer, Dry, 30 kVA | | | | | | | 265 | | | | | | | | | | | | | | | | | | |
| Maintain Secondary Transformer, Dry, 30 kVA | 58 | 58 | 58 | 58 | 58 | 58 | 58 | 58 | 58 | 58 | 58 | 58 | 58 | 58 | 58 | 58 | | 58 | 58 | 58 | 58 | 58 | 58 | 58 | 58 |
| Maintain Power Panel Board, 208 Y/120 V, 200 Amp. | 58 | 58 | 58 | 58 | 58 | 58 | 58 | 58 | 58 | 58 | 58 | 58 | | 58 | 58 | 58 | 58 | 58 | 58 | 58 | 58 | 58 | 58 | 58 | 58 |
| Repair Secondary Transformer, Dry, 2 kVA | | | | | | | 236 | | | | | | | | | | | | | | | | | | |
| Maintain Power Panel Board, 208 Y/120 V, 225 Amp. | 857 | 857 | 857 | 857 | 857 | 857 | 857 | 857 | 857 | 857 | 857 | 857 | 857 | 857 | 857 | 857 | | 857 | 857 | 857 | 857 | 857 | 857 | 857 | 857 |
| Replace Power Panel Board, 480 V, 400 Amp. | | | | | | | | | | | | | | | | | 26,735 | | | | | | | | |
| Repair Power Panel Board, 480 V, 400 Amp. | | | | | | | 381 | | | | | | | | | | | | | | | | | | |
| Maintain Power Panel Board, 480 V, 400 Amp. | 172 | 172 | 172 | 172 | 172 | 172 | 172 | 172 | 172 | 172 | 172 | 172 | 172 | 172 | 172 | 172 | | 172 | 172 | 172 | 172 | 172 | 172 | 172 | 172 |
| Replace Power Panel Board, 480 V, 200 Amp. | | | | | | | | | | | | | | | | | 38,159 | | | | | | | | |
| Repair Power Panel Board, 480 V, 200 Amp. | | | | | | | 459 | | | | | | | | | | | | | | | | | | |
| Maintain Power Panel Board, 480 V, 200 Amp. | 286 | 286 | 286 | 286 | 286 | 286 | 286 | 286 | 286 | 286 | 286 | 286 | 286 | 286 | 286 | 286 | | 286 | 286 | 286 | 286 | 286 | 286 | 286 | 286 |
| Replace Power Panel Board, 480 V, 100 Amp. | | | | | | | | | | | | | | | | | 5,500 | | | | | | | | |
| Repair Power Panel Board, 480 V, 100 Amp. | | | | | | | 92 | | | | | | | | | | | | | | | | | | |
| Maintain Power Panel Board, 480 V, 100 Amp. | 58 | 58 | 58 | 58 | 58 | 58 | 58 | 58 | 58 | 58 | 58 | 58 | 58 | 58 | 58 | 58 | | 58 | 58 | 58 | 58 | 58 | 58 | 58 | 58 |
| Replace Power Panel Board, 208 Y/120 V, 225 Amp. | | | | | | | | | | | | | | | | | 89,560 | | | | | | | | |
| Repair Power Panel Board, 208 Y/120 V, 225 Amp. | | | | | | | 1,375 | | | | | | | | | | | | | | | | | | |
| Replace Secondary Transformer, Dry, 2 kVA | | | | | | | | | | | | | | | | | 2,191 | | | | | | | | |
| E10 Equipment | | | | | | | | | | | | | | | | | | | | | | | | | |
| Replace Icemaker, Commercial | | | 16,699 | | | | | | | | | | 16,699 | | | | | | | | | | 16,699 | | |
| Maintain Icemaker, Commercial | 826 | 826 | | 826 | 826 | 826 | 826 | 826 | 826 | 826 | 826 | 826 | | 826 | 826 | 826 | 826 | 826 | 826 | 826 | 826 | 826 | | 826 | 826 |

Operation Costs Summary

Whitestone Research

Building: Office Building

Building Number: 1045/62/178


Facility: Marshall Space Flight Center

City: Huntsville, AL

Built Date: 1964

| GSFT: | 110,929 |
|--------------------|-----------------------|
| Replacement Value: | \$20,520,846 |
| Building Use: | Office |
| Building Type: | Engineering Office |

| Operation | Annual Cost/GSFT | Annual Total | Percent |
|----------------|---------------------|-----------------|---------|
| Custodial | \$0.736 | \$81,605 | 7.1% |
| Energy | \$1.046 | \$116,033 | 10.1% |
| Grounds | \$0.125 | \$13,910 | 1.2% |
| M&R | \$4.773 | \$529,409 | 46.0% |
| Management | \$0.462 | \$51,302 | 4.5% |
| Pest Control | \$0.067 | \$7,423 | 0.6% |
| Refuse | \$0.033 | \$3,682 | 0.3% |
| Road Clearance | \$0.002 | \$253 | 0.0% |
| Security | \$0.526 | \$58,384 | 5.1% |
| Telecom | \$2.532 | \$280,923 | 24.4% |
| Water/Sewer | \$0.082 | \$9,137 | 0.8% |
| Building Total | \$10.39 | \$1,152,060 | 100.0% |



Building Operations Task Details

Whitestone Research

| Building: Office | Building | Year Built: 1964 | Building Ty | pe: Engineering | Office |
|------------------------|-------------|--|-------------|-----------------|----------|
| Facility: Marsha | all Space I | Flight Center Original Cost: \$1 | Building Nu | im: 1045/62/178 | |
| City: Huntsv | ville, AL | Replacement Value: \$20,520,846 per SF: \$185 | Building G | sft: 110,929 | |
| Functional Area | FA GSFT | Task | Labor Cost | Material Cost | Task Cos |
| Operation: Custodial | | Level of Service: Low | | | |
| Office | 87633 | Vacuum Carpet with 14" Upright Vacuum | \$30,624 | \$4,976 | \$35,600 |
| Office | 87633 | Empty Trash; Wipe Clean & Re-line Basket | \$8,750 | \$1,422 | \$10,172 |
| Office | 87633 | Clean and Wipe Furniture with Trigger Sprayer & Cloth | \$5,371 | \$873 | \$6,244 |
| Office | 87633 | Dust Surfaces with Duster | \$4,038 | \$656 | \$4,695 |
| Office | 87633 | Vacuum Upholstered Furniture with Tank or Canister Vacuum | \$3,362 | \$546 | \$3,908 |
| Office | 87633 | Dust Window Blinds | \$1,938 | \$315 | \$2,253 |
| Mechanical/Equipment | 8874 | Sweep Hard Floor with 48" Push Broom | \$159 | \$26 | \$185 |
| Mechanical/Equipment | 8874 | Empty Trash; Wipe Clean & Re-line Basket | \$102 | \$17 | \$119 |
| Common/Circulation Are | 5546 | Vacuum Carpet with 14" Upright Vacuum | \$3,876 | \$630 | \$4,506 |
| Conference Room | 5546 | Vacuum Carpet with 14" Upright Vacuum | \$1,938 | \$315 | \$2,253 |
| Conference Room | 5546 | Clean and Wipe Furniture with Trigger Sprayer & Cloth | \$736 | \$120 | \$856 |
| Common/Circulation Are | 5546 | Empty Trash; Wipe Clean & Re-line Basket | \$554 | \$90 | \$644 |
| Common/Circulation Are | 5546 | Vacuum Upholstered Furniture with Tank or Canister Vacuum | \$426 | \$69 | \$495 |
| Conference Room | 5546 | Empty Trash; Wipe Clean & Re-line Basket | \$277 | \$45 | \$322 |
| Restroom | 3327 | Service Restroom: Empty Trash, Clean & Disinfect Fixtures, Wipe Mirrors, Replace Supplies, Wet | \$6,976 | \$1,134 | \$8,109 |
| Restroom | 3327 | Service Restroom: Empty Trash, Replace Supplies & Touch Up as Needed | \$1,070 | \$174 | \$1,243 |
| Total: | | | \$70,198 | \$11,407 | \$81,605 |
| Operation: Grounds | | Level of Service: Low | | | |
| Grounds, Improved | 66557 | Mow Turfgrass with 21" Power Mower | \$2,458 | \$1,022 | \$3,480 |
| Grounds, Improved | 66557 | Aerate Improved Grounds | \$1,907 | \$793 | \$2,700 |
| Grounds, Improved | 66557 | Clear Shrubs | \$1,592 | \$662 | \$2,255 |
| Grounds, Improved | 66557 | Edge Clean & Trim Walks with Gas Powered Edger | \$1,020 | \$424 | \$1,444 |
| Grounds, Improved | 66557 | Overseed, Improved Grounds | \$953 | \$397 | \$1,350 |
| Grounds, Improved | 66557 | Vacuum with 30" Billy Goat | \$637 | \$265 | \$902 |
| Grounds, Improved | 66557 | Clear Crabgrass | \$477 | \$198 | \$675 |
| Grounds, Improved | 66557 | Clear Weeds with 15" Boom, Improved Grounds | \$254 | \$106 | \$359 |
| Grounds, Improved | 66557 | Trim Around Raised Objects with String Edger | \$209 | \$87 | \$296 |

| Functional Area | FA GSFT | Task | Labor Cost | Material Cost | Task Cost |
|---------------------|---------|--|------------|---------------|-----------|
| Grounds, Improved | 66557 | Fertilize Improved Grounds | \$191 | \$79 | \$270 |
| Grounds, Improved | 66557 | Sweep with 30" Power Rake | \$126 | \$52 | \$178 |
| Grounds, Improved | 66557 | Fertilize Using Power Take Off Broadcast | \$O | \$0 | \$0 |
| Total: | | | \$9,823 | \$4,086 | \$13,910 |
| Operation: Pest Cor | ntrol | Level of Service: Medium | | | |
| Pest Controlled | 110929 | Install, or Check and Re-Bait 5 Rodent Boxes | \$2,563 | \$1,066 | \$3,629 |
| Pest Controlled | 110929 | Perform Crawling Insect Abatement | \$1,924 | \$800 | \$2,725 |
| Pest Controlled | 110929 | Inspect Building for Pests | \$1,070 | \$0 | \$1,070 |
| Total: | | | \$5,557 | \$1,867 | \$7,423 |
| Operation: Road Cle | earance | Level of Service: Medium | | | |
| Pavement NASA | 88743 | Plow Paved Area | \$195 | \$59 | \$253 |
| Total: | | | \$195 | \$59 | \$253 |
| Operation: Security | | Level of Service: Medium | | | |
| Secured Area | 110929 | Patrol Building Perimeter | \$21,085 | \$3,426 | \$24,511 |
| Secured Area | 110929 | Guard Lobby/Parking | \$0 | \$0 | \$0 |
| Total: | | | \$21,085 | \$3,426 | \$24,511 |

Building Operations Utility Details

Whitestone Research

| Building | : Office Building | Year Buil | lt: 1964 | | Building Typ | be: Engineering | Office |
|------------|-------------------|----------------------------|------------------------|---------------|--------------|------------------------|-----------|
| Facility | : Marshall Space | Flight Center Original Cos | st: \$1 | | Building Nu | m: 1045/62/178 | } |
| City | : Huntsville, AL | Replacement Value | e: \$20,520,846 | per SF: \$185 | Building G | sft: 110,929 | |
| | | Utility | GSFT | Demand | UM | Rate | Cost |
| Operation: | Energy | Level of Service: Medium | | | | | |
| | | Electricity | 110929 | 11.027 | kWh | \$0.0833 | \$101,897 |
| | | Natural Gas | 110929 | 0.161 | Thm | \$0.7900 | \$14,135 |
| | | Diesel | 110929 | 0.000 | Gal | \$3.2100 | \$0 |
| | | Total: | | 11.189 | | | \$116,033 |
| Operation: | Refuse | Level of Service: Medium | | | | | |
| | | Municipal Solid Waste | 110929 | 0.370 | Lbs | \$0.0717 | \$2,943 |
| | | Recycling | 110929 | 0.180 | Lbs | \$0.0370 | \$739 |
| | | Total: | | 0.550 | | | \$3,682 |
| Operation: | Water/Sewer | Level of Service: Medium | | | | | |
| | | Sewer | 110929 | 17.160 | Gal | \$0.0034 | \$6,472 |
| | | Water | 110929 | 21.840 | Gal | \$0.0011 | \$2,665 |
| | | Total: | | 39.000 | | | \$9,137 |

| Building Operations Mana | gement De | etails | | | Whitesto | ne Researc |
|------------------------------------|--------------|---------------------------------|---------------|----------|--------------------------|------------|
| Building: Office Building | | Year Built: 1964 | | Building | Type: Engineering | g Office |
| Facility: Marshall Space Flight Ce | nter | Original Cost: \$1 | | Building | Num: 1045/62/17 | 8 |
| City: Huntsville, AL | | Replacement Value: \$20,520,846 | per SF: \$185 | Building | Gsft: 110,929 | |
| | Service | | Demand | UM | PRV | Cost |
| Operation: Management Level o | Service: Low | | | | | |
| | Management | t | 0.3% | PRV | \$20,520,846 | \$51,302 |
| | Total: | | | | | \$51,302 |

| Operation: | Security | Level of Service: Medium | |
|------------|----------|-------------------------------|---------|
| | | Intrusion Detection Systems 3 | \$4,986 |
| | | System Monitoring 3 | \$3,615 |
| | | Access Control 3 | \$2,690 |
| | | Total: | |
| Operation: | Telecom | Level of Service: High | |
| | | Local Telephone 312 | \$468 |
| | | Data 312 | \$3,588 |
| | | Long Distance Telephone 312 | \$192 |
| | | Total: | |
| | | | |
| | | | |

Year Built: 1964

Replacement Value: \$20,520,846

Original Cost: \$1

FTEs: 312

per SF: \$185

Building Operations Service Details

Facility: Marshall Space Flight Center

Building: Office Building

City: Huntsville, AL

Whitestone Research

Cost

\$14,958 \$10,845 \$8,070 \$33,873

\$146,016 \$75,004 \$59,904 \$280,924

Building Type: Engineering Office

Rate

Building Num: 1045/62/178

Building Gsft: 110,929

Quantity

Service*