

15-Dec-2020 12:36

Start Template

Page 1

```
*-----Camio Version 8.1-----*
| Part Number:.... MOVEABLE SECTION | Revision:..... ;
| Job Number:..... 33221             | Operator:..... JH
| Customer:..... NOTRE DAME          | Serial #:..... 3
*-----*
```

(mm)	ACTUAL	NOMINAL	LO-TOL	HI-TOL	DEVIATION	GRAPHIC	ERROR
------	--------	---------	--------	--------	-----------	---------	-------

Temperature Compensation: OFF

*

*

SURFACE FLATNESS

=====

Plane:PLN001

Flatness	0.0009	0.0050				+*--	
----------	--------	--------	--	--	--	------	--

*

*

OVERALL WIDTH

=====

Point:PNT007

X-axis	19.9992	20.0000	-0.0040	+0.0040	-0.0008	--*+---	
--------	---------	---------	---------	---------	---------	---------	--

Point:PNT008

X-axis	19.9992	20.0000	-0.0040	+0.0040	-0.0008	--*+---	
--------	---------	---------	---------	---------	---------	---------	--

Point:PNT009

X-axis	19.9991	20.0000	-0.0040	+0.0040	-0.0009	--*+---	
--------	---------	---------	---------	---------	---------	---------	--

*

*

OVERALL LENGTH

=====

Point:PNT010

Y-axis	35.7500	35.7500	-0.0040	+0.0040	0.0000	---*---	
--------	---------	---------	---------	---------	--------	---------	--

Point:PNT011

Y-axis	35.7496	35.7500	-0.0040	+0.0040	-0.0004	---*---	
--------	---------	---------	---------	---------	---------	---------	--

Point:PNT012

Y-axis	35.7492	35.7500	-0.0040	+0.0040	-0.0008	--*+---	
--------	---------	---------	---------	---------	---------	---------	--

*

*

.500 THICKNESS

=====

Plane:PLN002

Z-axis	-0.5040	-0.5000	-0.0040	+0.0040	-0.0040	<--+---	0.0000
--------	---------	---------	---------	---------	---------	---------	--------

*

*

Duration 4 mins 48 secs

FAIL in:7 out:1

End of Report

=====