

UNCLASSIFIED

J. G. Parker

COPY



NATIONAL AERONAUTICS AND SPACE ADMINISTRATION

(JULY 26 LAUNCH)

* APOLLO 15

LM-10

BASIC LM CUE CARDS

INDEXING DATA


DATE	OPN	#	T	PGM	SUBJECT	SIGNATOR	LOC
5/10/71	MSC	00	Q	APD	*	WILKINS	CE0-13A

PREPARED BY

FLIGHT DATA SECTION

FLIGHT PLANNING BRANCH

CREW PROCEDURES DIVISION



MANNED SPACECRAFT CENTER
HOUSTON, TEXAS

MAY 10, 1971

(TRIM FRONT PAGE ON SOLID CROP MARKS; BACK PAGE ON DASH CROP MARKS.)

APOLLO 15

LM CUE CARDS

MAY 10, 1971

PREPARED BY:

C. E. WILKINS
BOOK MANAGER

APPROVED BY:

J. W. O'NEILL, CHIEF
FLIGHT PLANNING BRANCH
CREW PROCEDURES DIVISION

It is requested that any organization having comments, questions, or suggestions concerning this document contact C. E. Wilkins, TRW Task 81, Building 4, room 265, telephone 483-3953.

This document is under the configuration control of the Crew Procedures Control Board (CPCB). All proposed changes should be submitted to the Apollo Flight Data File Manager, T. W. Holloway, CG5, Building 4, room 230, telephone 483-4271.

Distribution of this document is controlled by Flight Data File Manager, T. W. Holloway, Flight Planning Branch, Crew Procedures Division.

DATE

DATE

LM CUE CARDS

LIST OF EFFECTIVE PAGES

Basic 5/10/71


PAGE		DATE
i	5/10/71
ii	5/10/71
iii	CUE CARD LOCATIONS	5/10/71
1	FT NM	5/10/71
	VELCRO LOCATIONS (BACK OF CARD)	5/10/71
2	S-BD ANTENNA ANGLES	5/10/71
	VELCRO LOCATIONS (BACK OF CARD)	5/10/71
3	DEDA ADDRESSES	5/10/71
	VELCRO LOCATIONS (BACK OF CARD)	5/10/71
4	DPS, APS, RCS	5/10/71
	VELCRO LOCATIONS (BACK OF CARD)	5/10/71
5	CDR BUS LOST	
	LMP BUS LOST	5/10/71
	VELCRO LOCATIONS (BACK OF CARD)	5/10/71
6	DPS PRE PRESS RNG	
	She PRESS RNG	5/10/71
	VELCRO LOCATIONS (BACK OF CARD)	5/10/71
7	LM COMM MODES	5/10/71
8	LOSS OF COMM (PDI)	
	LOSS OF COMM (EVA)	
	LM COORDINATES STEERABLE ANTENNA	5/10/71
9	ASCENT MONITOR CHART	5/10/71
	VELCRO LOCATIONS (BACK OF CARD)	5/10/71
10	DPS - ASCENT	
	NOUN LIST	
	RR RANGE	
	DAP DATA LOAD	
	NO6 OR N12 OPTION CODES	5/10/71
	VELCRO LOCATIONS (BACK OF CARD)	5/10/71
11	DESCENT PROCEDURE	
	VERB LIST	
	NOUN LIST	
	ALARM CODES	5/10/71
12	COAS BORESIGHT LOG	5/10/71
13	ABORT - OPS	
	MANUAL ABORTS	
	ABORT STAGE - ASC	
	INSERTION	5/10/71
	MANUAL STAGE	
	NO PDI +12 APS ABORT	5/10/71

LIST OF EFFECTIVE PAGES (CONT)

PAGE		DATE
14	DPS BURN	5/10/71
15	NO PDI +12 APS ABORT APS BURN	5/10/71
16	DPS ABORT INSERTION APS ABORT INSERTION ABORT RULES	5/10/71
17	STAGING DPS ABORT/APS INSERTION	5/10/71
18	ALARM CODES (PDI)	5/10/71
19	MISSION RULES NO GO'S	5/10/71
20	ABNORMAL VEHICLE DYNAMICS RAPID IMU REALIGN LIGHT/MEANING/IMMEDIATE ACTION	5/10/71
21	LIGHT/MEANING/IMMEDIATE ACTION (CONT)	5/10/71
22	DESCENT H vs HDOT VELCRO LOCATIONS (BACK OF CARD)	5/10/71
23	CDR WARNING LIGHTS	5/10/71
24	VELCRO LOCATION	5/10/71
25	BUS LOSS VELCRO LOCATIONS (BACK OF CARD)	5/10/71
26	CONTINGENCY EVT	5/10/71
27	SEVA ONE MAN EVA EVA 1 PREP EVA 2 PREP EVA 3 PREP	5/10/71

NOTE: These pages also serve as a table of contents.

LM CUE CARD LOCATIONS



CDR WARNING LIGHTS
ABOVE PANEL 1 #20

DPS ABORT
APS ABORT
ABORT
WARNING LIGHTS PROCEDURES

S-BAND ANTENNA ANGLES

COMM MODES

ABORT CARD
DESCENT PROCEDURES

M/6
APS BURN
DPS BURN
MISSION RULES

ASCENT #4
MONITOR
CHART
&
H vs HDOT #21

CDR BUS LOSS #12
FT VS NM #13

CDR BUS LOSS #19
STOWED UNLESS NEEDED


EVA CARDS

DEDA ADDRESSES

F13

813

ft	nm
500	= 0.08
1000	= 0.16
1500	= 0.25
2000	= 0.33
2500	= 0.41
3000	= 0.49
3500	= 0.58
4000	= 0.66
4500	= 0.74
5000	= 0.82
5500	= 0.91
6000	= 0.99
6500	= 1.07
7000	= 1.15
7500	= 1.23
8000	= 1.32
8500	= 1.40
9000	= 1.48
9500	= 1.56





5/10/71

5/10/71

S-BAND
ANTENNA ANGLES
DESCENT REFSMMAT

PAGE 2	YAW=0°		IGA (PITCH)
	ANTENNA		
	P	Y	
	72	-63	0
	53	-60	10
	38	-55	20
	26	-49	30
	17	-42	40
	8	-35	50
	7	-28	60
	-6	-21	70
	-13	-14	80
	-20	-7	90
	-26	-1	100
	-34	5	110
	-41	11	120
	-50	16	130
	-58	20	140
	-68	23	150
	282	25	160
	271	26	170
	261	26	180
	251	24	190
	241	21	200
	232	17	210
	223	12	220
	215	7	230
	208	1	240
	201	-6	250
	194	-12	260
	188	-19	270
	181	-26	280
	174	-33	290
	166	-40	300
	156	-47	310
	145	-53	320
	131	-59	330
	113	-62	340
	93	-64	350



DEDA ADDRESSES

Vi	433		V16N78 R/RDOT
HDOT	367(360 UPDATE)		V16N92 %THROT/HDOT/H
H	337(223 UPDATE)		V21N69 *RLS
Ha	315		
Hp	403	AUTO	MAN
Y	211(-)(100Ft)	417+1	
YDOT	270,263	411+1	411+0
R	317	621 R	415+1
RDOT	440	606+R NEXT	316 E R
e	277	-ROOT NEXT	503 E ROOT
		411+0 STOP	

12/01/5

5/10/75



F8

DPS	APS	RCS
<p>TEMP/PRESS MON</p> <p>>30 PSI @ PD!</p> <p>HELIUM NOM</p> <p>>1000<1150</p> <p>PSI PRE PCI</p>	<p>TEMP PRESS MON</p> <p>>78 PSI OX</p> <p>>114 PSI FU</p> <p>40 - 90°F</p> <p>ΔT<10°F NOM</p> <p>HELIUM NOM</p> <p>PRESS 3125 PSI</p>	<p>He >1400 PSI</p> <p>PRPLNT</p> <p>PRESS >100 PSI</p> <p>TEMP 40 - 100°F</p> <p>FUEL/OXID MANF</p> <p>PRESS >100 PSI</p> <p>ΔP <80 PSI</p> <p>QUAD TEMP >119°F</p> <p>(25 MIN TO FIRING)</p>

5/19/78

12/01/78

HOX
VEL CRD
1/8 SHIM

HOX
VEL CRD
1/8 SHIM

F12


COR BUS LOST

LMP BUS LOST

AGS, INV 2, SUIT FAN 2
 S-BD XMTR/RCVR-PRIM
 S-BD PWR AMPL-PRIM
 CDR AUDIO CONT-BU
 ACTIVATE SEC GLY LOOP
 SEE EPS 1, BLOCK 17

INV 1, SUIT FAN 1
 LMP AUDIO CONT - BU
 S-BD PWR AMPL - SEC
 ON VOICE - BU, BIDMED - OFF
 S-BD ANT - OMNI
 SEE EPS 1, BLOCK 28

5/10/71



812


5/10/71

F9

	DPS PRE FUEL	PRESS RING OXID
TEMP	50°-75°	50°-75°
PRESS	70-122	41-78

TIME	She PRESS RING
LOI ABORT	610-1130
DPS PRESS (106:20)	725-1320

5/10/71



5/10/71


LM COMM MODES

COMM BASIC CONFIGURATION	PRIOR TO DOCKING	PREP FOR UNDOCKING	LM RELAY WITH VHF RNG	CSM RELAY	LUMAR STAY	PLSS/EVCS WITH TV (EVA)	PLSS/EVCS WITH LCRU (EVA)
CB 11 ALL COMM CLOSED							
PNL 8 AUDIO SWITCHES							
S-BD T/R - T/R				REC			
ICS T/R - T/R							
RELAY ON/OFF - OFF							
MODE - ICS/PTT			VOX			VOX	VOX
AUDIO CONT - NORM							
VHF A - T/R					OFF	OFF	OFF
VHF B - OFF	RCV	RCV	RCV	REC	RCV		
VOX SENS - MAX INCR							
CB 16 ALL COMM CLOSED							
CB 18 TV - OPEN						CLOSED	OPEN
PNL 14 UPSQU - AS DES	ENABLE	ENABLE	ENABLE	OFF	OFF*	ENABLE	ENABLE
PNL 12 UPDATA LNK-OFF							
PNL 12 AUDIO SWITCHES							
S-BD T/R - T/R			RCV	REC			
ICS T/R - T/R							
RELAY ON/OFF - OFF			ON			ON	ON
MODE - ICS/PTT			VOX			VOX	VOX
AUDIO CONT - NORM							
VHF A - T/R					OFF		
VHF B - OFF	RCV	RCV	RCV	REC	RCV	RCV	RCV
VOX SENS - MAX INCR							
PNL 12 COMM SWITCHES							
S-BD MODULATE - FM						FM	FM
S-BD XMTR/RCVR - SEC							
S-BD PWR AMPL - PRIM							OFF
S-BD VOICE - VOICE							
S-BD PCM - PCM							
S-BD RNG - OFF/RESET		RANGE			AS REQ		
VHF A XMTR - VOICE	VOICE/RNG		VOICE OR VOICE/RNG	VOICE/RNG	OFF		
VHF A RCVR - ON			OFF	OFF			
VHF B XMTR - OFF				OFF	OFF		
VHF B RCVR - OFF	ON	ON	ON	ON		ON	ON
SQUELCH VHF A - NORM						N+1 1/2	N+1 1/2
SQUELCH VHF B - NORM						N+1 1/2	N+1 1/2
TLM BIOMED - AS REQ	RIGHT	LEFT	OFF			OFF	OFF
TLM PCM - HI		LO					
RECORDER - OFF	AS DES	AS DES	AS DES	AS DES	AS DES	ON	ON
PNL 12 COMM ANTENNAS							
TRACK MODE - AUTO					AS REQ	SLEW	SLEW
PITCH CONT - COMP #							
YAW CONT - COMP #							
S-BD SEL - SLEW					AS REQ	SLEW	SLEW
VHF SEL - AFT OR FWD					AFT	EVA	EVA

*DURING EVA - ENABLE.

5/10/71

B15



LOSS OF COMM (PDI)

- 1 VERIFY STANDARD COMM CONFIG
- 2 S-BD SIG STR LOW (<3.0)-REACQ WITH STEERABLE
- 3 STILL NO COMM(SIG STR LOW<3.0)-SELECT BEST OMNI
- 4 STILL NO COMM
ON VOICE BU, BIOMED - OFF (HOT MIKE)
- 5 STILL NO COMM
S-BD: XMTR/RCVR - PRIM AND PWR AMPL - SEC
- 6 60 SEC, STILL NO COMM
VOICE and FM
- 7 60 SEC, STILL NO COMM
CSM RELAY

PM

S-BD AUDIO (BOTH) - OFF
NOTIFY CSM TO CONFIG FOR RELAY

LOSS OF COMM (EVA)

- 1 CK COMM CBs
- 2 SEL ALT S-BD XMTR/RCVR
- 3 IF SIG STR METER < 3.9,
SEL STEERABLE ANT
- 4 CONFIG FOR CDR RELAY:
AUDIO (LMP) AUDIO (CDR)
RELAY-OFF RELAY-ON
VHF A-OFF VHF A-T/R
VHF B-OFF VHF B-RCV
IF COMM OK, PLSS MODE-AR
- 5 CONFIG LM TO B/U EVA MODE
XMTR A-OFF
XMTR B-VOICE
AUDIO (CDR)
VHF A-RCV
VHF B-T/R
PLSS MODE-A(CDR), B(LMP)
- 6 S-BD - ON VOICE BU
- 7 UPDATA LINK - VOICE BU
- 8 VHF ANT-AFT

LM COORD	STER ANT	
	PITCH	YAW
+X	90	-45
-X		
+Y	90	45
-Y		
+Z	0	0
-Z	180	0



B4

TF1	•	H	HOOT	OHW	He
:30	308	1.8	91	40	28
1:	305	5.1	124	38	26
1:30	302	9.2	151	35	25
2:	299	14.0	170	34	23
2:30	296	19.4	183	32	21
3:	292	25.0	189	29	20
3:30	289	30.7	190	27	18
4:	285	35.3	184	25	17
4:30	281	41.7	173	22	15
5:	278	45.6	156	19	14
5:30	273	51.0	135	17	12
6:	269	54.7	109	14	11
6:30	265	57.5	81	11	10
7:	260	59.5	50	8	8

LPD LOCAL HORIZONTAL = 8.5°




5-10-71

5-10-71

B6

F6



(DPS)-ASCENT
 (DECA GMBL AC-CLSD)
 S/C CB's(AEA)-CLSD
 (16)DISP OVRO-CLSD
 (THR AUTO-CDR)
 ATT TRANS-4 JETT
 BAL CPL - ON
 (ENG GMBL - ENABLE)
 (DES OVRO - OFF)
 AB/AB STG - RESET
 DB - MIN, RATE - 25
 ATT CONT(3) - MODE
 MODE CONT(2) - AUTO
 STOP(2) - RESET
 TTCA-(THR/-MIN)-JETT

	LM	CSM
400 nm	1.64	1.68
200 nm	1.94	2.02
100 nm	2.22	2.26
50 nm	2.42	2.48
25 nm	2.60	2.67
12.5 nm	2.74	2.83
6.25 nm	2.86	2.94
3.12 nm	2.94	3.02
2.0 nm	3.00	3.05
6000 ft	3.02	3.06
3000 ft	3.04	3.08
1500 ft	3.06	3.13
800 ft	3.12	3.22

49	54	55	56	60	63	64	
.ΔR	.RX	1/2P	.AZ	V.FWD	ΔH.	TG LP	
Δ.V	RD.T	.EL	.EL	HD.T	HD.T	HD.T	
SEC	.θX	C.EN		H.	H.	H.	
67	68	69	72	74	75	76	77
LRX	R.G	DN.	.TR	TFI	Δ.H	V.H	TG
LRV	TB	X.	.SH	.YX	ΔT	V.V	VG.Y
LRZ	V.I	UP.		.PX	ΔT	X.R	V.I
78	79	90	92	94	99	TIME	
.RX	.CR	.YX	THR	VG.X	POS	NOUNS	
RD.T	.SP	YD.T	HD.T	HD.T	VE.L	11:CSI	
TFI	POS	P.SI	H.	H.	MR.	13:CDH	
	PRE ASC/CSI			POST		37:TPI	
W	+10000+100+15		+2000+20+5			16:EX.V	
49	+200+120		+80+50			33:TIG	
525:SIDE LOBE-V32				RR NULL-REINIT			
MAIN-ALIGN COAS				N05 INCR-			
PGNS NULL(N49)-V32				REINIT			
VEH	X	ACA	DB	RATE			
	CUT OUT						
		0 4.	0 .3	0 .2			
1 ASC	0 2-A	1 20.	1 1.	1 .5			
2 DES	1 2-B	CSM.4	2 5.	2 2.			
3 CSM	2 4-AB		PWR 1	3 10			
	MIN	20/	.3/.4Y	5/10P			
ASC	MAX	7.5	5.	30			
	MIN	20	.3/.4Y	5/10P			
DES	MAX	17	5.	10			

F5

V57:ENABLE LR
58:DISABLE LR
59:LR TO POS 2
68:TERM TERRAIN

N60:V FWD,HDOT,H
63:ΔH,HDOT,H
64:TR/LPD,HDOT,H
68:NG,TG,VI
92:THR,HDOT,H
94:VGX,HDOT,H

214:AGS
402:AGS (IF 4 TIMES)
500:LR DES/1
511:LR-HVR,N63 FOR
ΔΔH NONE LR DES

520:LR RUPT,GO
522:LR Δ POS,GO
523:LR NDT 2,GO
1107:AGS 1410:AGS
1406:P66 (PGNS MAN
1407:P66 THR)
1466:AGS
2XXXX:AGS 3XXXX:RSET

-10:V25N69,P63, (0,311,310)
:V40N20
- 5:CB LR - CLOSE
- 4:FINAL TRIM, GO - NO GO
- 1:MASTER ARM - ON,MODE - PGNS
-:30 ENG ARM - DES
-:07 ULLAGE (+X MANUAL)
:00 104:28:55 (11 + 03)
:02 (NO IGR - START)
:05 DES OVRD - ON,MA - OFF
TH >80,T/W>1.6,N68VI>18

:26 THR UP(TTCA-UP BY 31:)(AB)
1:00 ✓AGS ATT (ERR,RATE<5,
SHe INCR)
2:00 V21N69 SYS CK
3:00 YAW R to ~ 0°
ΔH OK > 10 SEC:V57 (V58)
ALT: 30 25 20 15 10
ΔH: 17 15 12 3 7000
CONV, THEN OUT →P64
NO LOCK OR 169 BY 6K(AB)
→P64:NO LOCK BY 20 SEC(AB)
LOSS OF LOCK - 60


5:00 V24N69 SYS CK
5:30 TFI THR DOWN
6:00 AUTO YAW AT 30K
7:28 THR<57% MCC ± 10 SEC
CMD +40 SEC + ATT CHG(AB)
P64 +15 SEC : (AB)
8:00 V23N69
EVAL MAN CONT : PGNS-AUTO
8:20 N68:P64 AT TGO = 100(9:23)

ABORT STG - PUSH PGNS - ATT
ENG ARM - ASC HOLD
STOP - RESET AGS - AUTO
START - PUSH P7}


ENG STOP - PUSH
ENG ARM - OFF
PRO
DES OVRD - OFF
PGNS - ATT HOLD
AGS - AUTO
PROP/TEMP MON - ASC,
THEN DES
ASC He MON - 1, 2
CB LR - OPEN
SHe STEADY (DCR:MCC)
OX:20-40,FUEL:8,CLOSE

5/10/71


85



CCAS BORESIGHT
LOG



5/10/71



ABORT - DPS	MANUAL	INSERTION
GUID SW -	+ 0: 0°	500:MAIN SOV - OPEN
MODE CONT - AUTO	+20:300°	ASC FEED (2) - CLOSE
ENG ARM - DES	PDI+():270°	200:OES OVRD - OFF
THROTTLE - MAX	POI+():250°	(EXCEPT BUS LOSS)
<u>TIG:ABORT</u>	SHUTDN=PDI()	ASC ARM - OFF
DES OVRD - ON		(EXCEPT BUS LOSS)
YAW RT 40°		(>30:DPS C.O.-AB STG)
31% DES REG - CLOSE TO 160		0:ABORT/AB STG - RESET
ABORT STAGE - ASC		STOP - PUSH
GUID SW -	BAT 1,3 - OFF	MODE CONT (2)-ATT HOLD
MODE CONT-AUTO	CABIN REPRESS	ARM - OFF
<u>TIG:ABORT STG</u>	DES O2-CLOSE	>400:ATT HOLD :45X9°
ENG ARM - ASC	#1 ASC O2-OPN	<400:ATT HOLD NUL N85
START - PUSH	PRESS REG	PGNS-AGS <10:NULL VGX
ASC FEED-OPEN	A&B EGRESS	TWEAK:257°,10° OHW, 2
MAIN SOV-CL SE	SUIT GAS	CB RR(2) CLOSE
YAW RT 40°	DIVERT-EGRESS	RR-LGC P20 AUTO
PRPLNT QTY-OFF	CAB GAS RET -	V95 V80 (2.0/12.0)
PRPLNT T/P-ASC	EGRESS	
He MON - ASC	H2O SEL - ASC	
ASC He SEL-BOTH	DES H2O-CLOSE	
MASTER ARM - ON	ASC H2O-OPEN	
THR - JETT		

MANUAL STAGE
ASC BATT(2) - ON
DES BATS - OFF
GUID - 11002 V77, P47
DEADBAND - MIN
ATT CONT (3) - MODE CONT
MODE CONT - ATT HOLD
MASTER ARM - ON
ASC He SEL - BOTH
He PRESS ASC - FIRE
-X:2 fps
STAGE - FIRE, +X:2 fps
NO PDI + 12 APS ABORT
P30
P42 1706 - PRO
N86
N18(0,270,0)
He MON - ASC PRESS
MASTER ARM - ON
ASC He SEL - BOTH
He PRESS ASC - FIRE



F16

PAGE 14

DPS BURN

CB(11) ECA GMBL AC - CLOSED
CB(16) DISP/ENG OVRD LOGIC - CLOSED
CB(11&16) STAB/CONT (ALL) - CLOSED
EXCEPT CB(11) AEA - OPEN

ATE SCALE PDI - 25°/SEC

THR CONT - MAN/CDR
- PDI AUTO/CDR

ATT/TRANSL - 4 JETS
BAL CPL - ON
ENG GMBL - ENABLE
ES ENG CMD OVRD - OFF
ABORT/ABORT STAGE - RESET
DEADBAND - MIN
ATT CONT(3) - MODE CONT

MODE CONT PDI PGNS - AUTO
AGS - AUTO

STOP PB (2) - RESET
TTCA (2) - THROT/Min PDI LMP TTCA-SOFT STOP

FOR PDI GO TO TIMELINE BOOK

-2:00 400+1

-1:00 MASTER ARM - ON (1st BURN)

- :30 ENG ARM - DES

FOR AGS BURN ABORT PB - PUSH (T=0 FOR AGS)

-:07.5 ULLAGE (MANUAL FOR AGS)

- :05 PRO

+ :01 DES He REG (1) - OPEN (>31%)
TFC-10 DES He REG (2) - CLOSE (<86%)
ΔV=0 STOP PB - PUSH
ENG ARM - OFF
ABORT PB - RESET

NO POI+12 APS ABORT

APS BURN

ASSUMPTIONS:
POI CHECKLIST COMPLETE TO TIG.
DPS INOPERATIVE.

V37E 30E
LOAD NO POI+12 PAD
V37E 42E
01706 ALARM, PRO
N86
410+5, LOAD ΔV
370 R

N18 R, P, Y (0, 270, 0)

SET DET

He MON - ASC PRESS
MASTER ARM - ON
ASC He SEL - BOTH
✓CB(11&16)
ED LOGIC PWR(2)-CLOSED
He PRESS ASC - FIRE

DES 02 - CLOSE
#1 ASC 02 - OPEN
H20 SEL - ASC
DES H20 - CLOSE
ASC H20 - OPEN

V48,11002

CHECK APS BURN

CB(16)
DISP/ENG OVRD LOGIC - CLOSED
CB(11&16) AEA AND DECA PWR AND
STAB/CONT (ALL) - CLOSED
EXCEPT
CB(11) AEA AND DECA PWR AND
CB(16) DES ENG OVRD - OPEN
CB(16) EPS:
CROSS TIE BAL LOADS - OPEN
RATE SCALE - 25°/SEC
ATT/TRANSL - 4 JETS
BAL CPL - ON
DEAD BAND - MIN
ABORT/ABORT STAGE - RESET
ATT CONT(3) - MODE CONT
MODE CONT - **ASCENT** - PGNS - AUTO
AGS - AUTO

STOP PB (2) - RESET
TTCA (2) JETS

-2:00 400+1
AGS/PGNS
-1:00 MASTER ARM - ON

RCS STAGE
--:14 MANUAL ULLAGE
--:10 STAGE-FIRE
-:10 ABORT STAGE PB - PUSH(T=0 FOR AGS)
ENG ARM - ASC

-:05 PRO


:00 ENG ON
+:01 ENG START - PUSH
200 fps ENG ARM - OFF
0 fps ABORT STAGE - RESET
STOP PB - PUSH

DPS ABORT/INSERTION

APS ABORT/INSERTION

/GUID SW
 THROTTLE-UP
 ABORT PB-PUSH
 MODE CONT(2)-AUTO
 YAW RT 40°
 623+1
 /INVERTER
 V16N85 (500R)
 31% DES He REG (2)-CLOSE
 200fps DES ENG CMD OVRD-OFF
 (UNLESS CDR BUS LOSS)
 TFC-10 DES He REG (2) -Close (<86%)
 STANDBY TO COPY GET
 0fps STOP PB - PUSH
 DET - STOP
 GET
 MODE CONT-ATT HOLD
 ENG ARM-OFF
 ABORT (STAGE)-RESET
 STOP PB - RESET
 ΔV 404,5,6=0 470R

/GUID SW
 ABORT STAGE PB-PUSH
 MODE CONT(2)-AUTO
 ENG ARM-ASC
 START PB-PUSH
 ASC FEED(2)-OPEN + (UNLESS
 MAIN SOV-CLOSE + BUS LOSS)
 YAW RT 40°
 623+1
 CABIN REPRESS - CLOSE
 DES O2-CLOSE, #1 ASC O2-OPEN
 PRESS REGS A&B - EGRESS
 SUIT GAS DIV - EGRESS
 CABIN GAS RETURN - EGRESS
 H2O SEL-ASC
 DES H2O-CLOSE, ASC H2O - OPEN
 PROP TEMP/PRESS-ASC
 He MON-ASC
 /XFEED
 /INVERTERS
 THROTTLE/JETS-JETS
 V16N85 (500R)
 MAIN SOV-OPEN +
 ASC FEED(2)-CLOSE +
 ENG ARM-OFF (UNLESS BUS LOSS)
 STANDBY TO COPY GET
 ABORT STAGE-RESET
 STOP PB-PUSH
 DET-STOP
 GET
 MODE CONT-ATT HOLD
 ΔV 404,5,6=0 470R



STAGING

ASC BATT (2)-ON(PRECONDITION)
 DES BATTs-OFF
 MODE CONT (2)-ATT HOLD
 DEADFACE
 ✓GUID SW (IF PGNS: DAP 11002, V77)
 ATT CONT (3)-MODE CONT
 BAL CPL-ON
 DEAD BAND-MIN
 P47, 404,5,6=0 470R
 HELIUM MON-✓ ASC PRESS
 MASTER ARM-ON
 ASC He SEL-80TH
 ✓CB ED LOGIC PWR (2)-CLOSED
 He PRESS ASC-FIRE
 STOP PB-PUSH
 -X TRANS 2 fps
 STAGE-FIRE
 +X TRANS 2 fps
 CB(11&16) ED LOGIC PWR (2)-OPEN
 CABIN REPRESS-CLOSE
 DES O2-CLOSE, #1 ASC O2-OPEN
 H2O SEL-ASC
 DES H2O-CLOSE, ASC H2O-OPEN
 PRESS REG A&B-EGRESS
 SUIT GAS DIV-EGRESS
 CABIN GAS RETURN-EGRESS
 ATT/TRANSL-2 JETS
 POO
 STOP PB-RESET

 ✓GUID SW

DPS ABORT/APS INSERTION

✓GUID SW
 THROTTLE-UP
 ABORT PB-PUSH
 MODE CONT (2)-AUTO
 YAW RT 40°
 623+1
 31% DES REG-CLOSE
 BURN DPS TO DEPLETION
 ABORT STAGE PB-PUSH
 ENG ARM-ASC
 START PB-PUSH
 ASC FEED(2)-OPEN + (UNLESS
 MAIN SOV-CLOSE+ BUS LOSS)
 CABIN REPRESS-CLOSE
 DES O2-CLOSE, #1 ASC O2-OPEN
 H2O SEL-ASC
 DES H2O-CLOSE, ASC H2O-OPEN
 PRESS REGS A&B-EGRESS
 SUIT GAS DIVERter-EGRESS
 CABIN GAS RETURN-EGRESS
 PROP TEMP/PRESS-ASC
 He MON-ASC
 ✓XFEED
 ✓INVERTER
 THROTTLE/JET-JETS
 CB(11) RR(2) - CLOSED
 V16NB5 (500R)
 500fps MAIN SOV-OPEN +
 ASC FEED (2) - CLOSE +
 200fps ENG ARM-OFF (UNLESS BUS LOSS)
 STANDBY TO COPY GET
 0fps ABORT STAGE-RESET
 STOP PB-PUSH
 OET-STOP
 GET
 MODE CONT-ATT HOLD
 ▲V 404,5,6=0 470R

ALARM CODES (PDI)

CODES	DEFINITION	ACTION
00214	LGC USING IMU WHEN POWER TURNED OFF	GUID CONT - AGS
00402 (4 TIMES)	DAP STEERING LOST	GUID CONT - AGS
00511	NEITHER OR BOTH LR ANT POSITION DISCRETES PRESENT	LOG ANT - HOVER, NO ΔH (N63) UPDATE (10 SEC): LDG ANT - DES
01107	PHASE TABLE DISCREPANCY	GUID CONT-AGS (LAND MANUALLY IF DESIRED)
RECURRING 01406	TGO COMP FAIL (P64)	NO GUIDANCE, SWITCH TO P66 OR SWITCH TO AGS
RECURRING 01410	DES GUIDANCE EQUATIONS OVERFLOW (P64)	NO GUIDANCE, SWITCH TO P66 OR SWITCH TO AGS
01412	NON CONVERGING P63 TIG	MSFN UPLINK NEW S.V. & TARGET
01466	INSUFFICIENT THROTTLE SERVICING (P66)	IF RECURS, MAN THR & ATT HOLD (or AGS)
01703	TIG SLIPPED DUE TO INTEGRATION	IF LARGE IGNITION DELAY-DO NOT BURN POI IF SMALL IGNITION DELAY-MANUALLY THROTTLE UP AT DET N+26
2XXXX	ALL P0000'S (EXCEPT 21406)	GUID CONT - AGS
21406	BAD RETURN FROM TIME TO TGT RTN (P63)	MSFN UPLINK NEW S.V. & RECALL P63
RECURRING 3XXXX	ALL SOFTWARE RESTARTS (BAILOUT)	CONTINUE-INSURE NO UNSAFE CONDITION DEVELOPS.
N49	RMAX VMAX <.3nm; 2.0fps	1. IF STEADY STATE-RESET 2. REJECT FIRST MARK THEN ACCEPT NEXT COUPLE OF MARKS AND MONITOR FOR NEXT CONVERGENCE >2.0nm OR 12.0fps PRIOR TO CSI OR >.8nm OR 5.0fps AFTER CSI CONSIDERED EXCESSIVE
F97N63	LGC THINKS ENG FAILED	PRO TO SET ΔV MON. DO NOT ENTER BECAUSE IT WILL SLIP TIG IF RECURRING, NO GUIDANCE

MISSION RULES NO-60'S

PAGE 19

518

	PRE POI	PDI TO PDI +6+10	PDI +6+10 TO HI GATE	HI GATE TO TO
	EPS ONE DC BUS ONE DESCENT FEEDER SHORTED ONE ASCENT FEEDER SHORTED 4 DESCENT BATS ONE ASCENT BAT BOTH INVERTERS AC BUS A AND B	ABORT ABORT ABORT ABORT ABORT ABORT ABORT	ABORT ABORT ABORT ABORT ABORT ABORT ABORT	ABORT ABORT ABORT GO GO GO GO
	ED ONE PYRO SYSTEM ARMED ONE PYRO SYSTEM DEARMED ONE STAGING RELAY CLOSED ONE PYRO SYSTEM BATTERY	ABORT ABORT ABORT ABORT	ABORT GO ABORT GO	ABORT GO ABORT GO
	ECS CABIN PRESS <4.4 SUIT LEAK BOTH SUIT FANS BOTH DEMAND REGS BOTH H2O SEPS BOTH DESCENT O2 TANKS BOTH ASC O2 TANKS PRI OR SEC COOLANT LOOP PRI OR SEC H2O FEED BOTH DESCENT H2O TANKS BOTH ASC H2O TANKS	ABORT ABORT ABORT ABORT ABORT ABORT ABORT ABORT ABORT ABORT ABORT	ABORT ABORT ABORT ABORT ABORT ABORT ABORT ABORT ABORT ABORT ABORT	GO ABORT GO GO GO GO GO GO GO GO GO
	G&C PGNS GUID STEER 3 AXIS ATT CONT PGNS RATE CMD & PGNS AUTO AGS RATE CMD 2 ACA AUTO +X & AUTO DPS IGNITION 2 FDAI-ATT/RATE/ERR LR REDNT APS N P & R GDA TRIM (IMPING CONST VIOL) MANUAL THROTTLE (2 TTCA) & AUTO THROT	ABORT ABORT ABORT ABORT GO OPTION ABORT ABORT ABORT ABORT	ABORT ABORT ABORT ABORT GO OPTION ABORT GO ABORT ABORT	GO OPTION OPTION OPTION GO OPTION GO GO ABORT ABORT
	DPS PROP LEAK (ΔQ FU/OX > 10%) FU OR OX INLET/ULLAGE < 160 BINGO/2%	ABORT ABORT	ABORT ABORT	ABORT ABORT ABORT
	APS PROP LEAK FU/OX INLET PRESS < 62, > 220 APS HE 1 OR 2 DECREASING	ABORT ABORT ABORT	ABORT ABORT ABORT	ABORT ABORT ABORT
	RCS HE/PROP LEAK PROP LEAK (DOWNSTREAM OF MAIN) FU/OX MNFLD A OR B PRESS < 100	ABORT ABORT	ABORT ABORT	GO GO

5/30/78

ABNORMAL VEHICLE DYNAMICS

Use ACA Hardover to Stabilize Vehicle
 If RCS TCA LT ON-CB QUAD TCA - OPEN
 GUID CONT-AGS, MODE CONT-ATT HOLD, ATT CONT(3)-MODE CONT,
 V77E (PGNS ONLY)
 If Not Stabilized-CB(11) STAB/CONT:ATT DIR CONT-OPEN
If Not Stabilized-TTCA/TRANSL(2) - DISABLE, DEADBAND - MAX
If Not Stabilized-ACA PROP(2) - DISABLE

RAPID IMU REALIGN

- 1) AGS INERTIAL FOAI TO 0°, 0°, 0°
 - 2) V41 N20E, E, E, E,
 - 3) V40 N20 0°, 0°, 0° ON AGS FOAI, ENTR
WAIT 11 SEC.
 - 4) P51E, PRO, POOE
 - 5) V25N07E, 77E, 10000E, 1E
 - 5) PERFORM P52, OPTION 3 (AUTO OPTICS ARE GOOD)
- NOTE: FOR TEMPORARY LOSS OF CDR'S BUS, UPDATE
 LGC CLOCK WITH V55 TO COMPLETE RECOVERY.

LIGHT	MEANING	IMMEDIATE ACTION (POSSIBLE OPERATIONAL IMPLICATIONS)
DC BUS BATTERY W&C LTS: CDR X-POINTER THRUST	CDR BUS FAILURE	(DPS GOES TO 100% And GOA LOCKED) GUIDE CONT - AGS, SUIT FAN - 2, CDR AUDIO CONT - BU, S-BD-XMTR/RCVR & PWR AMPL - PRIM, INV 2, Activate Sec Glycol Loop <u>TO START DPS:</u> DES ENG CMD OVRD - ON <u>TO STOP DPS:</u> DES ENG CMD OVRD - OFF, ENG ARM - OFF <u>TO START APS:</u> AGS Auto ON <u>TO STOP APS:</u> AGS Auto OFF, ABORT STAGE - Reset UNSTAGED (M45) STAGED (M47)
DC BUS BATTERY W&C LTS: LMP X-POINTER, PROP PRESS RCS PRESS, QTY ECS PRESS, GLYCOL, QTY	LMP BUS FAILURE	(DPS GOES TO 100% And GOA LOCKED) GUIDE CONT - PGNS, SUIT FAN - 1, LMP AUDIO CONT - BU, PWR AMPL - SEC, INV 1 <u>TO START APS/DPS:</u> ENG START - PUSH <u>TO STOP APS/DPS:</u> ENG STOP - PUSH UNSTAGED (M45) STAGED (M47)
ASC PRESS	Either He Press<2775psi (Before Staging)	<u>IF APS NOT PRESSURIZED</u> - CONSULT MSFN, GO TO MAL PROC APS-1 <u>IF APS PRESSURIZED</u> - CLOSE ASC He REG 1 & 2: MONITOR ASC He PRESS; IF BOTH <2775 AND DECREASING - IMMEDIATE LIFTOFF MONITOR FUEL/OXID PRESS; IF EITHER DECREASING - IMMEDIATE LIFTOFF (M37)
DES REG	220 psi>He Press>260psi	DES He REG 1 - CLOSE, DES He REG 2 - OPEN Monitor TEMP/PRESS, Maintain FUEL & OXID>160psi (M31)
CES AC	ATCA AC Out of Tolerance	GUIDE CONT - PGNS, GYRO TEST - POS RT. <u>If Light Stays ON</u> , CWEA Fail. Poss Loss of AGS Control, FOAI Rate Needles Unreliable, RR Usable In LGC Mode Only. (M27)
CES DC	ATCA DC Out of Tolerance	GUIDE CONT - PGNS, GYRO TEST - POS RT. <u>If Lt Stays ON</u> , CWEA Fail, <u>If Lt OFF</u> - Cycle CWEA CB, <u>If Lt Stays OFF</u> , Cycle DECA GMBL AC CB To Unlock Throttle. If Lt Reappears: Poss GOA Lock-up, DPS To 100%, No AGS Attitude Control (M27)
AGS	AGS Power Supply Out of Tolerance, AGS Heater Failed ON, AGS Self Test Failed	GUIDE CONT - PGNS. <u>If PGNS Unavailable:</u> MODE CONT (AGS) - ATT HOLD, AGS RATE CMD OK, But NO ATT HOLD (Free Drift). 412R, Self Test. (M17)

LIGHT	MEANING	IMMEDIATE ACTION (POSSIBLE OPERATIONAL IMPLICATIONS)	
LGC	LGC Power, Scaler, or Counter Fail	GUID CONT - AGS. Poss No Auto Eng Shutdown. If RESTART Lt ON, LGC Fail. CB(11)AEA - CLOSE	(M10)
SS	IMU, ICDU or PIPA (Thrusting) FAIL	GUID CONT - AGS. Pos No Auto Eng Shutdown. IF PROG Lt NOT On, CWEA Fail. CB(11) AEA - CLOSE	(M9)
RCS TCA	One Or More Thrusters Fail Off, Collinear Thrusters Firing Simultaneously	If Stable, Recycle CWEA. If Unstable (or unusual thruster activity) Affected CB QUAD TCA - Open, LGC THR PAIR CMDS - DISABLE During ullage (PDI), if RCS TCA lite and quad flag comes on: Pull CB for 1st flag. If 2nd flag appears, pull CB, DISABLE and reclose 1st CB	(M42)
RCS A REG RCS B REG	165psi > Reg Press > 218psi	Monitor MANF PRESS, When < 100psi: Bad System MAIN SOV - CLOSE, CRSFD - OPEN	(M42)
ASC HI REG	Manf Press > 220psi	ASC He REG 1 & 2 CLOSE, When < 220psi, Open Each REG Separately.	(M38)
ASC QTY	< 10 Sec Burn Time	MAIN SOV (2) - OPEN, ASC FEED 2 (2) - CLOSE	(M38)
ENG GMBL	GMBL On/Response Discrepancy	ENGN GMBL - OFF. If Lt Still ON: ENG GMBL - ENABLE (CWEA FAIL)	(M25)
INVERTER	AC VOLTS < 112 398 > FREQ > 402	Check AC VOLTS & FREQ. Switch to INV - 2. Bus A&B BUS TIE INV 1 (2) - OPEN (INV 1 Feeder Short). BUS B: BUS TIE INV 2 - OPEN (BUS B Short) BUS A&B: BUS TIE INV 1 (2) - CLOSE. Select INV 1. BUS A: BUS TIE INV 2 - OPEN (INV 2 Feeder Short). BUS A: BUS TIE INV 1 - OPEN (BUS A Short, Lt Stays ON; Close BUS B: BUS TIE INV 2 Before Selecting INV 2).	(M49)
BATTERY	BATT OVERTEMP REV CURRENT > 10A OVERCURRENT	UNSTAGED: Check All BATS VOLTS, AMPS & TB's If VOLTS, AMPS OK: Faulty BAT - OFF Then ON If VOLTS, AMPS NOT OK: Faulty BAT - OFF, CB (11&16) CROSS TIE BAL LOADS - CLOSE STAGED: Check BAT 5, 6 VOLTS, AMPS & TB'S If VOLTS, AMPS NOT OK: CB (11&16) CROSS TIE BUS - CLOSE Faulty BAT: NORMAL FEED - OFF, Good BAT: BACKUP FEED - ON	(M48) (M48)
STAGE RELAY	ED Relays K1 To K6 CLOSE With MASTER ARM - OFF	BEFORE PDI: Do NOT Set MASTER ARM-ON, STAGE RELAY - RESET, Appropriate LOGIC POWER CB - OPEN AFTER PDI: Do NOT Set MASTER ARM - ON, STAGE RELAY - RESET If STAGE SEQ RELAYS Lt still ON: ASC He PRESS - FIRE, Monitor ASC Fuel/Oxid Press. If APS Pressurizes, ABORT	(M73)
STAGE SEQ RELAY LT. OFF AT PDI	Possible Relay Fail	AT PDI: MASTER ARM - OFF, Open LOGIC PWR CB On System Which Had SEQ LT - ON, MASTER ARM - ON. At Ignition Monitor DPS She And FUEL/OXID PRESS. She Tank Inoperative: STOP PB - PUSH, ENG ARM - OFF. She Tank OK: MASTER ARM - OFF, LOGIC PWR CB - CLOSE	(M73)
RCS	A OR B He Press < 1700	Monitor He PRESS & RCS QUANTITY. Affected Sys: LGC THR PAIR CMDS (4) - DISABLE, MAIN SOV - CLOSE, CB(11 or 16) QUAD TCA (4) - Open. Monitor MANF PRESS Go to Mal Proc RCS 1	(M41)

F21	
H	HOOT
7000	162.0
6000	157.0
5000	135.0
4000	112.0
3000	90.0
2000	62.0
1000	33.0
500	16.0
400	13.0
300	9.0
200	5.0

821

F20

ASC PRESS	ASC He REGS CLOSE; MAINTAIN P>125, ΔP<10
GES REG	REG 1-CLOSE, 2-OPEN, MAINTAIN P>160
GES QTY	<5.8%
CES AC	GUID CONT-PGNS, GYRO TEST - POS RT (LT ON: CWEA)(NO AGS CONT, RR - LGC ONLY, NO RATE NEEDLES
CES DC	GUID CONT-PGNS, GYRO TEST - POS RT (LT ON: CWEA) LT OFF: CYCLE CWEA; LT OFF: CYCLE DECA GMBL TO UNLOCK THR CONT(NO THR, NO GMBL, NO AGS D.B., DPS TO 100%)(PGNS + AGS AUTO APS IGN LOST)
AGS	GUID CONT-PGNS (412R)(NO AEA, ATT HOLD - OK, NO ATT D.B.)
LGC	GUID CONT-AGS (RESTART, DSKY BLANK: LGC FAIL - CB [11] AEA - CLOSE)
ISS	GUID CONT-AGS (PROG:ISS)(NO PROG: CWEA)
RCS TCA	IF STABLE, CYCLE CWEA
RCS A REG	(165<MANIF PRESS<218); HI: GO, MON He, LO: IF <100, SOV, XFEED
DC BUS	+ BATT + DC FAULT + TB BP = FEED SHORT (IF BATT 5:NO AGS; IF BATT 6:NO PGNS) + DC FAULT + TB BP = NORM FEED FAIL GO BKUP FEED:5 TB:NO AGS, 6 TB:NO PGNS + NORM VOLTAGE = CWEA
CABIN	+ LO CABIN PRESS:DUMP VLVS-CLOSE, PRESS A/B-EGRESS
SUIT FAN	+ SUIT FAN COMP:CB 16 ΔP - OPEN + FLOW + SUIT PRESS = CWEA

ASC HI REG	ASC He REGS (2):CLOSE, OPEN (1) WHEN P<220
ASC QTY	BT <10 SEC
INVERTER	+ VOLTS<112:CB AC BUS A/B INV 1: OPEN:LT OFF:INV 1 FAIL
BATTERY	+ BATT FAULT - BATT FAIL (NONE = CWEA)
RNDZ RDR	+ NO TRACK:RDR TEST, RR (15 SEC) OR CB RR:OPEN (10 SEC), THEN SLEW (2 SEC) RR:SLEW:IF RR LT OFF:CWEA, ON:NO TK LT FAIL
PRE AMPS	+ CES AC:NO ASA, RR LGC ONLY + CB ATCA - CYCLE DECA GMBL
ED RELAYS	MASTER ARM:OFF, STG RELAY RESET, CB LOGIC - OPEN
RCS	+ He >1700:CWEA, He <1400: SOV-CLOSED
HEATER	RR TEMP, S-BAND TEMP MON: CB'S OPEN IF LT ON
ECS	IF NO COMP LT ON:CWEA
O2 QTY	O2 QTY >10%:CWEA
GLYCOL	+ GLY TEMP >50 + SUIT TEMP >60: PRI EVAP FLO 1 - CLOSED:PRI EVAP FLO 2:OPEN IF NO TEMP DECR (5 MIN):PRI EVAP FLO 1&2:CLOSE, H2O TK-SEC, GLY-SEC, CB GLY PUMP SEC-CLOSE, SEC EVAP FLO-OPEN + GLY TEMP <50:CB GLY PUMP 1 - OPEN: GLY PRESS DECR:LEAK
STG SEQ LT OFF:AT PD:MA-OFF, CB LGC(ON LT)-OPEN MA-ON. AT IGN, SHe INOP:STOP;SHe OK,MA-OFF, LGC-CLOSE	

5/10/71

B20



LGC + DC BUS + BATT

GUID CONT - AGS
DES ENG OVRD - ON
CDR AUDIO - BU
GLYCOL - SEC
SUIT FAN - 2
DPS MANUAL - OFF
(ARM, OVRD, STOP)

START (MAN)
GASTA
THRUST, TAPE
RCS - FEED A
RR, LR
INV 1
DIR, PULS, +X

CES DC + DC BUS + BATT

GUID CONT - PGNS
SUIT FAN - 1
LMP AUDIO - BU
INV - 1
ABT STG:
ENG ARM - ASC
MAN START, MAN STOP

DES OVRD
AUTO THROT, TH CMD
AUTO IGN, AUTO OFF
RATE NEEDLES
RCS - FEED B, XFD
RR SLEW, AUTO TRACK
INV 2

AC-A

CB BUS TIE A (2) - OPEN
RR - LGC
LMP FDAI - AGS
GDA
GASTA
CDR FDAI
TAPE HDOT/RDOT

AC-B

CB BUS TIE B (2) - OPEN
CDR FDAI - PGNS
DEA
FDAI - AGS
LMP - FDAI

5/10/73

12/01/75

