Failure Is Not An Option !

"My Darling"
Marta

U.S. AIR FORCE

SEAL OF THE PRESIDENT OF THE UNITED STATES

90158


GREENWICH MEAN TIME
COUNTDOWN – ELAPSED TIME
THE WORLD



LEADERSHIP





UNITED STATES

VALUES

believe that this nation
itself is achieving its
this decade is out of
on the moon and returning
to earth".
John F Kennedy
to Congress
May 1961
Task Accomplished.....
July 1969
APOLLO 11





APOLLO XIII
EX LUNA, SCIENTIA



TRUST



H14



TEAMWORK

MMENTS:





CSM LiOH CARTRIDGE ADAPTOR

APOLLO XIII

MID COURSE CORRECTION – 5

MET 105:18 DV = 7.8 fps Tb = 13.8 sec



RETROGRADE

ENTRY LM PREP

ELP-1

4/17/70
~~17:15~~
~~R+00~~
~~21:30~~
03:00

EI-6:00 PWR UP AGS

BAT 5 @ NORM FEED - ON
USE MODIFIED LM DPS/RCS 30-MIN ACTIVATION CHECKLIST
EXCEPT ~~CHGE PG 28 STEP 2 TO VOICE & RANGE~~ AS FOLLOWS:

EI-5:00 ~~MCC-7 (2)~~ MCC 7, If Req

~~CO~~ LM PRE-ENTRY PROCEDURE

MANEUVER TO SM SEP ATTITUDE
CONFIGURE FOR CSM HOT FIRE
DEADBAND - MAX
ATT CONTROL: (3) PULSE
PERFORM CSM HOT FIRE
~~CONFIGURE FOR~~ MANEUVER BACK TO SM SEP ATT
ATT CONTROL - P,R PULSE
- YAW - MODE CONTROL
~~MANEUVER TO SEP ATT~~

EI-4:30 CONFIGURE FOR CM/SM SEP
BAL COUPLE - ON
AGS 404+0, 405+0, 406+0, 470R
TRANSLATE +X .5FPS
CM/SM SEP
~~TRANS +X .5FPS~~ NULL 470 TO ZERO AFTER SEP
ATT CONT (3) - PULSE
PITCH TO ACQUIRE SM FOR PHOTOS (USE ACA FOR CONTROL)

EI-3:00 MANEUVER AND ATT HOLD FOR ~~CSM P51 & P52~~ MCON VIEW ATT UNTIL CM
~~MANEUVER FOR CSM/LM SEP~~ PLATFORM RELEASE

EI-2:30 POWER REMOVAL FROM CM/LM UMBILICAL — NEED HBR AND Sho have it

ASSUMES ALL DESCENT BATTERIES ON-LINE AND ASCENT BATTERIES 5&6 ON NORMAL FEED

Could be eliminated if needed

CSM
CB-LM PWR-1 MNB - OPEN
CB-LM PWR-2 MNB - OPEN
~~CB EPS SENSOR SIGNAL MAIN B - OPEN~~ Should with LMP

LM
CB (11&16) EPS: CROSS TIE BAL LOADS - CLOSE
CB(16) EPS: BAT FEED TIE (2) - OPEN
BAT 1 HV - OFF/RESET
~~BAT 5 OFF/RESET~~ BAT 5 NORM OFF/RESET
BAT 2 LV - OFF/RESET THEN ON (WAIT ~~5 MIN~~ FOR MSFN GO)
BAT 2 HV - OFF/RESET THEN ON
BAT 1 HV - ON
~~BAT 5 NORM FEED ON~~ BAT 5 NORM FEED - ON
CB(16) EPS: BAT FEED TIE (2) - CLOSE
LMP XFER TO CM

CB(16) EPS: BAT FEED TIE (2) - OPEN
ECA CONT - CLOSE

CB(16) EPS: BAT FEED TIE (2) - CLOSE
ECA CONT - OPEN
← after this

1:45 MANUVER TO CM/LM JETT ATT

Monitor ΔVX Via [redacted], 470 NAV AND 47?

~~When PRPLNT QTY = 27%~~
~~DES Ho REG 1 = CLOSE~~

~~TTCA (CDR) — Reduce to 10% when Vgo = 10 fps~~
SHUT DOWN on BURN TIME (minus) 1 Sec
~~When ΔVX = Final ΔVX+~~
~~ENG STOP = PUSH~~
~~ATT CONT: YAW = PULSE~~

~~Damp Excessive Rates Via LM Y, Z Translation~~
~~ATTD ERROR NEEDLES - Trim Address 470+~~ to 1st Use
~~GSM Resume Attitude Control~~

~~PRO, PUSH~~
~~ENG ARM = OFF~~
~~PRPLNT QTY MON = OFF~~
ENG STOP = RESET
TTCA (CDR) = JETS
~~Turn~~ TO ENTRY LDG LIST @ EI-5HRS
~~Deactivate~~ Deactivate RR

1. Att control (3) to pulse
2. Roll with TTCA until attitude to ~90 P, T, & O and Y = 0
3. When ~~at~~ attitude acq w/ ~~at~~ control
4. ~~Att~~ control yaw to null control
5. When rates are less than .05°/sec att control yaw to pulse.
6. Spin up to .3°/sec w/ yaw (12 pulses)
7. Mode control RGS—off
8. Pwr down per contingency checklist pwrs.

Basic Date 1/16/70
Changed 3/23/70

LM-7

30-MIN ACTIVATION | DOCKED APS BURN (PGNS)

2 HOUR ACTIVATION

P30 UPDATE (LM)

P30 LM MANEUVER

N85 +0.1 +0.1 +0.1
P30 +2.6

PURPOSE			DPS/PERIcynthion+2						MCC-7					
HR		N33	+	0	0	0	7	9	+	0	0	1	3	7
MIN	TIG		+	0	0	0	2	5	+	0	0	0	3	9
SEC			+	0	2	6	.	4	8	+	0	4	8	.	3	9
ΔVX		N81	+	1	6	3	3	.	0	−	0	0	0	3	.	1
ΔVY		LOCAL	−	0	0	1	4	.	5	+	0	0	0	0	.	0
ΔVZ		VERT	−	0	7	5	1	.	5	+	0	0	0	0	.	1
HA		N42	+		N/A			.		+		N/A			.	
HP			+	0	0	2	0	.	5	+	0	0	2	0	.	5
ΔVR			+	1	7	9	7	.	7	+	0	0	0	3	.	1
BT			X	X	X	8	:	3	5	X	X	X	0	:	2	3
R		FDAI	X	X	X	2	6	8		X	X	X	0	0	8	
P		INER	X	X	X	2	6	4		X	X	X	3	5	9	
ΔVX	AGS	N86	+	1	6	4	1	.	0							
ΔVY	AGS		−	0	0	1	4	.	5							
ΔVZ	AGS		−	0	7	3	3	.	8			N/A				
BSS			X	X	X		N/A			X	X					
SPA			X	X				.		X	X					
SXP			X	X	X			.		X	X	X				

Basic Dat 1/5/70
Changed

LM-7

REMARKS:

DPS GDA P58 P67.5

EPS

WATER 333# DESC 85# ACC 12# PLSS 430# TOTAL

ROCKWELL ABC DIV



APOLLO 13 BATTERY ENTRY DATA

Fig 4.





003
NAVY

C
NASA

WELCOME BACK!
VIII
IX
X
XI
XII
XIII
ODYSSEY
APOLLO XIII

ASTRONAUT
HAISE
APOLLO 13
SEAL OF THE PRESIDENT OF THE UNITED STATES

WELCOME BACK!
VIII
IX
X
XI
XII
Glynn S. Lunney
Milton L. Kindler

Failure Is Not An Option !

2
C
238050
U
U
BN

EXIT
N427E
F
6094

BLUE ANGELS
DANGER

FF
AF 03 044
K RF

EMBRY-RIDDLE
AERONAUTICAL UNIVERSITY
EMBRY-RIDDLE
compuSIGN.com
HARTZELL
GREAT PLANES
Futaba
THUNDERBOLT
GOODYEAR

RES GESTA PAR EXCELLENTIAM
MISSION CONTROL

EMBRY
AERONAUTICAL
RIDD
UNIVER
EMBRY-RIDDLE

Lt Craig Olson
Maj Chandler Seagraves
Blue Angels

Darling

FIRE EXIT
FIGHTING
BB

U.S. AIR FORCE
"My Darling"
Marta


XGAM-72A
CAM72
LAST
HAFB FLT
XA5 HOT



FF
AF
03 044

Capt. WM. T. WHISNER