

NASA

SECTION 37

1

MPS 17" Feedline Ball Strut Tie Rod Assembly Ball Crack

Presenter:
David Rigby

Date:
Orbiter 01/14/03

BSTRA Ball FOD Testing (cont):

- 2.24 Inch Severely Cracked Ball Shown

