

MSG 100 - FD11 MMT SUMMARY

1 The FD11 MMT met briefly to discuss mission progress. A full hard-drive here on the  
2 ground contributed to the Multi-Protocol Converter (MPC) issue that affected a recent High  
3 Definition video downlink. A subsequent downlink opportunity was used to verify that the  
4 shuttle MPC is performing nominally . A conjunction predicted for Flight Night 12 is being  
5 monitored to ensure that it will not present an issue. There are no open issues with the  
6 plans for using ALT DAP for the maneuver to the undocking attitude. The team adjusted the  
7 ISS solar array plan to protect for an unlikely failure of a primary FRCS jet and confirmed  
8 that staying in a NORM-Z DAP configuration outside of 75 feet will not present a loads  
9 concern for the ISS if the next worse jet failure occurs. A poll was conducted and the entire  
10 community is GO for undocking.

11  
12  
13  
14  
15  
16  
17  
18  
19  
20  
21  
22  
23  
24  
25  
26  
27  
28  
29  
30  
31  
32  
33  
34  
35  
36  
37  
38  
39  
40  
41  
42  
43  
44  
45  
46  
47  
48  
49  
50  
51