

Operations & Maintenance Cost Study for NASA Facilities

Final Report for Warehouse Facilities

August 12, 2015

Submitted to:

Peter Aitcheson National Aeronautics and Space Administration

Submitted by:

CBRE | Whitestone 2050 Alameda Padre Serra, STE 200 Santa Barbara, CA 93103-1704

Contract NNC09BA14B



Operations & Maintenance Cost Study for NASA Facilities: Final Report for Warehouses

Overview

National Aeronautics and Space Administration (NASA) requires a credible method for estimating the operations and maintenance (O&M) requirements of its facilities.¹ The failure to anticipate future costs can lead to under-funding and diminished service life.

NASA has over 1,100 buildings totaling 18.4 million GSFT distributed at 33 sites globally in the selected inventory for this project. It is not cost effective to inspect all facilities, yet NASA needs detailed sustainment and operations estimates to support its budget planning. This project developed cost models for a sample of NASA assets with inventory details collected through site surveys. Estimates were extrapolated by facility type and size and adjusted for location to generate requirements for the selected NASA inventory.

The project employed the MARS Facility Cost Forecast System to provide cost information. Now in its eighth version, MARS is a facility cost modeling tool developed by CBRE | Whitestone and used by many federal and commercial agencies.

Phases 1, 2, and 3 of this project estimated O&M costs for five facility types: Administration Buildings, Propulsion Buildings, Communications/Data Centers, Space Science (R&D and Test) Buildings, and Wind Tunnels. Sample buildings were chosen at Goddard and Marshall Space Flight Centers and Glenn Research Center. CBRE | Whitestone submitted formal reports for each facility type.

Phase 3A inspected a sample of five Warehouse facilities at Langley Research Center (LaRC) in Hampton, Virginia and Plum Brook Station (PBS) in Sandusky, OH and generated detailed models in MARS. Site inspections at LaRC were conducted by Jacobs Facilities, a long-time CBRE | Whitestone partner experienced in inspecting federal facilities and creating MARS component inventories. A team consisting of an architect, and electrical and mechanical engineers carried out the facility inspections. A component inventory for a typical PBS Igloo facility was also provided to create a model for the facility type. O&M estimates from the sample were extrapolated to the population of Warehouses in the NASA inventory by Classification Type and size.

This report describes the project methodology and presents final estimates for the Warehouse facilities in the NASA inventory.

Project Methodology

Parametric Estimates for Buildings

The project methodology entailed estimating O&M requirements for the selected NASA inventory based on the inspection and modeling of a sample of facilities. The project included four key steps:

¹ Operations include custodial (cleaning, pest control, and trash collection), utilities (energy, water, and sewer), grounds (landscape care, mowing, and snow removal), security, telecommunications, and management. Maintenance (also known as sustainment) includes preventative maintenance, minor repair, unscheduled maintenance, and renewal and replacement.

- 1. Validate the existing NASA inventory and develop a sample
- 2. Perform on-site inspections of the sample buildings
- 3. Develop and calibrate MARS models
- 4. Generate per square foot estimates of sustainment and operations costs for the sample and extrapolate to the project inventory

Study Sample

NASA has over 1,100 buildings at 33 sites globally in the selected inventory. Complete inspection of each site to estimate O&M requirements is impractical and costly. This project generated sustainment and operations estimates for a sample of buildings and extrapolated the costs to a selected NASA inventory.

NASA and CBRE | Whitestone selected five Warehouse facilities at Langley Research Center and Plum Brook Station as a representative sample of the population of NASA Warehouses. The project sample included the inspection of one small Covered Storage building, one small non-temperature controlled General Warehouse, one small temperature controlled Dehumidified Warehouse, and one large Receiving and Shipping building. Inspections were performed at LaRC to minimize travel costs. Plum Brook Station provided component information for a typical Igloo facility to create a model for the facility type. Component-level cost models were developed for the five Warehouse facilities using CBRE | Whitestone's MARS. O&M costs will be generated for the sample and extrapolated to the remaining inventory. Estimates for Administration, Propulsion, Communications, Space Science (R&D and Test) Buildings, and Wind Tunnels were generated in Phases 1, 2, and 3 of the project.

Table 1 shows the building detail for the inspected Warehouses.

Table 1. Warehouse	Table 1. Warehouse Facilities Inspection Sample											
Site	Classification	Property ID	Property No.	Property Name	Year Built	Size	CRV					
Langley Research Center	Covered Storage (Miscellaneous)	350	1265H	1265 COMPLEX	1981	1,517	\$91,020					
	Dehumidified Warehouse - Ready Issue	46	1175	STORAGE FACILITY	1988	3,448	\$223,719					
	General Warehouse - Ready Issue	212	1240	STORAGE FACILITY	1951	6,246	\$367,378					
	Receiving and Shipping Buildings	153	1206	DISTRIBUTION CENTER	1966	35,625	\$3,639,735					
Plum Brook Station	General Warehouse - Ready Issue	N/A	N/A	IGLOO	1942	1,953	\$309,368					
Total						48,789	\$4,631,220					

There are a number of variables that drive O&M costs. In Phases 1 and 2 of the project, building Classification Type and size were the key inputs used to determine appropriate mapping of sample facilities to the total inventory. An alternative sample may control for current replacement value (CRV), age, and location. Per square foot estimates were generated for the sample and extrapolated to the selected inventory by type (Administration, Propulsion, Communications, and Space Science (R&D and Test) Buildings) and size. In Phase 3, the unique systems and function of the Wind Tunnels prevented O&M costs from closely aligning with facility square footage. NASA and CBRE | Whitestone defined several variables and

associated factors used to map the sample models and extrapolate total O&M costs to the remainder of the inventory.

Similarities in Warehouse construction across the NASA inventory allow for an extrapolation methodology consistent with Phases 1 and 2. Classification Type and size were used to map the sample Warehouse facilities to the population of assets. Per square foot O&M estimates for the five Warehouses will be extrapolated to the individual mapped facilities and adjusted for location to generate costs for the entire NASA inventory.

Warehouse facilities represent 4.6 million GSFT with a \$680 million CRV. Table 2 shows the Warehouse inventory by site.

Table 2. NASA Warehouse Facilitie	es by Si	te	
Site	Count	Size	CRV
AMES Research Center	12	286,982	\$22,015,817
ARC Camp Parks	1	120,264	\$6,991,699
CAPE	16	82,005	\$19,868,559
Columbia Scientific Balloon Facility	3	7,188	\$350,600
Dryden Flight Research Center	10	74,329	\$8,239,018
Ellington Field (JSC)	7	52,563	\$5,179,917
Glenn Research Center	11	66,797	\$19,633,945
GODDARD SPACE FLIGHT CENTER	9	362,218	\$44,573,625
HAWAII STDN STATION	2	1,159	\$32,035
Jet Propulsion Laboratory	8	19,600	\$3,062,033
Johnson Space Center	57	328,626	\$34,817,504
JPL/Australia - Canberra Deep Space Comm.	3	6,868	\$1,466,102
JPL/Goldstone - Apollo Site	1	184	\$373,723
JPL/Goldstone - Echo Site	1	1,705	\$373,723
JPL/Goldstone - Mars Site	1	184	\$373,723
JPL/Goldstone - Venus Site	3	1,514	\$510,989
JPL/Spain - Madrid Deep Space Comm.	8	26,794	\$3,433,836
Kennedy Space Center	99	859,813	\$103,341,925
Langley Research Center	25	178,204	\$22,774,088
Marshall Space Flight Center	44	391,021	\$55,542,708
Michoud Assembly Facility	8	362,882	\$107,962,385
Moffett Federal Airfield	30	107,701	\$9,584,578
NASA/JSC/White Sands Test Facility	11	37,969	\$2,940,629
Plum Brook Station	112	261,813	\$46,302,279
Stennis Space Center	8	202,639	\$49,040,438
Stennis Space Center (MSAAP)	55	573,114	\$87,022,126
Stennis Space Center (Tenants)	10	50,539	\$5,030,853
Wallops Flight Facility	37	140,818	\$19,301,223
Total	592	4,605,493	\$680,140,080

Detailed cost models were developed for the four buildings using CBRE | Whitestone's MARS Facility Cost Forecast System.

Description of the MARS Model

CBRE | Whitestone used MARS to estimate preventative maintenance, unscheduled maintenance, repair, and renewal/replacement costs for this project. MARS is an asset management system that estimates both deferred maintenance and future requirements on the basis of asset components and their scheduled maintenance and repair. It also estimates costs for ten operations types in the typical commercial chart of accounts. MARS was originally developed in 1996, and is currently in its eighth version. It is used by many government agencies and commercial concerns.

Sustainment	Preventive Maintenance & Minor Repair Unscheduled Maintenance Renewal & Replacement
Operations	Custodial Energy Grounds Management Pest Control Refuse Road Clearance Security Telecom Water/Sewer

Note that the definition of future M&R requirements is the same as the "sustainment" requirements used for programming by DoD and an approach endorsed in a National Research Council (NRC) study of Department of Energy facility practices.² Among other agencies, the MARS Facility Cost Forecast System has been used to forecast budgets for the IRS, FAA, USDA, and CDC. It was recently used to benchmark costs for the Department of State Overseas Embassies. MARS is also the basis for the DoD Sustainment Model and a study for NNSA validating total life-cycle facility costs at eight nuclear weapons production and research sites.³ The model is used continuously to simulate alternative facility costs for the U.S. nuclear complex.

The MARS process begins with a component inventory of a building or structure. Derived from building plans, equipment inventory data, and on-site inspections, these components are organized into UNIFORMAT category level three elements and are identified specifically in terms of product characteristics, quantity, and output level; e.g. "Single-Ply Modified

² National Research Council, *Intelligent Sustainment and Renewal of Department of Energy Facilities and Infrastructure*, 2004. P. 44.

³ Jacobs Facilities and Whitestone Research, *Implementation of the Department of Defense Sustainment Model, Final Report*, May 2002.


Bituminous/Thermoplastic Roof," "Condenser, Air-Cooled, 60 Ton," or "Pipe & Fittings, 3/4" Copper."

Once the component inventory is completed, the MARS system relates maintenance tasks from a pre-defined task library to each selected component. New components and related tasks are defined as necessary. The frequency of each task determines the forecast of future required maintenance. MARS estimates four types of maintenance: preventative maintenance, unscheduled maintenance (service calls), repair, and renewal/replacement tasks. Tasks and their labor and material requirements are pre-defined by CBRE | Whitestone, but are also editable.

Other calibration steps include modifying default values for contract and in-house labor rates, specifying site-typical mark-up for contract expenditures, and identifying the utilization characteristics for each asset.

The sources for local wage rates and benefits are primarily the U.S. Department of Labor and Davis-Bacon Act labor agreements, and private sector employers. Both union and non-union wages are considered in determining prevailing rates by locality. State and local wage surveys are also used when available.

MARS Facility Cost Forecast System



MARS is also used to estimate operations costs other than maintenance and repair. These are based on the Facilities Operation Model developed jointly by the Department of Defense (DOD) and CBRE | Whitestone. This model provides costs for ten services, including those mentioned in the Federal Real Property Council (FRPC) guidance—utilities, cleaning and janitorial, and

roads and grounds.⁴ Each operation type for an asset can be calibrated for a level of service (low, medium, high) to reflect the level of demand or frequency at which certain operations task are performed.

The CBRE | Whitestone operations cost models provides estimates for the following services:

Custodial. The custodial function represents the expense of cleaning offices, work areas, restrooms and common areas. Costs include local wage rates and benefits, task productivity, mark-ups for equipment, materials, supervision, and assumptions concerning the level of service. Trash removal costs are not included. Custodial service levels are defined by altering the combination and frequency of common tasks.

Energy. Energy includes all expenses related to the purchase, generation, distribution, and conservation of energy and source fuels necessary to operate an asset. The main energy sources considered are electricity and natural gas. Not included are utilities maintenance and supervision, and utility tax rates. Service levels vary according to estimated commodity demand by asset use type.

Grounds. The grounds function includes any expense related to the maintenance of exterior landscaping. It does not include sweeping or the maintenance of signage, parking lots and roadways. Costs are estimated using local wage rates and benefits, task productivity, mark-ups for equipment, materials and supervision, and assumptions concerning the level of service. Service levels are defined by altering the combination and frequency of common tasks.

Management. The real property management function describes all costs associated with facility management, including: public works, contracts, material procurement, facility data, furnishings, real estate, and engineering services. Costs are expressed as a fixed percentage of Plant Replacement Value. Service levels are based on the distribution of costs found in institutional and commercial settings. For this project, the level of service for all NASA buildings was set to low to reflect economies of scale in a campus environment.

Pest Control. Pest control expenses cover indoor and outdoor pest control programs, separate from the grounds function. Costs are based on the frequency of common tasks for rodent and insect abatement and inspections. Costs include prevailing labor and material rates. Service levels are defined by altering the combination and frequency of common tasks.

Refuse. Refuse costs include all expenses related to trash collection and disposal, pickup services, fees, recycling operations and administration, composting, etc. Costs exclude handling and disposal of HAZMAT materials. Service levels vary according to estimated demand by asset use type.

Road Clearance. The road clearance function includes all expenses related to sweeping paved areas including sidewalks, walkways, and parking lots. Costs include prevailing labor and material rates, and climatic variables. Service levels are defined by altering the combination and frequency of common tasks.

⁴ Federal Real Property Council. *Guidance for Real Property Inventory Reporting.* Washington, D.C. August, 2012.

Security. Security expenses relate to the physical security of assets and occupants, and include personnel, operating and monitoring security equipment. Costs include relevant prevailing labor and material rates. Service levels are defined by altering the combination and frequency of common tasks and services.

Telecommunications. Telecommunication expenses cover the purchase of all the services ordinarily associated with commercial activities, such as voice and data equipment and service subscription. The level of telecommunications is defined by the combination of services selected.

Water and Sewer. Water and Sewer expenses include all costs related to providing the asset with potable water, irrigation water, and sewage service. Estimates include local commodity costs. Service levels vary according to estimated commodity demand by asset use type.

Data Collection and Calibration

MARS Model Development

The technical work for this task involved the definition of the component inventory for the five sample Warehouses. Langley Research Center staff supplied existing equipment inventories and construction design documents before the inspection. Jacobs Facilities inspected the buildings and created draft models in MARS. Plum Brook Station also provided component information for a typical Igloo facility to create a model for the facility type. In total, 226 MARS components were defined for the five facilities.

Jacobs submitted the MARS database to CBRE | Whitestone for a detailed component-by-component review. Three areas of focus included:

- 1) <u>Check for completeness</u>. Review the wall finishes (exterior and interior), roofing, plumbing, HVAC, fire protection, and electrical data to ensure the building model contains the appropriate components in each category.
- 2) <u>Check for consistency</u>. Review the building gross square feet for accuracy. Ensure the square footage of structural components (exterior walls, roofing system, interior finishes) are reasonable compared to building GSFT. Verify the capacity of the following is consistent with the building type and size:
 - Heating, cooling, and air distribution
 - Electrical service, distribution, and lighting
 - Plumbing fixtures and water distribution
 - Fire protection
- 3) <u>Forecast review</u>. Run the following building-level MARS reports and look for extraordinary costs (high or low) illustrating an error in the building model:
 - Average M&R Costs
 - Most Costly M&R Tasks

- Deferred Maintenance Detail
- Operation Cost Summary

We also compared the costs with known resources (*The Whitestone Facility Maintenance and Repair* and *Operations Cost References*, comparable CBRE | Whitestone project work with federal agencies, and third party sources).

Attachments A through E provide detailed MARS component lists for the inspected Warehouse facilities at LaRC and the Plum Brook Station Igloo model.

CBRE | Whitestone also collected information to calibrate the models for local site values.

Local Calibration of MARS

While the MARS system has pre-defined building models, labor and material costs, utility rates, and an extensive component library, all of these values can be changed or supplemented to reflect the actual site practices.

Calibration data was gathered to adjust MARS factors for maintenance & repair and operations costs of the Warehouses. Data was gathered at both the site and the building level. Site-level information, such as labor and utility rates, was directly used to estimate O&M costs for the Warehouses at LaRC and PBS. Building-level calibration data was applied to the sample models and then extrapolated to the remaining NASA inventory.

The following data was collected to calibrate the building models:

<u>Maintenance and Repair</u>. A default assumption in MARS assigns in-house labor to preventative maintenance, minor repair, and unscheduled maintenance, while contract labor performs major repair and replacement tasks. NASA staff indicated all maintenance was performed by contract laborers. CBRE | Whitestone adjusted the MARS database accordingly.

NASA personnel specified laborers must be paid prevailing wages for the area. We used the default MARS wage rates for this study, and included a 30 percent mark-up for contract overhead.

Table 3 shows the source of the maintenance and repair factors for each site.

Table 3. Data Sources by Site, Maintenance & Repair										
Site	In-house Shop Rates	In-house Markup Rates	Contract Labor Rates	Contract Overhead Rates	Utilization					
Langley Research Center Plum Brook Station	N/A N/A	N/A N/A	WST WST	WST WST	Site Site					
Plum Brook Station N/A N/A WST WST Site WST = Whitestone, Site = Respective NASA Site, N/A = Not applicable, no in-house maintenance staff										

MARS estimates also can be adjusted to reflect utilization factors that impact M&R. For example, many NASA facilities have special safety requirements which increase costs relative to conventional commercial practice. Other special requirements include high or low hours of operation and security. Langley Research Center defined utilization factors for the four sample Warehouse facilities.

Table 4 displays the average utilization multipliers for the sample Warehouses used to adjust for these requirements.

Table 4. Average Utilization Adjustment by Site ^A										
Site	Hours of Operation ^B	Security ^c	Safety & Permitting ^D	Sum ^E						
Langley Research Center Plum Brook Station	1.00 1.00	1.00 1.00	1.00 1.00	1.00 1.00						

^A Calculated from individual asset multipliers assigned by the sites.

<u>Operations</u>. MARS also estimates operations costs for ten services including: custodial, energy, grounds, management, pest control, refuse, road clearance, security, telecommunications, and water & sewer. Key drivers of operations estimates include utility rates, labor rates, and mark-ups, which were collected from LaRC and PBS staff.

In addition, MARS is populated with default levels of service by operation and building type. Each sample model was calibrated in terms of the level of service (low, medium, high, or none). The ratings reflect the level of utility demand or frequency of operations tasks in the facility. NASA staff defined levels of service for all operation types and also provided several utility rates.

Other utility rates, such as refuse, provided in Phase 1, 2, and 3 were significantly lower than the default MARS commercial rates. These discounts are often provided to large federal property holders like NASA. NASA staff provided utility rates for the remaining sites in the Warehouses inventory.

As with M&R, CBRE | Whitestone used the default MARS wage rates and a 30 percent mark-up for contract overhead.

Table 5 shows the source of the operations calibration data.

^B Hours of Operation rates building use on a weekly basis and is defined as follows: 0.80 = 40 hours, 1.00 = 41 to 80 hours, 1.37 = 80+ hours.

^c Security is defined as follows: 1.00 = free access, 1.01 = contractor training & daily check-in, 1.15 = full contractor accompanyment.

^D Safety & Permitting is defined as follows: 1.00 = typical commercial & service activity, 1.07 = non-specific laboratory, 1.75 = radiological or life science research, 3.00 = nuclear facility.

^E In combination the multipliers are additive such that the total multiplier = 1 + Σ (β - 1) where β = the multiplier value.

Site	Level of Service	Custodial Wage	Refuse Rates	Energy Rates	Water/Sewer Rates	Groundskeeper Wage	Pest Control Wage	Road Clearance Wage	Security Rates	Property Management	Telecom Rates
Langley Research Center	Site	WST	Site	Site	Site	WST	WST	WST	WST	Site	WST
Plum Brook Station	Site	Site	Site	Site	Site	Site	Site	Site	Site	Site	Site

Cost Estimates for Warehouse Facilities

Sustainment Costs

Detailed sustainment estimates for the small Covered Storage building, small non-temperature controlled General Warehouse, small temperature controlled Dehumidified Warehouse, and large Receiving and Shipping building are show in the MARS reports in Attachments A through E.

The sample estimates were extrapolated to the population. Table 6 shows sustainment costs by site for all Warehouses. Sustainment estimates are expressed as 30, 40, and 50-year averages. While CBRE | Whitestone computes annual requirements, average costs are presented to smooth the annual oscillations. Overall, the sustainment requirements are an average of \$16.6 million per year over 50 years, or \$3.59 per GSFT. Expressed another way, this amounts to 2.4 percent of the \$680 million replacement value.

Table 6.	Average Annual	Estimates of Sustainment	Requirements by	Site	, Warehouse F	acilities
----------	-----------------------	--------------------------	-----------------	------	---------------	-----------

						Susta	ainment	t ^A			
			30-Year	Estima	tes	40-Year	Estima	tes	50-Year	Estima	tes
Site	GSFT	CRV	Avg. Annual Estimate	Per GSFT	Percent CRV	Avg. Annual Estimate	Per GSFT	Percent CRV	Avg. Annual Estimate	Per GSFT	Percent CRV
AMES Research Center	286,982	\$22,015,817	\$1,647,951	\$5.74	7.5%	\$1,532,945	\$5.34	7.0%	\$1,602,658	\$5.58	7.3%
ARC Camp Parks	120,264	\$6,991,699	\$755,034	\$6.28	10.8%	\$702,299	\$5.84	10.0%	\$698,074	\$5.80	10.0%
CAPE	82,005	\$19,868,559	\$259,811	\$3.17	1.3%	\$241,050	\$2.94	1.2%	\$239,003	\$2.91	1.2%
Columbia Scientific Balloon Facility	7,188	\$350,600	\$14,501	\$2.02	4.1%	\$13,348	\$1.86	3.8%	\$14,222	\$1.98	4.1%
Dryden Flight Research Center	74,329	\$8,239,018	\$187,580	\$2.52	2.3%	\$175,202	\$2.36	2.1%	\$167,947	\$2.26	2.0%
Ellington Field (JSC)	52,563	\$5,179,917	\$163,277	\$3.11	3.2%	\$151,171	\$2.88	2.9%	\$151,637	\$2.88	2.9%
Glenn Research Center	66,797	\$19,633,945	\$243,099	\$3.64	1.2%	\$225,862	\$3.38	1.2%	\$256,810	\$3.84	1.3%
GODDARD SPACE FLIGHT CENTER	362,218	\$44,573,625	\$1,831,828	\$5.06	4.1%	\$1,703,419	\$4.70	3.8%	\$1,699,924	\$4.69	3.8%
HAWAII STDN STATION	1,159	\$32,035	\$3,434	\$2.96	10.7%	\$3,212	\$2.77	10.0%	\$5,735	\$4.95	17.9%
Jet Propulsion Laboratory	19,600	\$3,062,033	\$51,626	\$2.63	1.7%	\$47,956	\$2.45	1.6%	\$71,073	\$3.63	2.3%
Johnson Space Center	328,626	\$34,817,504	\$1,176,911	\$3.58	3.4%	\$1,094,674	\$3.33	3.1%	\$1,144,629	\$3.48	3.3%
JPL/Australia - Canberra Deep Space Comm.	6,868	\$1,466,102	\$14,779	\$2.15	1.0%	\$13,618	\$1.98	0.9%	\$15,180	\$2.21	1.0%
JPL/Goldstone - Apollo Site	184	\$373,723	\$511	\$2.78	0.1%	\$478	\$2.60	0.1%	\$853	\$4.64	0.2%
JPL/Goldstone - Echo Site	1,705	\$373,723	\$4,734	\$2.78	1.3%	\$4,427	\$2.60	1.2%	\$7,906	\$4.64	2.1%
JPL/Goldstone - Mars Site	184	\$373,723	\$511	\$2.78	0.1%	\$478	\$2.60	0.1%	\$853	\$4.64	0.2%
JPL/Goldstone - Venus Site	1,514	\$510,989	\$3,635	\$2.40	0.7%	\$3,334	\$2.20	0.7%	\$2,991	\$1.98	0.6%
JPL/Spain - Madrid Deep Space Comm.	26,794	\$3,433,836	\$46,379	\$1.73	1.4%	\$42,972	\$1.60	1.3%	\$58,692	\$2.19	1.7%
Kennedy Space Center	859,813	\$103,341,925	\$2,875,850	\$3.34	2.8%	\$2,672,673	\$3.11	2.6%	\$2,764,840	\$3.22	2.7%
Langley Research Center	178,204	\$22,774,088	\$556,743	\$3.12	2.4%	\$517,458	\$2.90	2.3%	\$552,545	\$3.10	2.4%
Marshall Space Flight Center	391,021	\$55,542,708	\$1,341,387	\$3.43	2.4%	\$1,245,145	\$3.18	2.2%	\$1,269,248	\$3.25	2.3%
Michoud Assembly Facility	362,882	\$107,962,385	\$1,633,545	\$4.50	1.5%	\$1,519,140	\$4.19	1.4%	\$1,513,603	\$4.17	1.4%
Moffett Federal Airfield	107,701	\$9,584,578	\$421,965	\$3.92	4.4%	\$391,880	\$3.64	4.1%	\$478,294	\$4.44	5.0%
NASA/JSC/White Sands Test Facility	37,969	\$2,940,629	\$109,856	\$2.89	3.7%	\$101,820	\$2.68	3.5%	\$103,081	\$2.71	3.5%
Plum Brook Station	261,813	\$46,302,279	\$504,715	\$1.93	1.1%	\$416,015	\$1.59	0.9%	\$365,442	\$1.40	0.8%
Stennis Space Center	202,639	\$49,040,438	\$888,029	\$4.38	1.8%	\$826,065	\$4.08	1.7%	\$822,607	\$4.06	1.7%
Stennis Space Center (MSAAP)	573,114	\$87,022,126	\$1,886,170	\$3.29	2.2%	\$1,742,935	\$3.04	2.0%	\$1,938,519	\$3.38	2.2%
Stennis Space Center (Tenants)	50,539	\$5,030,853	\$124,171	\$2.46	2.5%	\$114,474	\$2.27	2.3%	\$106,817	\$2.11	2.1%
Wallops Flight Facility	140,818	\$19,301,223	\$410,344	\$2.91	2.1%	\$382,677	\$2.72	2.0%	\$497,447	\$3.53	2.6%
Total ^B	4,605,493	\$680,140,080	\$17,158,377	\$3.73	2.5%	\$15,886,726	\$3.45	2.3%	\$16,550,631	\$3.59	2.4%

A Sustainment is the average annual sum of preventative maintenance, unscheduled maintenance, and major repair and replacement tasks.

Operation Costs

Estimates of ten operation costs are shown in Table 7. In total, the operation requirements for the selected Warehouses are an annual average of \$10.3 million, or \$2.24 per GSFT and 1.5 percent of replacement value. Note that in commercial accounting M&R (sustainment) is often included as an operating cost, but is reported separately above.

^B All costs expressed in \$2012.

Table 7. Annual Estimates of Operations Costs by Site, Warehouse Facilities															
							Operations	Type ^A							
									Road				•	Per	Percent
Site	GSFT	CRV	Custodial	Energy	Grounds	Management	Pest Control	Refuse	Clearance	Security	Telecom	Water/Sewer	Total Costs	GSFT	CRV
AMES Research Center	286,982	\$22,015,817	\$107,715	\$154,247	\$49,984	\$55,040	\$42,772	\$1,739	\$0	\$190,493	\$103,389	\$11,736	\$717,114	\$2.50	3.3%
ARC Camp Parks	120,264	\$6,991,699	\$52,492	\$51,132	\$20,949	\$17,479	\$17,924	\$808	\$0	\$60,728	\$45,594	\$5,287	\$272,393	\$2.26	3.9%
CAPE	82,005	\$19,868,559	\$18,516	\$31,665	\$10,123	\$49,671	\$8,315	\$373	\$0	\$41,186	\$24,472	\$3,302	\$187,623	\$2.29	0.9%
Columbia Scientific Balloon Facility	7,188	\$350,600	\$605	\$2,749	\$761	\$877	\$638	\$53	\$0	\$4,649	\$1,266	\$33	\$11,629	\$1.62	3.3%
Dryden Flight Research Center	74,329	\$8,239,018	\$8,322	\$29,230	\$13,664	\$20,598	\$7,187	\$191	\$0	\$40,876	\$11,612	\$933	\$132,612	\$1.78	1.6%
Ellington Field (JSC)	52,563	\$5,179,917	\$9,345	\$22,917	\$6,371	\$12,950	\$4,968	\$595	\$0	\$28,525	\$13,242	\$1,705	\$100,619	\$1.91	1.9%
Glenn Research Center	66,797	\$19,633,945	\$14,491	\$20,599	\$7,078	\$49,085	\$5,265	\$67	\$5,350	\$56,441	\$20,048	\$1,602	\$180,025	\$2.70	0.9%
GODDARD SPACE FLIGHT CENTER	362,218	\$44,573,625	\$164,886	\$161,695	\$45,416	\$111,434	\$49,408	\$2,119	\$5,601	\$194,118	\$132,843	\$26,624	\$894,143	\$2.47	2.0%
HAWAII STDN STATION	1,159	\$32,035	\$69	\$2,032	\$213	\$80	\$164	\$9	\$0	\$2,084	\$358	\$10	\$5,019	\$4.33	15.7%
Jet Propulsion Laboratory	19,600	\$3,062,033	\$1,464	\$6,185	\$3,602	\$7,655	\$1,894	\$50	\$0	\$24,975	\$4,866	\$96	\$50,788	\$2.59	1.7%
Johnson Space Center	328,626	\$34,817,504	\$68,492	\$130,796	\$39,832	\$87,044	\$31,058	\$1,366	\$0	\$210,152	\$98,313	\$10,957	\$678,008	\$2.06	1.9%
JPL/Australia - Canberra Deep Space Comm.	6,868	\$1,466,102	\$697	\$8,417	\$886	\$3,665	\$586	\$78	\$0	\$7,005	\$1,869	\$77	\$23,281	\$3.39	1.6%
JPL/Goldstone - Apollo Site	184	\$373,723	\$8	\$58	\$34	\$934	\$18	\$0	\$0	\$329	\$57	\$1	\$1,439	\$7.82	0.4%
JPL/Goldstone - Echo Site	1,705	\$373,723	\$72	\$538	\$313	\$934	\$165	\$4	\$0	\$3,049	\$526	\$8	\$5,611	\$3.29	1.5%
JPL/Goldstone - Mars Site	184	\$373,723	\$8	\$58	\$34	\$934	\$18	\$0	\$0	\$329	\$57	\$1	\$1,439	\$7.82	0.4%
JPL/Goldstone - Venus Site	1,514	\$510,989	\$193	\$478	\$278	\$1,277	\$146	\$4	\$0	\$658	\$227	\$7	\$3,269	\$2.16	0.6%
JPL/Spain - Madrid Deep Space Comm.	26,794	\$3,433,836	\$2,872	\$25,786	\$3,394	\$8,585	\$2,319	\$247	\$199	\$35,401	\$6,407	\$166	\$85,375	\$3.19	2.5%
Kennedy Space Center	859,813	\$103,341,925	\$202,392	\$340,455	\$106,131	\$258,355	\$87,175	\$4,113	\$0	\$520,760	\$280,127	\$38,059	\$1,837,567	\$2.14	1.8%
Langley Research Center	178,204	\$22,774,088	\$32,565	\$73,200	\$19,513	\$56,935	\$18,452	\$668	\$1,082	\$122,801	\$47,965	\$3,904	\$377,085	\$2.12	1.7%
Marshall Space Flight Center	391,021	\$55,542,708	\$88,521	\$167,050	\$48,861	\$138,857	\$26,172	\$1,786	\$893	\$231,727	\$114,600	\$5,099	\$823,566	\$2.11	1.5%
Michoud Assembly Facility	362,882	\$107,962,385	\$127,494	\$291,934	\$47,424	\$269,906	\$35,015	\$6,045	\$0	\$182,187	\$134,272	\$22,948	\$1,117,224	\$3.08	1.0%
Moffett Federal Airfield	107,701	\$9,584,578	\$20,064	\$37,310	\$18,753	\$23,961	\$16,053	\$420	\$0	\$107,279	\$29,758	\$1,689	\$255,287	\$2.37	2.7%
NASA/JSC/White Sands Test Facility	37,969	\$2,940,629	\$7,799	\$11,648	\$3,632	\$7,352	\$3,780	\$73	\$272	\$21,274	\$10,290	\$259	\$66,379	\$1.75	2.3%
Plum Brook Station	261,813	\$46,302,279	\$12,048	\$21,161	\$8,741	\$115,756	\$5,398	\$53	\$5,484	\$34,328	\$14,330	\$2,156	\$219,455	\$0.84	0.5%
Stennis Space Center	202,639	\$49,040,438	\$72,829	\$168,182	\$23,879	\$122,601	\$16,702	\$1,070	\$0	\$101,632	\$75,538	\$5,722	\$588,153	\$2.90	1.2%
Stennis Space Center (MSAAP)	573,114	\$87,022,126	\$122,946	\$187,409	\$60,710	\$217,555	\$42,103	\$2,081	\$0	\$430,927	\$166,939	\$7,549	\$1,238,219	\$2.16	1.4%
Stennis Space Center (Tenants)	50,539	\$5,030,853	\$8,355	\$20,394	\$5,955	\$12,577	\$4,167	\$144	\$0	\$22,548	\$9,918	\$387	\$84,445	\$1.67	1.7%
Wallops Flight Facility	140,818	\$19,301,223	\$18,533	\$69,864	\$15,415	\$48,253	\$14,578	\$1,473	\$855	\$159,739	\$41,491	\$4,770	\$374,972	\$2.66	1.9%
Total ^B	4,605,493	\$680,140,080	\$1,163,794	\$2,037,187	\$561,947	\$1,700,350	\$442,439	\$25,630	\$19,734	\$2,836,202	\$1,390,371	\$155,086	\$10,332,741	\$2.24	1.5%

[^] Operations include custodial (cleaning, pest control, and trash collection), utilities (energy, water, and sewer), grounds (landscape care, mowing, and snow removal), security, telecommunications, and management.

Total O&M Costs

Estimated total annual Warehouses costs are shown in Table 8. A combination of maintenance and repair (sustainment) and operations, these costs represent an annual average for the next 50 years. Total costs are an estimated \$26.9 million per year, or can also be expressed as \$5.84 per GSFT and 4.0 percent of CRV.

^B All costs expressed in \$2012.

Table 8. Total Annual Costs by Sit	e, Wareh	ouse Facilitie	es				
			O&M Est	timates			
			50-Year Avg.	Annual	-	Per	Percent
Site	GSFT	CRV	Sustainment ^A	Operations ^B	Total Costs	GSFT	CRV
AMES Research Center	286,982	\$22,015,817	\$1,602,658	\$717,114	\$2,319,773	\$8.08	10.5%
ARC Camp Parks	120,264	\$6,991,699	\$698,074	\$272,393	\$970,467	\$8.07	13.9%
CAPE	82,005	\$19,868,559	\$239,003	\$187,623	\$426,626	\$5.20	2.1%
Columbia Scientific Balloon Facility	7,188	\$350,600	\$14,222	\$11,629	\$25,851	\$3.60	7.4%
Dryden Flight Research Center	74,329	\$8,239,018	\$167,947	\$132,612	\$300,559	\$4.04	3.6%
Ellington Field (JSC)	52,563	\$5,179,917	\$151,637	\$100,619	\$252,255	\$4.80	4.9%
Glenn Research Center	66,797	\$19,633,945	\$256,810	\$180,025	\$436,835	\$6.54	2.2%
GODDARD SPACE FLIGHT CENTER	362,218	\$44,573,625	\$1,699,924	\$894,143	\$2,594,067	\$7.16	5.8%
HAWAII STDN STATION	1,159	\$32,035	\$5,735	\$5,019	\$10,754	\$9.28	33.6%
Jet Propulsion Laboratory	19,600	\$3,062,033	\$71,073	\$50,788	\$121,861	\$6.22	4.0%
Johnson Space Center	328,626	\$34,817,504	\$1,144,629	\$678,008	\$1,822,638	\$5.55	5.2%
JPL/Australia - Canberra Deep Space Comm.	6,868	\$1,466,102	\$15,180	\$23,281	\$38,461	\$5.60	2.6%
JPL/Goldstone - Apollo Site	184	\$373,723	\$853	\$1,439	\$2,292	\$12.46	0.6%
JPL/Goldstone - Echo Site	1,705	\$373,723	\$7,906	\$5,611	\$13,517	\$7.93	3.6%
JPL/Goldstone - Mars Site	184	\$373,723	\$853	\$1,439	\$2,292	\$12.46	0.6%
JPL/Goldstone - Venus Site	1,514	\$510,989	\$2,991	\$3,269	\$6,260	\$4.13	1.2%
JPL/Spain - Madrid Deep Space Comm.	26,794	\$3,433,836	\$58,692	\$85,375	\$144,067	\$5.38	4.2%
Kennedy Space Center	859,813	\$103,341,925	\$2,764,840	\$1,837,567	\$4,602,406	\$5.35	4.5%
Langley Research Center	178,204	\$22,774,088	\$552,545	\$377,085	\$929,630	\$5.22	4.1%
Marshall Space Flight Center	391,021	\$55,542,708	\$1,269,248	\$823,566	\$2,092,814	\$5.35	3.8%
Michoud Assembly Facility	362,882	\$107,962,385	\$1,513,603	\$1,117,224	\$2,630,827	\$7.25	2.4%
Moffett Federal Airfield	107,701	\$9,584,578	\$478,294	\$255,287	\$733,581	\$6.81	7.7%
NASA/JSC/White Sands Test Facility	37,969	\$2,940,629	\$103,081	\$66,379	\$169,460	\$4.46	5.8%
Plum Brook Station	261,813	\$46,302,279	\$365,442	\$219,455	\$584,897	\$2.23	1.3%
Stennis Space Center	202,639	\$49,040,438	\$822,607	\$588,153	\$1,410,761	\$6.96	2.9%
Stennis Space Center (MSAAP)	573,114	\$87,022,126	\$1,938,519	\$1,238,219	\$3,176,738	\$5.54	3.7%
Stennis Space Center (Tenants)	50,539	\$5,030,853	\$106,817	\$84,445	\$191,262	\$3.78	3.8%
Wallops Flight Facility	140,818	\$19,301,223	\$497,447	\$374,972	\$872,419	\$6.20	4.5%
Total ^c	4,605,493	\$680,140,080	\$16,550,631	\$10,332,741	\$26,883,371	\$5.84	4.0%

^A Sustainment is the average annual sum of preventative maintenance, unscheduled maintenance, and major repair and replacement tasks.

^B Operations include custodial (cleaning, pest control, and trash collection), utilities (energy, water, and sew er), grounds (landscape care, mow ing, and snow removal), security, telecommunications, and management. $^{\rm B}$ All costs expressed in \$2012.

Attachment A: Detailed MARS Reports for LaRC Property ID 350

Average M&R Costs

Whitestone Research

Building: 1265 Complex **GSFT:** 1,517

Building Number: 1265H PRV: \$91,020

Facility: Langley Research Center Built Date: 1981

City: Hampton, VA

M&R Average Annual Cost Forecasts

_	Current Year	5 Year	20 Year	50 Year
PM & Minor Repair:	\$473	\$526	\$492	\$488
Unscheduled Maintenance:	\$489	\$513	\$487	\$483
Renewal & Replacement:	\$737	\$1,641	\$2,697	\$4,902
Total M&R Costs:	\$1,699	\$2,680	\$3,676	\$5,873
Per GSFT:	\$1.12	\$1.77	\$2.42	\$3.87
As % of PRV:	0.12%	0.18%	0.25%	0.40%

Building Component List Whitestone Research

Building: 1265 Complex Year Built: 1981 Building Type: Non-Temperature Controll

Facility: Langley Research Center Original Cost: \$1 Building Num: 1265H

City: Hampton, VA Replacement Value: \$91,020 per SF: \$60 Building Gsft: 1,517

Uniformat	Asset Description	Component	Date	Quantity	Location	Notes
B2010		Steel, Painted, Exterior, 1st Floor	1981	2185 Sq Ft		
B2020		Aluminum Operable Window, 12 sf, 1st Floor	1981	4 Each		
B2030		Steel Single 12'x12', Painted, Roll-up Door	1981	2 Each		
B2030		Steel, Exterior Door	1981	2 Each		
B3010		Aluminum Gutter, Downspouts, Fittings	1981	0.45 K Ln Ft		
B3010		Metal Roof	1981	1520 Sq Ft		
B3020		Roof Skylight, 20 sf	1981	4 Each		
C3020		Concrete Flooring	1981	1517 Sq Ft		
C3030		Metal Ceiling	1981	1517 Sq Ft		
D2040		Aluminum Gutter, Downspouts, Fittings	1981	0.23 K Ln Ft		
D3040		Exhaust Fan, Propeller, 800 Cfm	1981	1 Each		
D4030		Fire Extinguisher	2010	1 Each		
D5010		Disconnect Switch, 30 Amp.	1981	1 Each		
D5020		Metal Halide Lighting Fixture, Wall Mount, 150 w	1981	2 Each		
D5020		Receptacle, 120 V, 15 Amp.	1981	10 Each		

Building: 1265 Complex Year Built: 1981 Building Type: Non-Temperature Controll

Facility: Langley Research Center Original Cost: \$1 Building Num: 1265H

City: Hampton, VA Replacement Value: \$91,020 per SF: \$60 Building Gsft: 1,517

Uniformat Asset Description	Component	Se	aining rvice .ife*	Quantity	Deferred** Maintenance	Degradation Cost***	Total Deferred Maintenance	Location	Notes
B2010	Steel, Painted, Exterior, 1st Floor	1981	42	2185 Sq Ft					
B2020	Aluminum Operable Window, 12 sf, 1st Floor	1981	42	4 Each					
B2030	Steel Single 12'x12', Painted, Roll-up Door	1981	2	2 Each					
B2030	Steel, Exterior Door	1981	42	2 Each					
B3010	Aluminum Gutter, Downspouts, Fittings	1981 -	-13	0.45 K Ln F	\$2,745	\$0	\$2,745		
B3010	Metal Roof	1981	7	1520 Sq Ft					
B3020	Roof Skylight, 20 sf	1981	7	4 Each					
C3020	Concrete Flooring	1981	42	1517 Sq Ft					
C3030	Metal Ceiling	1981	42	1517 Sq Ft					
D2040	Aluminum Gutter, Downspouts, Fittings	1981 -	-13	0.23 K Ln F	\$6,810	\$0	\$6,810		
D3040	Exhaust Fan, Propeller, 800 Cfm	1981 -	-14	1 Each	\$874	\$0	\$874		
D4030	Fire Extinguisher	2010	8	1 Each					
D5010	Disconnect Switch, 30 Amp.	1981	17	1 Each					
D5020	Metal Halide Lighting Fixture, Wall Mount, 150	1981 -	-13	2 Each	\$1,041	\$0	\$1,041		
D5020	Receptacle, 120 V, 15 Amp.	1981 -	-13	10 Each	\$417	\$0	\$417		

All costs expressed in (\$) 2012.

Forecast Year: 2013


^{*}Remaining Service Life shows years until scheduled Replacement Task; blank implies there is no Replacement Task.


^{**}Deferred Maintenance is defined as the cost of rebuilding or replacing components whose service life has exceeded their scheduled lifetime as of the Forecast Year. Preventative maintenance and minor repairs are not included.

^{***}Degradation Cost is defined as additional cost (penalty cost) incurred by maintenance deferral.

[§] Indicates Component set to have PM Tasks coincide with Replacement Task.

M&R Costs by System per Year Chart	Whitestone Research	23-Dec-14





Notes: A value of "0.00" means cost of more than \$.000 but less than \$.005 per gsft.


All costs expressed in (\$) 2012 per gsft.

Year 1-25


M&R Costs by System per Year Chart

Whitestone Research

23-Dec-14







Notes: A value of "0.00" means cost of more than \$.000 but less than \$.005 per gsft. Based on a 50-Year Forecast.

All costs expressed in (\$) 2012 per gsft.

Year 26-50

M&R Costs by Task Whitestone Research 23-Dec-14

Building: 1265 Complex Facility: Langley Research Center

Building Num: 1265H City: Hampton, VA

Forecast Year:	2013	4	5	6	7	2018	9	0	1	2	2023	4	5	6	7	2028	9	0	1	2	2033	4	5	6	7
B20 Exterior Enclosure																									
Replace Steel Single 12'x12', Painted, Roll-up Door				5,170																					
Replace Steel, Exterior Door																									
Repair Steel, Exterior Door														354											
Replace Steel, Exterior Door Locks									645										645						
Refinish Steel, Painted, Exterior, 1st Floor									2,600										2,600						
Finish Replaced Steel Single 12'x12', Painted, Roll-up Door				293																					
Refinish Steel Single 12'x12', Painted, Roll-up Door														293										293	
Repair Steel Single 12'x12', Painted, Roll-up Door														1,273										1,273	
Replace Aluminum Operable Window, 12 sf, 1st Floor																									
Repair Aluminum Operable Window, 12 sf, 1st Floor														105											
Finish Replaced Steel, Painted, Exterior, 1st Floor																									
Replace Steel, Painted, Exterior, 1st Floor																									
Finish Repaired Steel, Painted, Exterior, 1st Floor																			52						
Repair Steel, Painted, Exterior, 1st Floor (2% of Walls)																			1,200						
Maintain Steel, Exterior Door Locks				42					42					42					42					42	
B30 Roofing																									
Repair Roof Skylight, 20 sf					1,462										1,462						1,462				
Maintain Aluminum Gutter, Downspouts, Fittings	139	139	139	139	139	139	139	139		139	139	139	139	139	139	139	139	139	139	139	139	139	139	139	139
Replace Aluminum Gutter, Downspouts, Fittings	100	100	100	100	100	100	100		2,745	100	100	100	100	100	100	100	100	100	100	100	100	100	100	100	100
Maintain Metal Roof	152	152	152	152	152	152	152	152	2,7 10	152	152	152	152	152	152	152	152	152	152	152	152	152	152	152	152
Repair Metal Roof	102	102	.02	356	102	102	102	102		102	102	102	102	356	102	102	102	.02	356	.02	102	.02	.02	356	102
Minor Replacement, Metal Roof (2% of Roof)				000										000					000					000	
Replace Roof Skylight, 20 sf									3,117																
Replace Metal Roof									15,767																
Replace Metal Roof									.0,.0.																
C30 Interior Finishes																									
Repair Concrete Flooring (2% of Floors)														220											
Replace Concrete Flooring																									
Repair Metal Ceiling (2% of Ceiling)	737								737								737								737
Replace Metal Ceiling																									
D20 Plumbing																									
	71	71	71	71	71	71	71	71		71	71	71	71	71	71	71	71	71	71	71	71	71	71	71	71
Maintain Aluminum Gutter, Downspouts, Fittings	, ,	, ,	/ 1	7.1	, ,	/ 1	/ !	71	6,810	, ,	/ !	/ 1	, ,	, ,	/ !	71	/ !	71	, ,	71	, ,	71	/ !	71	7.1
Replace Aluminum Gutter, Downspouts, Fittings									0,010																

D30 HVAC

M&R Costs by Task Whitestone Research 23-Dec-14

Building: 1265 Complex Facility: Langley Research Center

Building Num: 1265H City: Hampton, VA

Forecast Year: 2038 9 0 1 2 2043 4 5 6 7 2048 9 0 1 2 2053 4 5 6 7 2058 9 0 1

B20	Exterior	Enclosure

Replace Steel Single 12'x12', Painted, Roll-up Door			5,170		
Replace Steel, Exterior Door				1,726	
Repair Steel, Exterior Door	354				
Replace Steel, Exterior Door Locks	645		645		
Refinish Steel, Painted, Exterior, 1st Floor	2,600		2,600		
Finish Replaced Steel Single 12'x12', Painted, Roll-up Door			293		
Refinish Steel Single 12'x12', Painted, Roll-up Door		293			293
Repair Steel Single 12'x12', Painted, Roll-up Door		1,273			1,273
Replace Aluminum Operable Window, 12 sf, 1st Floor				2,996	
Repair Aluminum Operable Window, 12 sf, 1st Floor	105				
Finish Replaced Steel, Painted, Exterior, 1st Floor				4,917	
Replace Steel, Painted, Exterior, 1st Floor				59,992	
Finish Repaired Steel, Painted, Exterior, 1st Floor					
Repair Steel, Painted, Exterior, 1st Floor (2% of Walls)					
Maintain Steel, Exterior Door Locks	42	42	42		42

B30 Roofing

<u></u>																									
Repair Roof Skylight, 20 sf		1,462						1,462						1,462						1,462					
Maintain Aluminum Gutter, Downspouts, Fittings	139	139	139		139	139	139	139	139	139	139	139	139	139	139	139	139	139	139	139	139	139	139		139
Replace Aluminum Gutter, Downspouts, Fittings				2,745																			2	2,745	
Maintain Metal Roof	152	152	152	152	152	152	152	152	152	152	152	152	152	152	152	152	152	152	152	152	152	152	152		152
Repair Metal Roof				356					356					356					356						
Minor Replacement, Metal Roof (2% of Roof)				315																					
Replace Roof Skylight, 20 sf																							:	3,117	
Replace Metal Roof																							15	5,767	

C30 Interior Finishes

Repair Concrete Flooring (2% of Floors)	220			
Replace Concrete Flooring				11,000
Repair Metal Ceiling (2% of Ceiling)		737	737	
Replace Metal Ceiling				37,102

D20 Plumbing

Maintain Aluminum Gutter, Downspouts, Fittings	71	71	71	71	71	71	71	71	71	71	71	71	71	71	71	71	71	71	71	71	71	71	71
Replace Aluminum Gutter, Downspouts, Fittings			6,810																			6,810	

D30 HVAC

M&R Costs by Task Whitestone Research 23-Dec-14


Building: 1265 Complex					Fa	cilit	y: La	ngley	Res	earcl	h Ce	nter														
Building Num: 1265H						Cit	y: Ha	mpto	n, V	Ą																
Foreca	ast Year:	2013	4	5	6	7	2018	9	0	1	2	2023	4	5	6	7	2028	9	0	1	2	2033	4	5	6	7
Maintain Exhaust Fan, Propeller, 800 Cfm		91	91	91	91	91	91		91	91	91	91	91	91	91	91	91	91	91	91	91	91	91	91	91	91
Repair Exhaust Fan, Propeller, 800 Cfm			188																188							
Replace Exhaust Fan, Propeller, 800 Cfm								874																		
D40 Fire Protection				00					20							00										
Inspect & Test Fire Extinguisher				32					32		005					32					32		005			
Replace Fire Extinguisher											295												295			
D50 Electrical																										
Replace Receptacle, 120 V, 15 Amp.										417																
Maintain Disconnect Switch, 30 Amp.		20	20	20	20	20	20	20	20	20	20	20	20	20	20	20	20	20	20		20	20	20	20	20	20
Repair Disconnect Switch, 30 Amp.										125																
Replace Disconnect Switch, 30 Amp.																				333						
Replace Lamp, Metal Halide Lighting Fixture, Wall Mo	unt, 150				192										192					192					192	
Replace Ballast, Metal Halide Lighting Fixture, Wall Mo	ount, 150																			401						
Replace Metal Halide Lighting Fixture, Wall Mount, 15	60 w									1,041																

M&R Costs by Task Whitestone Research 23-Dec-14

Building: 1265 Complex	x				Fa	cilit	y: La	ngley	Res	earch	n Ce	nter														
Building Num: 1265H						Cit	y: Ha	mpto	n, VA	١																
Fore	ecast Year:	2038	9	0	1	2	2043	4	5	6	7	2048	9	0	1	2	2053	4	5	6	7	2058	9	0	1	2
Maintain Exhaust Fan, Propeller, 800 Cfm			91	91	91	91	91	91	91	91	91	91	91	91	91	91	91	91	91	91		91	91	91	91	91
Repair Exhaust Fan, Propeller, 800 Cfm													188													
Replace Exhaust Fan, Propeller, 800 Cfm		874																			874					
D40 Fire Protection Inspect & Test Fire Extinguisher			32					32							32					32						
Replace Fire Extinguisher										295												295				
D50 Electrical Replace Receptacle, 120 V, 15 Amp.					417																				417	
Maintain Disconnect Switch, 30 Amp.		20	20	20	20	20	20	20	20	20	20	20	20	20	20	20	20	20	20	20	20	20	20	20	20	20
Repair Disconnect Switch, 30 Amp.		20	20	20	125	20	20		20	20	20	20	20	20	125	20	20		20	20	20	20	20	20	125	20
Replace Disconnect Switch, 30 Amp.					.20										120										.20	
Replace Lamp, Metal Halide Lighting Fixture, Wall	II Mount, 150									192					192					192						
Replace Ballast, Metal Halide Lighting Fixture, Wa	all Mount, 15														401											
Replace Metal Halide Lighting Fixture, Wall Mount	t, 150 w				1,041																				1,041	

Building: 1265 Complex Building Num: 1265H

City: Hampton, VA



All costs expressed in (\$) 2012.

Forecast Year: 2013

^{*}Deferred Maintenance is defined as the cost of rebuilding or replacing components whose service life has exceeded their scheduled lifetime as of the Forecast Year. Preventative maintenance and minor repairs are not included.

^{**}Degradation Cost is defined as additional cost (penalty cost) incurred by maintenance deferral and is included in Total Deferred Maintenance. Based on a 50-Year Forecast.

Building Deferred Maintenance Detail

Whitestone Research

Building: 1265 Complex

Year Built: 1981

Building Type: Non- Temperature
Controlled

Facility: Langley Research Center Original Cost: \$1

City: Hampton, VA Replacement Value: \$91,020 Building Gsft: 1,517

per SF: \$60 Building Number: 1265H

Year Installed	Years Deferred	Deferred Maintenance Task*		Deferred* Maintenance	Degradation Cost**	Total Deferred Maintenance
1981	12	Replace Aluminum Gutter, Downspouts, Fittings		\$6,810	\$0	\$6,810
1981	12	Replace Aluminum Gutter, Downspouts, Fittings		\$2,745	\$0	\$2,745
1981	12	Replace Metal Halide Lighting Fixture, Wall Mount, 150 w		\$1,041	\$0	\$1,041
1981	13	Replace Exhaust Fan, Propeller, 800 Cfm		\$874	\$0	\$874
1981	12	Replace Receptacle, 120 V, 15 Amp.		\$417	\$0	\$417
			Total	\$11,887	\$0	\$11,887

All costs expressed in (\$) 2012.

Forecast Year: 2013

^{*}Deferred Maintenance is defined as the cost of rebuilding or replacing components whose service life has exceeded their scheduled lifetime as of the Forecast Year. Preventative maintenance and minor repairs are not included.

Building: 1265 Complex GSFT: 1,517

Building Number: 1265H Replacement Value: \$91,020


Facility: Langley Research Center Building Use: Warehouse and Storage

City: Hampton, VA

Building Type: Non-Temperature
Controlled Warehouse

Built Date: 1981

	Annual	Annual	
Operation	Cost/GSFT	Total	Percent
Custodial	\$0.034	\$52	0.5%
Energy	\$0.301	\$456	4.5%
Grounds	\$0.109	\$166	1.6%
M&R	\$3.872	\$5,874	58.1%
Management	\$0.150	\$228	2.3%
Pest Control	\$0.104	\$157	1.6%
Refuse	\$0.002	\$4	0.0%
Road Clearance	\$0.006	\$9	0.1%
Security	\$1.773	\$2,690	26.6%
Telecom	\$0.309	\$468	4.6%
Water/Sewer	\$0.004	\$6	0.1%
Building Total	\$6.66	\$10,111	100.0%



Building Operations Utility Details

Whitestone Research

Building: 1265 Complex Year Built: 1981 Building Type: Non-Temperature Controll

Facility: Langley Research Center Original Cost: \$1 Building Num: 1265H

City: Hampton, VA Replacement Value: \$91,020 per SF: \$60 Building Gsft: 1,517

		Utility	GSFT	Demand	UM	Rate	Cost
Operation:	Energy	Level of Service: Low					
		Electricity	1517	3.717	kWh	\$0.0700	\$395
		Natural Gas	1517	0.054	Thm	\$0.7480	\$62
		Diesel	1517	0.000	Gal	\$3.1876	\$0
		Total:		3.771			\$456
Operation: Refuse		Level of Service: Low					
		Municipal Solid Waste	1517	0.030	Lbs	\$0.0674	\$3
		Recycling	1517	0.010	Lbs	\$0.0348	\$1
		Total:		0.040			\$4
Operation:	Water/Sewer	Level of Service: Low					
		Water	1517	0.560	Gal	\$0.0056	\$5
		Sewer	1517	0.440	Gal	\$0.0023	\$2
		Total:		1.000			\$6

Building Operations Task Details

Whitestone Research

Building: 1265 Complex Year Built: 1981 Building Type: Non-Temperature Controll

Facility: Langley Research Center Original Cost: \$1 Building Num: 1265H

City: Hampton, VA Replacement Value: \$91,020 per SF: \$60 Building Gsft: 1,517

Functional Area Labor Cost Task Cost FA GSFT Task **Material Cost** Operation: Custodial Level of Service: Low Warehouse 1517 Sweep Hard Floor with 48" Push Broom \$27 \$4 \$32 Warehouse 1517 Empty Trash; Wipe Clean & Re-line Basket \$18 \$3 \$20 \$52 Total: \$45 \$7 Operation: Grounds Level of Service: Low Grounds, Improved Mow Turfgrass with 21" Power Mower \$32 \$13 \$45 \$22 Grounds, Improved Aerate Improved Grounds \$9 \$31 Grounds, Improved Clear Shrubs 910 \$18 \$8 \$26 Grounds, Improved Edge Clean & Trim Walks with Gas Powered Edger \$13 \$5 \$19 Overseed, Improved Grounds Grounds, Improved \$11 \$4 \$15 Grounds, Improved 910 Vacuum with 30" Billy Goat \$7 \$3 \$10 \$2 Grounds, Improved Clear Crabgrass \$5 \$8 Grounds, Improved Clear Weeds with 15" Boom, Improved Grounds \$3 \$1 \$4 Grounds, Improved 910 Trim Around Raised Objects with String Edger \$3 \$1 \$4 Grounds, Improved Fertilize Improved Grounds \$2 \$1 \$3 910 Grounds, Improved 910 Sweep with 30" Power Rake \$1 \$1 \$2 \$0 Grounds, Improved Fertilize Using Power Take Off Broadcast \$0 \$0 Total: \$117 \$49 \$166 Operation: Pest Control Level of Service: Medium Pest Controlled Install, or Check and Re-Bait 5 Rodent Boxes \$23 \$77 1517 \$54 Pest Controlled 1517 Perform Crawling Insect Abatement \$41 \$17 \$58 Pest Controlled Inspect Building for Pests \$23 \$0 \$23 1517 Total: \$118 \$39 \$157 **Operation: Road Clearance** Level of Service: Medium Pavement NASA 1213 Plow Paved Area \$7 \$2 \$9 Total: \$7 \$2 \$9

Functional Area	FA GSFT	Task	Labor Cost	Material Cost	Task Cost
Operation: Security		Level of Service: Low			
Secured Area	1517	Patrol Building Perimeter	\$0	\$0	\$0
Secured Area	1517	Guard Lobby/Parking	\$0	\$0	\$0
Total:			\$0	\$0	\$0

All costs expressed in (\$) 2012.

Building Operations Service Details

Whitestone Research

Building: 1265 Complex Year Built: 1981 FTEs: 1 Building Type: Non-Temperature Controll

Facility: Langley Research Center Original Cost: \$1 Building Num: 1265H

City: Hampton, VA Replacement Value: \$91,020 per SF: \$60 Building Gsft: 1,517

		Service*	Quantity	Rate	Cost
Operation:	Security	Level of Service: Low			
		Access Control	1	\$2,690	\$2,690
		Total:			\$2,690
Operation:	Telecom	Level of Service: Low			
		Local Telephone	1	\$468	\$468
		Total:			\$468

All costs expressed in (\$) 2012.

^{*} Secutity may be composed of service and task based cost. See Building Operations Task Details for Security Tasks.

Building Operations Management Details

Whitestone Research

Building: 1265 Complex Year Built: 1981 Building Type: Non-Temperature Controll

Facility: Langley Research Center Original Cost: \$1 Building Num: 1265H

City: Hampton, VA Replacement Value: \$91,020 per SF: \$60 Building Gsft: 1,517

-	Service	Demand	UM	PRV	Cost
Operation: Management	Level of Service: Low				
	Management	0.3%	PRV	\$1,454,251	\$3,636
	Total:				\$3,636

All costs expressed in (\$) 2012.

Attachment B: Detailed MARS Reports for LaRC Property ID 46

Average M&R Costs

Whitestone Research

Building: Storage Facility GSFT: 3,448

Building Number: 1175 PRV: \$223,719

Facility: Langley Research Center Built Date: 1988

City: Hampton, VA

M&R Average Annual Cost Forecasts

	Current Year	5 Year	20 Year	50 Year
PM & Minor Repair:	\$2,791	\$2,826	\$2,678	\$2,701
Unscheduled Maintenance:	\$1,823	\$1,812	\$1,724	\$1,746
Renewal & Replacement:	\$3,258	\$959	\$5,886	\$4,500
Total M&R Costs:	\$7,872	\$5,597	\$10,288	\$8,947
Per GSFT:	\$2.28	\$1.62	\$2.98	\$2.59
As % of PRV:	3.52%	2.50%	4.60%	4.00%

Building Component List Whitestone Research

Building: Storage Facility

Year Built: 1988

Building Type: Temperature Controlled W

Facility: Langley Research Center Original Cost: \$1 Building Num: 1175

City: Hampton, VA Replacement Value: \$223,719 per SF: \$65 Building Gsft: 3,448

Uniformat	Asset Description	Component	Date	Quantity	Location	Notes
B2010		Steel, Painted, Exterior, 1st Floor	1988	4050 Sq Ft		
B2030		Steel, 10'x8', Painted, Overhead Coiling Door, Motorized	1988	1 Each		
B2030		Steel, Painted, Insulated, Exterior Door	1988	1 Each		
B3010		Aluminum Gutter, Downspouts, Fittings	1988	0.45 K Ln Ft		
B3010		Metal Roof	1988	3500 Sq Ft		
C3020		Concrete Flooring	1988	3448 Sq Ft		
D3050	Bard Manufacturing M#	Heat Pump, 3 Ton	1988	2 Each		4 Ton Through the wall type
D3060		Thermostat	1988	2 Each		
D4010		Fire Alarm Control Panel	1988	1 Each		
D4030		Fire Extinguisher	2010	2 Each		
D5010		Disconnect Switch, 30 Amp.	1988	4 Each		
D5010		Power Panel Board, 208 Y/120 V, 200 Amp.	1988	2 Each		
D5010		Secondary Transformer, Dry, 112-1/2 kVA	1988	1 Each		
D5020		Emergency Lighting Pack, 2 Light w/ Battery	2000	1 Each		
D5020		Exit Lighting Fixture, w/ Battery	2000	1 Each		
D5020		Fluorescent Lighting Fixture, T8, 2-32w	1988	12 Each		
D5020		Receptacle, 120 V, 15 Amp.	1988	16 Each		
D5020		Wiring Device, Switch	1988	5 Each		
D5030		Fire Alarm Bell, 6"	2000	2 Each		
D5030		Manual Pull Station	2000	1 Each		
G2040		Chain Link Fence Pedestrian Gate, 4' Wide	2000	2 Each		
G2040		Chain Link Fence, 8'	2000	130 Ln Ft		

Building: Storage Facility

Year Built: 1988

Building Type: Temperature Controlled W

Facility: Langley Research Center Original Cost: \$1 Building Num: 1175

City: Hampton, VA Replacement Value: \$223,719 per SF: \$65 Building Gsft: 3,448

B2010 Steel, Painted, Exterior, 1st Floor 1988 49 4050 Sq Ft B2030 Steel, 10'x8', Painted, Overhead Coiling Door, 1988 9 1 Each	
R2030 Steel 10/y8! Painted Overhead Coiling Door 1988 0 1 Each	
b2000 Steel, 1000, Failited, Overhead Colling Dool, 1300 3 I Lacil	
B2030 Steel, Painted, Insulated, Exterior Door 1988 49 1 Each	
B3010 Aluminum Gutter, Downspouts, Fittings 1988 -6 0.45 K Ln Ft \$2,745 \$0 \$2,745	
B3010 Metal Roof 1988 14 3500 Sq Ft	
C3020 Concrete Flooring 1988 49 3448 Sq Ft	
D3050 Bard Manufacturing M Heat Pump, 3 Ton 1988 6 2 Each 4 Ton Ti	rough the wall
D3060 Thermostat 1988 -16 2 Each \$700 \$0 \$700	
D4010 Fire Alarm Control Panel 1988 -11 1 Each \$3,041 \$0 \$3,041	
D4030 Fire Extinguisher 2010 8 2 Each	
D5010 Disconnect Switch, 30 Amp. 1988 24 4 Each	
D5010 Power Panel Board, 208 Y/120 V, 200 Amp. 1988 4 2 Each	
D5010 Secondary Transformer, Dry, 112-1/2 kVA 1988 4 1 Each	
D5020 Emergency Lighting Pack, 2 Light w/ Battery 2000 6 1 Each	
D5020 Exit Lighting Fixture, w/ Battery 2000 6 1 Each	
D5020 Fluorescent Lighting Fixture, T8, 2-32w 1988 -6 12 Each \$1,994 \$0 \$1,994	
D5020 Receptacle, 120 V, 15 Amp. 1988 -6 16 Each \$667 \$0 \$667	
D5020 Wiring Device, Switch 1988 -11 5 Each \$169 \$0 \$169	
D5030 Fire Alarm Bell, 6" 2000 6 2 Each	
D5030 Manual Pull Station 2000 1 1 Each	
G2040 Chain Link Fence Pedestrian Gate, 4' Wide 2000 -4 2 Each \$812 \$0 \$812	

^{*}Remaining Service Life shows years until scheduled Replacement Task; blank implies there is no Replacement Task.

All costs expressed in (\$) 2012.

Forecast Year: 2013

^{**}Deferred Maintenance is defined as the cost of rebuilding or replacing components whose service life has exceeded their scheduled lifetime as of the Forecast Year. Preventative maintenance and minor repairs are not included.

^{***}Degradation Cost is defined as additional cost (penalty cost) incurred by maintenance deferral.

[§] Indicates Component set to have PM Tasks coincide with Replacement Task.

Uniformat Asset Description	Component	P Date	Remaining Service Life*	Quantity	Deferred** Maintenance	Degradation Cost***	Total Deferred Maintenance	Location	Notes	
G2040	Chain Link Fence 8'	2000	16	130 I n Ft						

^{*}Remaining Service Life shows years until scheduled Replacement Task; blank implies there is no Replacement Task.

^{**}Deferred Maintenance is defined as the cost of rebuilding or replacing components whose service life has exceeded their scheduled lifetime as of the Forecast Year. Preventative maintenance and minor repairs are not included.


^{***}Degradation Cost is defined as additional cost (penalty cost) incurred by maintenance deferral.

[§] Indicates Component set to have PM Tasks coincide with Replacement Task.


M&R Costs by System per Year Chart

Whitestone Research

23-Dec-14







Notes: A value of "0.00" means cost of more than \$.000 but less than \$.005 per gsft.


All costs expressed in (\$) 2012 per gsft.

Year 1-25


M&R Costs by System per Year Chart

Whitestone Research

23-Dec-14







Notes: A value of "0.00" means cost of more than \$.000 but less than \$.005 per gsft.

All costs expressed in (\$) 2012 per gsft.

Year 26-50

Building: Storage Facility Facility: Langley Research Center City: Hampton, VA **Building Num: 1175** Forecast Year: 2013 2 2023 7 2028 **B20 Exterior Enclosure** Repair Steel, Painted, Exterior, 1st Floor (2% of Walls) 2,224 Finish Repaired Steel, Painted, Exterior, 1st Floor 96 Maintain Steel, 10'x8', Painted, Overhead Coiling Door, Motoriz Repair Steel, 10'x8', Painted, Overhead Coiling Door, Motorize Refinish Steel, 10'x8', Painted, Overhead Coiling Door, Motoriz 147 Replace Steel, 10'x8', Painted, Overhead Coiling Door, Motoriz Finish Replaced Steel, 10'x8', Painted, Overhead Coiling Door, Maintain Steel, Painted, Insulated, Exterior Door Locks Replace Steel, Painted, Insulated, Exterior Door Locks Refinish Steel, Painted, Insulated, Exterior Door Repair Steel, Painted, Insulated, Exterior Door Refinish Steel, Painted, Exterior, 1st Floor **B30** Roofing Replace Aluminum Gutter, Downspouts, Fittings 2.745 Replace Metal Roof 36,306 Minor Replacement, Metal Roof (2% of Roof) Maintain Metal Roof Maintain Aluminum Gutter, Downspouts, Fittings 139 139 139 139 139 139 139 Repair Metal Roof 820 C30 Interior Finishes Repair Concrete Flooring (2% of Floors) D30 HVAC 1,155 1,155 1,155 1,155 1,155 1,155 1,155 1.155 1.155 1.155 Maintain Heat Pump, 3 Ton 1,155 1,155 1,155 1,155 1.155 1,155 Repair Heat Pump, 3 Ton Replace Heat Pump, 3 Ton Maintain Thermostat Replace Thermostat **D40 Fire Protection** Inspect & Test Fire Extinguisher Replace Fire Extinguisher Inspect & Test Fire Alarm Control Panel Repair Fire Alarm Control Panel Replace Fire Alarm Control Panel 3,041 3,041

Building: Storage Facility Facility: Langley Research Center **Building Num: 1175** City: Hampton, VA Forecast Year: 7 2048 2 2053 **B20 Exterior Enclosure** Repair Steel, Painted, Exterior, 1st Floor (2% of Walls) 2,224 Finish Repaired Steel, Painted, Exterior, 1st Floor 96 Maintain Steel, 10'x8', Painted, Overhead Coiling Door, Motori Repair Steel, 10'x8', Painted, Overhead Coiling Door, Motoriz Refinish Steel, 10'x8', Painted, Overhead Coiling Door, Motori Replace Steel, 10'x8', Painted, Overhead Coiling Door, Motori 4,125 Finish Replaced Steel, 10'x8', Painted, Overhead Coiling Door Maintain Steel, Painted, Insulated, Exterior Door Locks Replace Steel, Painted, Insulated, Exterior Door Locks 316 316 Refinish Steel, Painted, Insulated, Exterior Door 26 Repair Steel, Painted, Insulated, Exterior Door Refinish Steel, Painted, Exterior, 1st Floor 4,819 4,819 **B30** Roofing Replace Aluminum Gutter, Downspouts, Fittings 2.745 Replace Metal Roof Minor Replacement, Metal Roof (2% of Roof) Maintain Metal Roof Maintain Aluminum Gutter, Downspouts, Fittings 139 139 139 139 139 139 139 139 139 139 Repair Metal Roof 820 820 C30 Interior Finishes Repair Concrete Flooring (2% of Floors) D30 HVAC 1,155 1,155 1,155 1,155 1,155 1,155 1,155 1,155 1,155 1.155 Maintain Heat Pump, 3 Ton 1.155 1.155 1.155 1,155 1,155 1,155 1,155 Repair Heat Pump, 3 Ton Replace Heat Pump, 3 Ton Maintain Thermostat Replace Thermostat 700 **D40 Fire Protection** Inspect & Test Fire Extinguisher Replace Fire Extinguisher 590 Inspect & Test Fire Alarm Control Panel 128 118 Repair Fire Alarm Control Panel 118 Replace Fire Alarm Control Panel 3,041

Building: Storage Facility Facility: Langley Research Center

Building Num: 1175					City	/ : Ha	ampto	on, V	Д																
Forecast Year:	2013	4	5	6	7	2018	9	0	1	2	2023	4	5	6	7	2028	9	0	1	2	2033	4	5	6	7
D50 Electrical																									
Replace Lamp, Exit Lighting Fixture, w/ Battery			71										71					71					71		
Replace Manual Pull Station			116															116							
Check & Repair Manual Pull Station													50												
Replace Fire Alarm Bell, 6"								360																	
Replace Wiring Device, Switch						169															169				
Repair Wiring Device, Switch																164									
Replace Receptacle, 120 V, 15 Amp.																667									
Replace Fluorescent Lighting Fixture, T8, 2-32 w																1,994									
Replace Exit Lighting Fixture, w/ Battery								328																	
Replace Emergency Lighting Pack, 2 Light w/ Battery								1,004																	
Repair Power Panel Board, 208 Y/120 V, 200 Amp.																192									
Maintain Disconnect Switch, 30 Amp.	79	79	79	79	79	79	79	79	79	79	79	79	79	79	79	79	79	79	79	79	79	79	79	79	79
Repair Disconnect Switch, 30 Amp.						501										501									
Replace Ballast & Lamps, Fluorescent Lighting Fixture, T8, 2-3						1,250																			
Maintain Power Panel Board, 208 Y/120 V, 200 Amp.	120	120	120	120	120		120	120	120	120	120	120	120	120	120	120	120	120	120	120	120	120	120	120	120
Replace Lens, Replace Emergency Lighting Pack, 2 Light w/ Ba																		32							
Replace Power Panel Board, 208 Y/120 V, 200 Amp.						11,239																			
Maintain Secondary Transformer, Dry, 112-1/2 kVA	60	60	60	60	60		60	60	60	60	60	60	60	60	60	60	60	60	60	60	60	60	60	60	60
Repair Secondary Transformer, Dry, 112-1/2 kVA																268									
Replace Secondary Transformer, Dry, 112-1/2 kVA						8,873																			
Replace Lamp, Replace Emergency Lighting Pack, 2 Light w/ B		64		64		64				64		64		64		64		64		64		64		64	
Replace Disconnect Switch, 30 Amp.																									
G20 Site Improvements																									
Maintain Chain Link Fence Pedestrian Gate, 4' Wide	235	235	235	235	235	235	235		235	235	235	235	235	235	235	235	235		235	235	235	235	235	235	235
Maintain Chain Link Fence, 8'	370	370	370	370	370	370	370	370	370	370	370	370	370	370	370	370	370		370	370	370	370	370	370	370
Replace Chain Link Fence Pedestrian Gate, 4' Wide								812										812							

Maintain Chain Link Fence Pedestrian Gate, 4' Wide	235	235	235	235	235	235	235		235	235	235	235	235	235	235	235	235		235	235	235	235	235	235	235
Maintain Chain Link Fence, 8'	370	370	370	370	370	370	370	370	370	370	370	370	370	370	370	370	370		370	370	370	370	370	370	370
Replace Chain Link Fence Pedestrian Gate, 4' Wide								812										812							
Replace 2" Gate Posts, Pedestrian Gate			1,422										1,422										1,422		
Replace Chain Link Fence, 8'																		8,458							

Building: Storage Facility Facility: Langley Research Center

Building Num: 1175 City: Hampton, VA

D50	Ε	ec	t	ri	C	â	ı	
D I -				_				


Dou Electrical																									
Replace Lamp, Exit Lighting Fixture, w/ Battery								71					71					71							
Replace Manual Pull Station								116															116		
Check & Repair Manual Pull Station			50															50							
Replace Fire Alarm Bell, 6"			360																				360		
Replace Wiring Device, Switch											169														
Repair Wiring Device, Switch						164															164				
Replace Receptacle, 120 V, 15 Amp.											667														
Replace Fluorescent Lighting Fixture, T8, 2-32 w											1,994														
Replace Exit Lighting Fixture, w/ Battery			328																				328		
Replace Emergency Lighting Pack, 2 Light w/ Battery			1,004																				1,004		
Repair Power Panel Board, 208 Y/120 V, 200 Amp.	192																				192				
Maintain Disconnect Switch, 30 Amp.		79	79	79	79	79	79	79	79	79	79	79	79	79	79	79	79	79	79	79	79	79	79	79	79
Repair Disconnect Switch, 30 Amp.											501										501				
Replace Ballast & Lamps, Fluorescent Lighting Fixture, T8, 2-	1,250																				1,250				
Maintain Power Panel Board, 208 Y/120 V, 200 Amp.	120	120	120	120	120	120	120	120	120	120		120	120	120	120	120	120	120	120	120	120	120	120	120	120
Replace Lens, Replace Emergency Lighting Pack, 2 Light w/													32												
Replace Power Panel Board, 208 Y/120 V, 200 Amp.											11,239														
Maintain Secondary Transformer, Dry, 112-1/2 kVA	60	60	60	60	60	60	60	60	60	60		60	60	60	60	60	60	60	60	60	60	60	60	60	60
Repair Secondary Transformer, Dry, 112-1/2 kVA	268																				268				
Replace Secondary Transformer, Dry, 112-1/2 kVA											8,873														
Replace Lamp, Replace Emergency Lighting Pack, 2 Light w/	64				64		64		64		64		64		64		64		64		64				64
Replace Disconnect Switch, 30 Amp.	1,334																								
G20 Site Improvements																									
Maintain Chain Link Fence Pedestrian Gate, 4' Wide	235	235		235	235	235	235	235	235	235	235	235		235	235	235	235	235	235	235	235	235		235	235
Maintain Chain Link Fence, 8'	370	370	370	370	370	370	370	370	370	370	370	370	370	370	370	370	370	370	370	370	370	370		370	370
Replace Chain Link Fence Pedestrian Gate, 4' Wide			812										812										812		
Replace 2" Gate Posts, Pedestrian Gate								1,422										1,422							

Maintain Chain Link Fence Pedestrian Gate, 4' Wide	235	235		235	235	235	235	235	235	235	235	235		235	235	235	235	235	235	235	235	235		235	235
Maintain Chain Link Fence, 8'	370	370	370	370	370	370	370	370	370	370	370	370	370	370	370	370	370	370	370	370	370	370		370	370
Replace Chain Link Fence Pedestrian Gate, 4' Wide			812										812										812		
Replace 2" Gate Posts, Pedestrian Gate								1,422										1,422							
Replace Chain Link Fence, 8'																							8,458		

Building Deferred Maintenance by System Chart

Building: Storage Facility Building Num: 1175

City: Hampton, VA



All costs expressed in (\$) 2012.

^{*}Deferred Maintenance is defined as the cost of rebuilding or replacing components whose service life has exceeded their scheduled lifetime as of the Forecast Year. Preventative maintenance and minor repairs are not included.

^{**}Degradation Cost is defined as additional cost (penalty cost) incurred by maintenance deferral and is included in Total Deferred Maintenance. Based on a 50-Year Forecast.

Building Deferred Maintenance Detail

Whitestone Research

Building: Storage Facility

Year Built: 1988

Building Type: Temperature

Facility: Langley Research Center Original Cost: \$1

Controlled Warehouse

City: Hampton, VA Replacement Value: \$223,719 Building Gsft: 3,448

per SF: \$65 Building Number: 1175

Year Installed	Years Deferred	Deferred Maintenance Task*		Deferred* Maintenance	Degradation Cost**	Total Deferred Maintenance
1988	10	Replace Fire Alarm Control Panel		\$3,041	\$0	\$3,041
1988	5	Replace Aluminum Gutter, Downspouts, Fittings		\$2,745	\$0	\$2,745
1988	5	Replace Fluorescent Lighting Fixture, T8, 2-32 w		\$1,994	\$0	\$1,994
2000	3	Replace Chain Link Fence Pedestrian Gate, 4' Wide		\$812	\$0	\$812
1988	15	Replace Thermostat		\$700	\$0	\$700
1988	5	Replace Receptacle, 120 V, 15 Amp.		\$667	\$0	\$667
1988	10	Replace Wiring Device, Switch		\$169	\$0	\$169
			Total	\$10,128	\$0	\$10,128

All costs expressed in (\$) 2012.

^{*}Deferred Maintenance is defined as the cost of rebuilding or replacing components whose service life has exceeded their scheduled lifetime as of the Forecast Year. Preventative maintenance and minor repairs are not included.

Built Date: 1988


Building: Storage Facility GSFT: 3,448
Building Number: 1175 Replacement Value: \$223,719

Facility: Langley Research Center Building Use: Warehouse and Storage

City: Hampton, VA Building Type: Temperature Controlled

Warehouse

	Annual	Annual	
Operation	Cost/GSFT	Total	Percent
Custodial	\$0.034	\$119	0.7%
Energy	\$0.873	\$3,012	18.0%
Grounds	\$0.109	\$377	2.3%
M&R	\$2.595	\$8,947	53.4%
Management	\$0.162	\$559	3.3%
Pest Control	\$0.104	\$357	2.1%
Refuse	\$0.002	\$8	0.0%
Road Clearance	\$0.006	\$21	0.1%
Security	\$0.780	\$2,690	16.1%
Telecom	\$0.136	\$468	2.8%
Water/Sewer	\$0.054	\$187	1.1%
Building Total	\$4.86	\$16,745	100.0%



Building Operations Utility Details

Whitestone Research

Building: Storage Facility

Year Built: 1988

Building Type: Temperature Controlled W

Facility: Langley Research Center Original Cost: \$1 Building Num: 1175

City: Hampton, VA Replacement Value: \$223,719 per SF: \$65 Building Gsft: 3,448

		Utility	GSFT	Demand	UM	Rate	Cost
Operation:	Energy	Level of Service: Medium					
		Electricity	3448	10.791	kWh	\$0.0700	\$2,605
		Natural Gas	3448	0.158	Thm	\$0.7480	\$407
		Diesel	3448	0.000	Gal	\$3.1876	\$0
		Total:		10.949			\$3,012
Operation:	Refuse	Level of Service: Low					
		Municipal Solid Waste	3448	0.030	Lbs	\$0.0674	\$7
		Recycling	3448	0.010	Lbs	\$0.0348	\$1
		Total:		0.040			\$8
Operation:	Water/Sewer	Level of Service: Medium					
		Water	3448	7.280	Gal	\$0.0056	\$141
		Sewer	3448	5.720	Gal	\$0.0023	\$46
		Total:		13.000			\$187

Building Operations Task Details

Whitestone Research

Building: Storage Facility

Year Built: 1988

Building Type: Temperature Controlled W

Facility: Langley Research Center Original Cost: \$1 Building Num: 1175

City: Hampton, VA Replacement Value: \$223,719 per SF: \$65 Building Gsft: 3,448

Functional Area	FA GSFT	Task	Labor Cost	Material Cost	Task Cost
Operation: Custodia	al	Level of Service: Low			
Warehouse	3448	Sweep Hard Floor with 48" Push Broom	\$62	\$10	\$72
Warehouse	3448	Empty Trash; Wipe Clean & Re-line Basket	\$40	\$6	\$46
Total:			\$102	\$17	\$119
Operation: Grounds	5	Level of Service: Low			
Grounds, Improved	2068	Mow Turfgrass with 21" Power Mower	\$72	\$30	\$102
Grounds, Improved	2068	Aerate Improved Grounds	\$49	\$20	\$70
Grounds, Improved	2068	Clear Shrubs	\$41	\$17	\$58
Grounds, Improved	2068	Edge Clean & Trim Walks with Gas Powered Edger	\$30	\$12	\$43
Grounds, Improved	2068	Overseed, Improved Grounds	\$25	\$10	\$35
Grounds, Improved	2068	Vacuum with 30" Billy Goat	\$16	\$7	\$23
Grounds, Improved	2068	Clear Crabgrass	\$12	\$5	\$17
Grounds, Improved	2068	Clear Weeds with 15" Boom, Improved Grounds	\$7	\$3	\$9
Grounds, Improved	2068	Trim Around Raised Objects with String Edger	\$6	\$3	\$9
Grounds, Improved	2068	Fertilize Improved Grounds	\$5	\$2	\$7
Grounds, Improved	2068	Sweep with 30" Power Rake	\$3	\$1	\$5
Grounds, Improved	2068	Fertilize Using Power Take Off Broadcast	\$0	\$0	\$0
Total:			\$267	\$111	\$377
Operation: Pest Cor	ntrol	Level of Service: Medium			
Pest Controlled	3448	Install, or Check and Re-Bait 5 Rodent Boxes	\$123	\$51	\$174
Pest Controlled	3448	Perform Crawling Insect Abatement	\$93	\$38	\$131
Pest Controlled	3448	Inspect Building for Pests	\$51	\$0	\$51
Total:			\$267	\$90	\$357
Operation: Road Cl	earance	Level of Service: Medium			
Pavement NASA	2758	Plow Paved Area	\$16	\$5	\$21
Total:			\$16	\$5	\$21

Functional Area	FA GSFT	Task	Labor Cost	Material Cost	Task Cost
Operation: Security		Level of Service: Low			
Secured Area	3448	Patrol Building Perimeter	\$0	\$0	\$0
Secured Area	3448	Guard Lobby/Parking	\$0	\$0	\$0
Total:			\$0	\$0	\$0

Building Operations Service Details

Whitestone Research

Building: Storage Facility

Year Built: 1988

FTEs: 1

Building Type: Temperature Controlled W

Facility: Langley Research Center Original Cost: \$1 Building Num: 1175

City: Hampton, VA Replacement Value: \$223,719 per SF: \$65 Building Gsft: 3,448

		Service*	Quantity	Rate	Cost
Operation:	Security	Level of Service: Low			
		Access Control	1	\$2,690	\$2,690
		Total:			\$2,690
Operation:	Telecom	Level of Service: Low			
		Local Telephone	1	\$468	\$468
		Total:			\$468

^{*} Secutity may be composed of service and task based cost. See Building Operations Task Details for Security Tasks.

Building Operations Management Details

Whitestone Research

Building: Storage Facility

Year Built: 1988

Building Type: Temperature Controlled W

Facility: Langley Research Center Original Cost: \$1 Building Num: 1175

City: Hampton, VA Replacement Value: \$223,719 per SF: \$65 Building Gsft: 3,448

	Service	Demand	UM	PRV	Cost
Operation: Management	Level of Service: Low				
	Management	0.3%	PRV	\$223,719	\$559
	Total:				\$559

Attachment C: Detailed MARS Reports for LaRC Property ID 212

Average M&R Costs

Whitestone Research

Building: Storage Facility **GSFT:** 6,246

Building Number: 1240 PRV: \$367,378

Facility: Langley Research Center Built Date: 1951

City: Hampton, VA

M&R Average Annual Cost Forecasts

_	Current Year	5 Year	20 Year	50 Year
PM & Minor Repair:	\$1,417	\$1,379	\$1,423	\$1,435
Unscheduled Maintenance:	\$1,298	\$1,245	\$1,280	\$1,299
Renewal & Replacement:	\$3,215	\$5,070	\$13,083	\$7,570
Total M&R Costs:	\$5,930	\$7,694	\$15,786	\$10,304
Per GSFT:	\$0.95	\$1.23	\$2.53	\$1.65
As % of PRV:	1.61%	2.09%	4.30%	2.80%

Building Component List

Whitestone Research

Building: Storage Facility

Year Built: 1951

Building Type: Non-Temperature Controll

Facility: Langley Research Center Original Cost: \$1 Building Num: 1240

City: Hampton, VA Replacement Value: \$367,378 per SF: \$59 Building Gsft: 6,246

Uniformat	Asset Description	Component	Date	Quantity	Location	Notes
B2010		Steel, Painted, Exterior, 1st Floor	1951	3900 Sq Ft		
B2020		Aluminum Fixed Window, 12 sf, 1st Floor	1990	14 Each		
B2030		Steel w/ Safety Glass, Painted, Exterior Door	1951	2 Each		
B2030		Steel, 14'x10', Painted, Overhead Coiling Door, Motorized	1980	2 Each		
B3010		Aluminum Gutter, Downspouts, Fittings	1951	0.5 K Ln Ft		
B3010		Metal Roof	1951	3600 Sq Ft		
C1020		Steel, Painted, Interior Door	1951	3 Each		
C3010		Gypsum Board, Interior Wall Finish	1951	700 Sq Ft		
C3010		Wood, Finished, Interior Paneling	1951	600 Sq Ft		
C3020		Carpet, Nylon 20 oz., High Traffic	2005	450 Sq Ft		
C3020		Concrete Flooring	1951	3050 Sq Ft		
D3040		Exhaust Fan, Propeller, 375 Cfm	1951	1 Each		
D3050		Air Conditioner, Window, 1 Ton	1951	4 Each		
D3050		Baseboard Heating Units	1951	7 Each		
D4030		Fire Extinguisher	2010	4 Each		
D5010		Disconnect Switch, 30 Amp.	1951	4 Each		
D5010		Power Panel Board, 208 Y/120 V, 400 Amp.	1951	1 Each		
D5020		Fluorescent Lighting Fixture, T8, 2-32w	1951	12 Each		
D5020		Fluorescent Lighting Fixture, T8, 4-32 w	1951	36 Each		
D5020		Metal Halide Lighting Fixture, Wall Mount, 150 w	2000	2 Each		
D5020		Receptacle, 120 V, 15 Amp.	1951	30 Each		
D5020		Wiring Device, Switch	1951	10 Each		
D5030		Public Address Speaker	1951	3 Each		

23-Dec-14

Building: Storage Facility

Year Built: 1951

Building Type: Non-Temperature Controll

Facility: Langley Research Center Original Cost: \$1 Building Num: 1240

City: Hampton, VA Replacement Value: \$367,378 per SF: \$59 Building Gsft: 6,246

Uniformat Asset Description	Component	Date	Remaining Service Life*	Quantity	Deferred** Maintenance	Degradation Cost***	Total Deferred Maintenance	Location	Notes
B2010	Steel, Painted, Exterior, 1st Floor	1951	12	3900 Sq Ft					
B2020	Aluminum Fixed Window, 12 sf, 1st Floor	1990	51	14 Each					
B2030	Steel w/ Safety Glass, Painted, Exterior Door	1951	12	2 Each					
B2030	Steel, 14'x10', Painted, Overhead Coiling Door	1980	1	2 Each					
B3010	Aluminum Gutter, Downspouts, Fittings	1951	-43	0.5 K Ln Ft	\$3,050	\$0	\$3,050		
B3010	Metal Roof	1951	-23	3600 Sq Ft	\$37,343	\$0	\$37,343		
C1020	Steel, Painted, Interior Door	1951	12	3 Each					
C3010	Gypsum Board, Interior Wall Finish	1951	12	700 Sq Ft					
C3010	Wood, Finished, Interior Paneling	1951	12	600 Sq Ft					
C3020	Carpet, Nylon 20 oz., High Traffic	2005	-1	450 Sq Ft					
C3020	Concrete Flooring	1951	12	3050 Sq Ft					
D3040	Exhaust Fan, Propeller, 375 Cfm	1951	-44	1 Each	\$614	\$0	\$614		
D3050	Air Conditioner, Window, 1 Ton	1951	-31	4 Each	\$5,666	\$0	\$5,666		
D3050	Baseboard Heating Units	1951	-43	7 Each	\$1,804	\$0	\$1,804		
D4030	Fire Extinguisher	2010	8	4 Each					
D5010	Disconnect Switch, 30 Amp.	1951	-13	4 Each	\$1,334	\$0	\$1,334		
D5010	Power Panel Board, 208 Y/120 V, 400 Amp.	1951	-33	1 Each	\$7,107	\$0	\$7,107		
D5020	Fluorescent Lighting Fixture, T8, 2-32w	1951	-43	12 Each	\$1,994	\$0	\$1,994		
D5020	Fluorescent Lighting Fixture, T8, 4-32 w	1951	-43	36 Each	\$5,981	\$0	\$5,981		
D5020	Metal Halide Lighting Fixture, Wall Mount, 150	2000	6	2 Each					
D5020	Receptacle, 120 V, 15 Amp.	1951	-43	30 Each	\$1,251	\$0	\$1,251		

^{*}Remaining Service Life shows years until scheduled Replacement Task; blank implies there is no Replacement Task.

All costs expressed in (\$) 2012.

^{**}Deferred Maintenance is defined as the cost of rebuilding or replacing components whose service life has exceeded their scheduled lifetime as of the Forecast Year. Preventative maintenance and minor repairs are not included.

^{***}Degradation Cost is defined as additional cost (penalty cost) incurred by maintenance deferral.

[§] Indicates Component set to have PM Tasks coincide with Replacement Task.

		F	Remaining				Total		
Uniformat Asset Description	Component	Date	Service Life*	Quantity	Deferred** Maintenance	Degradation Cost***	Deferred Maintenance	Location	Notes
D5020	Wiring Device, Switch	1951	-48	10 Each	\$339	\$0	\$339		
D5030	Public Address Speaker	1951	-48	3 Each	\$828	\$0	\$828		

^{*}Remaining Service Life shows years until scheduled Replacement Task; blank implies there is no Replacement Task.

^{**}Deferred Maintenance is defined as the cost of rebuilding or replacing components whose service life has exceeded their scheduled lifetime as of the Forecast Year. Preventative maintenance and minor repairs are not included.


^{***}Degradation Cost is defined as additional cost (penalty cost) incurred by maintenance deferral.


[§] Indicates Component set to have PM Tasks coincide with Replacement Task.

M&R Costs by System per Year Chart

Whitestone Research

23-Dec-14





\$25.00


\$5.00

\$0.00

2013 2014 2015 2016 2017 2018 2019 2020 2021 2022 2023 2024 2025 2026 2027 2028 2029 2030 2031 2032 2033 2034 2035 2036 2037

Building: Storage	e Fac	lity										y Res	earc	h Ce	nter			Ci	ity: ⊦	lam	pton, \	/A				
Building Num: 1240 Forecast Year: 2	038	9	0	1 2	2 20	143 4	4 5	G	SFT ∂			9	0	1	2	2053	4	5	6	7	2058	9	0	1	2	Total
A10 Foundations																										0.00
A20 Basement Construction																										0.00
B10 Super Structure																										0.00
B20 Exterior Enclosure	0.08	0.08	0.08	0.15	0.08	0.08	0.08	0.33	0.95	0.08	0.08	0.08	2.49	0.45	0.08	0.08	0.08	0.08	1.01	0.08	8 0.08	0.08	0.33	0.09	0.08	32.65
B30 Roofing	0.17	0.17	0.17	0.31	0.17	0.17	0.17	0.17	0.31	0.17	0.17	0.17	0.17	0.86	0.17	0.17	0.17	0.17	0.31	0.17	7 0.17	0.17	0.17	0.31	0.17	16.58
C10 Interior Construction	0.01			0.03	0.01				0.19				0.01	0.03			0.01		0.18		0.01			0.03	0.01	1.40
C20 Stairs																										0.00
C30 Interior Finishes		0.01		0.08		0.01		0.51	0.25	0.01		0.01		0.01		0.51		0.01	0.32	0.0	1	0.01		0.51		10.42
D10 Conveying																										0.00
D20 Plumbing D30 HVAC	0.40	0.40	0.40	0.40	0.40	0.40	0.40	0.40	0.00	0.00	0.40	0.40	0.40	0.40	0.40	0.40	0.40	0.40	0.40	0.44	0 0 4 0	0.40	0.40	0.40	0.40	0.00
D30 FivaC D40 Fire Protection	0.16	0.13	0.13	0.13	0.13	0.13	0.13	0.13	0.20	0.93	0.13	0.13	0.13	0.42	0.13	0.13	0.13	0.13	0.13	-	0.13		0.13	0.13	0.13	8.84 0.97
D50 Electrical	0.06		0.23	2.23	0.06	0.06		0.10		0.06	0.06	0.06	0.16		0.06	0.06	0.06	0.10	0.03				0.23	0.96	0.06	11.64
E10 Equipment	0.00	0.00	0.20	2.20	0.00	0.00	0.00	0.10	0.00	0.00	0.00	0.00	0.10	1.75	0.00	0.00	0.00	0.10	0.20	0.00	0.00	0.00	0.23	0.50	0.00	0.00
E20 Furnishings																										0.00
F10 Special Construction																										0.00
F20 Selective Bldg Demolition																										0.00
G10 Site Preparation																										0.00
G20 Site Improvements																										0.00
G30 Site Mechanical Utilities																										0.00
G40 Site Electrical Utilities																										0.00
G90 Other Site Construction	0.46						0.40	4.0.															4 0 6			0.00
Total	0.48	0.47	0.60	2.92	0.45	0.44	0.46	1.24	2.15	1.2	5 0.4	13 0.44	2.90	6 3.59	0.4	3 0.9	0.45	0.48	2.19	9 0.4	18 O.6	4 0.4	4 0.85	2.02	0.45	82.49





Notes: A value of "0.00" means cost of more than \$.000 but less than \$.005 per gsft. Based on a 50-Year Forecast.

All costs expressed in (\$) 2012 per gsft.

Year 26-50

Building: Storage Facility Facility: Langley Research Center

Building Num: 1240 City: Hampton, VA

Forecast Year:	2013	4	5	6	7	2018	9	0	1	2	2023	4	5	6	7	2028	9	0	1	2	2033	4	5	6	7
B20 Exterior Enclosure																									
Replace Steel, 14'x10', Painted, Overhead Coiling Door, Motori			14,941																						
Refinish Steel, Painted, Exterior, 1st Floor									4,641															4,641	
Replace Steel w/ Safety Glass, Painted, Exterior Door														2,371											
Repair Steel w/ Safety Glass, Painted, Exterior Door																									
Refinish Steel w/ Safety Glass, Painted, Exterior Door									52															52	
Replace Steel w/ Safety Glass, Painted, Exterior Door Locks									645															645	
Finish Replaced Steel, 14'x10', Painted, Overhead Coiling Door			293																						
Finish Replaced Steel w/ Safety Glass, Painted, Exterior Door														52											
Refinish Steel, 14'x10', Painted, Overhead Coiling Door, Motori													293										293		
Repair Steel, 14'x10', Painted, Overhead Coiling Door, Motoriz													1,273										1,273		
Maintain Steel, 14'x10', Painted, Overhead Coiling Door, Motori	191	191		191	191	191	191	191	191	191	191	191	191	191	191	191	191	191	191	191	191	191	191	191	191
Repair Aluminum Fixed Window, 12 sf, 1st Floor																		302							
Finish Replaced Steel, Painted, Exterior, 1st Floor														8,777											
Replace Steel, Painted, Exterior, 1st Floor													1	07,080											
Finish Repaired Steel, Painted, Exterior, 1st Floor																									
Repair Steel, Painted, Exterior, 1st Floor (2% of Walls)																									
Maintain Steel w/ Safety Glass, Painted, Exterior Door Locks				42					42										42					42	
B30 Roofing																									
Repair Metal Roof				844					844					844										844	
Replace Metal Roof																		3	37,343						
Minor Replacement, Metal Roof (2% of Roof)																									
Maintain Metal Roof	360	360	360	360	360	360	360	360	360	360	360	360	360	360	360	360	360	360		360	360	360	360	360	360
Maintain Aluminum Gutter, Downspouts, Fittings	154	154	154	154	154	154	154	154	154	154	154	154	154	154	154	154	154	154		154	154	154	154	154	154
Replace Aluminum Gutter, Downspouts, Fittings																			3,050						
C10 Interior Construction																									
C10 Interior Construction			78				78				78							78				70			
Refinish Steel, Painted, Interior Door			78	63			78		63		78							78	63			78		63	
Maintain Steel, Painted, Interior Door Locks				03					926										03					926	
Replace Steel, Painted, Interior Door Locks									920					2,500										920	
Replace Steel, Painted, Interior Door														78											
Finish Replaced Steel, Painted, Interior Door														70											
C30 Interior Finishes																									
Repair Wood, Finished, Interior Paneling (2% of Walls)									196															196	
Refinish Gypsum Board, Interior Wall Finish									681															681	
Repair Gypsum Board, Interior Wall Finish (2% of Walls)																									

Building: Storage Facility Facility: Langley Research Center

Building Num: 1240 City: Hampton, VA

Forecast Year: 2038 9 0 1 2 2043 4 5 6 7 2048 9 0 1 2 2053 4 5 6 7 2058 9 0 1

Forecast Year:	2038	9	O	1	2	2043	4	5	6	7	2048	9	U	1	2	2053	4	5	6	7	2058	9	U	1	2
B20 Exterior Enclosure																									
Replace Steel, 14'x10', Painted, Overhead Coiling Door, Moto													14,941												
Refinish Steel, Painted, Exterior, 1st Floor									4,641										4,641						
Replace Steel w/ Safety Glass, Painted, Exterior Door																									
Repair Steel w/ Safety Glass, Painted, Exterior Door				354															354						
Refinish Steel w/ Safety Glass, Painted, Exterior Door									52										52						
Replace Steel w/ Safety Glass, Painted, Exterior Door Locks									645										645						
Finish Replaced Steel, 14'x10', Painted, Overhead Coiling Do													293												
Finish Replaced Steel w/ Safety Glass, Painted, Exterior Door																									
Refinish Steel, 14'x10', Painted, Overhead Coiling Door, Moto								293															293		
Repair Steel, 14'x10', Painted, Overhead Coiling Door, Motori								1,273															1,273		
Maintain Steel, 14'x10', Painted, Overhead Coiling Door, Moto	191	191	191	191	191	191	191	191	191	191	191	191		191	191	191	191	191	191	191	191	191	191	191	191
Repair Aluminum Fixed Window, 12 sf, 1st Floor													302												
Finish Replaced Steel, Painted, Exterior, 1st Floor																									
Replace Steel, Painted, Exterior, 1st Floor																									
Finish Repaired Steel, Painted, Exterior, 1st Floor														93											
Repair Steel, Painted, Exterior, 1st Floor (2% of Walls)														2,142											
Maintain Steel w/ Safety Glass, Painted, Exterior Door Locks				42					42					42					42					42	
B30 Roofing																									
Repair Metal Roof				844					844					844					844					844	
Replace Metal Roof																									
Minor Replacement, Metal Roof (2% of Roof)														747											
Maintain Metal Roof	360	360	360	360	360	360	360	360	360	360	360	360	360	360	360	360	360	360	360	360	360	360	360	360	360
Maintain Aluminum Gutter, Downspouts, Fittings	154	154	154	154	154	154	154	154	154	154	154	154	154		154	154	154	154	154	154	154	154	154	154	154
Replace Aluminum Gutter, Downspouts, Fittings														3,050											
C10 Interior Construction																									
Refinish Steel, Painted, Interior Door	78				78				78				78				78				78				78
Maintain Steel, Painted, Interior Door Locks				63					63					63					63					63	
Replace Steel, Painted, Interior Door Locks									926										926						
Replace Steel, Painted, Interior Door																									
Finish Replaced Steel, Painted, Interior Door																									
C30 Interior Finishes																									
Repair Wood, Finished, Interior Paneling (2% of Walls)									196										196						
Refinish Gypsum Board, Interior Wall Finish									681										681						
Repair Gypsum Board, Interior Wall Finish (2% of Walls)									30																

Building: Storage Facility				Fa	cility	/ : La	ngley	/ Res	searc	h Ce	nter														
Building Num: 1240					City	/ : Ha	ampto	on, V	Α																
Forecast Year:	2013	4	5	6	7	2018	9	0	1	2	2023	4	5	6	7	2028	9	0	1	2	2033	4	5	6	7
Finish Repaired Gypsum Board, Interior Wall Finish																									
Replace Gypsum Board, Interior Wall Finish														1,488											
Finish Replaced Gypsum Board, Interior Wall Finish														681											
Finish Repaired Wood, Finished, Interior Paneling									13															13	
Replace Wood, Finished, Interior Paneling														9,437											
Finished Replaced Wood, Finished, Interior Paneling														644											
Repair Carpet, Nylon 20 oz., High Traffic (2% of Carpet)			64		64		64				64		64		64				64		64		64		
Replace Carpet, Nylon 20 oz., High Traffic	3,215								3,215								3,215								3,215
Repair Concrete Flooring (2% of Floors)																									
Replace Concrete Flooring														22,115											
Refinish Wood, Finished, Interior Paneling									644															644	
D30 HVAC																									
Repair Air Conditioner, Window, 1 Ton																			402						
Repair Baseboard Heating Units																									
Replace Air Conditioner, Window, 1 Ton			5,666																						
Maintain Air Conditioner, Window, 1 Ton	422	422		422	422	422	422	422	422	422	422	422	422	422	422	422	422	422	422	422	422	422	422	422	422
Replace Exhaust Fan, Propeller, 375 Cfm															614										
Repair Exhaust Fan, Propeller, 375 Cfm					188																				
Maintain Exhaust Fan, Propeller, 375 Cfm	91	91	91	91	91	91	91	91	91	91	91	91	91	91		91	91	91	91	91	91	91	91	91	91
Replace Baseboard Heating Units, 5' Long																			1,804						
D40 Fire Protection																									
Replace Fire Extinguisher										1,180												1,180			
Inspect & Test Fire Extinguisher			127					127							127					127					
D50 Electrical																									
Replace Fluorescent Lighting Fixture, T8, 4-32 w																			5,981						
Maintain Public Address Speaker	60	60	60	60	60	60	60	60	60	60	60	60	60		60	60	60	60	60	60	60	60	60	60	60
Replace Wiring Device, Switch														339											
Repair Wiring Device, Switch									328															328	
Replace Receptacle, 120 V, 15 Amp.																			1,251						
Replace Metal Halide Lighting Fixture, Wall Mount, 150 w								1,041																	
Replace Ballast, Metal Halide Lighting Fixture, Wall Mount, 150																		401							
Replace Lamp, Metal Halide Lighting Fixture, Wall Mount, 150			192										192					192					192		
Replace Fluorescent Lighting Fixture, T8, 2-32 w																			1,994						
Replace Ballast & Lamps, Fluorescent Lighting Fixture, T8, 4-3									3,751																
Replace Ballast & Lamps, Fluorescent Lighting Fixture, T8, 2-3									1,250																
Replace Power Panel Board, 208 Y/120 V, 400 Amp.																									

Building: Storage Facility				Fa	-	/ : La				h Ce	nter														
Building Num: 1240					City	/: Ha	mpto	n, V	4																
Forecast Year:	2038	9	0	1	2	2043	4	5	6	7	2048	9	0	1	2	2053	4	5	6	7	2058	9	0	1	2
Finish Repaired Gypsum Board, Interior Wall Finish									14																
Replace Gypsum Board, Interior Wall Finish																									
Finish Replaced Gypsum Board, Interior Wall Finish																									
Finish Repaired Wood, Finished, Interior Paneling									13										13						
Replace Wood, Finished, Interior Paneling																									
Finished Replaced Wood, Finished, Interior Paneling																									
Repair Carpet, Nylon 20 oz., High Traffic (2% of Carpet)		64		64		64				64		64		64				64		64		64			
Replace Carpet, Nylon 20 oz., High Traffic								3,215								3,215								3,215	
Repair Concrete Flooring (2% of Floors)				442															442						
Replace Concrete Flooring																									
Refinish Wood, Finished, Interior Paneling									644										644						
D00 10/40																									
D30 HVAC																									
Repair Air Conditioner, Window, 1 Ton																									
Repair Baseboard Heating Units																									
Replace Air Conditioner, Window, 1 Ton										5,666															
Maintain Air Conditioner, Window, 1 Ton	422	422	422	422	422	422	422	422	422		422	422	422	422	422	422	422	422	422	422	422	422	422	422	422
Replace Exhaust Fan, Propeller, 375 Cfm									614																
Repair Exhaust Fan, Propeller, 375 Cfm	188																			188					
Maintain Exhaust Fan, Propeller, 375 Cfm	91	91	91	91	91	91	91	91		91	91	91	91	91	91	91	91	91	91	91	91	91	91	91	91
Replace Baseboard Heating Units, 5' Long														1,804											
D40 Fire Protection																									
Replace Fire Extinguisher									1,180												1,180				
Inspect & Test Fire Extinguisher		127					127							127					127						
DE0 E1 4 1 1																									
D50 Electrical																									
Replace Fluorescent Lighting Fixture, T8, 4-32 w														5,981											
Maintain Public Address Speaker	60	60	60		60	60	60	60	60	60	60	60	60	60	60	60	60	60		60	60	60	60	60	60
Replace Wiring Device, Switch				339															339						
Repair Wiring Device, Switch														328											
Replace Receptacle, 120 V, 15 Amp.														1,251											
Replace Metal Halide Lighting Fixture, Wall Mount, 150 w			1,041																				1,041		
Replace Ballast, Metal Halide Lighting Fixture, Wall Mount, 15													401												
Replace Lamp, Metal Halide Lighting Fixture, Wall Mount, 150								192					192					192							
Replace Fluorescent Lighting Fixture, T8, 2-32 w														1,994											
Replace Ballast & Lamps, Fluorescent Lighting Fixture, T8, 4-				3,751																				3,751	
Replace Ballast & Lamps, Fluorescent Lighting Fixture, T8, 2-				1,250																				1,250	
Replace Power Panel Board, 208 Y/120 V, 400 Amp.				7,107																					

Building: Storage Facility Facility: Langley Research Center

Building Num: 1240 City: Hampton, VA

Forecast Year:	2013	4	5	6	7	2018	9	0	1	2	2023	4	5	6	7	2028	9	0	1	2	2033	4	5	6	7
Repair Power Panel Board, 208 Y/120 V, 400 Amp.									96										96						
Maintain Power Panel Board, 208 Y/120 V, 400 Amp.	60	60	60	60	60	60	60	60	60	60	60	60	60	60	60	60	60	60	60	60	60	60	60	60	60
Replace Disconnect Switch, 30 Amp.																									
Maintain Disconnect Switch, 30 Amp.	79	79	79	79	79	79	79	79	79	79	79	79	79	79	79	79	79	79	79	79	79	79	79	79	79
Replace Public Address Speaker														828											
Repair Disconnect Switch, 30 Amp.									501										501						

Building: Storage Facility Facility: Langley Research Center


Building Num: 1240 City: Hampton, VA

Forecast Year:	2038	9	0	1	2	2043	4	5	6	7	2048	9	0	1	2	2053	4	5	6	7	2058	9	0	1	2
Repair Power Panel Board, 208 Y/120 V, 400 Amp.														96										96	
Maintain Power Panel Board, 208 Y/120 V, 400 Amp.	60	60	60		60	60	60	60	60	60	60	60	60	60	60	60	60	60	60	60	60	60	60	60	60
Replace Disconnect Switch, 30 Amp.														1,334											
Maintain Disconnect Switch, 30 Amp.	79	79	79	79	79	79	79	79	79	79	79	79	79		79	79	79	79	79	79	79	79	79	79	79
Replace Public Address Speaker				828															828						
Repair Disconnect Switch, 30 Amp.				501																				501	

Building Deferred Maintenance by System Chart

Building: Storage Facility Building Num: 1240

City: Hampton, VA



All costs expressed in (\$) 2012.

^{*}Deferred Maintenance is defined as the cost of rebuilding or replacing components whose service life has exceeded their scheduled lifetime as of the Forecast Year. Preventative maintenance and minor repairs are not included.

^{**}Degradation Cost is defined as additional cost (penalty cost) incurred by maintenance deferral and is included in Total Deferred Maintenance. Based on a 50-Year Forecast.

Building Deferred Maintenance Detail

Whitestone Research

Building: Storage Facility

Year Built: 1951

Building Type: Non-

Facility: Langley Research Center Original Cost: \$1

Temperature Controlled

City: Hampton, VA Replacement Value: \$367,378 Building Gsft: 6,246

per SF: \$59 Building Number: 1240

Year Installed	Deferred	Deferred Maintenance Task*	Deferred* Maintenance	Degradation Cost**	Deferred Maintenance
1951	22	Replace Metal Roof	\$37,343	\$0	\$37,343
1951	32	Replace Power Panel Board, 208 Y/120 V, 400 Amp.	\$7,107	\$0	\$7,107
1951	42	Replace Fluorescent Lighting Fixture, T8, 4-32 w	\$5,981	\$0	\$5,981
1951	30	Replace Air Conditioner, Window, 1 Ton	\$5,666	\$0	\$5,666
1951	42	Replace Aluminum Gutter, Downspouts, Fittings	\$3,050	\$0	\$3,050
1951	42	Replace Fluorescent Lighting Fixture, T8, 2-32 w	\$1,994	\$0	\$1,994
1951	42	Replace Baseboard Heating Units, 5' Long	\$1,804	\$0	\$1,804
1951	12	Replace Disconnect Switch, 30 Amp.	\$1,334	\$0	\$1,334
1951	42	Replace Receptacle, 120 V, 15 Amp.	\$1,251	\$0	\$1,251
1951	47	Replace Public Address Speaker	\$828	\$0	\$828
1951	43	Replace Exhaust Fan, Propeller, 375 Cfm	\$614	\$0	\$614
1951	47	Replace Wiring Device, Switch	\$339	\$0	\$339
		To	otal \$67,311	\$0	\$67,311

All costs expressed in (\$) 2012.

^{*}Deferred Maintenance is defined as the cost of rebuilding or replacing components whose service life has exceeded their scheduled lifetime as of the Forecast Year. Preventative maintenance and minor repairs are not included.

Building: Storage Facility **GSFT:** 6,246


Building Number: 1240 Replacement Value: \$367,378

Facility: Langley Research Center Building Use: Warehouse and Storage

City: Hampton, VA Building Type: Non-Temperature

Built Date: 1951 Controlled Warehouse

	Annual	Annual	
Operation	Cost/GSFT	Total	Percent
Custodial	\$0.103	\$642	3.4%
Energy	\$0.301	\$1,879	10.0%
Grounds	\$0.109	\$684	3.6%
M&R	\$1.650	\$10,305	54.9%
Management	\$0.147	\$918	4.9%
Pest Control	\$0.104	\$647	3.4%
Refuse	\$0.002	\$15	0.1%
Road Clearance	\$0.006	\$38	0.2%
Security	\$0.431	\$2,690	14.3%
Telecom	\$0.150	\$936	5.0%
Water/Sewer	\$0.004	\$26	0.1%
Building Total	\$3.01	\$18,780	100.0%



Building Operations Utility Details

Whitestone Research

Building: Storage Facility

Year Built: 1951

Building Type: Non-Temperature Controll

Facility: Langley Research Center Original Cost: \$1 Building Num: 1240

City: Hampton, VA Replacement Value: \$367,378 per SF: \$59 Building Gsft: 6,246

		Utility	GSFT	Demand	UM	Rate	Cost
Operation:	Energy	Level of Service: Low					
		Electricity	6246	3.717	kWh	\$0.0700	\$1,625
		Natural Gas	6246	0.054	Thm	\$0.7480	\$254
		Diesel	6246	0.000	Gal	\$3.1876	\$0
		Total:		3.771			\$1,879
Operation:	Refuse	Level of Service: Low					
		Municipal Solid Waste	6246	0.030	Lbs	\$0.0674	\$13
		Recycling	6246	0.010	Lbs	\$0.0348	\$2
		Total:		0.040			\$15
Operation:	Water/Sewer	Level of Service: Low					
		Water	6246	0.560	Gal	\$0.0056	\$20
		Sewer	6246	0.440	Gal	\$0.0023	\$6
		Total:		1.000			\$26

Building Operations Task Details

Whitestone Research

Building: Storage Facility

Year Built: 1951

Building Type: Non-Temperature Controll

Facility: Langley Research Center Original Cost: \$1 Building Num: 1240

City: Hampton, VA Replacement Value: \$367,378 per SF: \$59 Building Gsft: 6,246

Functional Area Labor Cost Material Cost Task Cost FA GSFT Task Operation: Custodial Level of Service: Low 5621 Sweep Hard Floor with 48" Push Broom \$101 \$16 \$118 Warehouse Warehouse 5621 Empty Trash; Wipe Clean & Re-line Basket \$65 \$11 \$75 Office \$219 \$36 \$254 624 Vacuum Carpet with 14" Upright Vacuum Office 624 Empty Trash; Wipe Clean & Re-line Basket \$62 \$10 \$73 Office Clean and Wipe Furniture with Trigger Sprayer & Cloth \$38 \$6 \$45 624 Office 624 **Dust Surfaces with Duster** \$29 \$5 \$34 Office Vacuum Upholstered Furniture with Tank or Canister Vacuum \$24 \$4 \$28 624 \$2 Office **Dust Window Blinds** \$14 \$16 Total: \$552 \$90 \$642 Operation: Grounds Level of Service: Low Grounds, Improved 3747 Mow Turfgrass with 21" Power Mower \$131 \$55 \$186 Grounds, Improved 3747 Aerate Improved Grounds \$89 \$37 \$126 Grounds, Improved 3747 Clear Shrubs \$74 \$31 \$105 Grounds, Improved Edge Clean & Trim Walks with Gas Powered Edger \$54 \$23 \$77 3747 Grounds, Improved 3747 Overseed, Improved Grounds \$44 \$19 \$63 Grounds, Improved 3747 Vacuum with 30" Billy Goat \$30 \$12 \$42 Grounds, Improved 3747 Clear Crabgrass \$22 \$9 \$32 Grounds, Improved Clear Weeds with 15" Boom, Improved Grounds \$12 \$5 \$17 3747 Grounds, Improved 3747 Trim Around Raised Objects with String Edger \$11 \$5 \$16 \$4 Grounds, Improved 3747 Fertilize Improved Grounds \$9 \$13 Grounds, Improved 3747 Sweep with 30" Power Rake \$6 \$2 \$8 3747 \$0 \$0 \$0 Grounds, Improved Fertilize Using Power Take Off Broadcast \$483 \$201 \$684 Total: Operation: Pest Control Level of Service: Medium Pest Controlled 6246 Install, or Check and Re-Bait 5 Rodent Boxes \$223 \$93 \$316 Pest Controlled 6246 Perform Crawling Insect Abatement \$168 \$70 \$237

Functional Area	FA GSFT	Task	Labor Cost	Material Cost	Task Cost
Pest Controlled	6246	Inspect Building for Pests	\$93	\$0	\$93
Total:			\$484	\$163	\$647
Operation: Road 0	Clearance	Level of Service: Medium			
Pavement NASA	4996	Plow Paved Area	\$29	\$9	\$38
Total:			\$29	\$9	\$38
Operation: Securi	ty	Level of Service: Low			
Secured Area	6246	Patrol Building Perimeter	\$0	\$0	\$0
Secured Area	6246	Guard Lobby/Parking	\$0	\$0	\$0
Total:			\$0	\$0	\$0

Building Operations Service Details

Whitestone Research

Building: Storage Facility

Year Built: 1951

FTEs: 2

Building Type: Non-Temperature Controll

Facility: Langley Research Center Original Cost: \$1 Building Num: 1240

City: Hampton, VA Replacement Value: \$367,378 per SF: \$59 Building Gsft: 6,246

		Service*	Quantity	Rate	Cost
Operation:	Security	Level of Service: Low			
		Access Control	1	\$2,690	\$2,690
		Total:			\$2,690
Operation:	Telecom	Level of Service: Low			
		Local Telephone	2	\$468	\$936
		Total:			\$936

^{*} Secutity may be composed of service and task based cost. See Building Operations Task Details for Security Tasks.

Building Operations Management Details

Whitestone Research

Building: Storage Facility

Year Built: 1951

Building Type: Non-Temperature Controll

Facility: Langley Research Center Original Cost: \$1 Building Num: 1240

City: Hampton, VA Replacement Value: \$367,378 per SF: \$59 Building Gsft: 6,246

	Service	Demand	UM	PRV	Cost
Operation: Management	Level of Service: Low				
	Management	0.3%	PRV	\$367,378	\$918
	Total:				\$918

Attachment D: Detailed MARS Reports for LaRC Property ID 153

Average M&R Costs

Whitestone Research

Distribution Center GSFT: 35,625

Building Number: 1206 **PRV:** \$3,639,735

Facility: Langley Research Center Built Date: 1966

City: Hampton, VA

M&R Average Annual Cost Forecasts

_	Current Year	5 Year	20 Year	50 Year
PM & Minor Repair:	\$25,685	\$26,333	\$26,112	\$26,143
Unscheduled Maintenance:	\$19,534	\$20,043	\$19,389	\$19,471
Renewal & Replacement:	\$485	\$67,417	\$84,316	\$105,440
Total M&R Costs:	\$45,704	\$113,793	\$129,817	\$151,054
Per GSFT:	\$1.28	\$3.19	\$3.64	\$4.24
As % of PRV:	1.26%	3.13%	3.57%	4.15%

Building Component List

Whitestone Research

Building: Distribution Center Year Built: 1966 Building Type: Temperature Controlled W

Facility: Langley Research Center Original Cost: \$1 Building Num: 1206

City: Hampton, VA Replacement Value: \$3,639,735 per SF: \$102 Building Gsft: 35,625

Uniformat	Asset Description	Component	Date	Quantity	Location	Notes
B1010		Concrete Decking	1966	1223 Sq Ft		
B1010		Concrete Ramp	1966	399 Sq Ft		
B2010		Steel, Insulated Wall Panels, Painted, Exterior, 2"	1966	11810 Sq Ft		
B2020		Steel Operable Window, 12 sf, 1st Fl	1966	19 Each		
B2030		Steel, 14'x10', Painted, Overhead Coiling Door, Motorized	1990	5 Each		
B2030		Steel, Painted, Exterior Door	1966	7 Each		
B2030		Steel, Painted, Exterior Double Door	1966	2 Each		
B3010		Aluminum Gutter, Downspouts, Fittings	1966	0.8 K Ln Ft		
B3010		Metal Canopy	1966	1733 Sq Ft		
B3010		Metal Roof	1966	36800 Sq Ft		sprayed with foam
C1010		Plexiglass Fixed Window, UV Filtering, 24 Sf	1966	5 Each		
C1010		Toilet Partitions, Painted Metal, Overhead Braced	1966	4 Each		
C1020		Steel, 10'x8', Painted, Overhead Coiling Door, Motorized	1990	2 Each		
C1020		Steel, Painted, Interior Double Door w/ Safety Glass	1966	1 Each		
C1020		Wood, Hollow Core, Painted, Interior Door	1966	19 Each		
C2010		Concrete, Exterior Stairs	1966	131 Sq Ft		
C2010		Concrete, Interior Stairs	1966	39 Sq Ft	120	
C2010		Metal, Painted, Exterior Railing	1966	107 Ln Ft		
C2010		Metal, Painted, Exterior Stairs	1966	31 Sq Ft		
C2010		Metal, Painted, Interior Railing	1966	70 Ln Ft		
C2010		Metal, Painted, Interior Stairs	1966	198 Sq Ft		
C3010		Ceramic Tile, 4"x4", Interior Wall Finish	1966	250 Sq Ft	104,107	
C3010		Ceramic Tile, 4"x4", Interior Wall Finish	1966	777 Sq Ft	109,112	
C3010		Concrete Block, Interior Wall Finish	1966	3829 Sq Ft	101	
C3010		Concrete Block, Painted, Interior Wall Finish	1966	812 Sq Ft	110	
C3010		Concrete Block, Painted, Interior Wall Finish	1966	250 Sq Ft	104,107	
C3010		Concrete Block, Painted, Interior Wall Finish	1966	726 Sq Ft	105	
C3010		Concrete Block, Painted, Interior Wall Finish	1966	776 Sq Ft	109,112	

[§] Indicates Component set to have PM Tasks coincide with Replacement Task. All costs expressed in (\$) 2012.

Uniformat	Asset Description	Component	Date	Quantity	Location	Notes
C3010		Concrete Block, Painted, Interior Wall Finish	1966	944 Sq Ft	114	
C3010		Concrete Block, Painted, Interior Wall Finish	1966	1730 Sq Ft	116	
C3010		Concrete Block, Painted, Interior Wall Finish	1966	179 Sq Ft	108E	
C3010		Concrete Block, Painted, Interior Wall Finish	1966	158 Sq Ft	108D	
C3010		Concrete Block, Painted, Interior Wall Finish	1966	7644 Sq Ft	108	
C3010		Concrete Block, Painted, Interior Wall Finish	1966	670 Sq Ft	119	
C3010		Concrete Block, Painted, Interior Wall Finish	1966	2257 Sq Ft	120	
C3010		Concrete Block, Painted, Interior Wall Finish	1966	599 Sq Ft	122,121,123	
C3010		Gypsum Board, Interior Wall Finish	1966	2351 Sq Ft	122,121,123	
C3010		Gypsum Board, Interior Wall Finish	1966	7698 Sq Ft	124,125,126,127,128,129,130,131,H	
C3010		Gypsum Board, Interior Wall Finish	1966	1636 Sq Ft	119	
C3010		Gypsum Board, Interior Wall Finish	1966	1334 Sq Ft	120	
C3010		Gypsum Board, Interior Wall Finish	1966	438 Sq Ft	108D	
C3010		Gypsum Board, Interior Wall Finish	1966	734 Sq Ft	108A	
C3010		Gypsum Board, Interior Wall Finish	1966	425 Sq Ft	108	
C3010		Gypsum Board, Interior Wall Finish	1966	334 Sq Ft	116	
C3010		Gypsum Board, Interior Wall Finish	1966	965 Sq Ft	108B	
C3010		Gypsum Board, Interior Wall Finish	1966	445 Sq Ft	108E	
C3010		Gypsum Board, Interior Wall Finish	1966	1192 Sq Ft	102,103,103A	
C3010		Steel, Painted, Interior Wall Finish	1966	935 Sq Ft		
C3020		Carpet, Nylon 20 oz., High Traffic	1966	961 Sq Ft	121,122,123	
C3020		Carpet, Nylon 20 oz., High Traffic	1966	1036 Sq Ft	108B,116	
C3020		Carpet, Nylon 20 oz., High Traffic	1966	148 Sq Ft	108A	
C3020		Carpet, Nylon 20 oz., High Traffic	1966	779 Sq Ft	119	
C3020		Carpet, Nylon 20 oz., High Traffic	1966	1792 Sq Ft	125,126,127,H1A,129,128,124,130,1	
C3020		Carpet, Nylon 20 oz., High Traffic	1966	1080 Sq Ft	102,103,103A	
C3020		Ceramic Tile Flooring	1966	314 Sq Ft	109,112	
C3020		Ceramic Tile Flooring	1966	49 Sq Ft	107	
C3020		Ceramic Tile Flooring	1966	151 Sq Ft	104	
C3020		Concrete Flooring	1966	7412 Sq Ft	101, above 102,103,103A	
C3020		Concrete Flooring	1966	145 Sq Ft		
C3020		Concrete Flooring	1966	14726 Sq Ft	108,108D,108E,110	
C3020		Concrete Flooring	1966	2141 Sq Ft	120	
C3020		Concrete Flooring	1966	230 Sq Ft	114	
C3020		Metal Floor Grating	1966	4662 Sq Ft	108 2nd floor	
C3030		Acoustical Tile Ceiling	1966	1768 Sq Ft	125,126,127,H1A,129,128,124,130,1	

[§] Indicates Component set to have PM Tasks coincide with Replacement Task. All costs expressed in (\$) 2012.

Uniformat	Asset Description	Component	Date	Quantity	Location	Notes
C3030		Acoustical Tile Ceiling	1966	310 Sq Ft	109,112	
C3030		Acoustical Tile Ceiling	1966	149 Sq Ft	104	
C3030		Acoustical Tile Ceiling	1966	48 Sq Ft	107	
C3030		Acoustical Tile Ceiling	1966	948 Sq Ft	121,122,123	
C3030		Acoustical Tile Ceiling	1966	1066 Sq Ft	102,103,103A	
C3030		Gypsum Board, Finished Ceiling	1966	768 Sq Ft	119	
C3030		Gypsum Board, Finished Ceiling	1966	1022 Sq Ft	108B,116	
C3030		Metal Ceiling	1966	14527 Sq Ft	108,108D,108E,110	
C3030		Metal Ceiling	1966	2112 Sq Ft	120	
C3030		Metal Ceiling	1966	5797 Sq Ft	101	
C3030		Metal Ceiling	1966	227 Sq Ft	114	
C3030		Metal Ceiling	1966	143 Sq Ft		
C3030		Plywood Ceiling, Painted	1966	146 Sq Ft		
D1090		Dock Ramp Leveler	1966	4 Each		
D2010		Emergency Eye Wash	1966	1 Each		
D2010		Lavatory, Vitreous China	1966	5 Each		
D2010		Service Sink, Iron, Enamel	1966	1 Each		
D2010		Sink, Stainless Steel	1966	1 Each		
D2010		Tankless Water Closet	1966	6 Each		
D2010		Urinal, Vitreous China	1966	4 Each		
D2010		Water Cooler, Electric	1995	4 Each		
D2020		Hose Bib	1966	1 Each		
D2020		Pipe & Fittings, 3/4" Copper, Cold Water	1966	0.35 K Ln Ft		
D2020		Pipe & Fittings, 3/4" Copper, Hot Water	1966	0.35 K Ln Ft		
D2020		Pipe Insulation, Fiberglass, Cold Water	1966	0.35 K Ln Ft		
D2020		Pipe Insulation, Fiberglass, Hot Water	1966	0.35 K Ln Ft		
D2020	Bradford-White MI20U5	Water Heater, Electric, 15 Gal.	1966	1 Each		
D2020		Water Heater, Electric, 5 Gal.	1966	1 Each		6 Gal
D2030		Backflow Preventer, 2"	2000	2 Each		
D2030		Backflow Preventer, 3/4"	2000	1 Each		
D2030		Floor Drain	1966	1 Each		
D2030		Pipe & Fittings, 2" PVC	1990	0.05 K Ln Ft		
D2030		Pipe & Fittings, 3" Cast Iron	1966	0.3 K Ln Ft		
D2030		Pipe & Fittings, 4" Cast Iron	1966	0.1 K Ln Ft		
D3010		Pressure Reducer Valve, 2"	1966	2 Each		
D3020		Boiler, Gas, 100 Mbh	2000	1 Each		

[§] Indicates Component set to have PM Tasks coincide with Replacement Task. All costs expressed in (\$) 2012.

Uniformat	Asset Description	Component	Date	Quantity	Location	Notes
D3020		Condensate Removal Pump System, 1/50 HP	2006	1 Each		
D3020		Gate Valve, 6"	1966	2 Each		
D3020		Heat Exchanger, Steam-to-Water, 15 Gpm	2006	1 Each		
D3020		Pipe & Fittings, 10" Steel	1966	0.05 K Ln Ft		
D3020		Pipe & Fittings, 2" Steel	1966	0.35 K Ln Ft		
D3020		Pipe & Fittings, 4" Steel	1966	0.1 K Ln Ft		
D3020		Pipe Insulation, Fiberglass, Heating Water/Steam	1966	0.35 K Ln Ft		
D3020		Steam Trap, F&T, 2"	1966	40 Each		
D3020		Valve, Non-Drain, 10"	1966	2 Each		Steam Valve
D3030		Ball Valve, 1"	1966	6 Each		Relief Valve
D3030		Condenser, Air-Cooled, 1 Ton	1994	8 Each		
D3030		Condenser, Air-Cooled, 10 Ton	2006	1 Each		
D3030		Expansion Tank, 30 Gal.	1966	1 Each		
D3040		Air Handler, Single Zone, 8,000 Cfm	2006	1 Each		American Standard M#TWE120A300
D3040		Dehumidifier & Control, 120-150 lbs, 4,500 Cfm	2000	1 Each		
D3040		Duct Insulation, Fiberglass Blanket	2006	150 Sq Ft		
D3040		Ductwork	2006	350 Lbs		
D3040		Exhaust Fan, Propeller, 1,000 Cfm	1966	4 Each		
D3040		Residential Type Ceiling Fan	2000	4 Each		
D3050		Air Conditioner, DX Packaged, Air Cooled, 1 Ton	1994	8 Each		
D3050		Air Conditioner, Window, 1 Ton	2000	11 Each		
D3050		Heat Pump, 3 Ton	1990	2 Each		
D3050		Suspended Heater, Hot Water, 1,200 Cfm, 55 Mbh	1990	19 Each		
D3050		Suspended Heater, Hot Water, 2,000 Cfm, 180 Mbh	1990	8 Each		
D3060		Thermostat	1994	9 Each		
D4010		Fire Alarm Control Panel	2000	1 Each		
D4010		Fire Department Connection, Siamese, 3"	1990	1 Each		
D4010		Fire Sprinkler Head	1990	158 Each		
D4010		Fire Sprinkler System	1990	1 Each		
D4010		Pipe & Fittings, 1" Steel	1990	0.45 K Ln Ft		
D4010		Pipe & Fittings, 2" Steel	1990	0.1 K Ln Ft		
D4010		Pipe & Fittings, 4" Steel	1990	0.05 K Ln Ft		
D4010		Valves & Components, Sprinkler System, 3"	1990	1 Each		
D4030		Fire Extinguisher	2010	8 Each		
D5010		Disconnect Switch, 30 Amp.	1980	17 Each		
D5010		Disconnect Switch, 60 Amp.	1980	2 Each		

[§] Indicates Component set to have PM Tasks coincide with Replacement Task.

D5010 Power Panel Board, 208 Y/120 V, 100 Amp. 1980 2 Each	Uniformat	Asset Description	Component	Date	Quantity	Location	Notes	
D5010 Primary Transformer, Dry, 500 kVA 1980 1 Each D5010 Secondary Transformer, Dry, 150 kVA 1980 1 Each D5020 Emergency Lighting Pack, 2 Light w Battery 2005 9 Each D5020 Exit Lighting Fixture, W Battery 2000 5 Each D5020 Fluorescent Lighting Fixture, 18, 2-32w 1995 137 Each D5020 Fluorescent Lighting Fixture, 18, 4-32 w 1995 14 Each D5020 Incandescent Lighting Fixture, 18, 4-32 w 1995 14 Each D5020 Incandescent Lighting Fixture, 100 w 2010 3 Each Wall Mounted D5020 LED Lighting Fixture, 100 w 2010 2 Each Wall Mounted D5020 Metal Halide Lighting Fixture, Wall Mount, 150 w 2010 2 Each Wall Mounted D5020 Receptacle, 120 V, 15 Amp. 1996 50 Each Seach D5020 Receptacle, 120 V, 15 Amp. 1996 50 Each D5030 Fire Alarm Bell, 6° 2000 4 Each D5030 Gas Monitoring System 200 <td< td=""><td>D5010</td><td></td><td>Power Panel Board, 208 Y/120 V, 100 Amp.</td><td>1980</td><td>2 Each</td><td></td><td></td><td></td></td<>	D5010		Power Panel Board, 208 Y/120 V, 100 Amp.	1980	2 Each			
D5010 Secondary Transformer, Dry, 150 kVA 1980 1 Each D5020 Emergency Lighting Pack, 2 Light w/ Battery 2005 9 Each D5020 Exit Lighting Fixture, We Battery 2000 5 Each D5020 Fluorescent Lighting Fixture, T8, 2-32w 1995 137 Each D5020 Fluorescent Lighting Fixture, T8, 4-32 w 1995 14 Each D5020 Incandescent Lighting Fixture, Basic, 100 w 1995 2 Each Exterior D5020 LED Lighting Fixture, Wall Mount, 150 w 2010 3 Each Wall Mounted D5020 Metal Halide Lighting Fixture, Wall Mount, 150 w 2010 2 Each Wall Mounted D5020 Receptacle, 120 V, 15 Amp. 1990 60 Each Wall Mounted D5020 Receptacle, 120 V, 15 Amp. 1996 50 Each D5030 Fire Alarm Bell, 6" 2000 4 Each D5030 Fire Alarm Horn & Strobe 2000 5 Each D5030 Gas Monitoring System 2005 1 Each D5030 Manual Pull Station 2000 6 Each	D5010		Power Panel Board, 208 Y/120 V, 225 Amp	1990	1 Each			
D5020 Emergency Lighting Pack, 2 Light w Battery 2005 9 Each D5020 Exit Lighting Fixture, w/ Battery 2000 5 Each D5020 Fluorescent Lighting Fixture, T8, 2-32w 1995 137 Each D5020 Fluorescent Lighting Fixture, T8, 4-32 w 1995 14 Each D5020 Incandescent Lighting Fixture, Basic, 100 w 1995 2 Each Exterior D5020 LED Lighting Fixture, 100 w 2010 3 Each Wall Mounted D5020 Metal Halide Lighting Fixture, Wall Mount, 150 w 2010 2 Each Exterior D5020 Receptacle, 120 V, 15 Amp. 1990 60 Each 60 Each D5020 Receptacle, 120 V, 15 Amp. 1996 50 Each D5020 Wiring Device, Switch 1995 30 Each D5030 Fire Alarm Bell, 6° 2000 4 Each D5030 Fire Alarm Horn & Strobe 2000 5 Each D5030 Gas Monitoring System 2010 1 Each D5030 Manual Pull Station 200 6 Each <td< td=""><td>D5010</td><td></td><td>Primary Transformer, Dry, 500 kVA</td><td>1980</td><td>1 Each</td><td></td><td></td><td></td></td<>	D5010		Primary Transformer, Dry, 500 kVA	1980	1 Each			
D5020 Exit Lighting Fixture, w/ Battery 2000 5 Each D5020 Fluorescent Lighting Fixture, T8, 2-32w 1995 137 Each D5020 Fluorescent Lighting Fixture, T8, 4-32 w 1995 14 Each D5020 Incandescent Lighting Fixture, Basic, 100 w 1995 2 Each Exterior D5020 LED Lighting Fixture, 100 w 2010 3 Each Wall Mounted D5020 Metal Halide Lighting Fixture, Wall Mount, 150 w 2010 2 Each Wall Mounted D5020 Metal Halide Lighting Fixture, Wall Mount, 150 w 2010 2 Each Wall Mounted D5020 Metal Halide Lighting Fixture, Wall Mount, 150 w 2010 2 Each Wall Mounted D5020 Receptacle, 120 V, 15 Amp. 1990 60 Each 60 Each 60 Each D5020 Receptacle, 120 V, 15 Amp. 1996 50 Each 50 Each 50 Each D5030 Fire Alarm Bell, 6" 2000 4 Each 50 Each 50 Each D5030 Gas Monitoring System 2005 1 Each 6 Each D5030 <td>D5010</td> <td></td> <td>Secondary Transformer, Dry, 150 kVA</td> <td>1980</td> <td>1 Each</td> <td></td> <td></td> <td></td>	D5010		Secondary Transformer, Dry, 150 kVA	1980	1 Each			
D5020 Fluorescent Lighting Fixture, T8, 2-32w 1995 137 Each	D5020		Emergency Lighting Pack, 2 Light w/ Battery	2005	9 Each			
D5020 Fluorescent Lighting Fixture, T8, 4-32 w 1995 14 Each	D5020		Exit Lighting Fixture, w/ Battery	2000	5 Each			
D5020 Incandescent Lighting Fixture, Basic, 100 w 1995 2 Each Exterior D5020 LED Lighting Fixture, 100 w 2010 3 Each Wall Mounted D5020 Metal Halide Lighting Fixture, Wall Mount, 150 w 2010 2 Each Valid Mounted D5020 Receptacle, 120 V, 15 Amp. 1990 60 Each 60 Each D5020 Receptacle, 120 V, 15 Amp. 1996 50 Each D5020 Wirring Device, Switch 1995 30 Each D5030 Fire Alarm Bell, 6" 2000 4 Each D5030 Fire Alarm Horn & Strobe 2000 5 Each D5030 Gas Monitoring System 2005 1 Each D5030 Keypad 2010 1 Each D5030 Manual Pull Station 2000 6 Each D5030 Public Address Speaker 1990 6 Each D5030 Smoke Detector 2000 8 Each D5090 Battery Charger 1990 3 Each E1010 Icemaker, Commercial 2010 1 Each <td>D5020</td> <td></td> <td>Fluorescent Lighting Fixture, T8, 2-32w</td> <td>1995</td> <td>137 Each</td> <td></td> <td></td> <td></td>	D5020		Fluorescent Lighting Fixture, T8, 2-32w	1995	137 Each			
D5020 LED Lighting Fixture, 100 w 2010 3 Each Wall Mounted D5020 Metal Halide Lighting Fixture, Wall Mount, 150 w 2010 2 Each D5020 Receptacle, 120 V, 15 Amp. 1990 60 Each D5020 Receptacle, 120 V, 15 Amp. 1966 50 Each D5020 Wiring Device, Switch 1995 30 Each D5030 Fire Alarm Bell, 6" 2000 4 Each D5030 Fire Alarm Horn & Strobe 2000 5 Each D5030 Gas Monitoring System 2005 1 Each D5030 Keypad 2010 1 Each D5030 Manual Pull Station 2000 6 Each D5030 Public Address Speaker 1990 6 Each D5030 Smoke Detector 2000 8 Each D5090 Battery Charger 1990 3 Each E1010 Icemaker, Commercial 2010 1 Each	D5020		Fluorescent Lighting Fixture, T8, 4-32 w	1995	14 Each			
D5020 Metal Halide Lighting Fixture, Wall Mount, 150 w 2010 2 Each D5020 Receptacle, 120 V, 15 Amp. 1990 60 Each D5020 Receptacle, 120 V, 15 Amp. 1966 50 Each D5020 Wiring Device, Switch 1995 30 Each D5030 Fire Alarm Bell, 6" 2000 4 Each D5030 Fire Alarm Horn & Strobe 2000 5 Each D5030 Gas Monitoring System 2005 1 Each D5030 Keypad 2010 1 Each D5030 Manual Pull Station 2000 6 Each D5030 Public Address Speaker 1990 6 Each D5030 Smoke Detector 2000 8 Each D5090 Battery Charger 1990 3 Each E1010 Icemaker, Commercial 2010 1 Each	D5020		Incandescent Lighting Fixture, Basic, 100 w	1995	2 Each	Exterior		
D5020 Receptacle, 120 V, 15 Amp. 1990 60 Each D5020 Receptacle, 120 V, 15 Amp. 1966 50 Each D5020 Wiring Device, Switch 1995 30 Each D5030 Fire Alarm Bell, 6" 2000 4 Each D5030 Fire Alarm Horn & Strobe 2000 5 Each D5030 Gas Monitoring System 2005 1 Each D5030 Keypad 2010 1 Each D5030 Manual Pull Station 2000 6 Each D5030 Public Address Speaker 1990 6 Each D5030 Smoke Detector 2000 8 Each D5090 Battery Charger 1990 3 Each E1010 Icemaker, Commercial 2010 1 Each	D5020		LED Lighting Fixture, 100 w	2010	3 Each		Wall Mounted	
D5020 Receptacle, 120 V, 15 Amp. 1966 50 Each D5020 Wiring Device, Switch 1995 30 Each D5030 Fire Alarm Bell, 6" 2000 4 Each D5030 Fire Alarm Horn & Strobe 2000 5 Each D5030 Gas Monitoring System 2005 1 Each D5030 Keypad 2010 1 Each D5030 Manual Pull Station 2000 6 Each D5030 Public Address Speaker 1990 6 Each D5030 Smoke Detector 2000 8 Each D5030 Battery Charger 1990 3 Each E1010 Icemaker, Commercial 2010 1 Each	D5020		Metal Halide Lighting Fixture, Wall Mount, 150 w	2010	2 Each			
D5020 Wiring Device, Switch 1995 30 Each D5030 Fire Alarm Bell, 6" 2000 4 Each D5030 Fire Alarm Horn & Strobe 2000 5 Each D5030 Gas Monitoring System 2005 1 Each D5030 Keypad 2010 1 Each D5030 Manual Pull Station 2000 6 Each D5030 Public Address Speaker 1990 6 Each D5030 Smoke Detector 2000 8 Each D5090 Battery Charger 1990 3 Each E1010 Icemaker, Commercial 2010 1 Each	D5020		Receptacle, 120 V, 15 Amp.	1990	60 Each			
D5030 Fire Alarm Bell, 6" 2000 4 Each D5030 Fire Alarm Horn & Strobe 2000 5 Each D5030 Gas Monitoring System 2005 1 Each D5030 Keypad 2010 1 Each D5030 Manual Pull Station 2000 6 Each D5030 Public Address Speaker 1990 6 Each D5030 Smoke Detector 2000 8 Each D5090 Battery Charger 1990 3 Each E1010 Icemaker, Commercial 2010 1 Each	D5020		Receptacle, 120 V, 15 Amp.	1966	50 Each			
D5030 Fire Alarm Horn & Strobe 2000 5 Each D5030 Gas Monitoring System 2005 1 Each D5030 Keypad 2010 1 Each D5030 Manual Pull Station 2000 6 Each D5030 Public Address Speaker 1990 6 Each D5030 Smoke Detector 2000 8 Each D5090 Battery Charger 1990 3 Each E1010 Icemaker, Commercial 2010 1 Each	D5020		Wiring Device, Switch	1995	30 Each			
D5030 Gas Monitoring System 2005 1 Each D5030 Keypad 2010 1 Each D5030 Manual Pull Station 2000 6 Each D5030 Public Address Speaker 1990 6 Each D5030 Smoke Detector 2000 8 Each D5090 Battery Charger 1990 3 Each E1010 Icemaker, Commercial 2010 1 Each	D5030		Fire Alarm Bell, 6"	2000	4 Each			
D5030 Keypad 2010 1 Each D5030 Manual Pull Station 2000 6 Each D5030 Public Address Speaker 1990 6 Each D5030 Smoke Detector 2000 8 Each D5090 Battery Charger 1990 3 Each E1010 Icemaker, Commercial 2010 1 Each	D5030		Fire Alarm Horn & Strobe	2000	5 Each			
D5030 Manual Pull Station 2000 6 Each D5030 Public Address Speaker 1990 6 Each D5030 Smoke Detector 2000 8 Each D5090 Battery Charger 1990 3 Each E1010 Icemaker, Commercial 2010 1 Each	D5030		Gas Monitoring System	2005	1 Each			
D5030 Public Address Speaker 1990 6 Each D5030 Smoke Detector 2000 8 Each D5090 Battery Charger 1990 3 Each E1010 Icemaker, Commercial 2010 1 Each	D5030		Keypad	2010	1 Each			
D5030 Smoke Detector 2000 8 Each D5090 Battery Charger 1990 3 Each E1010 Icemaker, Commercial 2010 1 Each	D5030		Manual Pull Station	2000	6 Each			
D5090 Battery Charger 1990 3 Each E1010 Icemaker, Commercial 2010 1 Each	D5030		Public Address Speaker	1990	6 Each			
E1010 Icemaker, Commercial 2010 1 Each	D5030		Smoke Detector	2000	8 Each			
	D5090		Battery Charger	1990	3 Each			
E1010 Microwave Oven 2010 1 Each	E1010		Icemaker, Commercial	2010	1 Each			
	E1010		Microwave Oven	2010	1 Each			
E1010 Refrigerator, Domestic 2010 1 Each	E1010		Refrigerator, Domestic	2010	1 Each			
G3010 Post Indicator Valve 1990 1 Each	G3010		Post Indicator Valve	1990	1 Each			

Building: Distribution Center Year Built: 1966 Building Type: Temperature Controlled W

Facility: Langley Research Center Original Cost: \$1 Building Num: 1206

City: Hampton, VA Replacement Value: \$3,639,735 per SF: \$102 Building Gsft: 35,625

			Remainino Service			Degradation			N .
Uniformat Asset Description	Component	Date	Life*	Quantity	Maintenance	Cost***	Maintenance	Location	Notes
B1010	Concrete Decking	1966	27	1223 Sq Ft					
B1010	Concrete Ramp	1966	27	399 Sq Ft					
B2010	Steel, Insulated Wall Panels, Painted, Exterior,	1966	-8	11810 Sq Ft	\$209,722	\$0	\$209,722		
B2020	Steel Operable Window, 12 sf, 1st Fl	1966	27	19 Each					
B2030	Steel, 14'x10', Painted, Overhead Coiling Door	1990	11	5 Each					
B2030	Steel, Painted, Exterior Door	1966	27	7 Each					
B2030	Steel, Painted, Exterior Double Door	1966	27	2 Each					
B3010	Aluminum Gutter, Downspouts, Fittings	1966	4	0.8 K Ln Ft	t				
B3010	Metal Canopy	1966	4	1733 Sq Ft					
B3010	Metal Roof	1966	4	36800 Sq Ft					sprayed with foam
C1010	Plexiglass Fixed Window, UV Filtering, 24 Sf	1966	27	5 Each					
C1010	Toilet Partitions, Painted Metal, Overhead Bra	1966	-28	4 Each	\$3,205	\$0	\$3,205		
C1020	Steel, 10'x8', Painted, Overhead Coiling Door,	1990	11	2 Each					
C1020	Steel, Painted, Interior Double Door w/ Safety	1966	27	1 Each					
C1020	Wood, Hollow Core, Painted, Interior Door	1966	-18	19 Each	\$9,949	\$0	\$9,949		
C2010	Concrete, Exterior Stairs	1966	2	131 Sq Ft					
C2010	Concrete, Interior Stairs	1966	27	39 Sq Ft				120	
C2010	Metal, Painted, Exterior Railing	1966	-18	107 Ln Ft	\$4,868	\$0	\$4,868		
C2010	Metal, Painted, Exterior Stairs	1966	2	31 Sq Ft					
C2010	Metal, Painted, Interior Railing	1966	2	70 Ln Ft					
C2010	Metal, Painted, Interior Stairs	1966	27	198 Sq Ft					

^{*}Remaining Service Life shows years until scheduled Replacement Task; blank implies there is no Replacement Task.

All costs expressed in (\$) 2012.

^{**}Deferred Maintenance is defined as the cost of rebuilding or replacing components whose service life has exceeded their scheduled lifetime as of the Forecast Year. Preventative maintenance and minor repairs are not included.

^{***}Degradation Cost is defined as additional cost (penalty cost) incurred by maintenance deferral.

[§] Indicates Component set to have PM Tasks coincide with Replacement Task.

		F	Remaining Service		Deferred** D	Degradation	Total Deferred		
Uniformat Asset Description	Component	Date	Life*	Quantity	Maintenance	Cost***	Maintenance	Location	Notes
C3010	Ceramic Tile, 4"x4", Interior Wall Finish	1966	27	250 Sq Ft				104,107	
C3010	Ceramic Tile, 4"x4", Interior Wall Finish	1966	27	777 Sq Ft				109,112	
C3010	Concrete Block, Interior Wall Finish	1966	27	3829 Sq Ft				101	
C3010	Concrete Block, Painted, Interior Wall Finish	1966	27	1730 Sq Ft				116	
C3010	Concrete Block, Painted, Interior Wall Finish	1966	27	726 Sq Ft				105	
C3010	Concrete Block, Painted, Interior Wall Finish	1966	27	812 Sq Ft				110	
C3010	Concrete Block, Painted, Interior Wall Finish	1966	27	776 Sq Ft				109,112	
C3010	Concrete Block, Painted, Interior Wall Finish	1966	27	944 Sq Ft				114	
C3010	Concrete Block, Painted, Interior Wall Finish	1966	27	2257 Sq Ft				120	
C3010	Concrete Block, Painted, Interior Wall Finish	1966	27	250 Sq Ft				104,107	
C3010	Concrete Block, Painted, Interior Wall Finish	1966	27	599 Sq Ft				122,121,123	
C3010	Concrete Block, Painted, Interior Wall Finish	1966	27	670 Sq Ft				119	
C3010	Concrete Block, Painted, Interior Wall Finish	1966	27	7644 Sq Ft				108	
C3010	Concrete Block, Painted, Interior Wall Finish	1966	27	179 Sq Ft				108E	
C3010	Concrete Block, Painted, Interior Wall Finish	1966	27	158 Sq Ft				108D	
C3010	Gypsum Board, Interior Wall Finish	1966	27	1636 Sq Ft				119	
C3010	Gypsum Board, Interior Wall Finish	1966	27	7698 Sq Ft				124,125,126,127,128,129, 130,131,H1A	
C3010	Gypsum Board, Interior Wall Finish	1966	27	2351 Sq Ft				122,121,123	
C3010	Gypsum Board, Interior Wall Finish	1966	27	438 Sq Ft				108D	
C3010	Gypsum Board, Interior Wall Finish	1966	27	965 Sq Ft				108B	
C3010	Gypsum Board, Interior Wall Finish	1966	27	445 Sq Ft				108E	
C3010	Gypsum Board, Interior Wall Finish	1966	27	1334 Sq Ft				120	
C3010	Gypsum Board, Interior Wall Finish	1966	27	425 Sq Ft				108	
C3010	Gypsum Board, Interior Wall Finish	1966	27	1192 Sq Ft				102,103,103A	
C3010	Gypsum Board, Interior Wall Finish	1966	27	734 Sq Ft				108A	
C3010	Gypsum Board, Interior Wall Finish	1966	27	334 Sq Ft				116	
C3010	Steel, Painted, Interior Wall Finish	1966	27	935 Sq Ft					
C3020	Carpet, Nylon 20 oz., High Traffic	1966	-40	1036 Sq Ft	\$7,476	\$0	\$7,476	108B,116	

^{*}Remaining Service Life shows years until scheduled Replacement Task; blank implies there is no Replacement Task.

^{**}Deferred Maintenance is defined as the cost of rebuilding or replacing components whose service life has exceeded their scheduled lifetime as of the Forecast Year. Preventative maintenance and minor repairs are not included.

^{***}Degradation Cost is defined as additional cost (penalty cost) incurred by maintenance deferral.

[§] Indicates Component set to have PM Tasks coincide with Replacement Task.

		F	Remaining Service		Defermed**		Total		
Uniformat Asset Description	Component	Date	Life*	Quantity	Deferred** I Maintenance	Degradation Cost***	Deferred Maintenance	Location	Notes
C3020	Carpet, Nylon 20 oz., High Traffic	1966	-40	1080 Sq Ft	\$7,793	\$0	\$7,793	102,103,103A	
C3020	Carpet, Nylon 20 oz., High Traffic	1966	-40	1792 Sq Ft	\$12,931	\$0	\$12,931	125,126,127,H1A,129,128, 124,130,131	
C3020	Carpet, Nylon 20 oz., High Traffic	1966	-40	779 Sq Ft	\$5,622	\$0	\$5,622	119	
C3020	Carpet, Nylon 20 oz., High Traffic	1966	-40	961 Sq Ft	\$6,935	\$0	\$6,935	121,122,123	
C3020	Carpet, Nylon 20 oz., High Traffic	1966	-40	148 Sq Ft	\$1,068	\$0	\$1,068	108A	
C3020	Ceramic Tile Flooring	1966	2	314 Sq Ft				109,112	
C3020	Ceramic Tile Flooring	1966	2	151 Sq Ft				104	
C3020	Ceramic Tile Flooring	1966	2	49 Sq Ft				107	
C3020	Concrete Flooring	1966	27	145 Sq Ft					
C3020	Concrete Flooring	1966	27	2141 Sq Ft				120	
C3020	Concrete Flooring	1966	27	14726 Sq Ft				108,108D,108E,110	
C3020	Concrete Flooring	1966	27	7412 Sq Ft				101, above 102,103,103A	
C3020	Concrete Flooring	1966	27	230 Sq Ft				114	
C3020	Metal Floor Grating	1966	-18	4662 Sq Ft	\$65,438	\$0	\$65,438	108 2nd floor	
C3030	Acoustical Tile Ceiling	1966	22	310 Sq Ft				109,112	
C3030	Acoustical Tile Ceiling	1966	22	1768 Sq Ft				125,126,127,H1A,129,128, 124,130,131	
C3030	Acoustical Tile Ceiling	1966	22	948 Sq Ft				121,122,123	
C3030	Acoustical Tile Ceiling	1966	22	48 Sq Ft				107	
C3030	Acoustical Tile Ceiling	1966	22	149 Sq Ft				104	
C3030	Acoustical Tile Ceiling	1966	22	1066 Sq Ft				102,103,103A	
C3030	Gypsum Board, Finished Ceiling	1966	27	768 Sq Ft				119	
C3030	Gypsum Board, Finished Ceiling	1966	27	1022 Sq Ft				108B,116	
C3030	Metal Ceiling	1966	27	5797 Sq Ft				101	
C3030	Metal Ceiling	1966	27	227 Sq Ft				114	
C3030	Metal Ceiling	1966	27	143 Sq Ft					
C3030	Metal Ceiling	1966	27	14527 Sq Ft				108,108D,108E,110	
C3030	Metal Ceiling	1966	27	2112 Sq Ft				120	
C3030	Plywood Ceiling, Painted	1966	-8	146 Sq Ft	\$1,168	\$0	\$1,168		

^{*}Remaining Service Life shows years until scheduled Replacement Task; blank implies there is no Replacement Task.

^{**}Deferred Maintenance is defined as the cost of rebuilding or replacing components whose service life has exceeded their scheduled lifetime as of the Forecast Year. Preventative maintenance and minor repairs are not included.

^{***}Degradation Cost is defined as additional cost (penalty cost) incurred by maintenance deferral.

[§] Indicates Component set to have PM Tasks coincide with Replacement Task.

Uniformat	Asset Description	Component	Date	Remaining Service Life*	Quantity	Deferred** Maintenance	Degradation Cost***	Total Deferred Maintenance	Location	Notes
D1090		Dock Ramp Leveler	1966	-23	4 Each	\$38,427	\$0	\$38,427		
D2010		Emergency Eye Wash	1966	-23	1 Each	\$772	\$0	\$772		
D2010		Lavatory, Vitreous China	1966	-13	5 Each	\$2,165	\$0	\$2,165		
D2010		Service Sink, Iron, Enamel	1966	-13	1 Each	\$962	\$0	\$962		
D2010		Sink, Stainless Steel	1966	-8	1 Each	\$939	\$0	\$939		
D2010		Tankless Water Closet	1966	-13	6 Each	\$3,657	\$0	\$3,657		
D2010		Urinal, Vitreous China	1966	-13	4 Each	\$2,914	\$0	\$2,914		
D2010		Water Cooler, Electric	1995	-9	4 Each	\$4,505	\$0	\$4,505		
D2020		Hose Bib	1966	-38	1 Each	\$52	\$0	\$52		
D2020		Pipe & Fittings, 3/4" Copper, Cold Water	1966	-23	0.35 K Ln F	t \$1,313	\$0	\$1,313		
D2020		Pipe & Fittings, 3/4" Copper, Hot Water	1966	-23	0.35 K Ln F	t \$1,313	\$0	\$1,313		
D2020		Pipe Insulation, Fiberglass, Cold Water	1966	-23	0.35 K Ln F	t \$274	\$0	\$274		
D2020		Pipe Insulation, Fiberglass, Hot Water	1966	-23	0.35 K Ln F	t \$274	\$0	\$274		
D2020	Bradford-White MI20	Water Heater, Electric, 15 Gal.	1966	-33	1 Each	\$1,040	\$0	\$1,040		
D2020		Water Heater, Electric, 5 Gal.	1966	-33	1 Each	\$714	\$0	\$714		6 Gal
D2030		Backflow Preventer, 2"	2000	-4	2 Each	\$3,556	\$0	\$3,556		
D2030		Backflow Preventer, 3/4"	2000	-4	1 Each	\$827	\$0	\$827		
D2030		Floor Drain	1966	-8	1 Each	\$283	\$0	\$283		
D2030		Pipe & Fittings, 2" PVC	1990	6	0.05 K Ln F	t				
D2030		Pipe & Fittings, 3" Cast Iron	1966	27	0.3 K Ln F	t				
D2030		Pipe & Fittings, 4" Cast Iron	1966	27	0.1 K Ln F	t				
D3010		Pressure Reducer Valve, 2"	1966	-42	2 Each	\$1,562	\$0	\$1,562		
D3020		Boiler, Gas, 100 Mbh	2000	14	1 Each					
D3020		Condensate Removal Pump System, 1/50 HP	2006	6	1 Each					
D3020		Gate Valve, 6"	1966	-29	2 Each	\$4,309	\$0	\$4,309		
D3020		Heat Exchanger, Steam-to-Water, 15 Gpm	2006	20	1 Each					
D3020		Pipe & Fittings, 10" Steel	1966	27	0.05 K Ln F	t				
D3020		Pipe & Fittings, 2" Steel	1966	27	0.35 K Ln F	t				

^{*}Remaining Service Life shows years until scheduled Replacement Task; blank implies there is no Replacement Task.

^{**}Deferred Maintenance is defined as the cost of rebuilding or replacing components whose service life has exceeded their scheduled lifetime as of the Forecast Year. Preventative maintenance and minor repairs are not included.

^{***}Degradation Cost is defined as additional cost (penalty cost) incurred by maintenance deferral.

[§] Indicates Component set to have PM Tasks coincide with Replacement Task.

Uniformat Asset Description	Component	Date	Remaining Service Life*	Quantity		Degradation		Location	Notes
	•				Maintenance	Cost***	Maintenance	Location	
D3020	Pipe & Fittings, 4" Steel	1966		0.1 K Ln F1		•			
D3020	Pipe Insulation, Fiberglass, Heating Water/Ste	1966		0.35 K Ln Ft		\$0	\$382		
D3020	Steam Trap, F&T, 2"	1966		40 Each	\$33,955	\$0	\$33,955		
D3020	Valve, Non-Drain, 10"	1966	-29	2 Each	\$11,669	\$0	\$11,669		Steam Valve
D3030	Ball Valve, 1"	1966	-31	6 Each	\$2,032	\$0	\$2,032		Relief Valve
D3030	Condenser, Air-Cooled, 1 Ton	1994	9	8 Each					
D3030	Condenser, Air-Cooled, 10 Ton	2006	21	1 Each					
D3030	Expansion Tank, 30 Gal.	1966	2	1 Each					
D3040	Air Handler, Single Zone, 8,000 Cfm	2006	7	1 Each					American Standard M#TWE120A300
D3040	Dehumidifier & Control, 120-150 lbs, 4,500 Cf	2000	5	1 Each					
D3040	Duct Insulation, Fiberglass Blanket	2006	24	150 Sq Ft					
D3040	Ductwork	2006	24	350 Lbs					
D3040	Exhaust Fan, Propeller, 1,000 Cfm	1966	-29	4 Each	\$3,950	\$0	\$3,950		
D3040	Residential Type Ceiling Fan	2000	6	4 Each					
D3050	Air Conditioner, DX Packaged, Air Cooled, 1 T	1994	12	8 Each					
D3050	Air Conditioner, Window, 1 Ton	2000	18	11 Each					
D3050	Heat Pump, 3 Ton	1990	8	2 Each					
D3050	Suspended Heater, Hot Water, 1,200 Cfm, 55	1990	5	19 Each					
D3050	Suspended Heater, Hot Water, 2,000 Cfm, 18	1990	5	8 Each					
D3060	Thermostat	1994	-10	9 Each	\$3,184	\$0	\$3,184		
D4010	Fire Alarm Control Panel	2000	1	1 Each					
D4010	Fire Department Connection, Siamese, 3"	1990	26	1 Each					
D4010	Fire Sprinkler Head	1990	26	158 Each					
D4010	Fire Sprinkler System	1990	NA	1 Each					
D4010	Pipe & Fittings, 1" Steel	1990	51	0.45 K Ln Ft	t				
D4010	Pipe & Fittings, 2" Steel	1990	51	0.1 K Ln Ft	t				
D4010	Pipe & Fittings, 4" Steel	1990	51	0.05 K Ln Ft	t				
D4010	Valves & Components, Sprinkler System, 3"	1990	-4	1 Each	\$3,210	\$0	\$3,210		

^{*}Remaining Service Life shows years until scheduled Replacement Task; blank implies there is no Replacement Task.

^{**}Deferred Maintenance is defined as the cost of rebuilding or replacing components whose service life has exceeded their scheduled lifetime as of the Forecast Year. Preventative maintenance and minor repairs are not included.

^{***}Degradation Cost is defined as additional cost (penalty cost) incurred by maintenance deferral.

[§] Indicates Component set to have PM Tasks coincide with Replacement Task.

Uniformat Asset Description	Component	Date	Remaining Service Life*	Quantity	Deferred** Maintenance	Degradation Cost***	Total Deferred Maintenance	Location	Notes
D4030	Fire Extinguisher	2010	8	8 Each					
D5010	Disconnect Switch, 30 Amp.	1980	16	17 Each					
D5010	Disconnect Switch, 60 Amp.	1980	16	2 Each					
D5010	Power Panel Board, 208 Y/120 V, 100 Amp.	1980	-4	2 Each	\$7,898	\$0	\$7,898		
D5010	Power Panel Board, 208 Y/120 V, 225 Amp	1990	6	1 Each					
D5010	Primary Transformer, Dry, 500 kVA	1980	-4	1 Each	\$53,292	\$0	\$53,292		
D5010	Secondary Transformer, Dry, 150 kVA	1980	-4	1 Each	\$11,773	\$0	\$11,773		
D5020	Emergency Lighting Pack, 2 Light w/ Battery	2005	11	9 Each					
D5020	Exit Lighting Fixture, w/ Battery	2000	6	5 Each					
D5020	Fluorescent Lighting Fixture, T8, 2-32w	1995	1	137 Each					
D5020	Fluorescent Lighting Fixture, T8, 4-32 w	1995	1	14 Each					
D5020	Incandescent Lighting Fixture, Basic, 100 w	1995	1	2 Each				Exterior	
D5020	LED Lighting Fixture, 100 w	2010	16	3 Each					Wall Mounted
D5020	Metal Halide Lighting Fixture, Wall Mount, 150	2010	16	2 Each					
D5020	Receptacle, 120 V, 15 Amp.	1966	-28	50 Each	\$2,106	\$0	\$2,106		
D5020	Receptacle, 120 V, 15 Amp.	1990	-4	60 Each	\$2,527	\$0	\$2,527		
D5020	Wiring Device, Switch	1995	-4	30 Each	\$1,027	\$0	\$1,027		
D5030	Fire Alarm Bell, 6"	2000	6	4 Each					
D5030	Fire Alarm Horn & Strobe	2000	6	5 Each					
D5030	Gas Monitoring System	2005	6	1 Each					
D5030	Keypad	2010	6	1 Each					
D5030	Manual Pull Station	2000	1	6 Each					
D5030	Public Address Speaker	1990	-9	6 Each	\$1,674	\$0	\$1,674		
D5030	Smoke Detector	2000	1	8 Each					
D5090	Battery Charger	1990	-4	3 Each	\$3,435	\$0	\$3,435		
E1010	Icemaker, Commercial	2010	6	1 Each					
E1010	Microwave Oven	2010	6	1 Each					
E1010	Refrigerator, Domestic	2010	6	1 Each					

^{*}Remaining Service Life shows years until scheduled Replacement Task; blank implies there is no Replacement Task.

^{**}Deferred Maintenance is defined as the cost of rebuilding or replacing components whose service life has exceeded their scheduled lifetime as of the Forecast Year. Preventative maintenance and minor repairs are not included.

^{***}Degradation Cost is defined as additional cost (penalty cost) incurred by maintenance deferral.

[§] Indicates Component set to have PM Tasks coincide with Replacement Task.

Uniformat Asset Des	cription Component	Remaining Service Date Life* Qu	Deferre uantity Mainten	 Total n Deferred Maintenance	Location	Notes
G3010	Post Indicator Valve	1990 11	1 Fach			

^{*}Remaining Service Life shows years until scheduled Replacement Task; blank implies there is no Replacement Task.

^{**}Deferred Maintenance is defined as the cost of rebuilding or replacing components whose service life has exceeded their scheduled lifetime as of the Forecast Year. Preventative maintenance and minor repairs are not included.

^{***}Degradation Cost is defined as additional cost (penalty cost) incurred by maintenance deferral.


[§] Indicates Component set to have PM Tasks coincide with Replacement Task.

Whitestone Research

23-Dec-14

Building: Distribution Center	Facility: Langley Research Cen 35625	nter City: Hampton, VA
Forecast Year: 2013 4 5 6 7 2018	9 0 1 2 2023 4 5 6	7 2028 9 0 1 2 2033 4 5 6 7
A10 Foundations A20 Basement Construction B10 Super Structure 0.05		.07 0.05
B20 Exterior Enclosure 0.03 0.03 0.03 0.73 0.03 0.03 B30 Roofing 0.23 0.23 0.23 0.56 0.23 12.75		.60
C10 Interior Construction 0.01 0.03 0.01 0.22 0.01 0.03		.23 0.23 0.30 0.23 0.23 0.23 0.23 0.47 0.23 0.23 0.23 0.23
C20 Stairs 0.01 0.21 0.01		.16 0.00 0.01 0.01 0.00 0.01 0.01
C30 Interior Finishes 1.69 2.91 0.22	0.03 1.69 0.02 3.3	.25
D10 Conveying 0.06 0.06 0.06 1.08 0.06 0.06	0.06 0.06 0.06 0.06 0.06 0.06 0.06 0.	.06 0.06 0.06 0.06 0.06 0.06 0.06 0.06
D20 Plumbing 0.03 0.04 0.17 0.17 0.03 0.03	0.03 0.14 0.03 0.06 0.03 0.03 0.15 0.	.13 0.03 0.03 0.05 0.14 0.03 0.03 0.03 0.03 0.15 0.32 0.03
D30 HVAC 0.73 1.35 0.72 0.85 1.20 0.72	5.18 1.69 1.33 1.03 2.30 0.80 0.72 1.	.73 0.73 0.92 1.61 0.72 0.76 1.59 0.72 0.95 1.69 1.24 0.72
D40 Fire Protection 0.07 0.07 0.16 0.07 0.07 0.07	0.07 0.25 0.07 0.13 0.07 0.07 0.07 0.0	.07
D50 Electrical 0.07 0.07 0.90 0.07 0.07 0.07	0.07 0.55 0.07 0.07 0.07 0.07 0.84 0.	.13 0.07 0.07 0.07 0.54 0.07 0.07 0.07 0.07 0.96 0.07 0.07
E10 Equipment 0.05 0.05 0.05 0.05 0.05 0.05	0.05 0.52 0.05 0.05 0.05 0.05 0.05 0.05	.05 0.05 0.05 0.05 0.52 0.05 0.05 0.05 0
E20 Furnishings		
F10 Special Construction		
F20 Selective Bldg Demolition		
G10 Site Preparation		
G20 Site Improvements		
G30 Site Mechanical Utilities 0.00 0.00 0.00 0.00 0.00 0.00	0.00 0.00 0.00 0.00 0.00 0.00 0.07 0.0	0.00 0.00 0.00 0.00 0.00 0.00 0.00 0.00 0.00 0.00 0.00 0.00
G40 Site Electrical Utilities		
G90 Other Site Construction		
Total 1.28 3.63 2.34 6.97 1.76 14.04	5.73 3.68 1.93 3.40 3.10 1.38 3.50 6.6	.89 1.29 1.83 2.19 4.37 1.39 2.18 1.52 1.82 3.41 4.32 1.27





Notes: A value of "0.00" means cost of more than \$.000 but less than \$.005 per gsft. All costs expressed in (\$) 2012 per gsft.

Year 1-25


M&R Costs by System per Year Chart

Whitestone Research

23-Dec-14

Building: Distrib Building Num: 1206	ution (Center	•						cility			y Res	earc	h Ce	nter			Ci	ity: ⊦	lamı	oton, \	/A				
Forecast Year: 2	2038	9	0 1	2	2 20	43 4	4 5		6			9	0	1	2	2053	4	5	6	7	2058	9	0	1	2	Total
A10 Foundations																										0.00
A20 Basement Construction																										0.00
B10 Super Structure				0.98										0.05					0.02					0.05		1.25
B20 Exterior Enclosure	0.03	0.03	0.03	2.19	0.03	0.03	0.03	0.15	5.93	0.03	0.03	0.03	0.03	0.14	0.03	0.03	0.03	0.15	0.50	0.03	0.03	0.03	1.08	0.15	0.03	14.77
B30 Roofing	0.99	0.23	0.23	0.23	0.23	0.47	0.23	0.23	0.23	0.23	2.26	0.23	0.23	0.23	0.23	0.47	0.23	0.23	0.23	0.23	3 11.05	0.23	0.23	0.23	0.23	39.27
C10 Interior Construction	0.03	0.01		0.27	0.03	0.01	0.01			0.01		0.02	0.03	0.06			0.03	0.06		0.02		0.01			0.02	3.39
C20 Stairs	0.01		0.00					0.01			0.00				0.00					0.01				0.02		0.88
C30 Interior Finishes	1.69		0.02		0.02			0.21	-			0.51					1.18		_	0.51			0.02	-	1.17	55.14
D10 Conveying	0.06	0.06		1.08	0.06							0.06					0.06	0.06		0.06		0.06		0.06	0.06	4.92
D20 Plumbing	0.04	0.03	0.14									0.03	• • • • •				0.03	0.15	-	0.05		0.03			0.04	3.79
D30 HVAC	3.93		• • • •	1.26				-	-	-		0.78			1.33		1.08	0.73	1.86		_		0.73		1.28	66.56
D40 Fire Protection	0.07	0.08	0.38									0.07					0.07	0.07		0.07		0.07			0.07	5.17
D50 Electrical	0.07	0.07	2.35						-			0.07					0.07	0.88					0.33		0.07	11.90
E10 Equipment	0.05	0.05	0.52	0.05	0.05	0.05	0.05	0.05	0.05	0.05	0.05	0.05	0.52	0.05	0.05	0.05	0.05	0.05	0.05	0.05	0.05	0.05	0.52	0.05	0.05	4.74
E20 Furnishings																										0.00
F10 Special Construction																										0.00
F20 Selective Bldg Demolition																										0.00
G10 Site Preparation																										0.00
G20 Site Improvements	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00		0.00	0.07	0.00	0.00	0.00
G30 Site Mechanical Utilities	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.07	0.00	0.00	0.22
G40 Site Electrical Utilities G90 Other Site Construction																										0.00
Total	6.97	1 45	4.48 3°	7 21	2 15	1 52	1 07	2 50	0.00	2.17	7 56	9 4 00	2.0	7 2 45	. 40	4 0 4	9 2.83	2.38	5.44	1 20	8 12.7	1 17	1 2 76	2 40	3.02	
lotai	0.31	1.70	7.70 3	7.31	2.13	1.00	1.07	2.55	9.02	. Z. I /	5.0	0 1.00	3.2	3.10	1.9	1 2.13	9 2.03	2.30	J. 4	1 3.5	0 12.7	1 1.7	1 3.70	, 3.40	3.02	212.01





Notes: A value of "0.00" means cost of more than \$.000 but less than \$.005 per gsft.

All costs expressed in (\$) 2012 per gsft.

Year 26-50

Building: Distribution Center Facility: Langley Research Center

Forecast Year	2013	4	5	6	7	2018	9	0	1	2	2023	4	5	6	7	2028	9	0	1	2	2033	4	5	6	7
B10 Super Structure																									
Refinish Concrete Decking				1,228										1,228										1,228	
Refinish Concrete Ramp				401										401										401	
Repair Concrete Decking (2% of Decking)														506											
Repair Concrete Ramp (2% of Ramp)														166											
Finish Repaired Concrete Decking														25											
Finish Repaired Concrete Ramp														8											
Replace Concrete Decking																									
Replace Concrete Ramp																									
Finish Replaced Concrete Decking																									
Finish Replaced Concrete Ramp																									
B20 Exterior Enclosure																									
Refinish Steel, Painted, Exterior Door				183										183										183	
Repair Steel, Painted, Exterior Door														1,251											
Replace Steel, Painted, Exterior Door																									
Finish Replaced Steel, Painted, Exterior Door																									
Maintain Steel, Painted, Exterior Double Door Locks				42					42					42					42					42	
Replace Steel, Painted, Exterior Double Door Locks				651										651										651	
Refinish Steel, Painted, Exterior Double Door				86										86										86	
Repair Steel, Painted, Exterior Double Door														666											
Replace Steel, Painted, Exterior Door Locks				2,281										2,281										2,281	
Finish Replaced Steel, Painted, Exterior Double Door																									
Repair Steel, 14'x10', Painted, Overhead Coiling Door, Motoriz	<u>:</u>							3,216															3,216		
Replace Steel, Painted, Exterior Double Door																									
Repair Steel Operable Window, 12 sf, 1st Fl														414											
Refinish Steel, Insulated Wall Panels, Painted, Exterior, 2"				14,194										14,194										14,194	
Repair Steel, Insulated Wall Panels, Painted, Exterior, 2" (2%	0			6,550																					
Finish Repaired Steel, Insulated Wall Panels, Painted, Exterio	Γ,			284																					
Replace Steel, 14'x10', Painted, Overhead Coiling Door, Moto	á –												37,726												
Finish Replaced Steel, Painted, Exterior, 1st Floor																									
Maintain Steel, Painted, Exterior Door Locks				147					147					147					147					147	
Replace Steel Operable Window, 12 sf, 1st Fl																									
Maintain Steel, 14'x10', Painted, Overhead Coiling Door, Moto	ri 483	483	483	483	483	483	483	483	483	483	483	483		483	483	483	483	483	483	483	483	483	483	483	483
Refinish Steel, 14'x10', Painted, Overhead Coiling Door, Motor	i							741															741		
Finish Replaced Steel, 14'x10', Painted, Overhead Coiling Doo	or												741												
Replace Steel, Insulated Wall Panels, Painted, Exterior, 2"																									

Building: Distribution Center Facility: Langley Research Center

	Forecast Year:	2038	9	0	1	2	2043	4	5	6	7	2048	9	0	1	2	2053	4	5	6	7	2058	9	0	1	2
B10 Super Structure																										
Refinish Concrete Decking															1,228										1,228	
Refinish Concrete Ramp															401										401	
Repair Concrete Decking (2% of Decking)																				506						
Repair Concrete Ramp (2% of Ramp)																				166						
Finish Repaired Concrete Decking																				25						
Finish Repaired Concrete Ramp																				8						
Replace Concrete Decking				2	5,171																					
Replace Concrete Ramp					8,212																					
Finish Replaced Concrete Decking					1,228																					
Finish Replaced Concrete Ramp					401																					
B20 Exterior Enclosure																										
Refinish Steel, Painted, Exterior Door															183										183	
Repair Steel, Painted, Exterior Door																				1,251						
Replace Steel, Painted, Exterior Door					6,099																					

B20 Exterior Enclosure																								
Refinish Steel, Painted, Exterior Door														183									18:	3
Repair Steel, Painted, Exterior Door																			1,251					
Replace Steel, Painted, Exterior Door				6,099																				
Finish Replaced Steel, Painted, Exterior Door				183																				
Maintain Steel, Painted, Exterior Double Door Locks									42					42					42				4:	2
Replace Steel, Painted, Exterior Double Door Locks														651									65	1
Refinish Steel, Painted, Exterior Double Door														86									8	6
Repair Steel, Painted, Exterior Double Door																			666					
Replace Steel, Painted, Exterior Door Locks														2,281									2,28	1
Finish Replaced Steel, Painted, Exterior Double Door				86																				
Repair Steel, 14'x10', Painted, Overhead Coiling Door, Motori								3,216										3,216						
Replace Steel, Painted, Exterior Double Door				3,905																				
Repair Steel Operable Window, 12 sf, 1st Fl																							41	4
Refinish Steel, Insulated Wall Panels, Painted, Exterior, 2"																			14,194					
Repair Steel, Insulated Wall Panels, Painted, Exterior, 2" (2%				6,550																				
Finish Repaired Steel, Insulated Wall Panels, Painted, Exterio				284																				
Replace Steel, 14'x10', Painted, Overhead Coiling Door, Moto																						37,7	26	
Finish Replaced Steel, Painted, Exterior, 1st Floor			:	26,845																				
Maintain Steel, Painted, Exterior Door Locks									147					147					147				14	7
Replace Steel Operable Window, 12 sf, 1st Fl			;	32,686																				
Maintain Steel, 14'x10', Painted, Overhead Coiling Door, Moto	483	483	483	483	483	483	483	483	483	483	483	483	483	483	483	483	483	483	483	483	483	483	48	3 483
Refinish Steel, 14'x10', Painted, Overhead Coiling Door, Moto								741										741						
Finish Replaced Steel, 14'x10', Painted, Overhead Coiling Do																						7	41	
Replace Steel, Insulated Wall Panels, Painted, Exterior, 2"								2	09,722															

Building: Distribution Center Facility: Langley Research Center

Building Num: 1206 City: Hampton, VA

Forecast Year: 2013 4 5 6 7 2018 9 0 1 2 2023 4 5 6 7 2028 9 0 1 2 2033 4 5 6

B30 Roofing

Replace Aluminum Gutter, Downspouts, Fittings					4,930																			
Maintain Metal Roof	3,715	3,715	3,715	3,715	3,715	3,715	3,715	3,715	3,715	3,715	3,715	3,715	3,715	3,715	3,715	3,715	3,715	3,715	3,715	3,715	3,715	3,715	3,715	3,715
Replace Metal Roof					385,550																			
Minor Replacement, Metal Roof (2% of Roof)																								
Repair Metal Roof				8,711						8,711					8,711					8,711				
Maintain Aluminum Gutter, Downspouts, Fittings	249	249	249	249	249	249	249	249	249	249	249	249	249	249	249	249	249	249	249	249	249	249	249	249
Refinish Metal Canopy				3,031											3,031									
Repair Metal Canopy																								
Replace Metal Canopy					63,694																			

C10 Interior Construction

<u> </u>																								
Replace Wood, Hollow Core, Painted, Interior Door													9,949											
Finish Replaced Steel, 10'x8', Painted, Overhead Coiling Door,													296											
Replace Steel, 10'x8', Painted, Overhead Coiling Door, Motoriz												8	,333											
Refinish Steel, 10'x8', Painted, Overhead Coiling Door, Motoriz								296														296		
Repair Steel, 10'x8', Painted, Overhead Coiling Door, Motorize								1,286														1,286		
Finish Replaced Wood, Hollow Core, Painted, Interior Door													496											
Replace Wood, Hollow Core, Painted, Interior Door Locks				5,924																			5,924	
Maintain Wood, Hollow Core, Painted, Interior Door Locks				401					401									401					401	
Refinish Wood, Hollow Core, Painted, Interior Door		496				496				496							496				496			
Replace Steel, Painted, Interior Double Door w/ Safety Glass																								
Replace Steel, Painted, Interior Double Door w/ Safety Glass L				312									312										312	
Maintain Steel, Painted, Interior Double Door w/ Safety Glass L				34					34				34					34					34	
Refinish Steel, Painted, Interior Double Door w/ Safety Glass		97				97				97			97				97				97			
Replace Toilet Partitions, Painted Metal, Overhead Braced													3,205											
Refinish Toilet Partitions, Painted Metal, Overhead Braced		104				104				104							104				104			
Replace Plexiglass Fixed Window, UV Filtering, 24 Sf																								
Repair Plexiglass Fixed Window, UV Filtering, 24 Sf													89											
Finish Replaced Steel, Painted, Interior Double Door w/ Safety																								
Maintain Steel, 10'x8', Painted, Overhead Coiling Door, Motoriz	193	193	193	193	193	193	193	193	193	193	193	193	193	193	193	193	193	193	193	193	193	193	193	19

C20 Stairs

Refinish Metal, Painted, Interior Stairs	196	196	196	196	196	196
Finish Replaced Metal, Painted, Interior Railing	7)				
Refinish Metal, Painted, Exterior Stairs				30		30
Repair Metal, Painted, Exterior Stairs					73	
Finish Repaired Metal, Painted, Exterior Stairs					1	

Building: Distribution Center Facility: Langley Research Center

Building Num: 1206 City: Hampton, VA

Forecast Year: 2038 9 0 1 2 2043 4 5 6 7 2048 9 0 1 2 2053 4 5 6 7 2058 9 0 1 2

B30 Roofing

Replace Aluminum Gutter, Downspouts, Fittings	4,930																				4,930				
Maintain Metal Roof	3,715	3,715	3,715	3,715	3,715	3,715	3,715	3,715	3,715	3,715	3,715	3,715	3,715	3,715	3,715	3,715	3,715	3,715	3,715	3,715		3,715	3,715	3,715	3,715
Replace Metal Roof																				38	35,550				
Minor Replacement, Metal Roof (2% of Roof)	7,710																								
Repair Metal Roof	8,711					8,711					8,711					8,711									
Maintain Aluminum Gutter, Downspouts, Fittings		249	249	249	249	249	249	249	249	249	249	249	249	249	249	249	249	249	249	249		249	249	249	249
Refinish Metal Canopy	3,031																				3,031				
Repair Metal Canopy	3,047																								
Replace Metal Canopy											63,694														

C10 Interior Construction

Replace Wood, Hollow Core, Painted, Interior Door																			9,949					
Finish Replaced Steel, 10'x8', Painted, Overhead Coiling Door																						296		
Replace Steel, 10'x8', Painted, Overhead Coiling Door, Motori																						8,333		
Refinish Steel, 10'x8', Painted, Overhead Coiling Door, Motori								296										296						
Repair Steel, 10'x8', Painted, Overhead Coiling Door, Motoriz								1,286										1,286						
Finish Replaced Wood, Hollow Core, Painted, Interior Door																			496					
Replace Wood, Hollow Core, Painted, Interior Door Locks									5,924															
Maintain Wood, Hollow Core, Painted, Interior Door Locks				401					401					401									401	
Refinish Wood, Hollow Core, Painted, Interior Door	496				496				496				496				496					496		
Replace Steel, Painted, Interior Double Door w/ Safety Glass				2,607																				
Replace Steel, Painted, Interior Double Door w/ Safety Glass														312									312	
Maintain Steel, Painted, Interior Double Door w/ Safety Glass									34					34					34				34	
Refinish Steel, Painted, Interior Double Door w/ Safety Glass	97							97				97				97				97			97	
Replace Toilet Partitions, Painted Metal, Overhead Braced									3,205															
Refinish Toilet Partitions, Painted Metal, Overhead Braced	104				104								104				104				104			104
Replace Plexiglass Fixed Window, UV Filtering, 24 Sf				5,315																				
Repair Plexiglass Fixed Window, UV Filtering, 24 Sf																							89	
Finish Replaced Steel, Painted, Interior Double Door w/ Safet				97																				
Maintain Steel, 10'x8', Painted, Overhead Coiling Door, Motori	193	193	193	193	193	193	193	193	193	193	193	193	193	193	193	193	193	193	193	193	193	193	193	193

C20 Stairs

Refinish Metal, Painted, Interior Stairs	196	196	196	196	196	196
Finish Replaced Metal, Painted, Interior Railing						
Refinish Metal, Painted, Exterior Stairs		30		:	30	
Repair Metal, Painted, Exterior Stairs		73				73
Finish Repaired Metal, Painted, Exterior Stairs		1				1

Building: Distribution Center Facility: Langley Research Center

Forecast Year:	2013	4	5 6	7 20	18 9	0	1	2 2023	4	5	6	7 202	28 9	0	1	2	2033	4	5	6	7
Replace Metal, Painted, Exterior Stairs			1,000																		
Finish Replaced Metal, Painted, Exterior Stairs			30																		
Repair Metal, Painted, Interior Stairs											463										
Replace Metal, Painted, Interior Railing			1,869																		
Finish Replaced Metal, Painted, Interior Stairs																					
Replace Metal, Painted, Interior Stairs																					
Repair Concrete, Interior Stairs											93										
Finish Repaired Metal, Painted, Interior Stairs											6										
Finish Repaired Metal, Painted, Interior Railing															2						
Replace Concrete, Exterior Stairs			4,233																		
Replace Concrete, Interior Stairs																					
Refinish Metal, Painted, Exterior Railing			111																	111	
Finish Repaired Metal, Painted, Exterior Railing																					
Replace Metal, Painted, Exterior Railing										4	4,868										
Repair Metal, Painted, Interior Railing															97						
Finish Replaced Metal, Painted, Exterior Railing											106										
Refinish Metal, Painted, Interior Railing		70				70			70			-	70			70				70	
Repair Metal, Painted, Exterior Railing																					
Repair Concrete, Exterior Stairs															319						

C30 Interior Finishes												
Replace Carpet, Nylon 20 oz., High Traffic	41,824				41,824				41,824			
Repair Acoustic Tile Ceiling (2% of Ceiling)				224				22	24			
Replace Metal Floor Grating							65,438					
Repair Metal Floor Grating (2% of Grating)		2,634										2,634
Replace Concrete Flooring												
Repair Concrete Flooring (2% of Floors)							3,611					
Repair Ceramic Tile Flooring (2% of Floors)									195	5		
Replace Metal Ceiling												
Repair Carpet, Nylon 20 oz., High Traffic (2% of Carpet)		835	835	835		835	835	835		835	835	835
Replace Ceramic Tile Flooring		6,445										
Refinish Gypsum Board, Finished Ceiling		2,374					2,374					2,374
Finish Repaired Gypsum Board, Finished Ceiling		47										
Replace Gypsum Board, Finished Ceiling												
Finish Replaced Steel, Painted, Interior Wall Finish												
Repair Metal Ceiling (2% of Ceiling)	11,183				11,183				11,183			
Replace Acoustic Tile Ceiling												11,274
Refinish Plywood Ceiling, Painted		194					194					194

Building: Distribution Center Facility: Langley Research Center

Forecast Year:	2038	9	0	1	2 2043	4	5	6	7 2048	9	0	1	2 2053	4	5	6	7 2	2058	9	0	1	2
Replace Metal, Painted, Exterior Stairs																						
Finish Replaced Metal, Painted, Exterior Stairs																						
Repair Metal, Painted, Interior Stairs																463						
Replace Metal, Painted, Interior Railing																						
Finish Replaced Metal, Painted, Interior Stairs			1	196																		
Replace Metal, Painted, Interior Stairs			6,3	385																		
Repair Concrete, Interior Stairs																					93	
Finish Repaired Metal, Painted, Interior Stairs																6						
Finish Repaired Metal, Painted, Interior Railing								2													2	
Replace Concrete, Exterior Stairs																						
Replace Concrete, Interior Stairs			1,2	237																		
Refinish Metal, Painted, Exterior Railing								111														
Finish Repaired Metal, Painted, Exterior Railing				3																		
Replace Metal, Painted, Exterior Railing																4,868						
Repair Metal, Painted, Interior Railing								97													97	
Finish Replaced Metal, Painted, Exterior Railing																106						
Refinish Metal, Painted, Interior Railing			70			70			70				70			70				70		
Repair Metal, Painted, Exterior Railing			1	147																		
Repair Concrete, Exterior Stairs								319													319	

Replace Carpet, Nylon 20 oz., High Traffic 41,824 4	C30 Interior Finishes													
Replace Metal Floor Grating (2% of Grating) Replace Concrete Flooring (2% of Floors) Replace Concrete Flooring (2% of Floors) Replace Metal Floor Grating (2% of Floors) Replace Metal Flooring (2% of Floors) Replace Metal Flooring (2% of Floors) Replace Metal Flooring (2% of Floors) Replace Metal Ceiling Replace Metal Ceiling Replace Metal Ceiling Replace Metal Ceiling Replace Gramic Tile Flooring (2% of Grating) Replace Metal Ceiling Refinish Gypsum Board, Finished Ceiling Refinish Gypsum Board, Finished Ceiling Replace Gypsum Board, Finished Ceiling	Replace Carpet, Nylon 20 oz., High Traffic	41,824				41,824				41,824				41,8
Repair Metal Floor Grating (2% of Grating) 180.552 Repair Concrete Flooring (2% of Floors) 195 Repair Ceramic Tile Flooring (2% of Floors) 195 Repair Ceramic Tile Flooring (2% of Floors) 195 Repair Carpet, Nylon 20 oz., High Traffic (2% of Carpet) 835	Repair Acoustic Tile Ceiling (2% of Ceiling)				224					224				
Replace Concrete Flooring (2% of Floors) Repair Concrete Flooring (2% of Floors) Repair Ceramic Tile Flooring (2% of Floors) Replace Metal Ceiling Replace Metal Ceiling Replace Metal Ceiling Replace Ceramic Tile Flooring Replace Gypsum Board, Finished Ceiling Replace Gypsum Geiling 11,183 11,183 11,183 11,183 11,183	Replace Metal Floor Grating										65,438			
Repair Concrete Flooring (2% of Floors) Repair Ceramic Tile Flooring (2% of Floors) Repair Ceramic Tile Flooring (2% of Floors) Replace Metal Ceiling Replace Metal Ceiling Repair Carpet, Nylon 20 oz., High Traffic (2% of Carpet) Replace Ceramic Tile Flooring Replace Ceramic Tile Flooring Replace Ceramic Tile Flooring Replace Geramic Tile Flooring Replace Geramic Tile Flooring Replace Geramic Tile Flooring Replace Gypsum Board, Finished Ceiling Replace Gypsum Gyport Wall Finish Replace Gypsum Gyport Wall Finish Replace Gypsum Gyport Wall Finish Replace Gypsum Gyport Ceiling 11,183 11,183 11,183 11,183	Repair Metal Floor Grating (2% of Grating)					2,634								
Repair Ceramic Tile Flooring (2% of Floors) 195 Replace Metal Ceiling 563,354 35 835	Replace Concrete Flooring		180,552											
Replace Metal Ceiling	Repair Concrete Flooring (2% of Floors)										3,611			
Repair Carpet, Nylon 20 oz., High Traffic (2% of Carpet) Replace Ceramic Tile Flooring Refinish Gypsum Board, Finished Ceiling Replace Steel, Painted, Interior Wall Finish Replaced Steel, Painted, Interior Wall Finish Replaced Steel, Painted, Interior Wall Finish Replace Acoustic Tile Ceiling	Repair Ceramic Tile Flooring (2% of Floors)					195								195
Replace Ceramic Tile Flooring Refinish Gypsum Board, Finished Ceiling Finish Repaired Gypsum Board, Finished Ceiling Replace Gypsum Board, Finished Ceiling 1,999 Repair Metal Ceiling (2% of Ceiling) 11,183 11,183 11,183	Replace Metal Ceiling		563,354											
Refinish Gypsum Board, Finished Ceiling Finish Repaired Gypsum Board, Finished Ceiling Replace Gypsum Board, Finished Ceiling Replace Gypsum Board, Finished Ceiling Finish Replaced Steel, Painted, Interior Wall Finish Replaced Steel, Painted, Interior Wall Finish Replaced Ceiling (2% of Ceiling) 11,183 11,183 11,183 11,183	Repair Carpet, Nylon 20 oz., High Traffic (2% of Carpet)		835	835	835		835	835	835		835	835	835	
Finish Repaired Gypsum Board, Finished Ceiling Replace Gypsum Board, Finished Ceiling 8,003 Finish Replaced Steel, Painted, Interior Wall Finish Replaced Steel, Painted, Interior Wall Finish Repair Metal Ceiling (2% of Ceiling) 11,183 11,183 11,183 11,183	Replace Ceramic Tile Flooring													
Replace Gypsum Board, Finished Ceiling 8,003 Finish Replaced Steel, Painted, Interior Wall Finish Repair Metal Ceiling (2% of Ceiling) 11,183 11,183 11,183 Replace Acoustic Tile Ceiling	Refinish Gypsum Board, Finished Ceiling							2,37	4					2,374
Finish Replaced Steel, Painted, Interior Wall Finish Repair Metal Ceiling (2% of Ceiling) 11,183 11,183 11,183 11,183	Finish Repaired Gypsum Board, Finished Ceiling													
Repair Metal Ceiling (2% of Ceiling) 11,183 11,183 11,183 11,183	Replace Gypsum Board, Finished Ceiling		8,003											
Replace Acoustic Tile Ceiling	Finish Replaced Steel, Painted, Interior Wall Finish		1,999											
	Repair Metal Ceiling (2% of Ceiling)	11,183					11,183				11,18	3		
Refinish Plywood Ceiling, Painted	Replace Acoustic Tile Ceiling													
	Refinish Plywood Ceiling, Painted										194			

Building: Distribution Center Facility: Langley Research Center City: Hampton, VA **Building Num: 1206** Forecast Year: 2013 7 2018 2 2023 7 2028 2 2033 Repair Plywood Ceiling, Painted (2% of Ceiling) Replace Plywood Ceiling Finish Replaced Gypsum Board, Finished Ceiling Replace Ceramic Tile, 4"x4", Interior Wall Finish Repair Gypsum Board, Finished Ceiling (2% of Ceiling) Replace Steel, Painted, Interior Wall Finish Repair Ceramic Tile, 4"x4", Interior Wall Finish (2% of Walls) Clean & Seal Concrete Block, Interior Wall Finish Repair Concrete Block, Interior Wall Finish (2% of Walls) Repoint (50% surface) Concrete Block, Interior Wall Finish Replace Concrete Block, Interior Wall Finish Refinish Concrete Block, Painted, Interior Wall Finish Repair Concrete Block, Painted, Interior Wall Finish (2% of Wal 3,704 Repoint (50% surface) Concrete Block, Painted, Interior Wall Fi 41,002 Refinish Steel, Painted, Interior Wall Finish Replace Concrete Block, Painted, Interior Wall Finish Finish Replaced Concrete Block, Painted, Interior Wall Finish Refinish Gypsum Board, Interior Wall Finish Repair Gypsum Board, Interior Wall Finish (2% of Walls) Finish Repaired Gypsum Board, Interior Wall Finish 345 Replace Gypsum Board, Interior Wall Finish Finish Replaced Gypsum Board, Interior Wall Finish Finish Repaired Steel, Painted, Interior Wall Finish Repair Steel, Painted, Interior Wall Finish (2% of Walls) Finish Repaired Concrete Block, Painted, Interior Wall Finish D10 Conveying Replace Dock Ramp Leveler 38,427 1,615 1,615 Maintain Dock Ramp Leveler 1,615 1,615 1,615 1,615 1,615 1,615 1,615 1,615 1,615 1,615 1,615 1,615 1,615 1,615 1,615 1,615 **D20 Plumbing** Replace Pipe & Fittings, 3/4" Copper, Cold Water (20% of Pipe 2.914 Replace Urinal, Vitreous China Replace Valve, Hose Bib Resolder Joint, Pipe & Fittings, 3/4" Copper, Cold Water Re-tape Pipe Insulation, Fiberglass, Hot Water Replace 10' Section, Pipe & Fittings, 3/4" Copper, Cold Water

Replace Tankless Water Closet

Building: Distribution Center Facility: Langley Research Center
Building Num: 1206 City: Hampton, VA

Forecast Year:	2038	9	0	1	2	2043	4	5	6	7	2048	9	0	1	2	2053	4	5	6	7	2058	9	0	1	2
Repair Plywood Ceiling, Painted (2% of Ceiling)																			23						
Replace Plywood Ceiling									1,168																
Finish Replaced Gypsum Board, Finished Ceiling				2,374																					
Replace Ceramic Tile, 4"x4", Interior Wall Finish				11,299																					
Repair Gypsum Board, Finished Ceiling (2% of Ceiling)																									
Replace Steel, Painted, Interior Wall Finish				23,872																					
Repair Ceramic Tile, 4"x4", Interior Wall Finish (2% of Walls)														225										225	
Clean & Seal Concrete Block, Interior Wall Finish	4,818							4,818				4,818				4,818				4,818				4,818	
Repair Concrete Block, Interior Wall Finish (2% of Walls)																									
Repoint (50% surface) Concrete Block, Interior Wall Finish																									
Replace Concrete Block, Interior Wall Finish				42,330																					
Refinish Concrete Block, Painted, Interior Wall Finish														16,845										16,845	
Repair Concrete Block, Painted, Interior Wall Finish (2% of W																									
Repoint (50% surface) Concrete Block, Painted, Interior Wall																									
Refinish Steel, Painted, Interior Wall Finish														997										997	
Replace Concrete Block, Painted, Interior Wall Finish				185,118																					
Finish Replaced Concrete Block, Painted, Interior Wall Finish				16,845																					
Refinish Gypsum Board, Interior Wall Finish														17,238										17,238	
Repair Gypsum Board, Interior Wall Finish (2% of Walls)																								753	
Finish Repaired Gypsum Board, Interior Wall Finish																								345	
Replace Gypsum Board, Interior Wall Finish				37,679																					
Finish Replaced Gypsum Board, Interior Wall Finish				17,238																					
Finish Repaired Steel, Painted, Interior Wall Finish																									
Repair Steel, Painted, Interior Wall Finish (2% of Walls)																									
Finish Repaired Concrete Block, Painted, Interior Wall Finish																									
D10 Conveying																									
Replace Dock Ramp Leveler				38,427																					
Maintain Dock Ramp Leveler	1.615	1.615	1.615		1.615	1.615																			

D20 Plumbing

Replace Pipe & Fittings, 3/4" Copper, Cold Water (20% of Pip	1,313				
Replace Urinal, Vitreous China					
Replace Valve, Hose Bib		52		52	
Resolder Joint, Pipe & Fittings, 3/4" Copper, Cold Water			120		120
Re-tape Pipe Insulation, Fiberglass, Hot Water		91	91	91	91
Replace 10' Section, Pipe & Fittings, 3/4" Copper, Cold Water					66
Replace Tankless Water Closet					

Building: Distribution Center Facility: Langley Research Center

Ballating Halli. 1200				Oit	y. 110	iiipto	, v,	`																
Forecast Year:	2013	4	5	7	2018	9	0	1	2	2023	4	5	6	7	2028	9	0	1	2	2033	4	5	6	7
Replace Flush Valve, Urinal, Vitreous China			516						516							516								
Resolder Joint, Pipe & Fittings, 3/4" Copper, Hot Water													120										120	
Replace 10' Section, Pipe & Fittings, 3/4" Copper, Hot Water																							66	
Replace Pipe & Fittings, 3/4" Copper, Hot Water (20% of Pipe)			1,313																					
Check Operation, Water Heater, Electric, 5 Gal.		19		19			19			19						19			19			19		
Replace Pipe Insulation, Fiberglass, Cold Water (20% of Insula			274																					
Replace Pipe Insulation, Fiberglass, Hot Water (20% of Insulati			274																					
Replace Flush Valve, Tankless Water Closet			115										115											
Replace Emergency Eye Wash Station			772																					
Re-tape Pipe Insulation, Fiberglass, Cold Water								91					91					91					91	
Replace Faucet Washer & Clean Trap, Sink, Iron, Enamel		19	19		19		19		19		19		19		19		19		19		19			
Check Operation, Water Heater, Electric, 15 Gal.		19		19			19			19						19			19			19		
Replace Coolant & Adjust Water Cooler, Electric	97			97		97		97		97				97		97		97		97				97
Replace Water Cooler, Electric			4,505								4,	,505									4	4,505		
Inspect & Clean Spray Heads, Emergency Eye Wash		19				19			19			19			19			19			19			19
Repack Valve Glands, Emergency Eye Wash													23										23	
Replace Faucet Washer & Clean Trap, Lavatory, Vitreous Chin		98	98		98		98		98		98		98		98		98		98		98			
Replace Washer & Spud Connection, Lavatory, Vitreous China			181						181							181								
Replace Lavatory, Vitreous China																						2	2,165	
Replace Sink, Stainless Steel																								
Repair Strainer, Sink, Iron, Enamel		58							58								58							
Replace Valve Set, Service Sink, Iron, Enamel			123										123											
Replace Service Sink, Iron, Enamel																							962	
Replace Faucet Washer & Clean Trap, Sink, Stainless Steel		19	19		19		19		19		19		19		19		19		19		19		19	
Repair Strainer, Sink, Stainless Steel		57							57								57							
Replace Valve Set, Sink, Stainless Steel			123										123										123	
Replace Valve Set, Lavatory, Vitreous China			616										616											
Replace 10' Section, Pipe & Fittings, 2" DWV PVC																	12							
Replace Water Heater, Electric, 5 Gal.													714											
Drain & Flush Water Heater, Electric, 5 Gal.			78						78											78				
Replace Pipe & Fittings, 2" DWV PVC (20% of Pipe)							253																	
Replace Pipe & Fittings, 4" Cast Iron (20% of Pipe)																								
Install New Gasket & Bolts, Pipe & Fittings, 4" Cast Iron			16																					
Replace 10' Section, Pipe & Fittings, 4" Cast Iron		57											57											
Replace Pipe & Fittings, 3" Cast Iron (20% of Pipe)																								
Install New Gasket & Bolts, Pipe & Fittings, 3" Cast Iron			35																					
Replace 10' Section, Pipe & Fittings, 3" Cast Iron		100											100											

Building: Distribution Center Facility: Langley Research Center

Danaing Itami. 1200					Oity.		Πρισι	ı, v/\																	
Forecast Year:	2038	9	0	1	2 2	2043	4	5	6	7	2048	9	0	1	2	2053	4	5	6	7	2058	9	0	1	2
Replace Flush Valve, Urinal, Vitreous China						516							516							516					
Resolder Joint, Pipe & Fittings, 3/4" Copper, Hot Water														120										120	
Replace 10' Section, Pipe & Fittings, 3/4" Copper, Hot Water																								66	
Replace Pipe & Fittings, 3/4" Copper, Hot Water (20% of Pipe				1,313																					
Check Operation, Water Heater, Electric, 5 Gal.	19						19			19			19			19						19			19
Replace Pipe Insulation, Fiberglass, Cold Water (20% of Insul				274																					
Replace Pipe Insulation, Fiberglass, Hot Water (20% of Insula				274																					
Replace Flush Valve, Tankless Water Closet									115										115						
Replace Emergency Eye Wash Station				772																					
Re-tape Pipe Insulation, Fiberglass, Cold Water									91					91					91					91	
Replace Faucet Washer & Clean Trap, Sink, Iron, Enamel	19		19		19		19		19		19		19		19		19		19		19		19		19
Check Operation, Water Heater, Electric, 15 Gal.	19						19			19			19			19						19			19
Replace Coolant & Adjust Water Cooler, Electric		97		97		97				97		97		97		97				97		97		97	
Replace Water Cooler, Electric							4	1,505									4	4,505							
Inspect & Clean Spray Heads, Emergency Eye Wash			19				19			19			19			19			19			19			19
Repack Valve Glands, Emergency Eye Wash														23										23	
Replace Faucet Washer & Clean Trap, Lavatory, Vitreous Chi	98		98		98		98		98		98		98		98		98		98		98		98		98
Replace Washer & Spud Connection, Lavatory, Vitreous Chin						181							181							181					
Replace Lavatory, Vitreous China																									
Replace Sink, Stainless Steel								9	939																
Repair Strainer, Sink, Iron, Enamel							58								58								58		
Replace Valve Set, Service Sink, Iron, Enamel									123										123						
Replace Service Sink, Iron, Enamel																									
Replace Faucet Washer & Clean Trap, Sink, Stainless Steel	19		19		19		19				19		19		19		19		19		19		19		19
Repair Strainer, Sink, Stainless Steel	57																57								57
Replace Valve Set, Sink, Stainless Steel																			123						
Replace Valve Set, Lavatory, Vitreous China								(616										616						
Replace 10' Section, Pipe & Fittings, 2" DWV PVC			12																				12		
Replace Water Heater, Electric, 5 Gal.				714															714						
Drain & Flush Water Heater, Electric, 5 Gal.			78								78							78							
Replace Pipe & Fittings, 2" DWV PVC (20% of Pipe)													253												
Replace Pipe & Fittings, 4" Cast Iron (20% of Pipe)				1,124																					
Install New Gasket & Bolts, Pipe & Fittings, 4" Cast Iron																									
Replace 10' Section, Pipe & Fittings, 4" Cast Iron	57															57									
Replace Pipe & Fittings, 3" Cast Iron (20% of Pipe)				2,005																					
Install New Gasket & Bolts, Pipe & Fittings, 3" Cast Iron																									
Replace 10' Section, Pipe & Fittings, 3" Cast Iron	100															100									

Building: Distribution Center Facility: Langley Research Center

Building Num: 1206						Cit	y: Ha	ampt	on, V	Ά																
Fo	recast Year:	2013	4	5	6	7	2018	9	0	1	2	2023	4	5	6	7	2028	9	0	1	2	2033	4	5	6	7
Replace Water Heater, Electric, 15 Gal.															1,040											
Replace Floor Drain																										
Drain & Flush Water Heater, Electric, 15 Gal.				156							156											156				
Maintain Backflow Preventer, 3/4"		45	45	45	45	45	45	45		45	45	45	45	45	45	45	45	45		45	45	45	45	45	45	45
Replace Backflow Preventer, 3/4"									827										827							
Maintain Backflow Preventer, 2"		208	208	208	208	208	208	208		208	208	208	208	208	208	208	208	208		208	208	208	208	208	208	208
Replace Backflow Preventer, 2"									3,556										3,556							
Maintain Floor Drain		22	22	22	22	22	22	22	22	22	22	22	22	22	22	22	22	22	22	22	22	22	22	22	22	22
D30 HVAC																										
Maintain Exhaust Fan, Propeller, 1,000 Cfm		367	367	367	367	367	367	367	367	367	367		367	367	367	367	367	367	367	367	367	367	367	367	367	367
Repair Condenser, Air-Cooled, 10 Ton											1,296															
Maintain Dehumidifier & Control, 120-150 lbs, 4,50	00 Cfm	618	618	618	618	618	618		618	618	618	618	618	618	618	618	618	618	618	618	618	618	618	618	618	618
Maintain Residential Type Ceiling Fan		256	256	256	256	256	256	256		256	256	256	256	256	256	256	256	256	256	256	256	256	256	256	256	256
Replace Existing Ductwork (20% of Ductwork)																										
Replace Duct Insulation (20% of Insulation)																										
Replace Dehumidifier & Control, 120-150 lbs, 4,50	00 Cfm							78,242																		
Replace Residential Type Ceiling Fan									762																	
Replace Air Handler, Single Zone, 8,000 Cfm										19,236															19,236	
Repair Air Handler, Single Zone, 8,000 Cfm					1,550															1,550						
Replace Condenser, Air-Cooled, 10 Ton																								5,606		
Replace Expansion Tank, 30 Gal.					1,703																					
Maintain Expansion Tank, 30 Gal.		19	19	19		19	19	19	19	19	19	19	19	19	19	19	19	19	19	19	19	19	19	19	19	19
Repair Exhaust Fan, Propeller, 1,000 Cfm										759													759			
Maintain Suspended Heater, Hot Water, 1,200 Cfr	m, 55 Mbh	3,991	3,991	3,991	3,991	3,991	3,991		3,991	3,991	3,991	3,991	3,991	3,991	3,991	3,991	3,991	3,991	3,991	3,991	3,991	3,991	3,991	3,991	3,991	3,991
Maintain Air Handler, Single Zone, 8,000 Cfm		473	473	473	473	473	473	473	473		473	473	473	473	473	473	473	473	473	473	473	473	473	473		473
Maintain Heat Pump, 3 Ton		1,167	1,167	1,167	1,167	1,167	1,167	1,167	1,167	1,167		1,167	1,167	1,167	1,167	1,167	1,167	1,167	1,167	1,167	1,167	1,167	1,167	1,167	1,167	1,167
Replace Thermostat			3,184										3,184										3,184			
Maintain Thermostat		174		174	174	174	174	174	174	174	174	174		174	174	174	174	174	174	174	174	174		174	174	174
Repair Suspended Heater, Hot Water, 2,000 Cfm,	, 180 Mbh																							3,394		
Replace Suspended Heater, Hot Water, 1,200 Cfr	m, 55 Mbh							63,660																		
Repair Suspended Heater, Hot Water, 1,200 Cfm,	, 55 Mbh																							8,051		
Maintain Suspended Heater, Hot Water, 2,000 Cfr	m, 180 Mbh	1,680	1,680	1,680	1,680	1,680	1,680		1,680	1,680	1,680	1,680	1,680	1,680	1,680	1,680	1,680	1,680	1,680	1,680	1,680	1,680	1,680	1,680	1,680	1,680
Repair Heat Pump, 3 Ton																										
Maintain Condenser, Air-Cooled, 10 Ton		105	105	105	105	105	105	105	105	105	105	105	105	105	105	105	105	105	105	105	105	105	105		105	105
Replace Exhaust Fan, Propeller, 1,000 Cfm												3,950														
Replace Air Conditioner, Window, 1 Ton																					15,737					
Repair Air Conditioner, Window, 1 Ton					1,118																					

Building: Distribution Center Facility: Langley Research Center

Building Num: 1206					Cit	y: Ha	ampt	on, V	Ά																
Forecast Year:	2038	9	0	1	2	2043	4	5	6	7	2048	9	0	1	2	2053	4	5	6	7	2058	9	0	1	2
Replace Water Heater, Electric, 15 Gal.				1,040															1,040						
Replace Floor Drain									283																
Drain & Flush Water Heater, Electric, 15 Gal.			156								156							156							
Maintain Backflow Preventer, 3/4"	45	45		45	45	45	45	45	45	45	45	45		45	45	45	45	45	45	45	45	45		45	45
Replace Backflow Preventer, 3/4"			827										827										827		
Maintain Backflow Preventer, 2"	208	208		208	208	208	208	208	208	208	208	208		208	208	208	208	208	208	208	208	208		208	208
Replace Backflow Preventer, 2"			3,556										3,556										3,556		
Maintain Floor Drain	22	22	22	22	22	22	22	22		22	22	22	22	22	22	22	22	22	22	22	22	22	22	22	22
D30 HVAC																									
Maintain Exhaust Fan, Propeller, 1,000 Cfm	367	367	367	367		367	367	367	367	367	367	367	367	367	367	367	367	367	367	367	367	367	367		367
Repair Condenser, Air-Cooled, 10 Ton														1,296											
Maintain Dehumidifier & Control, 120-150 lbs, 4,500 Cfm		618	618	618	618	618	618	618	618	618	618	618	618	618	618	618	618	618	618		618	618	618	618	618
Maintain Residential Type Ceiling Fan	256	256		256	256	256	256	256	256	256	256	256	256	256	256	256	256	256	256	256	256	256		256	256
Replace Existing Ductwork (20% of Ductwork)	554																								
Replace Duct Insulation (20% of Insulation)	122																								
Replace Dehumidifier & Control, 120-150 lbs, 4,500 Cfm	78,242																			78,242					
Replace Residential Type Ceiling Fan			762																				762		
Replace Air Handler, Single Zone, 8,000 Cfm														19,236											
Repair Air Handler, Single Zone, 8,000 Cfm									1,550															1,550	
Replace Condenser, Air-Cooled, 10 Ton																									
Replace Expansion Tank, 30 Gal.																									
Maintain Expansion Tank, 30 Gal.	19	19	19	19	19	19	19	19	19	19	19	19	19	19	19	19	19	19	19	19	19	19	19	19	19
Repair Exhaust Fan, Propeller, 1,000 Cfm																759									
Maintain Suspended Heater, Hot Water, 1,200 Cfm, 55 Mbh	3,991	3,991	3,991	3,991	3,991	3,991	3,991	3,991	3,991	3,991		3,991	3,991	3,991	3,991	3,991	3,991	3,991	3,991	3,991	3,991	3,991	3,991	3,991	3,991
Maintain Air Handler, Single Zone, 8,000 Cfm	473	473	473	473	473	473	473	473	473	473	473	473	473		473	473	473	473	473	473	473	473	473	473	473
Maintain Heat Pump, 3 Ton	1,167	1,167	1,167	1,167	1,167	1,167	1,167	1,167	1,167	1,167	1,167	1,167	1,167	1,167	1,167	1,167		1,167	1,167	1,167	1,167	1,167	1,167	1,167	1,167
Replace Thermostat							3,184										3,184								
Maintain Thermostat	174	174	174	174	174	174		174	174	174	174	174	174	174	174	174		174	174	174	174	174	174	174	174
Repair Suspended Heater, Hot Water, 2,000 Cfm, 180 Mbh																									
Replace Suspended Heater, Hot Water, 1,200 Cfm, 55 Mbh											63,660														
Repair Suspended Heater, Hot Water, 1,200 Cfm, 55 Mbh																									
Maintain Suspended Heater, Hot Water, 2,000 Cfm, 180 Mbh	1,680	1,680	1,680	1,680	1,680	1,680	1,680	1,680	1,680	1,680		1,680	1,680	1,680	1,680	1,680	1,680	1,680	1,680	1,680	1,680	1,680	1,680	1,680	1,680
Repair Heat Pump, 3 Ton	2,925																								
Maintain Condenser, Air-Cooled, 10 Ton	105	105	105	105	105	105	105	105	105	105	105	105	105	105	105	105	105	105	105	105	105	105	105	105	105
Replace Exhaust Fan, Propeller, 1,000 Cfm					3,950																			3,950	
Replace Air Conditioner, Window, 1 Ton																									
Repair Air Conditioner, Window, 1 Ton											1,118														

Building: Distribution Center Facility: Langley Research Center

_ ug						,		· · · , ·																	
Forecast Year:	2013	4	5	6	7	2018	9	0	1	2	2023	4	5	6	7	2028	9	0	1	2	2033	4	5	6	7
Maintain Air Conditioner, Window, 1 Ton	1,174	1,174	1,174	1,174	1,174	1,174	1,174	1,174	1,174	1,174	1,174	1,174	1,174	1,174	1,174	1,174	1,174	1,174	1,174		1,174	1,174	1,174	1,174	1,174
Replace Air Conditioner, DX Packaged, Air Cooled, 1 Ton														22,479											
Repair Air Conditioner, DX Packaged, Air Cooled, 1 Ton																									
Maintain Air Conditioner, DX Packaged, Air Cooled, 1 Ton	2,077	2,077	2,077	2,077	2,077	2,077	2,077	2,077	2,077	2,077	2,077	2,077	2,077		2,077	2,077	2,077	2,077	2,077	2,077	2,077	2,077	2,077	2,077	2,077
Replace Heat Pump, 3 Ton										11,821															
Repair Boiler, Gas, 100 Mbh		2,391							2,391														2,391		
Repair Heat Exchanger, Steam-to-Water, 15 Gpm	486							486							486										
Maintain Heat Exchanger, Steam-to-Water, 15 Gpm	70	70	70	70	70	70	70	70	70	70	70	70	70	70	70	70	70	70	70	70	70		70	70	70
Repack Gland, Gate Valve, 6"								96												96					
Install New Gasket & Bolts, Pipe & Fittings, 2" Steel				36																					
Replace 10' Section, Pipe & Fittings, 2" Steel		65												65											
Replace Condensate Removal Pump System, 1/50 HP								321														321			
Replace Heat Exchanger, Steam-to-Water, 15 Gpm																						2,817			
Replace Boiler, Gas, 100 Mbh																7,685									
Replace Gate Valve, 6"											4,309														
Clean Fire Box Boiler, Gas, 100 Mbh		65		65		65		65		65		65		65				65		65		65		65	
Inspect & Test Boiler, Gas, 100 Mbh	257	257	257	257	257	257	257	257	257	257	257	257	257	257	257		257	257	257	257	257	257	257	257	257
Replace Pressure Reducer Valve, 2"		1,562						1,562						1,562						1,562					
Maintain Pressure Reducer Valve, 2"	38		38	38	38	38	38		38	38	38	38	38		38	38	38	38	38		38	38	38	38	38
Replace Suspended Heater, Hot Water, 2,000 Cfm, 180 Mbh							28,075																		
Replace Condenser, Air-Cooled, 1 Ton											23,186														
Maintain Condensate Removal Pump System, 1/50 HP	59	59	59	59	59	59	59		59	59	59	59	59	59	59	59	59	59	59	59	59		59	59	59
Lubricate, Repack Gland, Valve, Non Drain, 10"	56	56	56	56	56	56	56	56	56	56		56	56	56	56	56	56	56	56	56	56	56	56	56	56
Repair Condenser, Air-Cooled, 1 Ton																									
Maintain Condenser, Air-Cooled, 1 Ton	840	840	840	840	840	840	840	840	840	840		840	840	840	840	840	840	840	840	840	840	840	840	840	840
Replace Ball Valve, 1"					2,032																	2,032			
Replace Pipe & Fittings, 2" Steel (20% of Pipe)																									
Replace Valve, Non-Drain, 10"											11,669														
Replace 10' Section, Pipe & Fittings, 4" Steel		39												39											
Replace Steam Trap, F&T, 2"								33,955									33,955								
Repair Steam Trap, F&T, 2"		15,473			15,473						15,473			15,473						15,473			15,473		
Maintain Steam Trap, F&T, 2"	1,167	1,167	1,167	1,167	1,167	1,167	1,167		1,167	1,167	1,167	1,167	1,167	1,167	1,167	1,167		1,167	1,167	1,167	1,167	1,167	1,167	1,167	1,167
Install New Gasket & Bolts, Pipe & Fittings, 4" Steel				16																					
Re-tape Pipe Insulation, Fiberglass, Heating Water/Steam									91					91					91					91	
Replace Pipe & Fittings, 10" Steel (20% of Pipe)																									
Install New Gasket & Bolts, Pipe & Fittings, 10" Steel				11																					
Replace 10' Section, Pipe & Fittings, 10" Steel		44												44											

Building: Distribution Center Facility: Langley Research Center

Danaing Italii. 1200					Oit	y	ampt	O11, V	, ,																
Forecast Year:	2038	9	0	1	2	2043	4	5	6	7	2048	9	0	1	2	2053	4	5	6	7	2058	9	0	1	2
Maintain Air Conditioner, Window, 1 Ton	1,174	1,174	1,174	1,174	1,174	1,174	1,174	1,174	1,174	1,174	1,174	1,174	1,174	1,174	1,174	1,174	1,174	1,174	1,174	1,174	1,174	1,174	1,174	1,174	1,174
Replace Air Conditioner, DX Packaged, Air Cooled, 1 Ton																					22,479				
Repair Air Conditioner, DX Packaged, Air Cooled, 1 Ton					8,036																				
Maintain Air Conditioner, DX Packaged, Air Cooled, 1 Ton	2,077	2,077	2,077	2,077	2,077	2,077	2,077	2,077	2,077	2,077	2,077	2,077	2,077	2,077	2,077	2,077	2,077	2,077	2,077	2,077		2,077	2,077	2,077	2,077
Replace Heat Pump, 3 Ton																	11,821								
Repair Boiler, Gas, 100 Mbh					2,391							2,391													
Repair Heat Exchanger, Steam-to-Water, 15 Gpm				486							486							486							
Maintain Heat Exchanger, Steam-to-Water, 15 Gpm	70	70	70	70	70	70	70	70	70	70	70	70	70	70	70	70	70	70	70	70	70	70	70	70	
Repack Gland, Gate Valve, 6"				96										96									96		
Install New Gasket & Bolts, Pipe & Fittings, 2" Steel																									
Replace 10' Section, Pipe & Fittings, 2" Steel	65															65									
Replace Condensate Removal Pump System, 1/50 HP											321														321
Replace Heat Exchanger, Steam-to-Water, 15 Gpm																									2,817
Replace Boiler, Gas, 100 Mbh																			7,685						
Replace Gate Valve, 6"					4,309																			4,309	
Clean Fire Box Boiler, Gas, 100 Mbh	65		65		65		65		65		65		65		65		65				65		65		65
Inspect & Test Boiler, Gas, 100 Mbh	257	257	257	257	257	257	257	257	257	257	257	257	257	257	257	257	257	257		257	257	257	257	257	257
Replace Pressure Reducer Valve, 2"	1,562						1,562						1,562						1,562						1,562
Maintain Pressure Reducer Valve, 2"		38	38	38	38	38		38	38	38	38	38		38	38	38	38	38		38	38	38	38	38	
Replace Suspended Heater, Hot Water, 2,000 Cfm, 180 Mbh											28,075														
Replace Condenser, Air-Cooled, 1 Ton															23,186										
Maintain Condensate Removal Pump System, 1/50 HP	59	59	59	59	59	59	59	59	59	59		59	59	59	59	59	59	59	59	59	59	59	59	59	
Lubricate, Repack Gland, Valve, Non Drain, 10"	56	56	56	56		56	56	56	56	56	56	56	56	56	56	56	56	56	56	56	56	56	56		56
Repair Condenser, Air-Cooled, 1 Ton		6,135																							
Maintain Condenser, Air-Cooled, 1 Ton	840	840	840	840	840	840	840	840	840	840	840	840	840	840		840	840	840	840	840	840	840	840	840	840
Replace Ball Valve, 1"														2,032											
Replace Pipe & Fittings, 2" Steel (20% of Pipe)				1,296																					
Replace Valve, Non-Drain, 10"					11,669																			11,669	
Replace 10' Section, Pipe & Fittings, 4" Steel	39															39									
Replace Steam Trap, F&T, 2"	33,955									33,955									33,955						
Repair Steam Trap, F&T, 2"				15,473			15,473						15,473			15,473						15,473			15,473
Maintain Steam Trap, F&T, 2"		1,167	1,167	1,167	1,167	1,167	1,167	1,167	1,167		1,167	1,167	1,167	1,167	1,167	1,167	1,167	1,167		1,167	1,167	1,167	1,167	1,167	1,167
Install New Gasket & Bolts, Pipe & Fittings, 4" Steel																									
Re-tape Pipe Insulation, Fiberglass, Heating Water/Steam									91					91					91					91	
Replace Pipe & Fittings, 10" Steel (20% of Pipe)				880																					
Install New Gasket & Bolts, Pipe & Fittings, 10" Steel																									
Replace 10' Section, Pipe & Fittings, 10" Steel	44															44									

Building: Distribution Center				Fa	cility	/ : La	ngley	/ Res	earc	h Ce	nter														
Building Num: 1206					City	/ : Ha	ampto	on, V	Д																
Forecast Year:	2013	4	5	6	7	2018	9	0	1	2	2023	4	5	6	7	2028	9	0	1	2	2033	4	5	6	7
Replace Pipe & Fittings, 4" Steel (20% of Pipe)																									
Replace Pipe Insulation, Fiberglass, Heating Water/Steam (20				382																					
Lubricate, Repack Gland, Ball Valve, 1"	166	166	166	166		166	166	166	166	166	166	166	166	166	166	166	166	166	166	166	166		166	166	166
D40 Fire Protection																									
Replace 10' Section, Pipe & Fittings, 1" Steel		60												60											
Install New Gasket & Bolts, Pipe & Fittings, 1" Steel			46																						
Replace 10' Section, Pipe & Fittings, 2" Steel		18												18											
Install New Gasket & Bolts, Pipe & Fittings, 2" Steel			10																						
Replace 10' Section, Pipe & Fittings, 4" Steel		19												19											
Install New Gasket & Bolts, Pipe & Fittings, 4" Steel			8																						
Replace Fire Extinguisher										2,383												2,383			
Repair Fire Alarm Control Panel								119					119										119		
Test Gages & Valves, Fire Sprinkler System	697	697	697	697	697	697	697	697	697	697	697	697	697	697	697	697	697	697	697	697	697	697	697	697	697
Inspect & Test Fire Extinguisher			256					256							256					256					
Replace Fire Department Connection, Siamese, 3"																									
Replace Fire Sprinkler Head																									
Test Fire Sprinkler Head								4,589										4,589							
Replace Fire Alarm Control Panel			3,071															3,071							
Inspect Fire Sprinkler Head	92	92	92	92	92	92	92	92	92	92	92	92	92	92	92	92	92	92	92	92	92	92	92	92	92
Inspect & Test Fire Alarm Control Panel	129	129		129	129	129	129	129	129	129	129	129	129	129	129	129	129		129	129	129	129	129	129	129
Inspect & Maintain Fire Department Connection, Siamese, 3"	113	113	113	113	113	113	113	113	113	113	113	113	113	113	113	113	113	113	113	113	113	113	113	113	113
Replace Valves & Components, Sprinkler System																		3,210							
Maintain Fire Sprinkler System	756	756	756	756	756	756	756	756	756	756	756	756	756	756	756	756	756	756	756	756	756	756	756	756	756
D50 Electrical																									
Repair Gas Monitoring System			41															41							
Replace Batteries & Check Operation, Gas Monitoring System	18	18	18	18	18	18	18		18	18	18	18	18	18	18	18	18	18	18	18	18	18		18	18
Replace Wiring Device, Switch													1,027												
Repair Wiring Device, Switch			995																				995		
Replace Receptacle, 120 V, 15 Amp.														2,106				2,527							
Replace Metal Halide Lighting Fixture, Wall Mount, 150 w																		1,051							
Replace Gas Monitoring System								2,353															2,353		
Replace Lamp, Metal Halide Lighting Fixture, Wall Mount, 150			194					194					194										194		
Replace Manual Pull Station			702															702							
Replace Incandescent Lighting Fixture, Basic, 100 w			275																				275		
Replace Lamp, Incandescent Lighting Fixture, Basic, 100 w								18					18					18							
Replace LED Lighting Fixture, 100 w																		665							
-1																									

Building: Distribution Center				Fa	cilit	y : La	ngley	/ Res	earc	h Ce	nter														
Building Num: 1206					Cit	y: Ha	mpto	n, V	4																
Forecast Year:	2038	9	0	1	2	2043	4	5	6	7	2048	9	0	1	2	2053	4	5	6	7	2058	9	0	1	2
Replace Pipe & Fittings, 4" Steel (20% of Pipe)				788																					
Replace Pipe Insulation, Fiberglass, Heating Water/Steam (20				382																					
Lubricate, Repack Gland, Ball Valve, 1"	166	166	166	166	166	166	166	166	166	166	166	166	166		166	166	166	166	166	166	166	166	166	166	166
D40 Fire Protection																									
Replace 10' Section, Pipe & Fittings, 1" Steel	60												60												60
Install New Gasket & Bolts, Pipe & Fittings, 1" Steel			46																						
Replace 10' Section, Pipe & Fittings, 2" Steel	18												18												18
Install New Gasket & Bolts, Pipe & Fittings, 2" Steel			10																						
Replace 10' Section, Pipe & Fittings, 4" Steel	19												19												19
Install New Gasket & Bolts, Pipe & Fittings, 4" Steel			8																						
Replace Fire Extinguisher									2,383												2,383				
Repair Fire Alarm Control Panel			119										119					119							
Test Gages & Valves, Fire Sprinkler System	697	697	697	697	697	697	697	697	697	697	697	697	697	697	697	697	697	697	697	697	697	697	697	697	697
Inspect & Test Fire Extinguisher		256					256							256					256						
Replace Fire Department Connection, Siamese, 3"			1,127																						
Replace Fire Sprinkler Head			10,031																						
Test Fire Sprinkler Head													4,589										4,589		
Replace Fire Alarm Control Panel								3,071															3,071		
Inspect Fire Sprinkler Head	92	92		92	92	92	92	92	92	92	92	92	92	92	92	92	92	92	92	92	92	92	92	92	92
Inspect & Test Fire Alarm Control Panel	129	129	129	129	129	129	129		129	129	129	129	129	129	129	129	129	129	129	129	129	129		129	129
Inspect & Maintain Fire Department Connection, Siamese, 3"	113	113		113	113	113	113	113	113	113	113	113	113	113	113	113	113	113	113	113	113	113	113	113	113
Replace Valves & Components, Sprinkler System													3,210												
Maintain Fire Sprinkler System	756	756	756	756	756	756	756	756	756	756	756	756	756	756	756	756	756	756	756	756	756	756	756	756	756
D50 Electrical																									
Repair Gas Monitoring System								41															41		
Replace Batteries & Check Operation, Gas Monitoring System	18	18	18	18	18	18	18	18	18	18	18	18		18	18	18	18	18	18	18	18	18	18	18	18
Replace Wiring Device, Switch			1,027															1,027							
Repair Wiring Device, Switch													995												
Replace Receptacle, 120 V, 15 Amp.									2,106				2,527												
Replace Metal Halide Lighting Fixture, Wall Mount, 150 w													1,051												
Replace Gas Monitoring System													2,353												
Replace Lamp, Metal Halide Lighting Fixture, Wall Mount, 150			194					194										194					194		
Replace Manual Pull Station								702															702		
Replace Incandescent Lighting Fixture, Basic, 100 w																		275							
Replace Lamp, Incandescent Lighting Fixture, Basic, 100 w			18					18					18										18		
Replace LED Lighting Fixture, 100 w													665												

Building: Distribution Center Facility: Langley Research Center

Danaing Hain. 1200					رادن		при	Jii, V	`																
Forecast Year:	2013	4	5	6	7	2018	9	0	1	2	2023	4	5	6	7	2028	9	0	1	2	2033	4	5	6	7
Replace Ballast, Metal Halide Lighting Fixture, Wall Mount, 150								405																	
Replace Fire Alarm Bell, 6"								727																	
Replace Fire Alarm Horn & Strobe								710																	
Maintain Keypad	61	61	61	61	61	61	61		61	61	61	61	61	61	61	61	61		61	61	61	61	61	61	61
Check & Repair Manual Pull Station													303												
Maintain Public Address Speaker	120	120	120	120	120	120	120		120	120	120	120	120	120	120	120	120	120	120	120	120	120		120	120
Replace Public Address Speaker								1,674															1,674		
Replace Batteries & Check Operation, Smoke Detector	147	147		147	147	147	147	147	147	147	147	147	147	147	147	147	147		147	147	147	147	147	147	147
Replace Battery Charger																		3,435							
Repair Smoke Detector													333												
Replace Smoke Detector			1,193															1,193							
Repair Battery Charger		701		701		701		701		701		701		701		701				701		701		701	
Replace Disconnect Switch, 30 Amp.																		5,725							
Replace Lamp, LED Lighting Fixture, 100 w			229					229					229										229		
Replace Access Keypad								500										500							
Replace Power Panel Board, 208 Y/120 V, 225 Amp.								6,035																	
Maintain Disconnect Switch, 30 Amp.	340	340	340	340	340	340	340	340	340	340	340	340	340	340	340	340	340		340	340	340	340	340	340	340
Repair Disconnect Switch, 30 Amp.								2,151																	
Maintain Disconnect Switch, 60 Amp.	40	40	40	40	40	40	40	40	40	40	40	40	40	40	40	40	40		40	40	40	40	40	40	40
Replace Disconnect Switch, 60 Amp.																		1,483							
Maintain Power Panel Board, 208 Y/120 V, 100 Amp.	121	121	121	121	121	121	121	121	121	121	121	121	121	121	121	121	121	121	121	121	121	121	121	121	121
Repair Power Panel Board, 208 Y/120 V, 100 Amp.								194										194							
Replace Power Panel Board, 208 Y/120 V, 100 Amp.																									
Repair Disconnect Switch, 60 Amp.								260																	
Repair Power Panel Board, 208 Y/120 V, 225 Amp.																		97							
Replace Fluorescent Lighting Fixture, T8, 4-32 w			2,349																				2,349		
Maintain Primary Transformer, Dry, 500 kVA	61	61	61	61	61	61	61	61	61	61	61	61	61	61	61	61	61	61	61	61	61	61	61	61	61
Repair Primary Transformer, Dry, 500 kVA													301												
Replace Ballast & Lamps, Fluorescent Lighting Fixture, T8, 2-3												1	14,419												
Maintain Power Panel Board, 208 Y/120 V, 225 Amp.	61	61	61	61	61	61	61		61	61	61	61	61	61	61	61	61	61	61	61	61	61	61	61	61
Replace Ballast & Lamps, Fluorescent Lighting Fixture, T8, 4-3													1,474												
Replace Primary Transformer, Dry, 500 kVA																									
Replace Exit Lighting Fixture, w/ Battery								1,655																	
Replace Lamp, Exit Lighting Fixture, w/ Battery			361										361					361					361		
Replace Emergency Lighting Pack, 2 Light w/ Battery													9,129												
Replace Lens, Replace Emergency Lighting Pack, 2 Light w/ Ba			290																				290		
Replace Lamp, Replace Emergency Lighting Pack, 2 Light w/ B	581		581		581		581		581		581				581		581		581		581		581		581

Building: Distribution Center Facility: Langley Research Center

Building Num. 1200					City	y. 116	ampu	JII, V	_																
Forecast Year:	2038	9	0	1	2	2043	4	5	6	7	2048	9	0	1	2	2053	4	5	6	7	2058	9	0	1	2
Replace Ballast, Metal Halide Lighting Fixture, Wall Mount, 15			405																				405		
Replace Fire Alarm Bell, 6"			727																				727		
Replace Fire Alarm Horn & Strobe			710																				710		
Maintain Keypad	61	61		61	61	61	61	61	61	61	61	61		61	61	61	61	61	61	61	61	61		61	61
Check & Repair Manual Pull Station			303															303							
Maintain Public Address Speaker	120	120	120	120	120	120	120	120	120	120	120	120		120	120	120	120	120	120	120	120	120	120	120	120
Replace Public Address Speaker													1,674												
Replace Batteries & Check Operation, Smoke Detector	147	147	147	147	147	147	147		147	147	147	147	147	147	147	147	147	147	147	147	147	147		147	147
Replace Battery Charger													3,435												
Repair Smoke Detector			333															333							
Replace Smoke Detector								1,193															1,193		
Repair Battery Charger	701		701		701		701		701		701				701		701		701		701		701		701
Replace Disconnect Switch, 30 Amp.																									
Replace Lamp, LED Lighting Fixture, 100 w			229					229										229					229		
Replace Access Keypad			500										500										500		
Replace Power Panel Board, 208 Y/120 V, 225 Amp.													6,035												
Maintain Disconnect Switch, 30 Amp.	340	340	340	340	340	340	340	340	340	340	340	340	340	340	340	340	340	340	340	340	340	340	340	340	340
Repair Disconnect Switch, 30 Amp.			2,151										2,151										2,151		
Maintain Disconnect Switch, 60 Amp.	40	40	40	40	40	40	40	40	40	40	40	40	40	40	40	40	40	40	40	40	40	40	40	40	40
Replace Disconnect Switch, 60 Amp.																									
Maintain Power Panel Board, 208 Y/120 V, 100 Amp.	121	121		121	121	121	121	121	121	121	121	121	121	121	121	121	121	121	121	121	121	121	121	121	121
Repair Power Panel Board, 208 Y/120 V, 100 Amp.													194										194		
Replace Power Panel Board, 208 Y/120 V, 100 Amp.			7,898																						
Repair Disconnect Switch, 60 Amp.			260										260										260		
Repair Power Panel Board, 208 Y/120 V, 225 Amp.			97																				97		
Replace Fluorescent Lighting Fixture, T8, 4-32 w																		2,349							
Maintain Primary Transformer, Dry, 500 kVA	61	61		61	61	61	61	61	61	61	61	61	61	61	61	61	61	61	61	61	61	61	61	61	61
Repair Primary Transformer, Dry, 500 kVA																		301							
Replace Ballast & Lamps, Fluorescent Lighting Fixture, T8, 2-								14,419																	
Maintain Power Panel Board, 208 Y/120 V, 225 Amp.	61	61	61	61	61	61	61	61	61	61	61	61		61	61	61	61	61	61	61	61	61	61	61	61
Replace Ballast & Lamps, Fluorescent Lighting Fixture, T8, 4-								1,474																	
Replace Primary Transformer, Dry, 500 kVA			53,292																						
Replace Exit Lighting Fixture, w/ Battery			1,655																				1,655		
Replace Lamp, Exit Lighting Fixture, w/ Battery								361					361					361							
Replace Emergency Lighting Pack, 2 Light w/ Battery								9,129																	
Replace Lens, Replace Emergency Lighting Pack, 2 Light w/																		290							
Replace Lamp, Replace Emergency Lighting Pack, 2 Light w/		581		581		581				581		581		581		581		581		581		581		581	


Building: Distribution Center				Fa	cility	/ : La	ngley	/ Res	earc	h Ce	nter														
Building Num: 1206					City	/ : Ha	mpto	n, V	4																
Forecast Year:	2013	4	5	6	7	2018	9	0	1	2	2023	4	5	6	7	2028	9	0	1	2	2033	4	5	6	7
Replace Secondary Transformer, Dry, 150 kVA																									
Repair Secondary Transformer, Dry, 150 kVA								271										271							
Maintain Secondary Transformer, Dry, 150 kVA	61	61	61	61	61	61	61	61	61	61	61	61	61	61	61	61	61	61	61	61	61	61	61	61	61
Replace Fluorescent Lighting Fixture, T8, 2-32 w			22,990																			2	22,990		
E10 Equipment																									
Maintain Icemaker, Commercial	813	813	813	813	813	813	813		813	813	813	813	813	813	813	813	813		813	813	813	813	813	813	813
Replace Icemaker, Commercial								16,685										16,685							
Replace Microwave Oven								547										547							
Maintain Refrigerator, Domestic	38	38	38	38	38	38	38		38	38	38	38	38	38	38	38	38		38	38	38	38	38	38	38
Replace Refrigerator, Domestic								1,385										1,385							
G30 Site Mechanical Utilities																									
Replace Post Indicator Valve													2,562												
Inspect & Test Post Indicator Valve	59	59	59	59	59	59	59	59	59	59	59	59		59	59	59	59	59	59	59	59	59	59	59	59

Building: Distribution Center				Fa	cility	/ : La	ngley	Res	earc	h Ce	nter														
Building Num: 1206					City	/: Ha	mpto	n, V	4																
Forecast Year:	2038	9	0	1	2	2043	4	5	6	7	2048	9	0	1	2	2053	4	5	6	7	2058	9	0	1	2
Replace Secondary Transformer, Dry, 150 kVA		11	1,773																						
Repair Secondary Transformer, Dry, 150 kVA													271										271		
Maintain Secondary Transformer, Dry, 150 kVA	61	61		61	61	61	61	61	61	61	61	61	61	61	61	61	61	61	61	61	61	61	61	61	61
Replace Fluorescent Lighting Fixture, T8, 2-32 w																	:	22,990							
E10 Equipment																									
Maintain Icemaker, Commercial	813	813		813	813	813	813	813	813	813	813	813		813	813	813	813	813	813	813	813	813		813	813
Replace Icemaker, Commercial		16	6,685										16,685										16,685		
Replace Microwave Oven			547										547										547		
Maintain Refrigerator, Domestic	38	38		38	38	38	38	38	38	38	38	38		38	38	38	38	38	38	38	38	38		38	38
Replace Refrigerator, Domestic		1	1,385										1,385										1,385		
G30 Site Mechanical Utilities																									
Replace Post Indicator Valve																							2,562		
Inspect & Test Post Indicator Valve	59	59	59	59	59	59	59	59	59	59	59	59	59	59	59	59	59	59	59	59	59	59		59	59

Building Deferred Maintenance by System Chart

Building: Distribution Center Building Num: 1206

City: Hampton, VA



All costs expressed in (\$) 2012.

^{*}Deferred Maintenance is defined as the cost of rebuilding or replacing components whose service life has exceeded their scheduled lifetime as of the Forecast Year. Preventative maintenance and minor repairs are not included.

^{**}Degradation Cost is defined as additional cost (penalty cost) incurred by maintenance deferral and is included in Total Deferred Maintenance. Based on a 50-Year Forecast.

Building Deferred Maintenance Detail

Whitestone Research

Total

Building: Distribution Center Year Built: 1966 Building Type: Temperature

Facility: Langley Research Center Original Cost: \$1 Controlled Warehouse

City: Hampton, VA Replacement Value: \$3,639,735 Building Gsft: 35,625

per SF: \$102 Building Number: 1206

Year Installed			Deferred* Maintenance	Degradation Cost**	Total Deferred Maintenance
1966	7	Replace Steel, Insulated Wall Panels, Painted, Exterior, 2"	\$209,722	\$0	\$209,722
1966	17	Replace Metal Floor Grating	\$65,438	\$0	\$65,438
1980	3	Replace Primary Transformer, Dry, 500 kVA	\$53,292	\$0	\$53,292
1966	22	Replace Dock Ramp Leveler	\$38,427	\$0	\$38,427
1966	38	Replace Steam Trap, F&T, 2"	\$33,955	\$0	\$33,955
1966	39	Replace Carpet, Nylon 20 oz., High Traffic	\$12,931	\$0	\$12,931
1980	3	Replace Secondary Transformer, Dry, 150 kVA	\$11,773	\$0	\$11,773
1966	28	Replace Valve, Non-Drain, 10"	\$11,669	\$0	\$11,669
1966	17	Replace Wood, Hollow Core, Painted, Interior Door	\$9,949	\$0	\$9,949
1980	3	Replace Power Panel Board, 208 Y/120 V, 100 Amp.	\$7,898	\$0	\$7,898
1966	39	Replace Carpet, Nylon 20 oz., High Traffic	\$7,793	\$0	\$7,793
1966	39	Replace Carpet, Nylon 20 oz., High Traffic	\$7,476	\$0	\$7,476
1966	39	Replace Carpet, Nylon 20 oz., High Traffic	\$6,935	\$0	\$6,935
1966	39	Replace Carpet, Nylon 20 oz., High Traffic	\$5,622	\$0	\$5,622
1966	17	Replace Metal, Painted, Exterior Railing	\$4,868	\$0	\$4,868
1995	8	Replace Water Cooler, Electric	\$4,505	\$0	\$4,505
1966	28	Replace Gate Valve, 6"	\$4,309	\$0	\$4,309
1966	28	Replace Exhaust Fan, Propeller, 1,000 Cfm	\$3,950	\$0	\$3,950
1966	12	Replace Tankless Water Closet	\$3,657	\$0	\$3,657
2000	3	Replace Backflow Preventer, 2"	\$3,556	\$0	\$3,556
1990	3	Replace Battery Charger	\$3,435	\$0	\$3,435
1990	3	Replace Valves & Components, Sprinkler System	\$3,210	\$0	\$3,210
1966	27	Replace Toilet Partitions, Painted Metal, Overhead Braced	\$3,205	\$0	\$3,205
1994	9	Replace Thermostat	\$3,184	\$0	\$3,184
1966	12	Replace Urinal, Vitreous China	\$2,914	\$0	\$2,914
1990	3	Replace Receptacle, 120 V, 15 Amp.	\$2,527	\$0	\$2,527
1966	12	Replace Lavatory, Vitreous China	\$2,165	\$0	\$2,165
1966	27	Replace Receptacle, 120 V, 15 Amp.	\$2,106	\$0	\$2,106
1966	30	Replace Ball Valve, 1"	\$2,032	\$0	\$2,032
1990	8	Replace Public Address Speaker	\$1,674	\$0	\$1,674
1966	41	Replace Pressure Reducer Valve, 2"	\$1,562	\$0	\$1,562
1966	22	Replace Pipe & Fittings, 3/4" Copper, Hot Water (20% of Pipe)	\$1,313	\$0	\$1,313
1966	22	Replace Pipe & Fittings, 3/4" Copper, Cold Water (20% of Pipe)	\$1,313	\$0	\$1,313

All costs expressed in (\$) 2012.

^{*}Deferred Maintenance is defined as the cost of rebuilding or replacing components whose service life has exceeded their scheduled lifetime as of the Forecast Year. Preventative maintenance and minor repairs are not included.

^{**}Degradation Cost is defined as additional cost (penalty cost) incurred by maintenance deferral. Based on a 50-Year Forecast.

Building Deferred Maintenance Detail

Whitestone Research

Total

Building: Distribution Center Year Built: 1966 Building Type: Temperature

Facility: Langley Research Center Original Cost: \$1 Controlled Warehouse

City: Hampton, VA Replacement Value: \$3,639,735 Building Gsft: 35,625

per SF: \$102 Building Number: 1206

Year Installed	Years Deferred	Deferred Maintenance Task*	Deferred* Maintenance	Degradation Cost**	Deferred Maintenance
1966	7	Replace Plywood Ceiling	\$1,168	\$0	\$1,168
1966	39	Replace Carpet, Nylon 20 oz., High Traffic	\$1,068	\$0	\$1,068
1966	32	Replace Water Heater, Electric, 15 Gal.	\$1,040	\$0	\$1,040
1995	3	Replace Wiring Device, Switch	\$1,027	\$0	\$1,027
1966	12	Replace Service Sink, Iron, Enamel	\$962	\$0	\$962
1966	7	Replace Sink, Stainless Steel	\$939	\$0	\$939
2000	3	Replace Backflow Preventer, 3/4"	\$827	\$0	\$827
1966	22	Replace Emergency Eye Wash Station	\$772	\$0	\$772
1966	32	Replace Water Heater, Electric, 5 Gal.	\$714	\$0	\$714
1966	22	Replace Pipe Insulation, Fiberglass, Heating Water/Steam (20% of	\$382	\$0	\$382
1966	7	Replace Floor Drain	\$283	\$0	\$283
1966	22	Replace Pipe Insulation, Fiberglass, Cold Water (20% of Insulation	\$274	\$0	\$274
1966	22	Replace Pipe Insulation, Fiberglass, Hot Water (20% of Insulation)	\$274	\$0	\$274
1966	37	Replace Valve, Hose Bib	\$52	\$0	\$52
		Total	\$548,143	\$0	\$548,143

All costs expressed in (\$) 2012.

^{*}Deferred Maintenance is defined as the cost of rebuilding or replacing components whose service life has exceeded their scheduled lifetime as of the Forecast Year. Preventative maintenance and minor repairs are not included.

^{**}Degradation Cost is defined as additional cost (penalty cost) incurred by maintenance deferral. Based on a 50-Year Forecast.

Built Date: 1966

Building Total

Building: Distribution Center GSFT: 35,625

Building Number: 1206 Replacement Value: \$3,639,735

Facility: Langley Research Center Building Use: Warehouse and Storage

City: Hampton, VA Building Type: Temperature Controlled


Warehouse

100.0%

	Annual	Annual	
Operation	Cost/GSFT	Total	Percent
Custodial	\$0.333	\$11,852	4.9%
Energy	\$0.873	\$31,116	12.8%
Grounds	\$0.110	\$3,902	1.6%
M&R	\$4.240	\$151,054	61.9%
Management	\$0.255	\$9,099	3.7%
Pest Control	\$0.104	\$3,688	1.5%
Refuse	\$0.006	\$205	0.1%
Road Clearance	\$0.006	\$216	0.1%
Security	\$0.489	\$17,408	7.1%
Telecom	\$0.379	\$13,506	5.5%
Water/Sewer	\$0.054	\$1,929	0.8%

\$6.85

\$243,975



Building Operations Utility Details

Whitestone Research

Building: Distribution Center Year Built: 1966 Building Type: Temperature Controlled W

Facility: Langley Research Center Original Cost: \$1 Building Num: 1206

City: Hampton, VA Replacement Value: \$3,639,735 per SF: \$102 Building Gsft: 35,625

		Utility	GSFT	Demand	UM	Rate	Cost
Operation:	Energy	Level of Service: Medium					
		Electricity	35625	10.791	kWh	\$0.0700	\$26,910
		Natural Gas	35625	0.158	Thm	\$0.7480	\$4,206
		Diesel	35625	0.000	Gal	\$3.1876	\$0
		Total:		10.949			\$31,116
Operation:	Refuse	Level of Service: Medium					
		Municipal Solid Waste	35625	0.070	Lbs	\$0.0674	\$168
		Recycling	35625	0.030	Lbs	\$0.0348	\$37
		Total:		0.100			\$205
Operation:	Water/Sewer	Level of Service: Medium					
		Water	35625	7.280	Gal	\$0.0056	\$1,452
		Sewer	35625	5.720	Gal	\$0.0023	\$477
		Total:		13.000			\$1,929

Building Operations Task Details

Whitestone Research

Building: Distribution Center Year Built: 1966 Building Type: Temperature Controlled W

Facility: Langley Research Center Original Cost: \$1 Building Num: 1206

City: Hampton, VA Replacement Value: \$3,639,735 per SF: \$102 Building Gsft: 35,625

Functional Area	FA GSFT	Task	Labor Cost	Material Cost	Task Cost
Operation: Custodial		Level of Service: Low			
Warehouse	13181	Sweep Hard Floor with 48" Push Broom	\$238	\$39	\$276
Warehouse	13181	Empty Trash; Wipe Clean & Re-line Basket	\$152	\$25	\$177
Logistics/Distribution	10687	Sweep Hard Floor with 48" Push Broom	\$193	\$31	\$224
Logistics/Distribution	10687	Empty Trash; Wipe Clean & Re-line Basket	\$123	\$20	\$144
Office	7125	Vacuum Carpet with 14" Upright Vacuum	\$2,497	\$406	\$2,902
Office	7125	Empty Trash; Wipe Clean & Re-line Basket	\$713	\$116	\$829
Office	7125	Clean and Wipe Furniture with Trigger Sprayer & Cloth	\$438	\$71	\$509
Office	7125	Dust Surfaces with Duster	\$329	\$53	\$383
Office	7125	Vacuum Upholstered Furniture with Tank or Canister Vacuum	\$274	\$45	\$319
Office	7125	Dust Window Blinds	\$158	\$26	\$184
Restroom	1781	Service Restroom: Empty Trash, Clean & Disinfect Fixtures, Wipe Mirrors, Replace Supplies, Wet	\$3,744	\$608	\$4,353
Restroom	1781	Service Restroom: Empty Trash, Replace Supplies & Touch Up as Needed	\$574	\$93	\$667
Shop	1425	Damp Mop Hard Floors with 24 oz. Mop Head Using Double Bucket & Wringer	\$522	\$85	\$607
Shop	1425	Empty Trash; Wipe Clean & Re-line Basket	\$198	\$32	\$230
Mechanical/Equipment	1425	Sweep Hard Floor with 48" Push Broom	\$26	\$4	\$30
Mechanical/Equipment	1425	Empty Trash; Wipe Clean & Re-line Basket	\$16	\$3	\$19
Total:			\$10,195	\$1,657	\$11,852
Operation: Grounds		Level of Service: Low			
Grounds, Improved	21375	Mow Turfgrass with 21" Power Mower	\$748	\$311	\$1,059
Grounds, Improved	21375	Aerate Improved Grounds	\$508	\$211	\$719
Grounds, Improved	21375	Clear Shrubs	\$424	\$176	\$600
Grounds, Improved	21375	Edge Clean & Trim Walks with Gas Powered Edger	\$310	\$129	\$439
Grounds, Improved	21375	Overseed, Improved Grounds	\$254	\$106	\$359
Grounds, Improved	21375	Vacuum with 30" Billy Goat	\$170	\$71	\$240
Grounds, Improved	21375	Clear Crabgrass	\$127	\$53	\$180
Grounds, Improved	21375	Clear Weeds with 15" Boom, Improved Grounds	\$68	\$28	\$96
Grounds, Improved	21375	Trim Around Raised Objects with String Edger	\$64	\$26	\$90

Functional Area	FA GSFT	Task	Labor Cost	Material Cost	Task Cost
Grounds, Improved	21375	Fertilize Improved Grounds	\$51	\$21	\$72
Grounds, Improved	21375	Sweep with 30" Power Rake	\$34	\$14	\$47
Grounds, Improved	21375	Fertilize Using Power Take Off Broadcast	\$0	\$0	\$0
Total:			\$2,755	\$1,146	\$3,902
Operation: Pest Co	ntrol	Level of Service: Medium			
Pest Controlled	35625	Install, or Check and Re-Bait 5 Rodent Boxes	\$1,273	\$530	\$1,803
Pest Controlled	35625	Perform Crawling Insect Abatement	\$956	\$398	\$1,354
Pest Controlled	35625	Inspect Building for Pests	\$531	\$0	\$531
Total:			\$2,761	\$927	\$3,688
Operation: Road Cl	earance	Level of Service: Medium			
Pavement NASA	28500	Plow Paved Area	\$166	\$50	\$216
Total:			\$166	\$50	\$216
Operation: Security		Level of Service: Medium			
Secured Area	35625	Patrol Building Perimeter	\$5,262	\$855	\$6,117
Secured Area	35625	Guard Lobby/Parking	\$0	\$0	\$0
Total:			\$5,262	\$855	\$6,117

Building Operations Service Details

Whitestone Research

Building: Distribution Center Year Built: 1966 FTEs: 15 Building Type: Temperature Controlled W

Facility: Langley Research Center Original Cost: \$1 Building Num: 1206

City: Hampton, VA Replacement Value: \$3,639,735 per SF: \$102 Building Gsft: 35,625

		Service*	Quantity	Rate	Cost
Operation:	Security	Level of Service: Medium			
		Intrusion Detection Systems	1	\$4,986	\$4,986
		System Monitoring	1	\$3,615	\$3,615
		Access Control	1	\$2,690	\$2,690
		Total:			\$11,291
Operation:	Telecom	Level of Service: High			
		Local Telephone	15	\$468	\$7,020
		Data	15	\$3,588	\$3,606
		Long Distance Telephone	15	\$192	\$2,880
		Total:			\$13,506

All costs expressed in (\$) 2012.

^{*} Secutity may be composed of service and task based cost. See Building Operations Task Details for Security Tasks.

Building Operations Management Details

Whitestone Research

Building: Distribution Center Year Built: 1966 Building Type: Temperature Controlled W

Facility: Langley Research Center Original Cost: \$1 Building Num: 1206

City: Hampton, VA Replacement Value: \$3,639,735 per SF: \$102 Building Gsft: 35,625

	Service	Demand	UM	PRV	Cost
Operation: Management	Level of Service: Low				
	Management	0.3%	PRV	\$3,639,735	\$9,099
	Total:				\$9,099

Attachment E: Detailed MARS Reports for PBS Igloo Model

Average M&R Costs

Whitestone Research

Plum Brook Igloo GSFT: 1,953

Building Number: Igloo PRV: \$309,368

Facility: Plum Brook Station Built Date: 1942

City: Cleveland, OH

M&R Average Annual Cost Forecasts

	Current Year	5 Year	20 Year	50 Year
PM & Minor Repair:	\$0	\$0	\$3	\$3
Unscheduled Maintenance:	\$0	\$0	\$4	\$6
Renewal & Replacement:	\$0	\$17,918	\$4,536	\$1,889
Total M&R Costs:	\$0	\$17,918	\$4,543	\$1,898
Per GSFT:	\$0.00	\$9.17	\$2.33	\$0.97
As % of PRV:	0.00%	5.79%	1.47%	0.61%

Building Component List Whitestone Research

Building: Plum Brook Igloo Year Built: 1942 Building Type: Non-Temperature Controll

Facility: Plum Brook Station

Original Cost: \$1

Building Num: Igloo

City: Cleveland, OH Replacement Value: \$309,368 per SF: \$158 Building Gsft: 1,953

Uniformat	Asset Description	Component	Date	Quantity	Location	Notes
B2030		Steel, Exterior Door	1942	1 Each		
C3020		Concrete Flooring	1942	1950 Sq Ft		
C3030		Concrete Ceiling	1942	2665 Sq Ft		
D3040		Ventilator, 12"	1942	1 Each		

Building Extended Component List with Remaining Service Life

Whitestone Research

30-Apr-15

Building: Plum Brook Igloo Year Built: 1942 Building Type: Non-Temperature Controll

Facility: Plum Brook Station Original Cost: \$1 Building Num: Igloo

City: Cleveland, OH Replacement Value: \$309,368 per SF: \$158 Building Gsft: 1,953

Uniformat Asset Description	Component		Remaining Service Life*	Quantity	Deferred** Maintenance	Degradation Cost***	Total Deferred Maintenance	Location	Notes
B2030	Steel, Exterior Door	1942	3	1 Each					
C3020	Concrete Flooring	1942	3	1950 Sq Ft					
C3030	Concrete Ceiling	1942	3	2665 Sq Ft					
D3040	Ventilator, 12"	1942	-46	1 Each	\$271	\$0	\$271		

^{*}Remaining Service Life shows years until scheduled Replacement Task; blank implies there is no Replacement Task.

^{**}Deferred Maintenance is defined as the cost of rebuilding or replacing components whose service life has exceeded their scheduled lifetime as of the Forecast Year. Preventative maintenance and minor repairs are not included.

^{***}Degradation Cost is defined as additional cost (penalty cost) incurred by maintenance deferral.

[§] Indicates Component set to have PM Tasks coincide with Replacement Task.

M&R Costs by System per Year Chart Whitestone Research 30-Apr-15 City: Cleveland, OH Building: Plum Brook Igloo Facility: Plum Brook Station 1953 Forecast Year: 2013 2018 2 2023 2028 2033 6 7 A10 Foundations A20 Basement Construction B10 Super Structure **B20 Exterior Enclosure** 0.46 0.03 0.19 0.12 0.19 B30 Roofing C10 Interior Construction C20 Stairs C30 Interior Finishes 45.42 0.18 D10 Conveying D20 Plumbing 0.14 D30 HVAC D40 Fire Protection D50 Electrical E10 Equipment E20 Furnishings F10 Special Construction F20 Selective Bldg Demolition G10 Site Preparation G20 Site Improvements G30 Site Mechanical Utilities G40 Site Electrical Utilities G90 Other Site Construction Total 45.87 0.14 0.03 0.19 0.31 0.19 \$50.00 \$45.00 \$40.00 \$35.00 \$30.00 \$25.00 Costs/Gsft \$20.00 \$15.00 \$10.00 \$5.00 \$0.00 2013 2014 2015 2016 2017 2018 2019 2020 2021 2022 2023 2024 2025 2026 2027 2028 2029 2030 2031 2032 2033 2034 2035 2036 2037

M&R Costs by System per Year Chart Whitestone Research 30-Apr-15 Building: Plum Brook Igloo Facility: Plum Brook Station City: Cleveland, OH **GSFT**: 1953 Building Num: Igloo Forecast Year: 2038 2043 4 7 2048 2 2058 Total A10 Foundations 0.00 A20 Basement Construction 0.00 B10 Super Structure 0.00 **B20 Exterior Enclosure** 0.03 0.29 0.03 0.19 0.12 1.65 B30 Roofing 0.00 C10 Interior Construction 0.00 C20 Stairs 0.00 C30 Interior Finishes 0.72 0.18 0.18 46.69 D10 Conveying 0.00 D20 Plumbing 0.00 0.14 D30 HVAC 0.28 D40 Fire Protection 0.00 D50 Electrical 0.00 E10 Equipment 0.00 E20 Furnishings 0.00 F10 Special Construction 0.00 F20 Selective Bldg Demolition 0.00 G10 Site Preparation 0.00 G20 Site Improvements 0.00 G30 Site Mechanical Utilities 0.00 G40 Site Electrical Utilities 0.00 G90 Other Site Construction 0.00 0.75 0.14 0.47 0.19 0.31 Total 0.03 \$0.80 \$0.70 \$0.60 \$0.50 \$0.40 Costs/Gsft \$0.30 \$0.20 \$0.10 \$0.00

Notes: A value of "0.00" means cost of more than \$.000 but less than \$.005 per gsft. Based on a 50-Year Forecast.

All costs expressed in (\$) 2012 per gsft.

2038 2039 2040 2041 2042 2043 2044 2045 2046 2047 2048 2049 2050 2051 2052 2053 2054 2055 2056 2057 2058 2059 2060 2061 2062

Year 26-50

M&R Costs by Task 30-Apr-15 Whitestone Research

Building: Plum Brook Igloo Facility: Plum Brook Station

Building Num: Igloo City: Cleveland, OH

> Forecast Year: 2013 2 2023 7 2028

B20 Exterior Enclosure

Replace Steel, Exterior Door Repair Steel, Exterior Door Replace Steel, Exterior Door Locks Maintain Steel, Exterior Door Locks

C30 Interior Finishes

Replace Concrete Ceiling Repair Concrete Ceiling (2% of Ceiling) Replace Concrete Flooring Repair Concrete Flooring (2% of Floors)

D30 HVAC

Replace Ventilator, 12"

M&R Costs by Task Whitestone Research 30-Apr-15

Building: Plum Brook Igloo Facility: Plum Brook Station

Building Num: Igloo City: Cleveland, OH

Forecast Year: 2038 9 0 1 2 2043 4 5 6 7 2048 9 0 1 2 2053 4 5 6 7 2058 9 0 1

B20 Exterior Enclosure

Replace Steel, Exterior Door Repair Steel, Exterior Door Replace Steel, Exterior Door Locks Maintain Steel, Exterior Door Locks

C30 Interior Finishes

Replace Concrete Ceiling
Repair Concrete Ceiling (2% of Ceiling)
Replace Concrete Flooring
Repair Concrete Flooring (2% of Floors)

D30 HVAC


Replace Ventilator, 12"

	189			189
	323		323	
2	1 21	21	21	21

271

Building Deferred Maintenance by System Chart

Building: Plum Brook Igloo Building Num: Igloo



All costs expressed in (\$) 2012.

^{*}Deferred Maintenance is defined as the cost of rebuilding or replacing components whose service life has exceeded their scheduled lifetime as of the Forecast Year. Preventative maintenance and minor repairs are not included.

^{**}Degradation Cost is defined as additional cost (penalty cost) incurred by maintenance deferral and is included in Total Deferred Maintenance. Based on a 50-Year Forecast.

Building Deferred Maintenance Detail

Whitestone Research

Building: Plum Brook Igloo Year Built: 1942 Building Type: Non-

Facility: Plum Brook Station

Original Cost: \$1

Temperature Controlled

City: Cleveland, OH Replacement Value: \$309,368 Building Gsft: 1,953

per SF: \$158 Building Number: Igloo

Year Installed	Years Deferred	Deferred Maintenance Task*		Deferred* Maintenance	Degradation Cost**	Deferred Maintenance
1942	45	Replace Ventilator, 12"		\$271	\$0	\$271
			Total	\$271	\$0	\$271

All costs expressed in (\$) 2012.

^{*}Deferred Maintenance is defined as the cost of rebuilding or replacing components whose service life has exceeded their scheduled lifetime as of the Forecast Year. Preventative maintenance and minor repairs are not included.

Built Date: 1942

Building: Plum Brook Igloo **GSFT:** 1,953


Building Number: Igloo Replacement Value: \$309,368

Facility: Plum Brook Station Building Use: Warehouse and Storage

City: Cleveland, OH Building Type: Non-Temperature

Controlled Warehouse

	Annual	Annual	
Operation	Cost/GSFT	Total	Percent
Custodial	\$0.000	\$0	0.0%
Energy	\$0.000	\$0	0.0%
Grounds	\$0.008	\$15	0.5%
M&R	\$0.972	\$1,899	70.7%
Management	\$0.396	\$773	28.8%
Refuse	\$0.000	\$0	0.0%
Security	\$0.000	\$0	0.0%
Telecom	\$0.000	\$0	0.0%
Water/Sewer	\$0.000	\$0	0.0%
Building Total	\$1.38	\$2,687	100.0%



Building Operations Utility Details

Whitestone Research

Building: Plum Brook Igloo Year Built: 1942 Building Type: Non-Temperature Controll

Facility:Plum Brook StationOriginal Cost:\$1Building Num:IglooCity:Cleveland, OHReplacement Value:\$309,368per SF:\$158Building Gsft:1,953

		Utility	GSFT	Demand	UM	Rate	Cost
Operation:	Energy	Level of Service: None					
		Diesel	1953	0.000	Gal	\$3.2669	\$0
		Natural Gas	1953	0.000	Thm	\$0.4800	\$0
		Electricity	1953	0.000	kWh	\$0.0700	\$0
		Total:		0.000			\$0
Operation: Ref	Refuse	Level of Service: None					
		Recycling	1953	0.000	Lbs	\$0.0363	\$0
		Municipal Solid Waste	1953	0.000	Lbs	\$0.0063	\$0
		Total:		0.000			\$0
Operation:	Water/Sewer	Level of Service: None					
		Sewer	1953	0.000	Gal	\$0.0036	\$0
		Water	1953	0.000	Gal	\$0.0153	\$0
		Total:		0.000			\$0

Building Operations Task Details

Whitestone Research

Building: Plum Brook Igloo Year Built: 1942 Building Type: Non-Temperature Controll

Facility: Plum Brook Station

Original Cost: \$1

Building Num: Igloo

City: Cleveland, OH Replacement Value: \$309,368 per SF: \$158 Building Gsft: 1,953

Functional Area	FA GSFT	Task	Labor Cost	Material Cost	Task Cost
Operation: Custodial		Level of Service: None			
Storage	1953	None	\$0	\$0	\$0
Total:			\$0	\$0	\$0
Operation: Grounds		Level of Service: Low			
Grounds, Semi-Improve	1171	Mow Turfgrass with 5-7' Gang Reel	\$4	\$2	\$6
Grounds, Semi-Improve	1171	Aerate Semi-Improved Grounds	\$3	\$1	\$4
Grounds, Semi-Improve	1171	Clear Weeds with 15" Boom, Semi-Improved Grounds	\$2	\$1	\$2
Grounds, Semi-Improve	1171	Fertilize Semi-Improved Grounds	\$2	\$1	\$2
Total:			\$10	\$4	\$15

Building Operations Service Details

Whitestone Research

Building: Plum Brook Igloo Year Built: 1942 FTEs: 0 Building Type: Non-Temperature Controll

Facility: Plum Brook Station Original Cost: \$1 Building Num: Igloo

City: Cleveland, OH Replacement Value: \$309,368 per SF: \$158 Building Gsft: 1,953

		Service*	Quantity	Rate	Cost
Operation:	Security	Level of Service: None			
		Access Control	0	\$2,690	\$0
		Total:			\$0
Operation: Telec	Telecom	Level of Service: None			
		Local Telephone	0	\$468	\$0
		Total:			\$0

All costs expressed in (\$) 2012.

Building Operations Management Details

Total:

Whitestone Research

\$773

Building: Plum Brook Igloo Year Built: 1942 Building Type: Non-Temperature Controll

Facility: Plum Brook Station Original Cost: \$1 Building Num: Igloo

City: Cleveland, OH Replacement Value: \$309,368 per SF: \$158 Building Gsft: 1,953

. <u>.</u>	Service	Demand	UM	PRV	Cost
Operation: Management	Level of Service: Low				
	Management	0.3%	PRV	\$309,368	\$773