

```
*-----Camio Version 8.1-----*
| Part Number:.... TRAILING FLAP | Revision:..... ; |
| Job Number:..... 33221 | Operator:..... JH |
| Customer:..... NOTRE DAME | Serial #:..... 1 |
*-----*
```

```
(mm)          ACTUAL    NOMINAL    LO-TOL    HI-TOL DEVIATION GRAPHIC          ERROR
```

Temperature Compensation: OFF

*

*

THICKNESS AT 3-STREAM AND 5-LATERAL INTERSECTING POINTS

=====

(AT 35% STREAM LOCATIONS)

Point:PNT007

Z-axis 0.4243 0.4239 -0.0040 +0.0040 0.0004 ---*---

Point:PNT008

Z-axis 0.3117 0.3150 -0.0040 +0.0040 -0.0033 -*+---

Point:PNT009

Z-axis 0.2445 0.2470 -0.0040 +0.0040 -0.0025 -*+---

Point:PNT010

Z-axis 0.1774 0.1793 -0.0040 +0.0040 -0.0019 --*+---

Point:PNT011

Z-axis 0.0659 0.0670 -0.0040 +0.0040 -0.0011 --*+---

(AT 50% STREAM LOCATIONS)

Point:PNT012

Z-axis 0.4235 0.4239 -0.0040 +0.0040 -0.0004 ---*---

Point:PNT013

Z-axis 0.3111 0.3150 -0.0040 +0.0040 -0.0039 *--+---

Point:PNT014

Z-axis 0.2435 0.2470 -0.0040 +0.0040 -0.0035 *--+---

Point:PNT015

Z-axis 0.1764 0.1793 -0.0040 +0.0040 -0.0029 -*+---

Point:PNT016

Z-axis 0.0639 0.0670 -0.0040 +0.0040 -0.0031 -*+---

(AT 65% STREAM LOCATIONS)

Point:PNT017

Z-axis 0.4247 0.4239 -0.0040 +0.0040 0.0008 ---+*--

=====

(in)	ACTUAL	NOMINAL	LO-TOL	HI-TOL	DEVIATION	GRAPHIC	ERROR
Point:PNT018							
Z-axis	0.3121	0.3150	-0.0040	+0.0040	-0.0029	-*-+---	
Point:PNT019							
Z-axis	0.2445	0.2470	-0.0040	+0.0040	-0.0025	-*-+---	
Point:PNT020							
Z-axis	0.1774	0.1793	-0.0040	+0.0040	-0.0019	--*+---	
Point:PNT021							
Z-axis	0.0658	0.0670	-0.0040	+0.0040	-0.0012	--*+---	
(POINTS AT 2/3 UP FROM HINGE FACE TAKEN ACROSS THE PART)							
Point:PNT022							
Z-axis	0.2026	0.2020	-0.0040	+0.0040	0.0006	---*---	
Point:PNT023							
Z-axis	0.2025	0.2020	-0.0040	+0.0040	0.0005	---*---	
Point:PNT024							
Z-axis	0.2002	0.2020	-0.0040	+0.0040	-0.0018	--*+---	
Point:PNT025							
Z-axis	0.2007	0.2020	-0.0040	+0.0040	-0.0013	--*+---	
Point:PNT026							
Z-axis	0.2000	0.2020	-0.0040	+0.0040	-0.0020	--*+---	
Point:PNT027							
Z-axis	0.1985	0.2020	-0.0040	+0.0040	-0.0035	*--+---	
Point:PNT028							
Z-axis	0.1978	0.2020	-0.0040	+0.0040	-0.0042	<--+---	-0.0002
Point:PNT029							
Z-axis	0.1992	0.2020	-0.0040	+0.0040	-0.0028	-*-+---	
Point:PNT030							
Z-axis	0.2013	0.2020	-0.0040	+0.0040	-0.0007	---*---	
Point:PNT031							
Z-axis	0.2007	0.2020	-0.0040	+0.0040	-0.0013	--*+---	
Point:PNT032							
Z-axis	0.2007	0.2020	-0.0040	+0.0040	-0.0013	--*+---	
Point:PNT033							
Z-axis	0.2013	0.2020	-0.0040	+0.0040	-0.0007	--*+---	
Point:PNT034							
Z-axis	0.2001	0.2020	-0.0040	+0.0040	-0.0019	--*+---	
Point:PNT035							
Z-axis	0.2049	0.2020	-0.0040	+0.0040	0.0029	---+*-	

17-Dec-2020 14:46

Start Template

Page 3

(in)	ACTUAL	NOMINAL	LO-TOL	HI-TOL	DEVIATION	GRAPHIC	ERROR
------	--------	---------	--------	--------	-----------	---------	-------

Duration 5 mins 57 secs

FAIL in:28 out:1

End of Report
=====