

**ВД-СУ MODE OFF/ON AND БИТС POWER CYCLING. BCC TEST**

GMT	CREW	ACTIVITY
06:00-06:10		Morning inspection
06:10-06:40		Post-sleep
06:40-07:30		BREAKFAST
07:30-07:45		Work prep
07:45-08:00		Daily Planning Conference ( <i>S-band</i> )
08:00-08:30		Skills training for the Shuttle R-Bar Pitch Maneuver
08:30-08:35	FE-1	Transferring images from RPM OBT from camera to U disk.
08:30-08:45	CDR	Work prep
08:35-10:20	FE-1	Gathering US trash to be loaded onto Progress 20P (Progress 355)
08:45-10:45	CDR	Installation of Noise Reduction Screen 17KC.215Ю 5315-0 on the Vozdukh Atmosphere Purification Unit. <i>Tagup with specialists (S-band)</i>
10:20-10:40	FE-1	CEVIS monthly maintenance
10:40-12:10	FE-1	Physical Exercise (CEVIS)
10:45-12:15	CDR	Medical Kits Inventory
12:10-13:10	FE-1	Physical Exercise (RED)
12:15-13:15	CDR	Physical exercise (VELO + Load Trainer/Cycle 1), day 4
13:15-13:20	CDR	<b>On MCC Go ISS</b> O2 repress from Progress 355 CpПК (start)
13:20-14:20		LUNCH
14:20-15:35	FE-1	Gathering US trash to be loaded onto Progress 20P (Progress 355)
14:20-14:25	CDR	ISS O2 repress from Progress 355 CpПК (terminate)
14:25-15:05	CDR	Replacing SM interior panels 204, 205 and relocating ДС-7А Smoke Detector. <i>Tagup with specialists as necessary (S-band)</i>
15:05-15:15	CDR	<b>On MCC GO</b> Mate telemetry data [ТМИ] connectors to БИТС2-12
15:15-15:55	CDR	Replacing SM interior panels 204, 205 and relocating ДС-7А Smoke Detector. <i>Tagup with specialists as necessary (S-band)</i>
15:35-16:05	FE-1	Defibrillator Checkout
15:55-16:25	CDR	SOUNDMETER. Set up and measurement after the installation of ССШ [Noise Reduction Screen]. <i>Tagup with specialists (S-band)</i>
16:05-16:25	FE-1	IMS update
16:25-16:40	FE-1	Download RS Acoustic Measurements to MEC.
16:25-16:40	CDR	Taking readings from АОК ГАНК-4М gas analyzer
16:40-17:35	FE-1	Relocation of medical accessories kit
16:40-18:10	CDR	Physical Exercise (TVIS) day 4
17:35-17:50	FE-1	Crew discretionary conference ( <i>S-band</i> )
17:50-17:55	FE-1	O2 and CO2 monitoring
17:55-18:25	FE-1	СОЖ maintenance. Inspection of БРПК separator ИП-1 Position Check
18:10-18:30	CDR	Evening work prep
18:25-18:30	FE-1	Transferring TVIS, RED, and HRM data to MEC

18:30-18:40	FE-1	Evening work prep
18:30-18:40	CDR	SOUNDMETER. Closeout ops. <i>Tagup with specialists (S-band)</i>
18:40-18:55		Daily Planning Conference ( <i>S-band</i> )
18:55-19:30		Evening work prep
19:30-20:00		DINNER
20:00-20:30	CDR	Daily Food Prep
20:00-20:30	FE-1	Daily Food Prep
20:30-21:30		Pre-sleep
21:30-06:00		SLEEP
<b>Task List</b>	CDR	Search for missing hardware

See OSTP for references to US activities.

End of Radiogram