

Radiogram No. 7093u

Form 24 for 11/06/2014

**TEST OF FGB KURS-P (- Y MRM1) IN A LOOP WITH TK 713 KURS-A WITH PRE-HEATING**

TIME	CREW	CREW
06:00-06:10	<b>CDR</b>	Morning Inspection. Laptop RS1(2) Reboot
06:00-06:10	<b>FE-1</b>	Morning Inspection. Laptop RSS2 Reboot
06:00-06:10	<b>FE-2</b>	Morning Inspection. SM ПСС (Caution & Warning Panel) Test
06:00-06:10	FE-3	Morning Inspection
06:00-06:05	FE-5	Reading REMINDER
06:00-06:05	FE-6	REMINDER - Reading Reminder
06:05-06:10	FE-5	Morning Inspection
06:05-06:20	FE-6	HRF - Generic Sample Operations
06:10-06:40	<b>CDR, FE-1, FE-2, FE-3, FE-5</b>	Post-sleep
06:20-06:25	FE-6	HRF Ops: MELFI Retrieval and Insertion Operations
06:25-06:55	FE-6	Post-sleep
06:40-07:30	<b>CDR, FE-1, FE-2, FE-3, FE-5</b>	BREAKFAST
06:55-07:45	FE-6	BREAKFAST
07:30-07:45	<b>CDR, FE-1, FE-2, FE-3, FE-5</b>	Work Prep
07:45-08:05		Daily Planning Conference ( <i>S-band</i> )
08:05-08:25	<b>CDR, FE-1, FE-2</b>	Work Prep
08:05-08:25	FE-3	Acoustic Dosimeter Ops
08:25-11:25	<b>CDR, FE-5, FE-6</b>	TK 713 Descent OBT. <i>Tagup with specialists</i>
08:25-09:55	<b>FE-1</b>	TKГ 424 (DC1) Transfers and IMS Ops
08:25-09:55	<b>FE-2</b>	RS Lights Audit (SM, MRM1, MRM2, DC1)
08:25-09:55	FE-3	ARED Exercise
09:55-10:40	<b>FE-1, FE-2, FE-3</b>	MEDICAL CONTINGENCY OBT
10:40-12:05	<b>FE-1</b>	БД-2 Exercise, Day 1
10:40-11:40	FE-3	T2 Exercise
10:45-12:00	<b>FE-2</b>	ARED Exercise
11:25-11:35	<b>CDR</b>	Charging GoPro HERO3 Camcorder Battery – start
11:25-11:35	FE-5	SPRINT - Power up and Warm up
11:30-11:45	FE-6	Private Medical Conference
11:35-11:50	<b>CDR</b>	ИП-1 Flow Sensor Position Verification
11:35-11:45	FE-5	Rodent Research Experiment. Rodent Research Sample Transfer from +4 deg C cold Dewar to -95 deg C cold stowage
11:45-12:00	FE-6	BODYM - Gather equipment in preparation for Body Measurements data collection operations
11:50-12:05	FE-3	COL - Clearing COL1D3 items
12:00-12:40	<b>FE-2</b>	COЖ Maintenance
12:00-13:10	FE-5	SPRINT Experiment Ops
12:00-13:30	FE-6	ARED Exercise

12:05-13:00	<b>CDR</b>	LBNP Exercise (PRELIMINARY). <i>Tagup with specialists</i>
12:05-13:00	<b>FE-1</b>	Assisting with LBNP Exercise
12:05-12:15	FE-3	MARES - EPM RUDP Switch Off Verification
12:15-13:50	FE-3	MARES - Battery Replacement
12:40-13:00	<b>FE-2</b>	Preparation for MO-21. Charging of Ekosfera Battery Pack
13:00-14:00	<b>CDR, FE-1, FE-2</b>	LUNCH
13:10-13:20	FE-5	MARES - Vibration Isolation Frame Installation Support
13:40-14:40	FE-5, FE-6	LUNCH
13:50-14:50	FE-3	LUNCH
14:00-15:00	<b>CDR</b>	Crew Departure Prep
14:00-15:00	<b>FE-1</b>	ISTOCHNIK-M. Test Activation of Hardware. <i>Tagup with specialists</i>
14:00-14:40	<b>FE-2</b>	MATRYOSHKA-R. Gathering and Initialization of Bubble-Dosimeter Detectors. <i>Tagup with specialists as necessary</i>
14:40-14:45	<b>FE-2</b>	MATRYOSHKA-R. Handover of BUBBLE-dosimeters to USOS
14:40-14:45	FE-6	RADIN - Handover of detectors
14:45-15:30	<b>FE-2</b>	MATRYOSHKA-R. BUBBLE-dosimeter detector initialization and deployment for exposure. <i>Tagup with specialists as necessary</i>
14:45-15:00	FE-5	Private Medical Conference
14:45-15:00	FE-6	RADIN - Dosimeter Installation
14:50-15:55	FE-3	MARES - Battery Status Monitoring
15:00-15:10	<b>CDR</b>	Charging GoPro HERO3 Camcorder Battery – end
15:10-16:10	<b>CDR</b>	Video camera GoPro HERO3 setup and Adjustment for Operation during TK 713 Descent (settings verification, clearing flash cards, CDR consultations). Removal of attachment plate SM-GoPro-U08 in TK 713 EO for descent stowage. <i>Tagup with specialists</i>
15:10-17:10	<b>FE-1</b>	TKГ 424 (DC1) Transfers
15:10-15:20	FE-6	AMINE - Screen Cleaning
15:20-15:50	FE-6	Crew Departure Prep
15:30-17:30	<b>FE-2</b>	TKГ 424 (DC1) Transfers and IMS Ops
15:30-16:50	FE-5	ARED Exercise
15:50-16:50	FE-6	T2 Exercise
16:00-16:15	FE-3	SDGR2. Crew OBT
16:10-16:40	<b>CDR</b>	IK0501 Gas Analyzer O2 readings adjustments. <b>U= 2.77V</b> . <i>Tagup with specialists</i>
16:15-16:30	FE-3	Private Psychological Conference
16:35-17:10	FE-3	MARES - Disconnecting from PUI
16:40-17:10	<b>CDR</b>	VZAIMODEISTVIYE. Experiment Ops
16:50-17:05	FE-6	MARES - Stowage support
16:55-18:15	FE-5	SPRINT-PPFS - Equipment Stowage
17:05-17:35	FE-6	Crew Departure Prep
17:10-18:10	<b>FE-1</b>	VELO Exercise, Day 1
17:10-17:40	FE-3	Ultrasound 2 - Scanning
17:20-17:35	<b>CDR</b>	Evening Work Prep
17:30-18:45	<b>FE-2</b>	БД-2 Exercise, Day 4
17:35-19:05	<b>CDR</b>	ARED Exercise

17:40-17:50	FE-3	Ultrasound - Scanning Prep
17:50-18:20	FE-3	Ultrasound 2 - Scanning
17:50-18:20	FE-6	Ultrasound 2 - CMO Scanning Ops
18:10-18:50	<b>FE-1</b>	Evening Work Prep
18:15-18:20	FE-5	Space Headaches Weekly Questionnaire
18:20-18:25	FE-3	Ultrasound Scanning
18:20-18:45	FE-5	Evening Work Prep
18:20-18:30	FE-6	MARES - EPM A31p Laptop Stowage
18:25-18:35	FE-3	Ultrasound Data Export
18:30-18:35	FE-6	XF305 - Camcorder Setup
18:35-18:55	FE-6	Installing Water Canister Bag for Crystall Experiment
18:45-19:05	<b>FE-2</b>	Evening Work Prep
18:45-19:05	FE-5	Pre-sleep
18:50-19:05	<b>FE-1</b>	Pre-sleep
18:50-19:05	FE-3	COL - Re-stow items into COL1D3 rack
18:55-19:05	FE-6	Clean Bench (CB) Closeout Prep
19:05-19:25		Daily Planning Conference ( <i>S-band</i> )
19:25-19:45		Flight Director / ISS Crew Tagup
19:45-21:30	<b>CDR, FE-1, FE-2</b>	Pre-sleep
19:45-19:55	FE-3	Terminate EMU METOX Regeneration
19:45-19:50	FE-5	SPRINT - Hardware Deactivation and Closeout
19:45-19:55	FE-6	Closing USOS Window Shutters
19:50-21:25	FE-5	Pre-sleep
19:55-20:00	FE-3	Ultrasound - Stowage
19:55-21:20	FE-6	Pre-sleep
20:00-21:30	FE-3	Pre-sleep
21:20-21:25	FE-6	REMINDER - Reading Body Measures Reminder
21:25-21:30	FE-5	Reading REMINDER
21:25-21:30	FE-6	REMINDER - Reading Reminder
21:30-06:00		SLEEP
<b>Task List</b>	<b>CDR, FE-1, FE-2</b>	Preparation of reports for Roscosmos site
		ECON-M. Observations and Photography
	<b>CDR</b>	IMS Delta File Prep

**Notes:**

1. See OSTPV for references to US activities.
2. Pre-sleep ops: daily food prep, dinner, pre-sleep
3. Russian crew uses US exercise equipment strictly per F24 or OSTPV